

System Reference Codes (Cxxx-Hxxx)

ESCALA Power7



REFERENCE
86 A1 49FF 02

ESCALA Power7

System Reference Codes (Cxxx-Hxxx)

The ESCALA Power7 publications concern the following models:

- Bull Escala E5-700 (Power 750 / 8233-E8B)
- Bull Escala M6-700 (Power 770 / 9117-MMB)
- Bull Escala M6-705 (Power 770 / 9117-MMC)
- Bull Escala M7-700 (Power 780 / 9179-MHB)
- Bull Escala M7-705 (Power 780 / 9179-MHC)
- Bull Escala E1-700 (Power 710 / 8231-E2B)
- Bull Escala E1-705 (Power 710 / 8231-E1C)
- Bull Escala E2-700 / E2-700T (Power 720 / 8202-E4B)
- Bull Escala E2-705 / E2-705T (Power 720 / 8202-E4C)
- Bull Escala E3-700 (Power 730 / 8231-E2B)
- Bull Escala E3-705 (Power 730 / 8231-E2C)
- Bull Escala E4-700 / E4-700T (Power 740 / 8205-E6B)
- Bull Escala E4-705 (Power 740 / 8205-E6C)

References to Power 755 / 8236-E8C models are irrelevant.

Hardware

October 2011

BULL CEDOC
357 AVENUE PATTON
B.P.20845
49008 ANGERS CEDEX 01
FRANCE

REFERENCE
86 A1 49FF 02

The following copyright notice protects this book under Copyright laws which prohibit such actions as, but not limited to, copying, distributing, modifying, and making derivative works.

Copyright © Bull SAS 2011

Printed in France

Suggestions and criticisms concerning the form, content, and presentation of this book are invited. A form is provided at the end of this book for this purpose.

To order additional copies of this book or other Bull Technical Publications, you are invited to use the Ordering Form also provided at the end of this book.

Trademarks and Acknowledgements

We acknowledge the right of proprietors of trademarks mentioned in this book.

The information in this document is subject to change without notice. Bull will not be liable for errors contained herein, or for incidental or consequential damages in connection with the use of this material.

Contents

Safety notices	v	(E302F1xx) Reference codes	171
System reference codes (Cxxx - Hxxx) overview	1	(E302F2xx) Reference codes	173
Block replacement of FRUs	1	(E302F7xx) Reference codes	175
(CBxx) Reference codes	3	(E302F8xx) Reference codes	179
(D818) Reference codes	9	(E302F9xx) Reference codes	201
(D910) Reference codes	11	(E302FAxx) Reference codes	223
(E20x) Reference codes	13	(E302FBxx) Reference codes	241
(E21x) Reference codes	43	(E302FCxx) Reference codes	259
(E22x) Reference codes	55	(E302FDxx) Reference codes	277
(E23x) Reference codes	67	(E302FExx) Reference codes	295
(E24x) Reference codes	81	(E302FFxx) Reference codes	313
(E25x) Reference codes	83	(E303) Reference codes	331
(E26x) Reference codes	91	(E316) Reference codes	345
(E27x) Reference codes	93	(E325) Reference codes	347
(E2Bx) Reference codes	95	(E332) Reference codes	349
(E2Cx) Reference codes	97	(E333) Reference codes	355
(E2Dx) Reference codes	99	(E338) Reference codes	357
(E2Fx) Reference codes	101	(E33A) Reference codes	367
(E2xx) Reference codes	131	(E341) Reference codes	369
(E302E0xx) Reference codes	133	(E35500xx) Reference codes	371
(E302E4xx) Reference codes	143	(E35501xx) Reference codes	377
(E302E5xx) Reference codes	145	(E35502xx) Reference codes	381
(E302EFxx) Reference codes	153	(E35504xx) Reference codes	383
(E302Exxx) Reference codes	159	(E35505xx) Reference codes	389
(E302F0xx) Reference codes	161	(E35507xx) Reference codes	393

(E35508xx) Reference codes	401	(E3E9) Reference codes	489
(E35509xx) Reference codes	405	(E3EA) Reference codes.	491
(E35510xx) Reference codes	413	(E3F0) Reference codes	495
(E35511xx) Reference codes	421	(E3xx) Reference codes	497
(E35A) Reference codes.	423	(EFxx) Reference codes	499
(E35B) Reference codes.	425	(0xxxxx) Reference codes	501
(E35C) Reference codes.	429	(HSCE) Reference codes	505
(E35F) Reference codes	435	(HSCF) Reference codes	525
(E361) Reference codes	437	(HSCI) Reference codes	539
(E369) Reference codes	443	(HSCL0xxx) Reference codes	541
(E36A) Reference codes.	447	(HSCL1xxx) Reference codes	589
(E36B) Reference codes.	449	(HSCL2xxx) Reference codes	617
(E36C) Reference codes.	451	(HSCL3xxx) Reference codes	631
(E372) Reference codes	453	(HSCL4xxx) Reference codes	651
(E392) Reference codes	455	(HSCL7xxx) Reference codes	655
(E39F) Reference codes	457	(HSCL8xxx) Reference codes	657
(E3A2) Reference codes.	459	(HSCL9xxx) Reference codes	661
(E3A3) Reference codes.	461	(HSCLAxxx) Reference codes	673
(E3CA) Reference codes	463	(HSCLBxxx) Reference codes	735
(E3CB) Reference codes	467	(HSCP) Reference codes	737
(E3CD) Reference codes	469	(HSCS) Reference codes	749
(E3CE) Reference codes.	471	Notices	765
(E3D3) Reference codes.	475	Trademarks	766
(E3D4) Reference codes.	477	Electronic emission notices	766
(E3D7) Reference codes.	485	Class A Notices.	767
(E3E4) Reference codes.	487	Class B Notices.	770
		Terms and conditions.	773

Safety notices

Safety notices may be printed throughout this guide:

- **DANGER** notices call attention to a situation that is potentially lethal or extremely hazardous to people.
- **CAUTION** notices call attention to a situation that is potentially hazardous to people because of some existing condition.
- **Attention** notices call attention to the possibility of damage to a program, device, system, or data.

World Trade safety information

Several countries require the safety information contained in product publications to be presented in their national languages. If this requirement applies to your country, a safety information booklet is included in the publications package shipped with the product. The booklet contains the safety information in your national language with references to the U.S. English source. Before using a U.S. English publication to install, operate, or service this product, you must first become familiar with the related safety information in the booklet. You should also refer to the booklet any time you do not clearly understand any safety information in the U.S. English publications.

German safety information

Das Produkt ist nicht für den Einsatz an Bildschirmarbeitsplätzen im Sinne § 2 der Bildschirmarbeitsverordnung geeignet.

Laser safety information

IBM® servers can use I/O cards or features that are fiber-optic based and that utilize lasers or LEDs.

Laser compliance

IBM servers may be installed inside or outside of an IT equipment rack.

DANGER

When working on or around the system, observe the following precautions:

Electrical voltage and current from power, telephone, and communication cables are hazardous. To avoid a shock hazard:

- Connect power to this unit only with the IBM provided power cord. Do not use the IBM provided power cord for any other product.
- Do not open or service any power supply assembly.
- Do not connect or disconnect any cables or perform installation, maintenance, or reconfiguration of this product during an electrical storm.
- The product might be equipped with multiple power cords. To remove all hazardous voltages, disconnect all power cords.
- Connect all power cords to a properly wired and grounded electrical outlet. Ensure that the outlet supplies proper voltage and phase rotation according to the system rating plate.
- Connect any equipment that will be attached to this product to properly wired outlets.
- When possible, use one hand only to connect or disconnect signal cables.
- Never turn on any equipment when there is evidence of fire, water, or structural damage.
- Disconnect the attached power cords, telecommunications systems, networks, and modems before you open the device covers, unless instructed otherwise in the installation and configuration procedures.
- Connect and disconnect cables as described in the following procedures when installing, moving, or opening covers on this product or attached devices.

To Disconnect:

1. Turn off everything (unless instructed otherwise).
2. Remove the power cords from the outlets.
3. Remove the signal cables from the connectors.
4. Remove all cables from the devices

To Connect:

1. Turn off everything (unless instructed otherwise).
2. Attach all cables to the devices.
3. Attach the signal cables to the connectors.
4. Attach the power cords to the outlets.
5. Turn on the devices.

(D005)

DANGER

Observe the following precautions when working on or around your IT rack system:

- Heavy equipment—personal injury or equipment damage might result if mishandled.
- Always lower the leveling pads on the rack cabinet.
- Always install stabilizer brackets on the rack cabinet.
- To avoid hazardous conditions due to uneven mechanical loading, always install the heaviest devices in the bottom of the rack cabinet. Always install servers and optional devices starting from the bottom of the rack cabinet.
- Rack-mounted devices are not to be used as shelves or work spaces. Do not place objects on top of rack-mounted devices.



- Each rack cabinet might have more than one power cord. Be sure to disconnect all power cords in the rack cabinet when directed to disconnect power during servicing.
- Connect all devices installed in a rack cabinet to power devices installed in the same rack cabinet. Do not plug a power cord from a device installed in one rack cabinet into a power device installed in a different rack cabinet.
- An electrical outlet that is not correctly wired could place hazardous voltage on the metal parts of the system or the devices that attach to the system. It is the responsibility of the customer to ensure that the outlet is correctly wired and grounded to prevent an electrical shock.

CAUTION

- Do not install a unit in a rack where the internal rack ambient temperatures will exceed the manufacturer's recommended ambient temperature for all your rack-mounted devices.
- Do not install a unit in a rack where the air flow is compromised. Ensure that air flow is not blocked or reduced on any side, front, or back of a unit used for air flow through the unit.
- Consideration should be given to the connection of the equipment to the supply circuit so that overloading of the circuits does not compromise the supply wiring or overcurrent protection. To provide the correct power connection to a rack, refer to the rating labels located on the equipment in the rack to determine the total power requirement of the supply circuit.
- *(For sliding drawers.)* Do not pull out or install any drawer or feature if the rack stabilizer brackets are not attached to the rack. Do not pull out more than one drawer at a time. The rack might become unstable if you pull out more than one drawer at a time.
- *(For fixed drawers.)* This drawer is a fixed drawer and must not be moved for servicing unless specified by the manufacturer. Attempting to move the drawer partially or completely out of the rack might cause the rack to become unstable or cause the drawer to fall out of the rack.

(R001)

CAUTION:

Removing components from the upper positions in the rack cabinet improves rack stability during relocation. Follow these general guidelines whenever you relocate a populated rack cabinet within a room or building:


- Reduce the weight of the rack cabinet by removing equipment starting at the top of the rack cabinet. When possible, restore the rack cabinet to the configuration of the rack cabinet as you received it. If this configuration is not known, you must observe the following precautions:
 - Remove all devices in the 32U position and above.
 - Ensure that the heaviest devices are installed in the bottom of the rack cabinet.
 - Ensure that there are no empty U-levels between devices installed in the rack cabinet below the 32U level.
- If the rack cabinet you are relocating is part of a suite of rack cabinets, detach the rack cabinet from the suite.
- Inspect the route that you plan to take to eliminate potential hazards.
- Verify that the route that you choose can support the weight of the loaded rack cabinet. Refer to the documentation that comes with your rack cabinet for the weight of a loaded rack cabinet.
- Verify that all door openings are at least 760 x 230 mm (30 x 80 in.).
- Ensure that all devices, shelves, drawers, doors, and cables are secure.
- Ensure that the four leveling pads are raised to their highest position.
- Ensure that there is no stabilizer bracket installed on the rack cabinet during movement.
- Do not use a ramp inclined at more than 10 degrees.
- When the rack cabinet is in the new location, complete the following steps:
 - Lower the four leveling pads.
 - Install stabilizer brackets on the rack cabinet.
 - If you removed any devices from the rack cabinet, repopulate the rack cabinet from the lowest position to the highest position.
- If a long-distance relocation is required, restore the rack cabinet to the configuration of the rack cabinet as you received it. Pack the rack cabinet in the original packaging material, or equivalent. Also lower the leveling pads to raise the casters off of the pallet and bolt the rack cabinet to the pallet.

(R002)


(L001)



(L002)



(L003)



or



All lasers are certified in the U.S. to conform to the requirements of DHHS 21 CFR Subchapter J for class 1 laser products. Outside the U.S., they are certified to be in compliance with IEC 60825 as a class 1 laser product. Consult the label on each part for laser certification numbers and approval information.

CAUTION:

This product might contain one or more of the following devices: CD-ROM drive, DVD-ROM drive, DVD-RAM drive, or laser module, which are Class 1 laser products. Note the following information:

- Do not remove the covers. Removing the covers of the laser product could result in exposure to hazardous laser radiation. There are no serviceable parts inside the device.
- Use of the controls or adjustments or performance of procedures other than those specified herein might result in hazardous radiation exposure.

(C026)

CAUTION:

Data processing environments can contain equipment transmitting on system links with laser modules that operate at greater than Class 1 power levels. For this reason, never look into the end of an optical fiber cable or open receptacle. (C027)

CAUTION:

This product contains a Class 1M laser. Do not view directly with optical instruments. (C028)

CAUTION:

Some laser products contain an embedded Class 3A or Class 3B laser diode. Note the following information: laser radiation when open. Do not stare into the beam, do not view directly with optical instruments, and avoid direct exposure to the beam. (C030)

CAUTION:

The battery contains lithium. To avoid possible explosion, do not burn or charge the battery.

Do Not:

- ___ Throw or immerse into water
- ___ Heat to more than 100°C (212°F)
- ___ Repair or disassemble

Exchange only with the IBM-approved part. Recycle or discard the battery as instructed by local regulations. In the United States, IBM has a process for the collection of this battery. For information, call 1-800-426-4333. Have the IBM part number for the battery unit available when you call. (C003)

Power and cabling information for NEBS (Network Equipment-Building System) GR-1089-CORE

The following comments apply to the IBM servers that have been designated as conforming to NEBS (Network Equipment-Building System) GR-1089-CORE:

The equipment is suitable for installation in the following:

- Network telecommunications facilities
- Locations where the NEC (National Electrical Code) applies

The intrabuilding ports of this equipment are suitable for connection to intrabuilding or unexposed wiring or cabling only. The intrabuilding ports of this equipment *must not* be metallically connected to the interfaces that connect to the OSP (outside plant) or its wiring. These interfaces are designed for use as intrabuilding interfaces only (Type 2 or Type 4 ports as described in GR-1089-CORE) and require isolation from the exposed OSP cabling. The addition of primary protectors is not sufficient protection to connect these interfaces metallically to OSP wiring.

Note: All Ethernet cables must be shielded and grounded at both ends.

The ac-powered system does not require the use of an external surge protection device (SPD).

The dc-powered system employs an isolated DC return (DC-I) design. The DC battery return terminal *shall not* be connected to the chassis or frame ground.

System reference codes (Cxxx - Hxxx) overview

Reference codes are diagnostics aids that help you find solutions to system problems.

Reference codes are diagnostic aids that help you determine the source of a hardware or operating system problem. Using a reference code enables you to find the solution to fix the problem. To use reference codes effectively, you must use them in conjunction with other service and support procedures.

Note: System reference codes (SRCs) often indicate failing items. Some failing items are required to be exchanged in groups until the problem is solved. Other failing items are flagged as mandatory exchange and must be exchanged before the service action is complete, even if the problem appears to have been repaired. For more information, see “Block replacement of FRUs.”

Block replacement of FRUs

Sometimes, multiple field replaceable units (FRUs) or procedures are called out for replacement by an SRC listed in the service action log (SAL). Each FRU or procedure has a priority, and procedures are always in priority order, from highest to lowest priority. Follow the steps below:

1. Perform all high priority or mandatory FRU replacements or procedures at the same time (as a block).
2. If the problem persists after performing the high priority FRU replacements or procedures, then perform the medium priority FRU replacements or procedures one at a time, unless a medium grouping priority is associated with the FRUs or procedures that are called out in the SRC. A medium grouping priority, shown with an A, B, or C, means that you need to perform all the FRU replacements or procedures in that group at the same time (as a block).
3. Finally, if the problem still persists after performing the medium priority FRU replacements or procedures, then perform the low priority FRU replacements or procedures one at a time.

The priorities of performing the FRU replacements or procedures are shown in the following ways, depending on how you view the SRC:

- Advanced System Management Interface (ASMI): The ASMI shows a priority with each callout in the log.
- Control panel: The control panel shows one of the following priorities with each callout:
 - H = High
 - M = Medium
 - MA = Medium group A
 - MB = Medium group B
 - MC = Medium group C
 - L = Low
- Management console: The details of the serviceable event display the FRU replacement priority as high, medium, and so on.
- Service action log: In the SAL, the Part Action for the FRU in the view of the event shows the replacement priority.

(CBxx) Reference codes

The IBM® Network Manager detected a failure.

Record the reference code and the location code, if available, then find the FRU in the *Guide to clustering systems using InfiniBand hardware Installation and service information*.

Note: Reference codes based on events detected by the InfiniBand switches (CBxxxxxx) do not support the Call Home feature. They will not be called home by Electronic Service Agent™. If you attempt to use the manual function to initiate Call Home, it will not successfully generate a service call, and you will not receive any indication that the service call was not generated.

CB100001 CB100001

Explanation: tsSensor::(tsSensor::tsDevSensor Temperature=warning)::1

Failing Item:

- IBNSTHM

CB100002 CB100002

Explanation: tsSensor::(tsSensor::tsDevSensor Temperature=normal)::2

Failing Item:

- IBNSTHM

CB100003 CB100003

Explanation: tsSensor::(tsSensor::tsDevSensor Temperature=critical)::3

Failing Item:

- IBNSTHM

CB102800 CB102800

Explanation: authenticationFailure

Failing Item:

- IBNSAUT

CB108800 CB108800

Explanation: tsCardDown

Failing Item:

- IBNSREM

CB109800 CB109800

Explanation: tsPowerSupplyDown

Failing Item:

- IBNSPOW

CB10A000 CB10A000

Explanation: tsFanDown

Failing Item:

- IBNSFAN

CB10B800 CB10B800

Explanation: tsCardRemove

Failing Item:

- IBNSREM

CB10C100 CB10C100

Explanation: tsEvent::ibSmSlaveToMaster(4)

Failing Item:

- IBNSNLS

CB10C1C0 CB10C1C0

Explanation: tsEvent::ibSmNodeDeleted(7)

Failing Item:

- IBNSNLS

CB10C4C0 CB10C4C0

Explanation: tsEvent::ibSmDbSyncNotSupported(19)

Failing Item:

- IBNSNLS

CB10C500 CB10C500

Explanation: tsEvent::ibSmDbSyncNotEnabled(20)

Failing Item:

- IBNSDBS

CB10C540 CB10C540

Explanation: tsEvent::ibSmDbSyncNoStandby(21)

CB10C580 • CB10C64C

Failing Item:

- IBNSNLS

CB10C580 CB10C580

Explanation: tsEvent::ibSmDbSyncDbVersion Mismatch(22)

Failing Item:

- IBNSSMU

CB10C5C0 CB10C5C0

Explanation: tsEvent::ibSmDbSyncColdSync Timeout (23)

Failing Item:

- IBNSSMR

CB10C600 CB10C600

Explanation: tsEvent::ibSmDbSyncSessionTimeout(24)

Failing Item:

- IBNSDBT

CB10C641 CB10C641

Explanation: tsEvent::hardwareError(25)::local I2C error::1

Failing Item:

- IBNSDIG

CB10C642 CB10C642

Explanation: tsEvent::hardwareError(25)::remote I2C error::2

Failing Item:

- IBNSDGA

CB10C643 CB10C643

Explanation: tsEvent::hardwareError(25)::card seeprom error::3

Failing Item:

- IBNSDIG

CB10C644 CB10C644

Explanation: tsEvent::hardwareError(25)::DiskOnChip Error::4

Failing Item:

- IBNSDIG

CB10C645 CB10C645

Explanation: tsEvent::hardwareError(25)::single bit memory error::5

Failing Item:

- IBNSDIG

CB10C646 CB10C646

Explanation: tsEvent::hardwareError(25)::double bit memory error::6

Failing Item:

- IBNSDIG

CB10C647 CB10C647

Explanation: tsEvent::hardwareError(25)::real-time clock stopped::7

Failing Item:

- IBNSBAT

CB10C648 CB10C648

Explanation: tsEvent::hardwareError(25)::real-time clock sync::8

Failing Item:

- IBNSBAT

CB10C649 CB10C649

Explanation: tsEvent::hardwareError(25)::no fan error::9

Failing Item:

- IBNSFAN

CB10C64A CB10C64A

Explanation: tsEvent::hardwareError(25)::FPGA error::10

Failing Item:

- IBNSDIG

CB10C64B CB10C64B

Explanation: tsEvent::hardwareError(25)::IB switch ASIC error::11

Failing Item:

- IBNSDIG

CB10C64C CB10C64C

Explanation: tsEvent::hardwareError(25)::IB switch firmware error::12

Failing Item:

- IBNSDIG

CB10C64D CB10C64D

Explanation: tsEvent::hardwareError(25)::voltage/current error::13

Failing Item:

- IBNSPOW

CB10C64E CB10C64E

Explanation: tsEvent::hardwareError(25)::cpu ext bus error::14

Failing Item:

- IBNSDIG

CB10C64F CB10C64F

Explanation: tsEvent::hardwareError(25)::cpu bus error::15

Failing Item:

- IBNSDIG

CB10C650 CB10C650

Explanation: tsEvent::hardwareError(25)::fru error::16

Failing Item:

- IBNSDIG

CB10C651 CB10C651

Explanation: tsEvent::hardwareError(25)::local ethernet error::17

Failing Item:

- IBNSDIG

CB10C652 CB10C652

Explanation: tsEvent::hardwareError(25)::management ethernet error::18

Failing Item:

- IBNSDIG

CB10C653 CB10C653

Explanation: tsEvent::hardwareError(25)::cpu error::19

Failing Item:

- IBNSDIG

CB10C654 CB10C654

Explanation: tsEvent::hardwareError(25)::na::20

Failing Item:

- IBNSSWE

CB10C655 CB10C655

Explanation: tsEvent::hardwareError(25)::na::21

Failing Item:

- IBNSSWE

CB10C656 CB10C656

Explanation: tsEvent::hardwareError(25)::na::22

Failing Item:

- IBNSSWE

CB10C657 CB10C657

Explanation: tsEvent::hardwareError(25)::na::23

Failing Item:

- IBNSSWE

CB10C658 CB10C658

Explanation: tsEvent::hardwareError(25)::na::24

Failing Item:

- IBNSSWE

CB10C659 CB10C659

Explanation: tsEvent::hardwareError(25)::na::25

Failing Item:

- IBNSSWE

CB10C65A CB10C65A

Explanation: tsEvent::hardwareError(25)::na::26

Failing Item:

- IBNSSWE

CB10C65B CB10C65B

Explanation: tsEvent::hardwareError(25)::na::27

Failing Item:

- IBNSSWE

CB10C65C CB10C65C

Explanation: tsEvent::hardwareError(25)::na::28

Failing Item:

- IBNSSWE

CB10C65D CB10C65D

Explanation: tsEvent::hardwareError(25)::na::29

Failing Item:

- IBNSSWE

CB10C65E • CB201800

CB10C65E **CB10C65E**

Explanation: tsEvent::hardwareError(25)::na::30

Failing Item:

- IBNSSWE
-

CB10C65F **CB10C65F**

Explanation: tsEvent::hardwareError(25)::na::31

Failing Item:

- IBNSSWE
-

CB10C660 **CB10C660**

Explanation: tsEvent::hardwareError(25)::na::32

Failing Item:

- IBNSSWE
-

CB10C661 **CB10C661**

Explanation: tsEvent::hardwareError(25)::na::33

Failing Item:

- IBNSSWE
-

CB10C662 **CB10C662**

Explanation: tsEvent::hardwareError(25)::na::34

Failing Item:

- IBNSSWE
-

CB10C663 **CB10C663**

Explanation: tsEvent::hardwareError(25)::na::35

Failing Item:

- IBNSSWE
-

CB10C664 **CB10C664**

Explanation: tsEvent::hardwareError(25)::na::36

Failing Item:

- IBNSSWE
-

CB10C665 **CB10C665**

Explanation: tsEvent::hardwareError(25)::na::37

Failing Item:

- IBNSSWE
-

CB10C666 **CB10C666**

Explanation: tsEvent::hardwareError(25)::na::38

Failing Item:

- IBNSSWE
-

CB10C667 **CB10C667**

Explanation: tsEvent::hardwareError(25)::na::39

Failing Item:

- IBNSSWE
-

CB10C6C1 **CB10C6C1**

Explanation: tsEvent::softwareInitiatedReboot(27);
watchdog::1

Failing Item:

- IBNSSWP
-

CB10C6C2 **CB10C6C2**

Explanation: tsEvent::softwareInitiatedReboot(27);
assertion::2

Failing Item:

- IBNSSWP
-

CB10C6C3 **CB10C6C3**

Explanation: tsEvent::softwareInitiatedReboot(27);
out-of-memory::3

Failing Item:

- IBNSSWP
-

CB10C6C4 **CB10C6C4**

Explanation: tsEvent::softwareInitiatedReboot(27); no
working fan::4

Failing Item:

- IBNSFAN
-

CB10C701 **CB10C701**

Explanation: tsEvent::hardwareInitiatedReboot(28);
watchdog::1

Failing Item:

- IBNSSWP
-

CB10FF00 **CB10FF00**

Explanation: VPD problem

Failing Item:

- IBNSVPD
-

CB201800 **CB201800**

Explanation: linkDown

Failing Item:

- IBNSLNK
-

CB20C230 CB20C230

Explanation: tsEvent::ibPmConnectionMonitorUtil
Change(32)

Failing Item:

- IBNSLNK
-

CB20C740 CB20C740

Explanation: tsEvent::ibPmPortMonitorThreshold
ErrorChange(29)

Failing Item:

- IBNSLNK
-

CB20C780 CB20C780

Explanation: tsEvent::ibPmPortMonitorThresholdUtil
Change(30)

Failing Item:

- IBNSLNK
-

CB20C7C0 CB20C7C0

Explanation: tsEvent::ibPmConnectionMonitorError
Change(31)

Failing Item:

- IBNSLNK
-

CBFF0000 CBFF0000

Explanation: Network Manager Diagnostics Event -
Report this side

Failing Item:

- IBNNMD
-

CBFF0001 CBFF0001

Explanation: Network Manager Diagnostics Event -
Report other side

Failing Item:

- IBNNMD
-

CBFF0002 CBFF0002

Explanation: Network Manager Diagnostics Event -
Report cable

Failing Item:

- IBNNMD
-

CBFF00FF CBFF00FF

Explanation: Unrecognized Unit Model

Failing Item:

- IBNNURM

(D818) Reference codes

D8183002 D8183002

Explanation: Addressed device is not responding

Failing Item:

- FCPORT
- FCDEV
- FCIOA
- FCINTF
- OPT_CLN

D8183010 D8183010

Explanation: Disk device returned wrong response to IOP

Failing Item:

- FCDEV
- FCIOA
- OPT_CLN

D8183020 D8183020

Explanation: Storage subsystem configuration error

Response: If an MES is being installed, verify the configuration.

Failing Item:

- FCDEV
- FCIOA
- OPT_CLN

D8183029 D8183029

Explanation: This SRC is surfaced when the IOP detects that a device has changed Serial numbers. A device replacement has occurred.

Response: No action required. This reference code is logged for information only.

D8183100 D8183100

Explanation: Fibre Channel interface error occurred

Failing Item:

- FCINTF
- FCDEV
- FCIOA
- OPT_CLN

D8183109 D8183109

Explanation: IOP timed out a disk command

Failing Item:

- FCDEV
- FCINTF
- FCIOA
- OPT_CLN

D8183160 D8183160

Explanation: The volume in use is no longer accessible

Response: The storage subsystem configuration was changed, causing the volume in use to no longer be accessible.

Failing Item:

- FCDEV

D8183161 D8183161

Explanation: The volume in use is no longer accessible.

Response: Storage subsystem copy services functions have caused the volume in use to no longer be accessible.

Failing Item:

- FCDEV

D81834FF D81834FF

Explanation: Format in progress

Response: The device indicated that a format is in progress. When the format is complete, the device should be useable. No action is required. This reference code is logged for information only.

D818FFF3 D818FFF3

Explanation: Disk media format bad

Failing Item:

- FCDEV

D818FFF4 D818FFF4

Explanation: Disk device problem

Failing Item:

- FCDEV

D818FFF5 D818FFF5

D818FFF6 • D818FFFE

Explanation: Disk sector read error

Failing Item:

- FCDEV
-

D818FFF6 D818FFF6

Explanation: Disk device detected recoverable error

Response: If this event appears in a serviceable event view, work with the failing item list found there. If this event does not appear in a serviceable event view, no service action is required.

Failing Item:

- FCDEV
-

D818FFFA D818FFFA

Explanation: Disk device wrong response was recovered by the IOP

Response: If this event appears in a serviceable event view, work with the failing item list found there. If this event does not appear in a serviceable event view, no service action is required.

Failing Item:

- FCDEV
 - FCIOA
 - OPT_CLN
-

D818FFFE D818FFFE

Explanation: Temporary Fibre Channel interface error.

Response: If this event appears in a serviceable event view, work with the failing item list found there. If this event does not appear in a serviceable event view, no service action is required.

Failing Item:

- FCINTF
- FCDEV
- FCIOA
- OPT_CLN

(D910) Reference codes

D9103002 D9103002

Explanation: Addressed device is not responding

Failing Item:

- FCPORT
- FCDEV
- FCIOA
- FCINTF
- OPT_CLN

D9103010 D9103010

Explanation: Disk device returned wrong response to IOP

Failing Item:

- FCDEV
- FCIOA
- OPT_CLN

D9103020 D9103020

Explanation: Storage subsystem configuration error

Response: If an MES is being installed, verify the configuration.

Failing Item:

- FCDEV
- FCIOA
- OPT_CLN

D9103029 D9103029

Explanation: This SRC is surfaced when the IOP detects that a device has changed Serial numbers. A device replacement has occurred.

Response: No action required. This reference code is logged for information only.

D9103100 D9103100

Explanation: Fibre Channel interface error occurred

Failing Item:

- FCINTF
- FCDEV
- FCIOA
- OPT_CLN

D9103109 D9103109

Explanation: IOP timed out a disk command

Failing Item:

- FCDEV
- FCINTF
- FCIOA
- OPT_CLN

D9103160 D9103160

Explanation: The volume in use is no longer accessible

Response: The storage subsystem configuration was changed, causing the volume in use to no longer be accessible.

Failing Item:

- FCDEV

D9103161 D9103161

Explanation: The volume in use is no longer accessible.

Response: Storage subsystem copy services functions have caused the volume in use to no longer be accessible.

Failing Item:

- FCDEV

D91034FF D91034FF

Explanation: Format in progress

Response: The device indicated that a format is in progress. When the format is complete, the device should be useable. No action is required. This reference code is logged for information only.

D910FFF3 D910FFF3

Explanation: Disk media format bad

Failing Item:

- FCDEV

D910FFF4 D910FFF4

Explanation: Disk device problem

Failing Item:

- FCDEV

D910FFF5 D910FFF5

D910FFF6 • D910FFFE

Explanation: Disk sector read error

Failing Item:

- FCDEV
-

D910FFF6 D910FFF6

Explanation: Disk device detected recoverable error

Response: If this event appears in a serviceable event view, work with the failing item list found there. If this event does not appear in a serviceable event view, no service action is required.

Failing Item:

- FCDEV
-

D910FFFA D910FFFA

Explanation: Disk device wrong response was recovered by the IOP

Response: If this event appears in a serviceable event view, work with the failing item list found there. If this event does not appear in a serviceable event view, no service action is required.

Failing Item:

- FCDEV
 - FCIOA
 - OPT_CLN
-

D910FFFE D910FFFE

Explanation: Temporary Fibre Channel interface error.

Response: If this event appears in a serviceable event view, work with the failing item list found there. If this event does not appear in a serviceable event view, no service action is required.

Failing Item:

- FCINTF
- FCDEV
- FCIOA
- OPT_CLN

(E20x) Reference codes

E202E7BA E202E7BA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory needed to query machine state trying to find out what partitions are LPAR partitions.

Problem determination: Call your next level of support.

E202F0FE E202F0FE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 78 - Error processing an I390 EC file Buffer passed is too small to receive the EC record

Problem determination: Call your next level of support.

E202F105 E202F105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to get a list of files (MCL files). Error reason = rc from xdfc_list_file_mem() This problem has been seen when the disk involved is not formatted. Refer to H5532 (and the older K0048) for further details. Extension is the DOSCALLS reason. Failure is most likely due to a bad build or bad disk.

Problem determination: Call your next level of support.

E202F200 E202F200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to disable CPU alerts during the AROM or manufacturing preload process.

Problem determination: Call your next level of support.

E202F201 E202F201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to enable CPU alerts after completion of the AROM or manufacturing preload process.

Problem determination: Call your next level of support.

E202F210 E202F210

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to disable CPU alerts while installing or removing internal code changes. The extension is the component return code from hosm_enable_cpu_alerts.

Problem determination: Call your next level of support.

E202F211 E202F211

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to enable CPU alerts after installing or removing internal code changes. The extension is the component return code from hosm_disable_cpu_alerts.

Problem determination: Call your next level of support.

E202F212 E202F212

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to execute the xnbGetBooleanArgument program to determine if we are enabling or disabling CPU alerts. The extension is the component return code from xnbGetBooleanArgument.

Problem determination: Call your next level of support.

E202F349 E202F349

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The pointer to the returned data area for the xmcm_query_ec_num() did not point to a valid memory address. The operation is aborted.

Problem determination: Call your next level of support.

E202F34A E202F34A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

E202F34B • E202F353

Response: The pointer to the string input parameter to `xmcm_query_ec_num()` describing the set of EC streams of interest does not point to a valid area of memory that is terminated by a null. The operation is aborted.

Problem determination: Call your next level of support.

E202F34B E202F34B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The string input parameter to `xmcm_query_ec_num()` describing the set of EC streams of interest does not contain a valid value. The valid values are "SYSTEM", "MAJOR", and "ALL" for the current implementation. The operation is aborted.

Problem determination: Call your next level of support.

E202F34C E202F34C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to instantiate an `EcVpdService Java™` object across the native interface. The attempt failed and the return code from `xnbInstantiateObject()` is the component return code of this log entry. The operation is aborted.

Problem determination: Call your next level of support.

E202F34D E202F34D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to execute the `EcVpdService.getEcCount()` method and the native bridge interface call, `xnbCallIntMethod()`, indicated the attempt failed. The component return code indicates the nature of the error. The operation is aborted.

Problem determination: Call your next level of support.

E202F34E E202F34E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted to release our reference to the `EcVpdService` object we instantiated for this request. The `xnbReleaseObjectReference()` failed and the component return code indicates the nature of the error. The operation is allowed to continue. The side effect is that the storage associates with the `EcVpdService` object will not be recovered until the next reboot.

Problem determination: Call your next level of support.

E202F34F E202F34F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The pointer to the string input parameter to `xmcm_ec_vpd()` describing the set of EC streams of interest does not point to a valid area of memory that is terminated by a null. The operation is aborted.

Problem determination: Call your next level of support.

E202F350 E202F350

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The pointer to the returned data area for the `xmcm_ec_vpd()` did not point to a valid memory area large enough to contain the output data. The operation is aborted.

Problem determination: Call your next level of support.

E202F351 E202F351

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The action input parameter to `xmcm_ec_vpd()` is not a value that is allowed. The valid values are 'R' and 'r'. The trace content will indicate the value provided. The operation is aborted.

Problem determination: Call your next level of support.

E202F352 E202F352

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The string input parameter to `xmcm_ec_vpd()` describing the set of EC streams of interest does not contain a valid value. The valid values are "SYSTEM", "MAJOR", and "ALL" for the current implementation. The operation is aborted.

Problem determination: Call your next level of support.

E202F353 E202F353

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to instantiate an `EcVpdService Java` object across the native interface. The attempt failed and the return code from `xnbInstantiateObject()` is the component return code of

this log entry. The operation is aborted.

Problem determination: Call your next level of support.

E202F354 E202F354

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to execute the EcVpdService.getEcVpdBytes() method and the native bridge interface, xnbCallObjectMethod(), indicated the attempt failed. The component return code indicates the nature of the error. The operation is aborted.

Problem determination: Call your next level of support.

E202F355 E202F355

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted to obtain the length of the data being returned from Java method used by this request. The xnbGetArrayLength() request failed and the component return code indicates the nature of the error. The operation is aborted.

Problem determination: Call your next level of support.

E202F356 E202F356

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: If the number of bytes of data returned from the Java method used by this request does not match the number of bytes in the buffer provided by the caller. The operation is aborted.

Problem determination: Call your next level of support.

E202F357 E202F357

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to transfer the data from the Java machine to to the callers buffer. The native bridge interface call to xnbGetByteArrayElements() failed. The component return code indicates the nature of the error. The operation is aborted.

Problem determination: Call your next level of support.

E202F358 E202F358

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted to release our reference to the EcVpdService object we instantiated for this request. The xnbReleaseObjectReference() failed and the component return code indicates the nature of the error. The operation is allowed to continue. The side effect is that the storage associates with the EcVpdService object will not be recovered until the next reboot.

Problem determination: Call your next level of support.

E202F359 E202F359

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted to release our reference to the data object used to return the data from the Java method used by this request. The xnbReleaseObjectReference() operation failed and the component return code indicates the nature of the error. The operation is allowed to continue. The side effect is that the storage associates with the EcVpdService object will not be recovered until the next reboot.

Problem determination: Call your next level of support.

E202F670 E202F670

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted to get a list of CF partitions on the machine, but failed. The extension is the component return code from xmcm_get_cf_partitions.

Problem determination: Call your next level of support.

E202F6A2 E202F6A2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to call the routine to load the cage controller code. We were applying MCLs disruptively. The extension is the component return code from pscnUpdateCCLoad.

Problem determination: Call your next level of support.

E202F6C0 E202F6C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The component return code pointer passed to xmcm_query_cdu_min_max() is not valid.

E202F6C1 • E202F6C9

Problem determination: Call your next level of support.

E202F6C1 E202F6C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The count pointer passed to `xmcm_query_cdu_min_max()` is not valid.

Problem determination: Call your next level of support.

E202F6C2 E202F6C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The pointer to the address to put the output buffer pointer passed to `xmcm_query_cdu_min_max()` is not valid.

Problem determination: Call your next level of support.

E202F6C3 E202F6C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to obtain a reference to the Java `CduMinMaxData` singleton object in `xmcm_query_cdu_min_max()`. The extension is the component return code. The component return code indicates the nature of that error.

Problem determination: Call your next level of support.

E202F6C4 E202F6C4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to obtain a reference to the Java byte array that contains the data that would be returned from `xmcm_query_cdu_min_max()`. The extension is the component return code. The component return code indicates the nature of that error.

Problem determination: Call your next level of support.

E202F6C5 E202F6C5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to obtain the length of the Java byte array that contains the data that would be returned from `xmcm_query_cdu_min_max()`. The extension is the

component return code. The component return code indicates the nature of that error.

Problem determination: Call your next level of support.

E202F6C6 E202F6C6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to obtain storage for the data that would be returned from `xmcm_query_cdu_min_max()`. The extension is the amount of storage that was requested.

Problem determination: Call your next level of support.

E202F6C7 E202F6C7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to transfer the output data from the Java byte array that contains the data that would be returned from `xmcm_query_cdu_min_max()` to the output buffer. The extension is the component return code. The component return code indicates the nature of that error.

Problem determination: Call your next level of support.

E202F6C8 E202F6C8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to release our reference to the singleton `CduMinMaxData` object. The extension is the component return code. The component return code indicates the nature of that error. This error does not prevent the operation from completing successfully.

Problem determination: Call your next level of support.

E202F6C9 E202F6C9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to release our reference byte array that contains the data that would be returned from `xmcm_query_cdu_min_max()`. The extension is the component return code. The component return code indicates the nature of that error. This error does not prevent the operation from completing successfully.

Problem determination: Call your next level of support.

E202F702 E202F702

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error converting received MCL level from the ECC or ECD file, while attempting to determine the installable concurrent and removable concurrent MCL levels

Problem determination: Call your next level of support.

E202F703 E202F703

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error converting accepted MCL level from the ECC or ECD file, while attempting to determine the installable concurrent and removable concurrent MCL levels

Problem determination: Call your next level of support.

E202F704 E202F704

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error converting activated MCL level from the ECC or ECD file, while attempting to determine the installable concurrent and removable concurrent MCL levels

Problem determination: Call your next level of support.

E202F70F E202F70F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading XMCF_I390PU_EC SIM field. The extension is the return code from xsim_read.

Problem determination: Call your next level of support.

E202F710 E202F710

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to determine whether to ignore the I390MC ECD file or the I390UC ECD file. An extension of 2 means we cannot find the ECD file to save. An extension of 4 means we cannot find the ECD file to ignore. Recovery: Run the ECD recovery icon under change management.

Problem determination: Call your next level of support.

E202F711 E202F711

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing XMCF_I390PU_EC SIM field. The extension is the return code from xsim_write.

Problem determination: Call your next level of support.

E202F712 E202F712

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error deleting the ECD file that is for the I390 system (microcode or millicode) that this machine is NOT. The extension is the return code from DFC

Problem determination: Call your next level of support.

E202F713 E202F713

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage to check the machine state to see if it is in status check

Problem determination: Call your next level of support.

E202F714 E202F714

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to check whether the machine is status checked or not. The extension is the component return code from xccf_st_machine.

Problem determination: Call your next level of support.

E202F715 E202F715

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing XMCF_I390PU_MCL SIM field. The extension is the return code from xsim_write.

Problem determination: Call your next level of support.

E202F716 E202F716

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening the ECD file when we are attempting to write the ignore_me bit. The extension is the return code from DFC

E202F717 • E202F721

Problem determination: Call your next level of support.

E202F717 E202F717

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading the ECD file when we are attempting to write the ignore_me bit. The extension is the return code from DFC

Problem determination: Call your next level of support.

E202F718 E202F718

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing the ECD file when we are attempting to write the ignore_me bit. The extension is the return code from DFC

Problem determination: Call your next level of support.

E202F719 E202F719

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing the ECD file when we are attempting to write the ignore_me bit. The extension is the return code from DFC

Problem determination: Call your next level of support.

E202F71A E202F71A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error handling the ECD file when we are attempting to write the ignore_me bit. The extension is the return code from ignore_this_ec

Problem determination: Call your next level of support.

E202F71B E202F71B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing XMCF_I390PH_EC SIM field. The extension is the return code from xsim_write.

Problem determination: Call your next level of support.

E202F71C E202F71C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing XMCF_I390PH_MCL SIM field. The extension is the return code from xsim_write.

Problem determination: Call your next level of support.

E202F71D E202F71D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage to check the machine type.

Problem determination: Call your next level of support.

E202F71E E202F71E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling VPD manager to discover the machine type. The extension is the return code from xvpd_mgr.

Problem determination: Call your next level of support.

E202F71F E202F71F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling query_machine_type to find the machine type. The extension is the component return code from query_machine_type

Problem determination: Call your next level of support.

E202F720 E202F720

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling query_machine_type to find the machine type. The extension is the component return code from query_machine_type

Problem determination: Call your next level of support.

E202F721 E202F721

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to compute whether the CF concurrent patches are concurrent. The extension is the return code from concur_mcl_data.

Problem determination: Call your next level of support.

E202F722 E202F722

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error converting the installable concurrent MCL level that was stored in a buffer to an integer This occurred while we were attempting to discover what MCLs can be installed concurrently.

Problem determination: Call your next level of support.

E202F723 E202F723

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error converting the removable concurrent MCL level that was stored in a buffer to an integer This occurred while we were attempting to discover what MCLs can be removed concurrently.

Problem determination: Call your next level of support.

E202F724 E202F724

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to determine if the XCrypto feature is installed on this machine. The extension is the component return code from hcon_get_xcrypto_hw_status.

Problem determination: Call your next level of support.

E202F725 E202F725

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to determine if the LD-IPL feature is enabled on this machine. The extension is the component return code from hcon_get_ldipl_status.

Problem determination: Call your next level of support.

E202F780 E202F780

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during check of dependencies while attempting to establish installable concurrent level

Problem determination: Call your next level of support.

E202F781 E202F781

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during call to find and process ECs while attempting to determine concurrency of dependencies.

Problem determination: Call your next level of support.

E202F782 E202F782

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during call to find and process ECs while attempting to determine concurrency of dependencies. This EC is part of a group of ECs that are ORed together.

Problem determination: Call your next level of support.

E202F783 E202F783

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error converting MCL level of an PREREQ or COREQ dependency, while attempting to determine the installable concurrent and removable concurrent MCL levels

Problem determination: Call your next level of support.

E202F784 E202F784

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during call to check a set of PREREQ or COREQ MCLs for installable concurrency. The extension is the component return code for concur_mcl_data.

Problem determination: Call your next level of support.

E202F785 E202F785

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during call to check a set of COREQ MCLs for removable concurrency. The extension is the component return code for concur_mcl_data.

Problem determination: Call your next level of support.

E202F786 • E202F78F

E202F786 E202F786

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during call to update the MCL concurrency levels for a PREREQ or COREQ MCL. The extension is the component return code for `concur_mcl_data`.

Problem determination: Call your next level of support.

E202F787 E202F787

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during call to update the MCL concurrency levels for an ACTREQ MCL. The extension is the component return code for `concur_mcl_data`.

Problem determination: Call your next level of support.

E202F788 E202F788

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error converting MCL level of an ACTREQ dependency, while attempting to determine the installable concurrent and removable concurrent MCL levels

Problem determination: Call your next level of support.

E202F789 E202F789

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during check of dependencies while attempting to establish installable concurrent level

Problem determination: Call your next level of support.

E202F78A E202F78A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: 86 - Error during search for MCLs that were forced to removable concurrent. A part number in the MCL could not be found in the buffer. This error can probably only be caused by memory becoming corrupted.

Problem determination: Call your next level of support.

E202F78B E202F78B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to reset the EC streams to the activated level, we took an error while querying the number of EC streams on the platform. The error is the return code from `xmcm_query_ec_num`.

Problem determination: Call your next level of support.

E202F78C E202F78C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to reset the EC streams to the activated level, we took an error while allocating memory to read in the EC streams that are on this platform. We are either out of memory or there are no EC streams on the platform.

Problem determination: Call your next level of support.

E202F78D E202F78D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to reset the EC streams to the activated level, we took an error while reading the EC streams on the platform. The error is the return code form `xmcm_ec_vpd`.

Problem determination: Call your next level of support.

E202F78E E202F78E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to reset the EC streams to the activated level, we took an error while reading the current date and time. The error is the return code form `xcsf_get_tod`.

Problem determination: Call your next level of support.

E202F78F E202F78F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to reset the EC streams to the activated level, we took an error while setting all EC levels on the platform to the activated level. The error is the return code form `xmcm_ec_vpd`.

Problem determination: Call your next level of support.

E202F7AA E202F7AA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While processing a patch session that includes the REACTIVATE_CFPS keyword, we attempted to get a list of CF partitions on the machine, but failed. The extension is the component return code from xmcm_get_cf_partitions.

Problem determination: Call your next level of support.

E202F7AB E202F7AB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to read the SIM field which indicates whether or not the REACTIVATE_CFPS SIM field has been encountered during this concurrent patch session. The extension is the component return code from xsim_read.

Problem determination: Call your next level of support.

E202F7AC E202F7AC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to read the SIM field which indicates which partitions need to be activated to complete processing of a CF concurrent patch. The extension is the component return code from xsim_read.

Problem determination: Call your next level of support.

E202F7AD E202F7AD

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to write the SIM field to indicate which partitions need to be activated, as a result of processing a REACTIVATE_CFPS SIM field. The extension is the component return code from xsim_write.

Problem determination: Call your next level of support.

E202F7AE E202F7AE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to write the SIM field which indicates what components have concurrent patch pending. The extension is the component return code from xsim_write.

Problem determination: Call your next level of support.

E202F7AF E202F7AF

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to read the SIM field which indicates what components have concurrent patch pending. The extension is the component return code from xsim_read.

Problem determination: Call your next level of support.

E202F7B0 E202F7B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Failed while trying to close the MCL list of as-required MCFs which are to be backed off. The extension is the component return code from xdfc_close_file.

Problem determination: Call your next level of support.

E202F7B1 E202F7B1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Failed while trying to open the MCL list of as-required MCFs which are to be backed off. The extension is the component return code from xdfc_search_file_open.

Problem determination: Call your next level of support.

E202F7B2 E202F7B2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Failed while trying to open the MCL list of as-required MCFs which are to be backed off. The extension is the component return code from xdfc_random_write.

Problem determination: Call your next level of support.

E202F7B3 E202F7B3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Failed while trying to close the MCL list of as-required MCFs which are to be backed off. The extension is the component return code from xdfc_close_file.

E202F7B4 • E202F7BE

Problem determination: Call your next level of support.

E202F7B4 E202F7B4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to get the file size of IQZMAREQ.DAT while checking whether we have as-required MCFs which can be activated.

Problem determination: Call your next level of support.

E202F7B5 E202F7B5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to get the file size of IQZMDEAC.DAT while checking whether we have as-required MCFs which can be deactivated.

Problem determination: Call your next level of support.

E202F7B6 E202F7B6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to get the file size of IQZMACT.DAT while checking whether we have as-required MCFs which can be activated.

Problem determination: Call your next level of support.

E202F7B7 E202F7B7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to rebuild IQZMAREQ.DAT based on which as-required MCFs are activated and deactivated. The extension is the return code from xmcm_redo_areq.

Problem determination: Call your next level of support.

E202F7B8 E202F7B8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while attempting to write the SIM field which indicates that we are working with as-required MCFs. The extension is the component return code from xsim_write.

Problem determination: Call your next level of support.

E202F7B9 E202F7B9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while calling the service required query function. The extension is the return code from xsrs_service_req_state.

Problem determination: Call your next level of support.

E202F7BB E202F7BB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling the routine to get all of the partition information on the machine, trying to find out which partitions are CF partitions. The extension is the return code from xuat_getpath.

Problem determination: Call your next level of support.

E202F7BC E202F7BC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling routine to check if a partition is a CF partiton. The extension is the component return code from xlpr_pcs_ck_partn_mode_zd

Problem determination: Call your next level of support.

E202F7BD E202F7BD

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling machine state trying to find out which partitions are CF partitions. The extension is the return code from xcsf_st_machine.

Problem determination: Call your next level of support.

E202F7BE E202F7BE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory needed to recieve the list of valid LPAR partitions The extension is the component return code from mcm_get_cf_partitions.

Problem determination: Call your next level of support.

E202F7BF **E202F7BF**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to copy the dump load file, prior to executing a concurrent patch which is to process coupling facility files. The code was unable to copy BB6CCFCP.DAT to BB6CCFCP.DAT The extension is the component return code from xdfc_file_copy.

Problem determination: Call your next level of support.

E202F7E8 **E202F7E8**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbInstantiateObject() failed. The error reason code indicates the nature of the error. The operation will be terminated as a failure.

Problem determination: Call your next level of support.

E202F7E9 **E202F7E9**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbCallIntMethod() failed. The error reason code indicates the nature of the error. This does not mean that the operation generated an error, but that there was an error trying to invoke the method to perform the operation. The operation will be terminated as a failure.

Problem determination: Call your next level of support.

E202F7EA **E202F7EA**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbReleaseObjectReference() failed when attempting to release the reference to the task object. The error reason code indicates the nature of the error. This error does not have any effect on the operation being processed. Some Java resources may not have been cleaned up.

Problem determination: Call your next level of support.

E202F7EB **E202F7EB**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbCallStaticObjectMethod() failed. It was attempting to get an instance of the BaseTower. The error reason code indicates the nature of the error.

The operation will be terminated as a failure.

Problem determination: Call your next level of support.

E202F7EC **E202F7EC**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbCallVoidMethod() failed. It was attempting to call the setUpdatingDisabled method in BaseTower. The error reason code indicates the nature of the error. This does not mean that the operation generated an error, but that there was an error trying to invoke the method to perform the operation. The operation will be terminated as a failure.

Problem determination: Call your next level of support.

E202F7ED **E202F7ED**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbReleaseObjectReference() failed when attempting to release the reference to the BaseTower. The error reason code indicates the nature of the error. This error does not have any effect on the operation being processed. Some Java resources may not have been cleaned up.

Problem determination: Call your next level of support.

E202F7EE **E202F7EE**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbCallBooleanMethod() failed. It was attempting to call the isUpdatingDisabled method in BaseTower. The error reason code indicates the nature of the error. This does not mean that the operation generated an error, but that there was an error trying to invoke the method to perform the operation. The operation will be terminated as a failure. start -59

Problem determination: Call your next level of support.

E202F7EF **E202F7EF**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to read an entire file into memory. Some aspect of the operation had an unexpected error. The error reason code indicates the nature of the error. 1 Bad component return code pointer argument 2 Bad filename argument 3 Bad data pointer argument 4 File not found or error getting file

E202F7F2 • E202FB06

size 5 Error allocating storage for file contents 6 Error opening file 7 Error reading file 8 Error closing file end -59 start -60 Note that 0xF7F0-0xF7F1 are reserved for another module

Problem determination: Call your next level of support.

E202F7F2 E202F7F2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to make a Java String object from the input C string and there was an unexpected error. The error reason code indicates the return code from the `xnbCreateStringFromUTF8()` call. The operation of permanently disabling change management fails.

Problem determination: Call your next level of support.

E202F7F3 E202F7F3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to call the `PermanentDisabling.disable()` method and there was an unexpected error. The error reason code indicates the return code from the `xnbCallStaticVoidMethod()` call. The operation of permanently disabling change management fails.

Problem determination: Call your next level of support.

E202F7F4 E202F7F4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to release the reference to a Java String used for the `PermanentDisabling.disable()` call and there was an unexpected error. The error reason code indicates the return code from the `xnbReleaseObjectReference()` call. The operation of permanently disabling change management is not affected by this error. end -60

Problem determination: Call your next level of support.

E202FB00 E202FB00

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error obtaining `bApply` argument. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB01 E202FB01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error obtaining `bRestore` argument. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB02 E202FB02

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error obtaining components argument. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB03 E202FB03

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error converting string of components to MISC and CHANNEL type masks. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB04 E202FB04

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error from concurrent activate. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB05 E202FB05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to return void result. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB06 E202FB06

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to write the `XMCF_MISC_TYPER SIM` field. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB07 E202FB07

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error returned from xmcmUpdateChannelLoadMask(). Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB08 E202FB08

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to write the XMCF_MISC_TYPES SIM field. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB0B E202FB0B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error obtaining CSA_MODE_IS_OK state from Java. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB0C E202FB0C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending CSA_MODE_IS_OK hardware message. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB0E E202FB0E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to allocate storage to determine components being patched. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB0F E202FB0F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error attempting to properly set service required state. This does not affect the completion of concurrent patch.

Problem determination: Call your next level of support.

E202FB10 E202FB10

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error obtaining IFCCS_MAY_OCCUR state from Java. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB11 E202FB11

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending IFCCS_MAY_OCCUR hardware message. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB12 E202FB12

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the array argument value from the native bridge. The xmcm_get_cf_partitions_bridge operation fails.

Problem determination: Call your next level of support.

E202FB13 E202FB13

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to create a string from an UTF8 element The xmcm_get_cf_partitions_bridge operation fails.

Problem determination: Call your next level of support.

E202FB14 E202FB14

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to set an array element into the array. The xmcm_get_cf_partitions_bridge operation fails.

Problem determination: Call your next level of support.

E202FB15 • E202FB1E

E202FB15 E202FB15

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to set the array back to the Java caller. The xmcm_get_cf_partitions_bridge operation fails.

Problem determination: Call your next level of support.

E202FB16 E202FB16

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from xmcm_get_cf_partitions_bridge() across the native bridge back to the calling Java method.

Problem determination: Call your next level of support.

E202FB17 E202FB17

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error obtaining REACTIVATE_CFPS state from Java.

Problem determination: Call your next level of support.

E202FB18 E202FB18

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory to receive the buffer containing information about active coupling facility partitions.

Problem determination: Call your next level of support.

E202FB19 E202FB19

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error running the program to receive the buffer containing information about active coupling facility partitions. The extension is the component return code from xmcm_get_cf_partitions

Problem determination: Call your next level of support.

E202FB1A E202FB1A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory to receive the buffer containing information . about active coupling facility partitions.

Problem determination: Call your next level of support.

E202FB1B E202FB1B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling routine to check if a CF partition is active. The extension is the component return code from xlpr_pcs_check_partn_active

Problem determination: Call your next level of support.

E202FB1C E202FB1C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading the XMCF_CHL_TYPES SIM field to obtain the mask that represents which channel types are about to be patched. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB1D E202FB1D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading the XMCF_CONFIG_OFF_ON SIM field to obtain the mask that represents which channel types which are to be placed in config off-on mode. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB1E E202FB1E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading the XMCF_CONFIG_OFF_ON_OVER SIM field to obtain the mask that represents which channel types which are to be placed in config off-on mode. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB1F E202FB1F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing the XMCF_CONFIG_OFF_ON SIM field to supply the mask that represents which channel types which are to be placed in config off-on mode. Concurrent patch fails.

Problem determination: Call your next level of support.

E202FB20 E202FB20

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from xmcmCheckForCfccTraps() across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB21 E202FB21

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from xmcmCheckForLparTraps() across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB22 E202FB22

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the undo argument value from the native bridge. The xmcmLoadCcAndPowerCode() operation fails.

Problem determination: Call your next level of support.

E202FB23 E202FB23

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to undo the IML via yimlp_fnUndoIml(). The patch operation is allowed to continue.

Problem determination: Call your next level of support.

E202FB24 E202FB24

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the doPower argument value from the native bridge. The xmcmLoadCcAndPowerCode() operation fails.

Problem determination: Call your next level of support.

E202FB25 E202FB25

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the doCc argument value from the native bridge. The xmcmLoadCcAndPowerCode() operation fails.

Problem determination: Call your next level of support.

E202FB26 E202FB26

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from xmcmLoadCcAndPowerCode() across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB27 E202FB27

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to load the power code disruptively. The xmcmLoadCcAndPowerCode() operation fails.

Problem determination: Call your next level of support.

E202FB28 E202FB28

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to load the cage controller code disruptively. The xmcmLoadCcAndPowerCode() operation fails.

Problem determination: Call your next level of support.

E202FB29 E202FB29

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to determine if there are any channel patches pending activation. The `xmcmQueryChannelsPending()` operation fails.

Problem determination: Call your next level of support.

E202FB2A E202FB2A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from `xmcmQueryChannelsPending()` across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB2B E202FB2B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the data argument value from the native bridge. The `xmcmWritePatchLog()` operation fails.

Problem determination: Call your next level of support.

E202FB2C E202FB2C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from `xmcmWritePatchLog()` across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB2D E202FB2D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to release the resources associated with the data argument value obtained from the native bridge. The `xmcmWritePatchLog()` operation ignores this error.

Problem determination: Call your next level of support.

E202FB2E E202FB2E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to write to the patch log. The `xmcmWritePatchLog()` operation fails.

Problem determination: Call your next level of support.

E202FB2F E202FB2F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to load the `libbbrfedf.so` shared object that contains the `pedf_reset()` entry point we need to call. We encountered an `EDF_RESET` keyword in an MCF and we were trying to reset the engineering data shared memory by calling `pedf_reset()`. The `pedf_reset()` reset operation fails. Engineering Data does not get reset.

Problem determination: Call your next level of support.

E202FB30 E202FB30

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error returned from `pedf_reset()`. We encountered an `EDF_RESET` keyword in an MCF and we were trying to reset the engineering data shared memory by calling `pedf_reset()`. Most likely, the Engineering Data did not get reset.

Problem determination: Call your next level of support.

E202FB31 E202FB31

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to release the `libbbrfedf.so` shared object that contains the `pedf_reset()` entry point we called. We were processing an `EDF_RESET` keyword in an MCF. We reset the engineering data shared memory by calling `pedf_reset()`. The Engineering Data was reset.

Problem determination: Call your next level of support.

E202FB32 E202FB32

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from `xmcmEdfReset()` across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB33 E202FB33

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling ckptr on incoming crc variable in xmcm_ImlTrackingInit.

Problem determination: Call your next level of support.

E202FB34 E202FB34

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling xmcm_IMLCompChk from xmcm_ImlTrackingInit.

Problem determination: Call your next level of support.

E202FB35 E202FB35

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling x2se_read_savearea from xmcm_ImlTrackingInit.

Problem determination: Call your next level of support.

E202FB36 E202FB36

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling xnbCreateNamedStringFromUTF8 to put the MCF MCLs that need to be tracked (from i390 mem) into NB registry. This was called from xmcm_ImlTrackingInit.

Problem determination: Call your next level of support.

E202FB37 E202FB37

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling xnbCallStaticVoidMethod to kick off the Java static method ImlTrackingRequiredMgr.warmstartInit. This was called from xmcm_ImlTrackingInit.

Problem determination: Call your next level of support.

E202FB38 E202FB38

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to determine if concurrent patch is enabled. The xmcmGetConcurrentPatchStatus() operation fails.

Problem determination: Call your next level of support.

E202FB39 E202FB39

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from xmcmGetConcurrentPatchStatus() across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB3A E202FB3A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the array argument value from the native bridge. The xmcmQueryChannelsPendingInfo operation fails.

Problem determination: Call your next level of support.

E202FB3B E202FB3B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to set an array element into the array. The xmcmQueryChannelsPendingInfo operation fails.

Problem determination: Call your next level of support.

E202FB3C E202FB3C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to set the array back to the Java caller. The xmcmQueryChannelsPendingInfo operation fails.

Problem determination: Call your next level of support.

E202FB3D • E202FB47

E202FB3D E202FB3D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from `xmcmQueryChannelsPendingInfo()` across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB3E E202FB3E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the data argument value from the native bridge. The `xmcmForceChannelPatch()` operation fails.

Problem determination: Call your next level of support.

E202FB3F E202FB3F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to force changes to the channels pending activation. The `xmcmForceChannelPatch()` operation fails.

Problem determination: Call your next level of support.

E202FB40 E202FB40

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from `xmcmForceChannelPatch()` across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB41 E202FB41

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to get memory in `xmcmReadI390ImlTracking`.

Problem determination: Call your next level of support.

E202FB42 E202FB42

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform a SIM read.

Problem determination: Call your next level of support.

E202FB43 E202FB43

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform a SIM write

Problem determination: Call your next level of support.

E202FB44 E202FB44

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to allocate memory in `xmcmWriteI390ImlTracking`.

Problem determination: Call your next level of support.

E202FB45 E202FB45

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from `xmcmSendDisableCMTtoHMC()` across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB46 E202FB46

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from `xmcmSetBacklevelPartitions()` across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB47 E202FB47

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the array argument value from the native bridge. The `xmcmQueryPendingChannelTypes` operation fails.

Problem determination: Call your next level of support.

E202FB48 E202FB48

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling the xmcmQueryConfigOffPendingTypes routine, attempting to discover which channel components are pending a config off for channels in the system. The extension is the component return code from xmcmQueryConfigOffPendingTypes

Problem determination: Call your next level of support.

E202FB49 E202FB49

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the mask of channel components which are pending a config off in the system. The extension is the component return code from xnbSetByteArrayElement

Problem determination: Call your next level of support.

E202FB4A E202FB4A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to return the output value from xmcmQueryPendingChannelTypes() across the native bridge to the calling Java method.

Problem determination: Call your next level of support.

E202FB50 E202FB50

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error instantiating Java class for intermediate report sending

Problem determination: Call your next level of support.

E202FB51 E202FB51

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending actual report data to Java method

Problem determination: Call your next level of support.

E202FB58 E202FB58

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An EC stream that is associated with a particular channel patch load is not present on the system. This implies that an EC is missing or that a channel load that is defined in the system cannot be patched. Also, it is possible that the channel load should not be defined on the system or that the ECD file for the EC stream does not have the correct content. This will not impair the processing for any other channel loads. The EC stream type for the missing channel load(s) can be found in the trace information for this log entry.

Problem determination: Call your next level of support.

E202FB59 E202FB59

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IO error occurred when we attempted to write to the data iqzm.channel_ec_mcl.data file. The component return code in the log entry indicates the operation that encountered the error (1003 - open, 1004 - write, 1005 - close). The trace information in the log entry will show the component return code from the operation.

Problem determination: Call your next level of support.

E202FB5A E202FB5A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the use of the native bridge support used to obtain EC stream and installed level data to place in the data iqzm.channel_ec_mcl.data file. The component return code in the log entry indicates the native bridge operation that encountered the error. The trace information in the log entry will show the component return code from the operation.

Problem determination: Call your next level of support.

E202FB5B E202FB5B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This function requires the Java tower support to be running to obtain the necessary information. This log indicates that the towers and the associated framework support are not running. This operation cannot be performed without the SE being operational.

E202FB5C • E202FE07

Problem determination: Call your next level of support.

E202FB5C E202FB5C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected, unrecognized error is being reported from iqzmcchut.c. Examination of the traces in the log entry will be required to determine the nature of the problem.

Problem determination: Call your next level of support.

E202FB60 E202FB60

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbCallBooleanMethod() failed. It was attempting to call the areTempMCFsApplied method in BaseTower. The error reason code indicates the nature of the error. The operation will be terminated as a failure.

Problem determination: Call your next level of support.

E202FB61 E202FB61

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Call to xnbCallStaticBooleanMethod() failed. It was attempting to call PermanentDisabling.isDisabled. The error reason code indicates the nature of the error. The operation will be terminated as a failure.

Problem determination: Call your next level of support.

E202FE00 E202FE00

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: unable to get addressability to the shared memory buffer --- no longer used ---

Problem determination: Call your next level of support.

E202FE01 E202FE01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_query_file_location error error reason = DFC's rc --- no longer used ---

Problem determination: Call your next level of support.

E202FE02 E202FE02

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_delete_file failed error reason = DFC's rc --- no longer used ---

Problem determination: Call your next level of support.

E202FE03 E202FE03

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: trace_index_file failed error reason = func's rc make sure trace index file iqzmtinx.trm exists and is valid.

Problem determination: Call your next level of support.

E202FE04 E202FE04

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: trace_index_file failed error reason = func's rc make sure trace index file iqzmtinx.trm exists and is valid.

Problem determination: Call your next level of support.

E202FE05 E202FE05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_search_file_open() failed error reason = func's rc make sure trace index file iqzmtinx.trm exists and is valid.

Problem determination: Call your next level of support.

E202FE06 E202FE06

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_read() failed error reason = func's rc make sure trace index file iqzmtinx.trm exists and is valid.

Problem determination: Call your next level of support.

E202FE07 E202FE07

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_close() failed error reason = func's rc

make sure trace index file iqzmtinx.trm exists and is valid.

Problem determination: Call your next level of support.

E202FE08 E202FE08

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_write() failed error reason = func's rc make sure trace index file iqzmtinx.trm exists and is valid.

Problem determination: Call your next level of support.

E202FE09 E202FE09

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: value from iqzmtinx.trm is too large. error reason = value read in from file.

Problem determination: Call your next level of support.

E202FE0A E202FE0A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_delete_file failed error reason = DFC's rc --- no longer used ---

Problem determination: Call your next level of support.

E202FE0B E202FE0B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosWaitEventSem failed error reason = OS 2's rc

Problem determination: Call your next level of support.

E202FE0C E202FE0C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosResetEventSem failed error reason = OS 2's rc

Problem determination: Call your next level of support.

E202FE0D E202FE0D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: unable to get addressability to the shared memory buffer arm_trace failed while being called from xmcm_trace

Problem determination: Call your next level of support.

E202FE0E E202FE0E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: unable to get addressability to the shared memory buffer arm_trace failed while being called from xmcm_dump_bytes --- no longer used ---

Problem determination: Call your next level of support.

E202FE0F E202FE0F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to get access to the trace buffer. Extension is the return code from DosRequestMutexSem Recovery: This problem can be ignored, since the MCF MCL internal trace is not critical to the operation of the SE. The problem will be resolved the next time the SE reboots.

Problem determination: Call your next level of support.

E202FE20 E202FE20

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading XMCF_TEMP_AUTO_LOCK extension is the return code from XSIM_read --- no longer used ---

Problem determination: Call your next level of support.

E202FE21 E202FE21

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading XMCF_PERM_ACT_AUTO_LOCK extension is the return code from XSIM_read --- no longer used ---

Problem determination: Call your next level of support.

E202FE22 • E202FE2C

E202FE22 E202FE22

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading XMCF_PERM_DEACT_AUTO_LOCK extension is the return code from XSIM_read --- no longer used ---

Problem determination: Call your next level of support.

E202FE23 E202FE23

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading XMCF_START_UP_STATUS extension is the return code from XSIM_read --- no longer used ---

Problem determination: Call your next level of support.

E202FE24 E202FE24

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading XMCF_BACKUP_IN_PROGRESS extension is the return code from XSIM_read --- no longer used ---

Problem determination: Call your next level of support.

E202FE25 E202FE25

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Wrap position stored in the extended attributes of the patch internal trace file exceeds the maximum size for the patch internal trace. Extension is the bad wrappos stored in the trace file

Problem determination: Call your next level of support.

E202FE26 E202FE26

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading XMCF_MCL_RET_FROM_RETAIN extension is the return code from XSIM_read --- no longer used ---

Problem determination: Call your next level of support.

E202FE27 E202FE27

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error obtaining shared memory ID during trace initialization - comp_rc = errno

Problem determination: Call your next level of support.

E202FE28 E202FE28

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error attaching shared memory during trace initialization - comp_rc = errno

Problem determination: Call your next level of support.

E202FE29 E202FE29

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Eye catcher in shared memory memory block indicates the block is not ours!

Problem determination: Call your next level of support.

E202FE2A E202FE2A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Failure obtaining the semaphore id for our buffer locking semaphore - comp_rc = errno

Problem determination: Call your next level of support.

E202FE2B E202FE2B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Failure obtaining the semaphore id for our write event semaphore - comp_rc = errno

Problem determination: Call your next level of support.

E202FE2C E202FE2C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to release access to the trace buffer. Recovery: This problem can be ignored, since the MCF MCL internal trace is not critical to the operation of the SE. The problem will be resolved the next time the SE reboots.

Problem determination: Call your next level of support.

E202FE2D E202FE2D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to initialize the attributes required to start the thread that writes patch trace records to the trace file. No patch trace file will be written. The patch trace memory buffer will hold the latest patch trace records. The component return code is the error from the pthread_init_attr() call that failed. --- no longer used ---

Problem determination: Call your next level of support.

E202FE2E E202FE2E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to set the attributes required to start the thread that writes patch trace records to the trace file. No patch trace file will be written. The patch trace memory buffer will hold the latest patch trace records. The component return code is the error from the pthread_attr_setdetachstate() call that failed. --- no longer used ---

Problem determination: Call your next level of support.

E202FE2F E202FE2F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to create and start the thread that writes patch trace records to the trace file. No patch trace file will be written. The patch trace memory buffer will hold the latest patch trace records. The component return code is the error from the pthread_create() call that failed. --- no longer used ---

Problem determination: Call your next level of support.

E202FE40 E202FE40

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to open the wrap position file used to record the current wrap position of a patch trace file. We will assume that we are not wrapping. The component return code is the error from the xdfc_search_file_open() call that failed.

Problem determination: Call your next level of support.

E202FE41 E202FE41

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to read the wrap position file used to record the current wrap position of a patch trace file. We will assume that we are not wrapping. The component return code is the errno value from the fgets() call that failed.

Problem determination: Call your next level of support.

E202FE42 E202FE42

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to close the wrap position file used to record the current wrap position of a patch trace file. The wrap position will be determined from the file data that was successfully read. The component return code is the error from the xdfc_close_file() call that failed.

Problem determination: Call your next level of support.

E202FE43 E202FE43

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to convert the wrap position data from the wrap position file used to record the current wrap position of a patch trace file. We will assume that we are not wrapping. The component return code is the errno value from the strtol() call that indicated the data was invalid.

Problem determination: Call your next level of support.

E202FE44 E202FE44

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to convert the wrap position data from the wrap position file used to record the current wrap position of a patch trace file. We will assume that we are not wrapping. The component return code indicates the nature of the "wrongness" of the data being converted.

Problem determination: Call your next level of support.

E202FE45 • E202FE4E

E202FE45 E202FE45

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to delete the wrap position file used to record the current wrap position of a patch trace file. We will continue processing. The component return code is the error from the `xdfc_delete_file()` call that failed.

Problem determination: Call your next level of support.

E202FE46 E202FE46

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to open the wrap position file used to record the current wrap position of a patch trace file. We will continue processing. The component return code is the error from the `xdfc_search_file_open()` call that failed.

Problem determination: Call your next level of support.

E202FE47 E202FE47

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to write the wrap position file used to record the current wrap position of a patch trace file. We will continue processing. The component return code is the `errno` value from the `xdfc_write()` call that failed.

Problem determination: Call your next level of support.

E202FE48 E202FE48

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to close the wrap position file used to record the current wrap position of a patch trace file. We will continue processing. The component return code is the error from the `xdfc_close_file()` call that failed.

Problem determination: Call your next level of support.

E202FE49 E202FE49

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The reset of the patch trace event semaphore failed. The component return code is the error from the semaphore operation that failed.

Problem determination: Call your next level of support.

E202FE4A E202FE4A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The attempt to add a termination user exit failed. The component return code is the error from the call to `xpce_add_user_exit()`. Patch trace initialization will not complete and patch tracing will not occur unless some other process successfully initiates it. --- no longer used ---

Problem determination: Call your next level of support.

E202FE4B E202FE4B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to convert the wrap position data from the wrap position file used to record the current wrap position of a patch trace file. We will assume that we are not wrapping. The component return code indicates the nature of the "wrongness" of the data being converted.

Problem determination: Call your next level of support.

E202FE4C E202FE4C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `xpce_setup()` failed. the reason is the `crc` returned from `xpce_setup()`.

Problem determination: Call your next level of support.

E202FE4D E202FE4D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `xpce_unset()` failed. the reason is the `crc` returned from `xpce_setup()`.

Problem determination: Call your next level of support.

E202FE4E E202FE4E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to open the trace data in preparation to transfer the data to disk from the trace buffer. We will continue processing. Only the first occurrence of this error and other related errors will be logged for a process. The component return

code is the error from the `xdfc_search_file_open()` call that failed.

Problem determination: Call your next level of support.

E202FE4F E202FE4F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to find the trace data file size in preparation to transfer the trace data to disk. Tracing will continue in the memory trace buffer, but we not try to dump any data from the buffer to disk at this time. Only the first occurrence of this error and other related errors will be logged for a process. The component return code is the error from the `xdfc_query_file_size()` call that failed.

Problem determination: Call your next level of support.

E202FE50 E202FE50

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to write trace data to disk from the trace buffer. Tracing will continue in the memory trace buffer, but we not try to dump any data from the buffer to disk at this time. Only the first occurrence of this error and other related errors will be logged for a process. The component return code is the error from the `xdfc_random_write()` call that failed.

Problem determination: Call your next level of support.

E202FE51 E202FE51

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The patch trace file writer program terminated for some reason. This should never happen unless the system is shutting down.

Problem determination: Call your next level of support.

E202FEF0 E202FEF0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `xpce_setup` failed. error reason = crc

Problem determination: Call your next level of support.

E202FEF1 E202FEF1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `xpce_unset` failed. error reason = crc

Problem determination: Call your next level of support.

E202FEF2 E202FEF2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `DosGetDateTime` failed error reason = OS 2's rc.

Problem determination: Call your next level of support.

E202FEF3 E202FEF3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Not an error; indicates that `iqzmcIn.exe` has purged all change management traces and reset the trace index number

Problem determination: Call your next level of support.

E20A0001 E20A0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `unlink` failed in `delete_file`. The component return code is the value returned in `errno`.

Problem determination: Call your next level of support.

E20A000A E20A000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `fwrite` failed in `list_file` updating the output file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E20A000B E20A000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: `DosWrite` failed in `list_file` updating the output file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E20A000C • E20A0017

E20A000C E20A000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosWrite failed in list_file updating the output file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E20A000D E20A000D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosClose failed in list_file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E20A000E E20A000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: readdir failed in list_file. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A000F E20A000F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: opendir failed in list_file . The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0010 E20A0010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: open failed in query_file_size. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0011 E20A0011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: open failed iq query_file date. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0012 E20A0012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: readdir failed in list_file_mem. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0013 E20A0013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fread failed in xdfc_read. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0014 E20A0014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: opendir failed in list_file_mem. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0015 E20A0015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fwrite failed in xdfc_write. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0016 E20A0016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fstat failed in query_file_size. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0017 E20A0017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fstat failed in query_file_date. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A001C E20A001C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fopen failed in search_file_open. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A001E E20A001E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: open failed for the IQZDDFC.TRM file. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A001F E20A001F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fstat failed in xdfc_init. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0020 E20A0020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: malloc failed in xdfc_init. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0021 E20A0021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: read failed reading IQZDDFC.TRM. The value in errno has been logged.

Problem determination: Call your next level of support.

E20A0022 E20A0022

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: close failed for IQZDDFC.TRM. The value in errno has been logged. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E20A0024 E20A0024

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Too many entries found in IQZDDFC.TRM. Error reason is the max number allowed.

Problem determination: Call your next level of support.

E20A0030 E20A0030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosDevIOctl failed attempting to determine if the DFC call failed for a diskette drive. The error reason is the OS 2 return code.

Problem determination: Call your next level of support.

E20A2001 E20A2001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: buffering(setvbuf) of input file failed

Problem determination: Call your next level of support.

E20A2002 E20A2002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: callers crc pointer is invalid rc = 1, , then xdfc_encode; rc = 2, then xdfc_decode

Problem determination: Call your next level of support.

E20A2003 E20A2003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pointer to in file invalid rc = 1, then xdfc_encode; rc = 2, then xdfc_decode

Problem determination: Call your next level of support.

E20A2004 E20A2004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: could not open input file rc = 1, , then xdfc_encode; rc = 2, then xdfc_decode

Problem determination: Call your next level of support.

E20A2005 • E20A2010

E20A2005 E20A2005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: could not open output file rc = 1, then xdfc_encode; rc = 2, then xdfc_decode

Problem determination: Call your next level of support.

E20A2006 E20A2006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: could not open output file rc = 1, then xdfc_encode; rc = 2, then xdfc_decode; rc = 3, then xdfc_mem_encode; rc = 4, then xdfc_mem_decode

Problem determination: Call your next level of support.

E20A2007 E20A2007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: expected 12 byte header, crc = length found

Problem determination: Call your next level of support.

E20A2008 E20A2008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: compression failed.

Problem determination: Call your next level of support.

E20A2009 E20A2009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: decompression failed

Problem determination: Call your next level of support.

E20A200A E20A200A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: stack exceeded in getcharfrmtree rtn

Problem determination: Call your next level of support.

E20A200B E20A200B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: move byte routine failed

Problem determination: Call your next level of support.

E20A200C E20A200C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: more byte routine failed

Problem determination: Call your next level of support.

E20A200D E20A200D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: get_tree_note routine failed

Problem determination: Call your next level of support.

E20A200E E20A200E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: i p file to decode size is less than header length.

Problem determination: Call your next level of support.

E20A200F E20A200F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: file to decode: wrong version of encode

Problem determination: Call your next level of support.

E20A2010 E20A2010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pointer to out file invalid rc = 1, then xdfc_encode; rc = 2, then xdfc_decode

Problem determination: Call your next level of support.

E20A2011 E20A2011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: compression failed.

Problem determination: Call your next level of support.

E20A2012 E20A2012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: decompression failed

Problem determination: Call your next level of support.

(E21x) Reference codes

E212E080 E212E080

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: can't get valid data

Problem determination: Call your next level of support.

E212E081 E212E081

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_read() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E082 E212E082

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_close_file() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E083 E212E083

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnb call failed

Problem determination: Call your next level of support.

E212E084 E212E084

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pthread_create failed 10

Problem determination: Call your next level of support.

E212E085 E212E085

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: malloc failed

Problem determination: Call your next level of support.

E212E086 E212E086

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xact_get_func_addr2 failed

Problem determination: Call your next level of support.

E212E087 E212E087

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: malloc failed

Problem determination: Call your next level of support.

E212E088 E212E088

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: malloc failed

Problem determination: Call your next level of support.

E212E089 E212E089

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: returned shmid was 0

Problem determination: Call your next level of support.

E212E08A E212E08A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: unable to get shared memory

Problem determination: Call your next level of support.

E212E08B E212E08B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: unable to allocate

Problem determination: Call your next level of support.

E212E08C • E212E0A0

E212E08C E212E08C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: unable to create semaphore

Problem determination: Call your next level of support.

E212E090 E212E090

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_search_file_open() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E091 E212E091

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_write() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E092 E212E092

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_write() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E093 E212E093

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_close_file() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E094 E212E094

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_close_file() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E095 E212E095

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_search_file_open() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E096 E212E096

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_write() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E097 E212E097

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_close_file() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E098 E212E098

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_read() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E099 E212E099

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_query_file_size() failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E0A0 E212E0A0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xque_create_q failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E0A1 E212E0A1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xque_read_q failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E0A2 E212E0A2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xque_close_q failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E0A3 E212E0A3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xque_free_elem failed Error reason = received RC.

Problem determination: Call your next level of support.

E212E0A4 E212E0A4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: override table overflow

Problem determination: Call your next level of support.

E212E0F1 E212E0F1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Bad SysRc passed to logger. Error reason is pre-defined

Problem determination: Call your next level of support.

E212E111 E212E111

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; RSS value for a process is too big Error reason = RSS size .

Problem determination: Call your next level of support.

E212E112 E212E112

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; DSIZ value for a process is too big Error reason = DSIZ value .

Problem determination: Call your next level of support.

E212E113 E212E113

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; total memory in use exceeds threshold Error reason = total in use .

Problem determination: Call your next level of support.

E212E114 E212E114

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; percent of total memory in use is over the allowed threshold Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E115 E212E115

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; VSIZE value for a process is too big Error reason = VSIZE size .

Problem determination: Call your next level of support.

E212E116 E212E116

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Thread Alert; too many threads in the system. Error reason = number of thds

Problem determination: Call your next level of support.

E212E117 E212E117

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; RSS abort value for a process is too big Error reason = RSS size

Problem determination: Call your next level of support.

E212E118 • E212E134

E212E118 E212E118

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; DSIZ abort value for a process is too big Error reason = DSIZ value

Problem determination: Call your next level of support.

E212E119 E212E119

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; VSIZE abort value for a process is too big Error reason = VSIZE size

Problem determination: Call your next level of support.

E212E11A E212E11A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; possible memory leak detected. Error reason = PID

Problem determination: Call your next level of support.

E212E11B E212E11B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; LowFree value is too low. Error reason = LowFree value

Problem determination: Call your next level of support.

E212E11C E212E11C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Memory Alert; total swap area is too small Error reason = swap area size

Problem determination: Call your next level of support.

E212E121 E212E121

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: partition's usage exceeds threshold. i.e. low on free DASD Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E122 E212E122

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: number of files on partition exceeds threshold i.e. low on free DASD Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E131 E212E131

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: console ffdc usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E132 E212E132

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: console usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E133 E212E133

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: ffdc usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E134 E212E134

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: var usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E135 E212E135

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: tmp usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E136 E212E136

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E137 E212E137

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: dev shm usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E138 E212E138

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: dump usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E139 E212E139

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: extra usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E13A E212E13A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: hmcdump usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E13B E212E13B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: mnt upgrade usage exceeds threshold. i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E141 E212E141

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: console ffdc number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E142 E212E142

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: console number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E143 E212E143

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: ffdc number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E144 • E212E151

E212E144 E212E144

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: var number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E145 E212E145

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: tmp number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E146 E212E146

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E147 E212E147

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: dev shm number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E148 E212E148

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: dump number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E149 E212E149

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: extra number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E14A E212E14A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: hmcDump number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E14B E212E14B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DASD Alert: mnt upgrade number of files over threshold i.e. low on free DASD on the mentioned DASD partition Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E150 E212E150

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: CPU Alert: a process was using too much SE HMC CPU time. Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E151 E212E151

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: CPU Alert: The SE HMC overall was way too busy for too long. Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E152 E212E152

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: CPU Alert: The SE HMC is running too slowly. Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E153 E212E153

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: CPU Alert: The SE HMC is running too slowly. This is triggered by a caller and not the linux monitor itself. Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E154 E212E154

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational CPU Alert: Some application has asked to disable performance checking.

Problem determination: Call your next level of support.

E212E155 E212E155

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational CPU Alert: Some application has asked to reenale performance checking

Problem determination: Call your next level of support.

E212E160 E212E160

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Too many open files in system Error reason = percent in use scaled by 10.

Problem determination: Call your next level of support.

E212E161 E212E161

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Too many open files in process Error reason = number in use

Problem determination: Call your next level of support.

E212E170 E212E170

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Someone has asked us to stop all monitoring. Error reason is 0. 20

Problem determination: Call your next level of support.

E212E200 E212E200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xpce_setup() failed. Error reason = received RC.

Problem determination: Call your next level of support.

E212E201 E212E201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xpce_unset() failed. Error reason = received RC.

Problem determination: Call your next level of support.

E212E301 E212E301

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: configuration parsing error Error reason = component RC

Problem determination: Call your next level of support.

E212E302 E212E302

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: JVM non-responsive Error reason = number of consecutive timeouts

Problem determination: Call your next level of support.

E212E303 E212E303

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The native bridge connection to JVM failed. Error reason = number of consecutive native bridge timeouts

E212E304 • E2160013

Problem determination: Call your next level of support.

E212E304 E212E304

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The web server connection to JVM failed. Error reason = number of consecutive web server timeouts

Problem determination: Call your next level of support.

E212E305 E212E305

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The native bridge connection to get the JVM memory failed. Error reason = the component RC of the native bridge call.

Problem determination: Call your next level of support.

E2160001 E2160001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocSeg failed OS 2 return code logged

Problem determination: Call your next level of support.

E2160002 E2160002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DFC Search file open failed for the SIM initialization data file. The DFC return code has been logged.

Problem determination: Call your next level of support.

E2160003 E2160003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DFC Search file open failed for the SIM permanent data file (Endicotts). The DFC return code has been logged.

Problem determination: Call your next level of support.

E2160004 E2160004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DFC Search file open failed for the SIM permanent data file (Boeblingen). The DFC return code has been logged.

Problem determination: Call your next level of support.

E2160005 E2160005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocMem failed for xxxxSIM.DAT read buffer. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216000B E216000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocSeg failed for xxxxSPR.DAT read buffer. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160011 E2160011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosRead failed for the IQZZSIM.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160012 E2160012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosRead failed for the BBRZSIM.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160013 E2160013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The memory required to hold the SIM table defined by IQZZSIM.DAT is greater than 64K.

Problem determination: Call your next level of support.

E2160014 **E2160014**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The memory required to hold the SIM table defined by BBRZSIM.DAT is greater than 64K.

Problem determination: Call your next level of support.

E2160015 **E2160015**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocSeg failed allocating memory for the SIM table as defined by IQZZSIM.DAT. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160016 **E2160016**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocSeg failed allocating memory for the SIM table as defined by BBRZSIM.DAT. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160017 **E2160017**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The memory required to hold the SIM fields defined by IQZZSIM.DAT is greater than 64K.

Problem determination: Call your next level of support.

E2160018 **E2160018**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The memory required to hold the SIM fields defined by BBRZSIM.DAT is greater than 64K.

Problem determination: Call your next level of support.

E2160019 **E2160019**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocSeg failed allocating memory for the SIM fields as defined by IQZZSIM.DAT and IQZZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216001A **E216001A**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocSeg failed allocating memory for the SIM fields as defined by BBRZSIM.DAT and BBRZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216001B **E216001B**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSubSet failed in memory allocated for SIM data as defined in IQZZSIM.DAT and IQZZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216001C **E216001C**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSubSet failed in memory allocated for SIM data as defined in IQZZSIM.DAT and IQZZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216001D **E216001D**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosRead failed reading IQZZSPR.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216001E **E216001E**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosRead failed reading BBRZSPR.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216001F E216001F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSubAlloc failed processing the SIM table memory as defined by IQZZSIM.DAT and IQZZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160020 E2160020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSubAlloc failed processing the SIM table memory as defined by BBRZSIM.DAT and BBRZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160021 E2160021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFreeMem failed freeing read buffer for the xxxxSIM.DAT file. The OS 2 return has been logged.

Problem determination: Call your next level of support.

E2160022 E2160022

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFreeMem failed freeing read buffer for the xxxspr.DAT file. The OS 2 return has been logged.

Problem determination: Call your next level of support.

E2160023 E2160023

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosClose failed for the IQZZSPR.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160024 E2160024

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosClose failed for the BBRZSPR.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160025 E2160025

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosClose failed for the IQZZSIM.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160026 E2160026

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosClose failed for the BBRZSIM.DAT file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160027 E2160027

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetShrSeg failed. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160028 E2160028

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM was found not to be initialized.

Problem determination: Call your next level of support.

E2160029 E2160029

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetSeg failed for the SIM table as defined by IQZZSIM and IQZZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216002A E216002A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetSeg failed for the SIM data as defined by IQZZSIM and IQZZSPR.DAT files The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216002B E216002B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetSeg failed for the SIM table as defined by BBRZSIM and BBRZSPR.DAT files. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216002C E216002C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetSeg failed for the SIM data as defined by BBRZSIM and BBRZSPR.DAT files The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216002D E216002D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM read. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216002E E216002E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM size. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216002F E216002F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM write. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160030 E2160030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM lock. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160031 E2160031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM sub read. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160032 E2160032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM sub write The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160033 E2160033

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosClose failed for the permanent SIM data file. The OS 2 return code has been logged

Problem determination: Call your next level of support.

E2160034 E2160034

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM file read The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160035 E2160035

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DFC Search File Open failed for the SIM permanent data file. The SIM field index number and OS 2 return code have been logged.

E2160036 • E216003E

Problem determination: Call your next level of support.

E2160036 E2160036

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosChgFilePtr failed for the SIM permanent data file. The SIM field index number and OS 2 return code have been logged.

Problem determination: Call your next level of support.

E2160037 E2160037

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosRead failed for the SIM permanent data file. The SIM field index number and OS 2 return code have been logged.

Problem determination: Call your next level of support.

E2160038 E2160038

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM file write. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E2160039 E2160039

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosWrite failed for the SIM permanent data file. The SIM field index number and OS 2 return code have been logged.

Problem determination: Call your next level of support.

E216003A E216003A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosChgFilePtr failed for the SIM permanent data file. The SIM field index number and OS 2 return code have been logged.

Problem determination: Call your next level of support.

E216003B E216003B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosWrite failed for the SIM permanent data file. The SIM field index number and OS 2 return code have been logged.

Problem determination: Call your next level of support.

E216003C E216003C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosClose failed for the SIM permanent data file. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216003D E216003D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemClear failed in the exit rtn. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

E216003E E216003E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFSRamSemRequest failed for SIM unlock. The OS 2 return code has been logged.

Problem determination: Call your next level of support.

(E22x) Reference codes

E22F0060 **E22F0060**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid pointer to member of list.

Problem determination: Call your next level of support.

E22F0102 **E22F0102**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage. -31 Error reason is NA.

Problem determination: Call your next level of support.

E22F0200 **E22F0200**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0201 **E22F0201**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPDC.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0203 **E22F0203**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0204 **E22F0204**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0205 **E22F0205**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0206 **E22F0206**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0207 **E22F0207**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDC.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0208 **E22F0208**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDC.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0209 **E22F0209**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPDC.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F020C • E22F0232

E22F020C E22F020C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDP.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F020D E22F020D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDP.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F020E E22F020E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPDP.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F020F E22F020F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0210 E22F0210

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0214 E22F0214

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPDS.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0215 E22F0215

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0216 E22F0216

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPDS.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0217 E22F0217

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDS.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0219 E22F0219

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening tempvpd.dat -31 Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0220 E22F0220

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0232 E22F0232

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting IQYVPD.DAT file size. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0233 E22F0233

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPD.DAT file. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0240 E22F0240

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening VPD file or Default-31 Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0241 E22F0241

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPD.DAT file. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0242 E22F0242

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing to a VPD file -64 Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0243 E22F0243

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not allocate memory -31 Error reason is NA

Problem determination: Call your next level of support.

E22F0244 E22F0244

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing to tempvpd.dat -31 in xvpd_write_file function. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0245 E22F0245

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening initial temporary file in xvpd_delete function. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0246 E22F0246

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing tempvpd.dat or -31 other file in xvpd_write_file(). Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0247 E22F0247

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing data to temporary file for FRUs in xvpd_delete function. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0248 E22F0248

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPDP.DAT Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F024C E22F024C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPDP.DAT Error reason is DFC comp rc. efine XVPD_FILE_CHECK_0700 0x0700 Spare -18

Problem determination: Call your next level of support.

E22F0252 E22F0252

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory. Error reason is malloc rc.

E22F0253 • E22F025E

Problem determination: Call your next level of support.

E22F0253 E22F0253

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Opening a System Semaphore Error reason DosOpenSem rc.

Problem determination: Call your next level of support.

E22F0254 E22F0254

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Opening a System Semaphore Error reason DosOpenSem rc.

Problem determination: Call your next level of support.

E22F0255 E22F0255

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSemRequest Error. Error reason DosSemRequest rc.

Problem determination: Call your next level of support.

E22F0256 E22F0256

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSemClear Error. Error reason DosSemClear rc.

Problem determination: Call your next level of support.

E22F0257 E22F0257

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosCloseSem Error. Error reason DosCloseSem rc.

Problem determination: Call your next level of support.

E22F0258 E22F0258

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosOpenMutexSem Error. Error reason DosOpenMutexSem rc.

Problem determination: Call your next level of support.

E22F0259 E22F0259

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosCreateMutexSem Error. Error reason DosCreateMutexSem rc.

Problem determination: Call your next level of support.

E22F025A E22F025A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosRequestMutexSem Error. Error reason DosRequestMutexSem rc.

Problem determination: Call your next level of support.

E22F025B E22F025B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosReleaseMutexSem Error. Error reason DosReleaseMutexSem rc.

Problem determination: Call your next level of support.

E22F025C E22F025C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosCloseMutexSem Error. Error reason DosCloseMutexSem rc.

Problem determination: Call your next level of support.

E22F025D E22F025D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error querying IQYVPDC.DAT file size Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F025E E22F025E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage. Error reason is NA.

Problem determination: Call your next level of support.

E22F025F E22F025F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDC.DAT file Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0260 E22F0260

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory for VPDC -10 Error reason = 1.

Problem determination: Call your next level of support.

E22F0261 E22F0261

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IQYVPDC.DAT unit data is bad Error reason is rc from xvpd_search_all_units function call.

Problem determination: Call your next level of support.

E22F0262 E22F0262

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPDS.TRM temp file Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0263 E22F0263

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting configuration data. Error reason is rc from xvpd_config_request function call.

Problem determination: Call your next level of support.

E22F0264 E22F0264

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing to IQYVPDS.TRM file Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0265 E22F0265

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing to IQYVPDS.TRM file Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0266 E22F0266

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IQYVPDC.DAT unit data is bad Error reason is rc from xvpd_search_all_units function call.

Problem determination: Call your next level of support.

E22F0267 E22F0267

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IQYVPDC.DAT unit data is bad Error reason is rc from xvpd_search_all_units function call.

Problem determination: Call your next level of support.

E22F0268 E22F0268

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing to IQYVPDC.DAT file. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0269 E22F0269

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage. Error reason is NA.

Problem determination: Call your next level of support.

E22F026A E22F026A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ZERO file size for IQYVPD.DAT file. Error reason is DFC comp rc.

E22F026B • E22F0276

Problem determination: Call your next level of support.

E22F026B E22F026B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F026C E22F026C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening file in -31 xvpd_write_file(). Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F026D E22F026D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPDC.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F026E E22F026E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F026F E22F026F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0270 E22F0270

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPD.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0271 E22F0271

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDC.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0272 E22F0272

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing IQYVPDC.DAT. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0273 E22F0273

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening DEFAULT file passed in Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0274 E22F0274

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading DEFAULT file passed in Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0275 E22F0275

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing record to the DEFAULT Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0276 E22F0276

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing record to the DEFAULT Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0277 E22F0277

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error deleting tempvpd.dat in -31 xvpd_write_file(). Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0278 E22F0278

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error copying tempvpd.dat -> file -31 Error reason is DFC comp rc. #define XVPD_DFC_279 0x0279 Error reading DEFAULT file passed in Error reason is DFC comp rc. #define XVPD_DFC_27A 0x027A Error writing to Temporary VPD file. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F027B E22F027B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error backing up IQYVPD.DAT to -10 TEMPVPD.DAT Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F027C E22F027C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing or deleting -10 IQYVPD.DAT Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F027D E22F027D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening updated -10 IQYVPD.DAT Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F027E E22F027E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing updated -10 IQYVPD.DAT Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F027F E22F027F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error deleting TEMPVPD.DAT -10 Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0280 E22F0280

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error backing up IQYVPDC.DAT -10 to IQYVPDC2.DAT. Error Reason is CRC from xdfc_file_copy().

Problem determination: Call your next level of support.

E22F0281 E22F0281

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing IQYVPDC.DAT. -10 Error reason is CRC from xdfc_close_file().

Problem determination: Call your next level of support.

E22F0282 E22F0282

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error deleting IQYVPDC.DAT. -10 Error reason is CRC from xdfc_delete_file().

Problem determination: Call your next level of support.

E22F0283 E22F0283

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error re-opening IQYVPDC.DAT. -10 Error reason is CRC from xdfc_search_file_open().

Problem determination: Call your next level of support.

E22F0284 • E22F028F

E22F0284 E22F0284

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error re-writing IQYVPDC.DAT. -10 Error reason is CRC from xdfc_random_write().

Problem determination: Call your next level of support.

E22F0285 E22F0285

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Greater than three extra bytes -10 in IQYVPDC.DAT. Error Reason is the number of extra bytes.

Problem determination: Call your next level of support.

E22F0286 E22F0286

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error backing up IQYVPDC.DAT -10 to IQYVPDC2.DAT. Error Reason is CRC from xdfc_file_copy().

Problem determination: Call your next level of support.

E22F0287 E22F0287

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage for VPDC-10 Error reason = 1.

Problem determination: Call your next level of support.

E22F0288 E22F0288

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDC.DAT into -10 "buffer". Error Reason is CRC from xdfc_random_read()

Problem determination: Call your next level of support.

E22F0289 E22F0289

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Cannot fixup IQYVPDC.DAT because-10 bytes cannot be classified. Error Reason = 1;

Problem determination: Call your next level of support.

E22F028A E22F028A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing IQYVPDC.DAT. -10 Error reason is CRC from xdfc_close_file().

Problem determination: Call your next level of support.

E22F028B E22F028B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error deleting IQYVPDC.DAT. -10 Error reason is CRC from xdfc_delete_file().

Problem determination: Call your next level of support.

E22F028C E22F028C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error re-opening IQYVPDC.DAT. -10 Error reason is CRC from xdfc_search_file_open().

Problem determination: Call your next level of support.

E22F028D E22F028D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error re-writing IQYVPDC.DAT. -10 Error reason is CRC from xdfc_random_write().

Problem determination: Call your next level of support.

E22F028E E22F028E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid Semaphore Handle passed -11 to xvpd_get_semaphore().

Problem determination: Call your next level of support.

E22F028F E22F028F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid location passed with -13 XVPD_ALTER command. Error Reason=0

Problem determination: Call your next level of support.

E22F0290 E22F0290

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening IQYVPDC.DAT -13 Error reason is CRC from xdfc_search_file_open().

Problem determination: Call your next level of support.

E22F0291 E22F0291

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid Part Number or CCIN -13 passed with XVPD_ALTER command. Error Reason = 0

Problem determination: Call your next level of support.

E22F0292 E22F0292

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid Pointer to CCIN data -13 passed with XVPD_DELETE_CCIN_DEFAULT Error Reason = 0 #define XVPD_DFC_293 0x0293 Error opening TEMPVPD.TRM. -13 Error reason is DFC comp rc. #define XVPD_DFC_294 0x0294 Error opening DEFAULT VPD file. -13 Error reason is DFC comp rc. #define XVPD_DFC_295 0x0295 Error reading DEFAULT VPD file. -13 Error reason is DFC comp rc. #define XVPD_DFC_296 0x0296 Error writing to DEFAULT search -13 stream. Err reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0297 E22F0297

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory in -31 xvpd_delete() Error reason = 0. #define XVPD_DFC_298 0x0298 Error copying DEFAULT search -13 results to buffer. Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F0299 E22F0299

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage for -14 VPD updates. Error Reason = 0

Problem determination: Call your next level of support.

E22F029A E22F029A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: BLANK or NULL location found in -14 IQYVPD.DAT. Error Reason = 0

Problem determination: Call your next level of support.

E22F029B E22F029B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid Pointer to CARD TYPE data-15 passed with XVPD_DELETE_CARD_TYPE_DF Error Reason = 0 -16

Problem determination: Call your next level of support.

E22F029C E22F029C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error deleting extra byte from -17 VPD File -24 Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F029D E22F029D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A VPD file contains extra bytes -17 that should not be present. -24 Error reason = number of extra bytes

Problem determination: Call your next level of support.

E22F029E E22F029E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: One of the VPD Mgr Interface -18 pointers is bad. Error reason is the number of the bad interface pointer.

Problem determination: Call your next level of support.

E22F029F • E22F02AA

E22F029F E22F029F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading IQYVPDC.DAT file -17 header data. -18 Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F02A0 E22F02A0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Writing IQYVPDC.DAT file -17 header data. -18 Error reason is DFC comp rc.

Problem determination: Call your next level of support.

E22F02A1 E22F02A1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: VPDC UNIT with invalid -20 "unit_serial" field. Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02A2 E22F02A2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: VPDC UNIT s with duplicate -20 "unit_serial" and "unit_type" data. Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02A3 E22F02A3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: VPDC UNIT with duplicate UPC S N -20 matching the CEC UPC S N Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02A4 E22F02A4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Duplicate CEC UNIT record in VPDC-20 Deleting the duplicate record. Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02A5 E22F02A5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: EXP Cage without a UPC Serial -20 Number. Delete this unit. Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02A6 E22F02A6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: VPDC UNIT with UPC serial number -20 matching another VPDC UNIT. Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02A7 E22F02A7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: VPDC UNITS with duplicate -20 "unit_type" and "location" Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02A8 E22F02A8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening DEFAULT file -21 passed in. Err reasn = DFC CRC.

Problem determination: Call your next level of support.

E22F02A9 E22F02A9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage for VPDC-23 Error reason = 1. #define XVPD_DFC_2AB 0x02AB Error opening DEFAULT file -26 passed in. Err reasn = DFC CRC.

Problem determination: Call your next level of support.

E22F02AA E22F02AA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: VPDC file does not contain a -22 version number in the first 3-bytes. Error reason is ZERO.

Problem determination: Call your next level of support.

E22F02AC E22F02AC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid Sem Handle passed to -27
xvpd_end_semaphore()

Problem determination: Call your next level of support.

E22F02AD E22F02AD

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating storage for VPD -31 Error reason = 1. Error reason = Sem Handle

Problem determination: Call your next level of support.

E22F02AE E22F02AE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Extra byte in a VPD file is not -31 EOF 0x1A. Error reason = Sem Handle

Problem determination: Call your next level of support.

E22F02AF E22F02AF

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading file in xvpd_read_file Error reason = DFC CRC. -31

Problem determination: Call your next level of support.

E22F02B0 E22F02B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Err writing file in xvpd_write_file Error reason = DFC CRC. -31

Problem determination: Call your next level of support.

E22F02B1 E22F02B1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Err opening DEFAULT VPD file in -31 xvpd_alter. Error reason = DFC CRC

(E23x) Reference codes

E2320002 E2320002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening the PA Request Queue. Error reason is the DosOpenQueue rc (reboot req'd if queue doesn't exist).

Problem determination: Call your next level of support.

E2320003 E2320003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: PA Memory allocation error. Error reason is the DosAllocSeg rc.

Problem determination: Call your next level of support.

E2320004 E2320004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in PA communications. Error reason is the DosGiveSeg rc.

Problem determination: Call your next level of support.

E2320005 E2320005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing to the PA Request Queue. Error reason is the DosWriteQueue rc.

Problem determination: Call your next level of support.

E2320006 E2320006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the PA process id. Error reason is the DosGetPID rc.

Problem determination: Call your next level of support.

E2320007 E2320007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: PA memory free error. Error reason is the DosFreeSeg rc.

Problem determination: Call your next level of support.

E2320008 E2320008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM read error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E2320009 E2320009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM read error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232000A E232000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational reference code. Problem analysis needed to be restarted for some unknown reason. Error reason is 0.

Problem determination: Call your next level of support.

E232000B E232000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM write error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232000C E232000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM write error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232000D E232000D

E2320100 • E232010A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM read error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E2320100 E2320100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening the PCINIT startup semaphore. Error reason is the DosOpenSem rc.

Problem determination: Call your next level of support.

E2320101 E2320101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating the PA Request Queue. Error reason is the DosCreateQueue rc.

Problem determination: Call your next level of support.

E2320102 E2320102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error clearing the PCINIT startup semaphore. Error reason is the DosSemClear rc.

Problem determination: Call your next level of support.

E2320103 E2320103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the time value from a PA table. Error reason is the xp00_get_table rc.

Problem determination: Call your next level of support.

E2320104 E2320104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the routine name from a PA table. Error reason is the xp00_get_table rc.

Problem determination: Call your next level of support.

E2320105 E2320105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown request was received in the PA Request Queue. Error reason is 0000.

Problem determination: Call your next level of support.

E2320106 E2320106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred loading a PA timer routine. Error reason is the DosLoadModule rc.

Problem determination: Call your next level of support.

E2320107 E2320107

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred get a PA timer routine's address. Error reason is the DosGetProcAddr rc.

Problem determination: Call your next level of support.

E2320108 E2320108

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred freeing a PA timer routine. Error reason is the DosFreeModule rc.

Problem determination: Call your next level of support.

E2320109 E2320109

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: R V verify mode SIM read error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232010A E232010A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not open the RV queue. Error reason is the DosOpenQueue rc.

Problem determination: Call your next level of support.

E232010B E232010B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not write to the RV queue. Error reason is the DosWriteQueue rc.

Problem determination: Call your next level of support.

E232010C E232010C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not open the RV sem. Error reason is the DosOpenSem rc.

Problem determination: Call your next level of support.

E232010D E232010D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not close the RV sem. Error reason is the DosCloseSem rc.

Problem determination: Call your next level of support.

E232010F E232010F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not begin the CM logging thread. Error reason is the _beginthread rc.

Problem determination: Call your next level of support.

E2320110 E2320110

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not begin the POH counting thread. Error reason is the _beginthread rc.

Problem determination: Call your next level of support.

E2320111 E2320111

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not begin the timer thread. Error reason is the _beginthread rc.

Problem determination: Call your next level of support.

E2320112 E2320112

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not set sem for stack for timer thread. Error reason is the _beginthread rc.

Problem determination: Call your next level of support.

E2320113 E2320113

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred loading Results Analysis. Error reason is the DosLoadModule rc.

Problem determination: Call your next level of support.

E2320114 E2320114

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred getting Results Analysis's address. Error reason is the DosGetProcAddr rc.

Problem determination: Call your next level of support.

E2320115 E2320115

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred freeing Results Analysis. Error reason is the DosFreeModule rc.

Problem determination: Call your next level of support.

E2320116 E2320116

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating the PA Display Queue. Error reason is the DosCreateQueue rc.

Problem determination: Call your next level of support.

E2320119 E2320119

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: REBOOT SIM read error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232011A • E2328003

E232011A E232011A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error rebooting SP. Error reason is the DosMonOpen rc.

Problem determination: Call your next level of support.

E232011B E232011B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating native bridge Error reason is the DosMonOpen rc.

Problem determination: Call your next level of support.

E232011C E232011C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending data to event generator Error reason is the native Bridge rc.

Problem determination: Call your next level of support.

E232011D E232011D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing the crash file Error reason is the fwrite rc

Problem determination: Call your next level of support.

E232011E E232011E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing the crash file Error reason is the fclose rc

Problem determination: Call your next level of support.

E232011F E232011F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending data to data port Error reason is the native Bridge rc.

Problem determination: Call your next level of support.

E2320120 E2320120

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error making the crash dir Error reason is the mkdir rc

Problem determination: Call your next level of support.

E2320121 E2320121

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error on the fopen for the crash file Error reason is the mkdir rc

Problem determination: Call your next level of support.

E2327001 E2327001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got a check ptr on the main Structure.

Problem determination: Call your next level of support.

E2328001 E2328001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening the PA Request Queue. Error reason is the DosOpenQueue rc (reboot req'd if queue doesn't exist).

Problem determination: Call your next level of support.

E2328002 E2328002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening the PA Request Queue. Error reason is the DosOpenQueue rc (reboot req'd if queue doesn't exist).

Problem determination: Call your next level of support.

E2328003 E2328003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: PA Memory allocation error. Error reason is the DosAllocSeg rc.

Problem determination: Call your next level of support.

E2328004 E2328004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in PA communications. Error reason is the DosGiveSeg rc.

Problem determination: Call your next level of support.

E2328005 E2328005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing to the PA Request Queue. Error reason is the DosWriteQueue rc.

Problem determination: Call your next level of support.

E2328006 E2328006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the PA process id. Error reason is the DosGetPID rc.

Problem determination: Call your next level of support.

E2328007 E2328007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: PA memory free error. Error reason is the DosFreeSeg rc.

Problem determination: Call your next level of support.

E2328008 E2328008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM read error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E2328009 E2328009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM read error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232800A E232800A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational reference code. Problem analysis needed to be restarted for some unknown reason. Error reason is 0.

Problem determination: Call your next level of support.

E232800B E232800B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM write error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232800C E232800C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM write error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232800D E232800D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SIM write error. Error reason is the SIM rc.

Problem determination: Call your next level of support.

E232800E E232800E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xpa_parms ptr bad

Problem determination: Call your next level of support.

E232800F E232800F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xp00_retain_file ptr bad

Problem determination: Call your next level of support.

E2329000 • E23C0009

E2329000 E2329000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Bad pointer to the comp rc. Error reason is the xpce_ckptr rc.

Problem determination: Call your next level of support.

E2329001 E2329001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error flattening the input tree. Error reason is the xp00_flatten_structure rc.

Problem determination: Call your next level of support.

E2329002 E2329002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error record the PA input log. Error reason is the xlog_record rc.

Problem determination: Call your next level of support.

E23C0001 E23C0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Check pointer routine detected error in log data pointer.

Problem determination: Call your next level of support.

E23C0002 E23C0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to allocate storage for input structure.

Problem determination: Call your next level of support.

E23C0003 E23C0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to create new file with fopen().

Problem determination: Call your next level of support.

E23C0004 E23C0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with DosLoadModule(). Error RC from DosLoadModule.

Problem determination: Call your next level of support.

E23C0005 E23C0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error from DosQueryProcAddr(). Error RC from DosQueryProcAddr

Problem determination: Call your next level of support.

E23C0006 E23C0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error from DosFreeModule(). Error RC from DosFreeModule.

Problem determination: Call your next level of support.

E23C0007 E23C0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in xdfc_query_file_size. Error RC returned.

Problem determination: Call your next level of support.

E23C0008 E23C0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in xdfc_search_file_open Error RC returned.

Problem determination: Call your next level of support.

E23C0009 E23C0009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to allocate storage.

Problem determination: Call your next level of support.

E23C000A E23C000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in xdfc_random_read. Error RC returned.

Problem determination: Call your next level of support.

E23C000B E23C000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in xdfc_close_file. Error RC returned.

Problem determination: Call your next level of support.

E23C000C E23C000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to allocate storage.

Problem determination: Call your next level of support.

E23C000D E23C000D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid DLL name in .trm file.

Problem determination: Call your next level of support.

E23C000E E23C000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to allocate storage for internal structure

Problem determination: Call your next level of support.

E23C5001 E23C5001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening file with log blk data Will log dfc return code

Problem determination: Call your next level of support.

E23C5002 E23C5002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading file with log blk data Will log dfc return code

Problem determination: Call your next level of support.

E23C5003 E23C5003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing file with log blk data Will log dfc return code

Problem determination: Call your next level of support.

E23C5004 E23C5004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory Will log expander bridge return code

Problem determination: Call your next level of support.

E23C5005 E23C5005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error issuing dlopen Will log expander bridge return code

Problem determination: Call your next level of support.

E23C5006 E23C5006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting address of where to load dll. (issuing dlsym) Will log expander bridge return code

Problem determination: Call your next level of support.

E23C5007 E23C5007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error issuing dlfree Will log expander bridge return code

Problem determination: Call your next level of support.

E23D0008 • E23D040A

E23D0008 E23D0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: comp rc for XPCE_EXIT_PROCESS(exception)

Problem determination: Call your next level of support.

E23D0009 E23D0009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: comp rc for XPCE_EXIT_PROCESS(kill req.)

Problem determination: Call your next level of support.

E23D0400 E23D0400

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exit list for PA- normal os 2 exit of PA

Problem determination: Call your next level of support.

E23D0401 E23D0401

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exit list for PA- hard error in PA proce

Problem determination: Call your next level of support.

E23D0402 E23D0402

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exit list for PA- trap occurred in PA pr

Problem determination: Call your next level of support.

E23D0403 E23D0403

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exit list for PA- un-intercepted DosKill

Problem determination: Call your next level of support.

E23D0404 E23D0404

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception occurred in the PA process

Problem determination: Call your next level of support.

E23D0405 E23D0405

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A divide by 0 occurred in a Temp or Perm

Problem determination: Call your next level of support.

E23D0406 E23D0406

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An inval. op occurred in a Temp or Perm

Problem determination: Call your next level of support.

E23D0407 E23D0407

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xpce_divide_ov called twice in same proc

Problem determination: Call your next level of support.

E23D0408 E23D0408

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xpce_invalid_op called twice in same pro

Problem determination: Call your next level of support.

E23D0409 E23D0409

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: in xpce_sig_handler, re-establishing sig

Problem determination: Call your next level of support.

E23D040A E23D040A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: temporary process ending, see trace

Problem determination: Call your next level of support.

E23D040B E23D040B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosExitList error; attempt to end exit list processing; compRc from OS 2

Problem determination: Call your next level of support.

E23D040C E23D040C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Permanent process ended

Problem determination: Call your next level of support.

E23D040D E23D040D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A permanent process ended w an rc = 0

Problem determination: Call your next level of support.

E23D040E E23D040E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Async process terminate request

Problem determination: Call your next level of support.

E23D0500 E23D0500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error setting up the signal handler for PCE server program. The application will continue to run, but in the event a program abends, no error logging will occur.

Problem determination: Call your next level of support.

E23D0501 E23D0501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error starting the PCE server program. The application will continue to run, but in the event a program abends, no error logging will occur.

Problem determination: Call your next level of support.

E23D0502 E23D0502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error threshold reached trying to starting the PCE server program. The application will continue to run, but in the event a program abends, no error logging will occur.

Problem determination: Call your next level of support.

E23D0503 E23D0503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: One or more core files were found when starting the PCE server program. This log is taken to make sure an error is logged for this situation and the core files get collected and then cleaned up appropriately.

Problem determination: Call your next level of support.

E23D0700 E23D0700

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Actual size %u != sent size %u. Socket is %u, Msg is %s

Problem determination: Call your next level of support.

E23D0701 E23D0701

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Total Message size %u != sent size %u. Socket is %u, Msg is %s

Problem determination: Call your next level of support.

E23D0702 E23D0702

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid process type of 0x%X passed to xpce_setup()

Problem determination: Call your next level of support.

E23D0703 • E23D07D2

E23D0703 E23D0703

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: atexit returned %u error is: %s

Problem determination: Call your next level of support.

E23D0704 E23D0704

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Count of active xpce_setup()'s still in effect is %d. It should be zero by program termination

Problem determination: Call your next level of support.

E23D0710 E23D0710

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pthread_key_create returned rc= %u trying to create key for stacks

Problem determination: Call your next level of support.

E23D0711 E23D0711

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pthread_setspecific returned rc= %u trying to set alternate stack value

Problem determination: Call your next level of support.

E23D0712 E23D0712

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pthread_setspecific returned rc= %u trying to set thread data value

Problem determination: Call your next level of support.

E23D0713 E23D0713

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to send registration request to Daemon process. rc = %u

Problem determination: Call your next level of support.

E23D0714 E23D0714

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to send de-registration request to Daemon process. rc = %u

Problem determination: Call your next level of support.

E23D0715 E23D0715

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Thread ended without performing the correct number of xpce_unsets. Active Thread Count= %d

Problem determination: Call your next level of support.

E23D0716 E23D0716

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Global Daemon process de-registration not performed because we appear to be handling a trap.

Problem determination: Call your next level of support.

E23D0717 E23D0717

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pthread_setspecific returned rc= %u trying to set value to NULL

Problem determination: Call your next level of support.

E23D07D1 E23D07D1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSetSigHandler error, crc from os 2

Problem determination: Call your next level of support.

E23D07D2 E23D07D2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xpce_setup parm invalid

Problem determination: Call your next level of support.

E23D07D3 E23D07D3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosError failed, cRc from os 2

Problem determination: Call your next level of support.

E23D07D4 E23D07D4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSetVec error(divide0)cRc from os 2

Problem determination: Call your next level of support.

E23D07D5 E23D07D5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSetVec error(inv. op)cRc from os 2

Problem determination: Call your next level of support.

E23D07D6 E23D07D6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosExitList error(temp),cRc from os 2

Problem determination: Call your next level of support.

E23D07D7 E23D07D7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosExitList error(perm),cRc from os 2

Problem determination: Call your next level of support.

E23D07D8 E23D07D8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSetVec fail, divide for pa

Problem determination: Call your next level of support.

E23D07D9 E23D07D9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosExitList fail;pa critical error i f

Problem determination: Call your next level of support.

E23D07DA E23D07DA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An asynchronous process terminate has occurred and no error was reported.

Problem determination: Call your next level of support.

E23D07DB E23D07DB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosSetExceptionHandler crc from os 2

Problem determination: Call your next level of support.

E23D07DC E23D07DC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosUnsetExceptionHandler crc from os 2

Problem determination: Call your next level of support.

E23D07DE E23D07DE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in XTrapHandler::addUserExit calling xpce_add_user_exit

Problem determination: Call your next level of support.

E23D07DF E23D07DF

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in XTrapHandler::removeUserExit calling xpce_remove_user_exit

Problem determination: Call your next level of support.

E23D07E0 E23D07E0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in XTrapHandler::TrapHandler calling xpce_setup

Problem determination: Call your next level of support.

E23D0800 • E23DA901

E23D0800 E23D0800

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosAllocMem buffer for process status data failed, os2 rc logged.

Problem determination: Call your next level of support.

E23D0801 E23D0801

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosQProcStatus failed, see crc.

Problem determination: Call your next level of support.

E23D0802 E23D0802

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetInfoBlocks failed, see crc.

Problem determination: Call your next level of support.

E23D0803 E23D0803

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ancestry for a process did not include TKD and it must.

Problem determination: Call your next level of support.

E23DA000 E23DA000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from select() in main select() loop

Problem determination: Call your next level of support.

E23DA001 E23DA001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Connection list record count already at zero! ptr = %p

Problem determination: Call your next level of support.

E23DA002 E23DA002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Actual size != received size. Specified is %u Actual size is %u

Problem determination: Call your next level of support.

E23DA003 E23DA003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Received unknown type of socket message. Message type is 0x%X

Problem determination: Call your next level of support.

E23DA004 E23DA004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Program 0x%X terminated without performing all needed xpce_unsets. Name is: %s

Problem determination: Call your next level of support.

E23DA881 E23DA881

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: _fmalloc failed. Requested Size was %u.

Problem determination: Call your next level of support.

E23DA900 E23DA900

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_query_file_location error. src= %u, crc= %u

Problem determination: Call your next level of support.

E23DA901 E23DA901

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Returned Prefix length of %u exceeds the maximum of %u.

Problem determination: Call your next level of support.

E23DAA21 E23DAA21

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from socket

Problem determination: Call your next level of support.

E23DAA82 E23DAA82

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from soclose

Problem determination: Call your next level of support.

E23DAA83 E23DAA83

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from bind

Problem determination: Call your next level of support.

E23DAA84 E23DAA84

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from listen

Problem determination: Call your next level of support.

E23DAA86 E23DAA86

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from connect()

Problem determination: Call your next level of support.

E23DAA87 E23DAA87

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from select()

Problem determination: Call your next level of support.

E23DAA88 E23DAA88

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from accept()

Problem determination: Call your next level of support.

E23DAA8C E23DAA8C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from setsockopt(), socket= %u

Problem determination: Call your next level of support.

E23DAA8E E23DAA8E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from send(), socket= %u

Problem determination: Call your next level of support.

E23DAA8F E23DAA8F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from fcntl() socket= %u

Problem determination: Call your next level of support.

E23DAA9B E23DAA9B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error %u returned from so_cancel() socket= %u

Problem determination: Call your next level of support.

E23DAB04 E23DAB04

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error locking pthread - errno=%u pid=%x tid=%x Timeout was %u

Problem determination: Call your next level of support.

E23DAB05 E23DAB05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error unlocking pthread - errno=%u pid=%x tid=%x

Problem determination: Call your next level of support.

E23DAC80 • E23DAD01

E23DAC80 E23DAC80

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Message Exceeds maximum length of %u. Length is %u. Message # %4.4X.

Problem determination: Call your next level of support.

E23DAD00 E23DAD00

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: sigaltstack() returned errno= %u"

Problem determination: Call your next level of support.

E23DAD01 E23DAD01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: sigaction() returned errno= %u. SIGNUM is %d. p_oldsig is %p, p_newsig is %p.

Problem determination: Call your next level of support.

(E24x) Reference codes

E2495000 E2495000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read rtn code

Problem determination: Call your next level of support.

E2495001 E2495001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read bytes.

Problem determination: Call your next level of support.

E2495002 E2495002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is file_offset.

Problem determination: Call your next level of support.

E2495003 E2495003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to file. Error reason is DosSetFilePtr or DosWrite sysrc.

Problem determination: Call your next level of support.

E2495004 E2495004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to file. Error reason is DosSetFilePtr or DosWrite sysrc.

Problem determination: Call your next level of support.

E2495005 E2495005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to query file. Error reason is sysrc from xdfc_query_file_size.

Problem determination: Call your next level of support.

E2495006 E2495006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is DosAllocMem sysrc.

Problem determination: Call your next level of support.

E2495007 E2495007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is DosAllocMem sysrc.

Problem determination: Call your next level of support.

E2495008 E2495008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is DosAllocMem sysrc.

Problem determination: Call your next level of support.

E2495009 E2495009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read bytes.

Problem determination: Call your next level of support.

E249500A E249500A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is file_offset.

Problem determination: Call your next level of support.

E249500B • E2495011

E249500B E249500B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to file. Error reason is DosSetFilePtr or DosWrite sysrc.

Problem determination: Call your next level of support.

E249500C E249500C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to file. Error reason is DosSetFilePtr or DosWrite sysrc.

Problem determination: Call your next level of support.

E249500D E249500D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to query file. Error reason is sysrc from xdfc_query_file_size.

Problem determination: Call your next level of support.

E249500E E249500E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read bytes.

Problem determination: Call your next level of support.

E249500F E249500F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is file_offset.

Problem determination: Call your next level of support.

E2495010 E2495010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to DosOpen log file. Error reason is DosOpen return code.

Problem determination: Call your next level of support.

E2495011 E2495011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to DosOpen log file. Error reason is DosOpen return code.

Problem determination: Call your next level of support.

(E25x) Reference codes

E25CD200 E25CD200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An xpce_setup error occurred. The error reason is sysrc

Problem determination: Call your next level of support.

E25CD201 E25CD201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was encountered in x47_37 The error reason is comp_rc

Problem determination: Call your next level of support.

E25CD202 E25CD202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Xsim read backup status. The error reason is sysrc

Problem determination: Call your next level of support.

E25CD203 E25CD203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Pri IQYP35PN.DAT open error. The error reason is sysrc

Problem determination: Call your next level of support.

E25CD204 E25CD204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Pri IQYP35PN.DAT read error. The error reason is sysrc

Problem determination: Call your next level of support.

E25CD205 E25CD205

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD delete IQYVPD.DAT error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD206 E25CD206

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD alter IQYVPD.DAT error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD207 E25CD207

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XPCE unset failed. The error reason is comp_rc

Problem determination: Call your next level of support.

E25CD208 E25CD208

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD search for default vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD209 E25CD209

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XSIM read for RV mode status error. The error reason is comp_rc

Problem determination: Call your next level of support.

E25CD20A E25CD20A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Info log taken, missing ALT-SE data

Problem determination: Call your next level of support.

E25CD20B E25CD20B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Token Ring Adapter is an unsupported LAN connection in the HMC

Problem determination: Call your next level of support.

E25CD20C E25CD20C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XSIM read for hardware frus error. The error reason is comp_rc

Problem determination: Call your next level of support.

E25CD20D E25CD20D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD cfg req for system vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD20E E25CD20E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD cfg req for system vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD210 E25CD210

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD delete vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD211 E25CD211

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD alter vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD212 E25CD212

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD alter vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD213 E25CD213

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD alter vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD214 E25CD214

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD alter vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD215 E25CD215

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: XVPD request vpd error. The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD218 E25CD218

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: X2SE ALTSE IN VPD error The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD219 E25CD219

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: HCON_GET_SC_LOC function err The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD21E E25CD21E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_query_file_location() error The error reason is sys_rc

Problem determination: Call your next level of support.

E25CD21F E25CD21F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fopen() error on system file The error reason is sys_rc

Problem determination: Call your next level of support.

E25E0001 E25E0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_open error. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0002 E25E0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_libdef error. Lib = Call Auth panel lib. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0003 E25E0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_open error. Panel = 1st Call Auth panel. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0004 E25E0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_open error. Panel = IQYP0K4. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0005 E25E0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_open error. Panel = IQYP0K2. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0006 E25E0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_open error. Panel = IQYP0K7. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0007 E25E0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_open error. Panel = IQYP0K3. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0008 E25E0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_display error. Panel = 1st Call Auth panel. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0009 E25E0009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_display error. Panel = IQYP0K4. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E000A E25E000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_display error. Panel = IQYP0K2. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E000B • E25E0016

E25E000B E25E000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_display error. Panel = IQYP0K7. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E000C E25E000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_display error. Panel = IQYP0K3. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E000D E25E000D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_close error. Panel = 1st Call Auth panel. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E000E E25E000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_close error. Panel = IQYP0K4. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E000F E25E000F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_close error. Panel = IQYP0K2. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0010 E25E0010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_close error. Panel = IQYP0K7. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0011 E25E0011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_close error. Panel = IQYP0K3. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0012 E25E0012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_close error. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0013 E25E0013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_message error. Pop up for pst time input. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0014 E25E0014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_libdef error. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0015 E25E0015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_libdef error. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0016 E25E0016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_forcexit error. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0017 E25E0017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_open error. Panel = 1st Call Auth panel. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0018 E25E0018

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_display error. Panel = 1st Call Auth panel. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0019 E25E0019

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_panel_close error. Panel = IQYP0K7. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E001A E25E001A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_addpop error. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E001B E25E001B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdm_rempop error. Error reason = SDM component return code.

Problem determination: Call your next level of support.

E25E0068 E25E0068

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosLoadModule error. Loading XP12 (gen alert) Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E0069 E25E0069

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetProcAddress error. Handle for _xp12_galert Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E006A E25E006A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xp12_galert error. Generating generic alert. Error reason = xp12_galert component return code.

Problem determination: Call your next level of support.

E25E0100 E25E0100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_search_file_open error. File = log mgr usr file. Error reason = DFC component return code.

Problem determination: Call your next level of support.

E25E0101 E25E0101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xdfc_random_read error. File = log mgr usr file. Error reason = DFC component return code.

Problem determination: Call your next level of support.

E25E0200 E25E0200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xemp_msg error. Error reason = EMP component return code.

Problem determination: Call your next level of support.

E25E0600 E25E0600

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosLoadModule error. Loading SSI. Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E0601 • E25E0805

E25E0601 E25E0601

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetProcAddress error. Handle for _xssi_connect. Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E0602 E25E0602

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetProcAddress error. Handle for _xssi_transmit. Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E0603 E25E0603

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosFreeModule error. Freeing SSI. Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E0604 E25E0604

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosLoadModule error. Loading SSIQ. Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E0605 E25E0605

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DosGetProcAddress error. Handle for _xssi_queue. Error reason = Dos return code.

Problem determination: Call your next level of support.

E25E0700 E25E0700

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xp00_timer error. Setting timer for delaying authorizing call. Error reason = timer component return code.

Problem determination: Call your next level of support.

E25E0800 E25E0800

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_retrieve error. Locating PAPU Std log for a given problem number. Error reason = new log manager component return code.

Problem determination: Call your next level of support.

E25E0801 E25E0801

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_retrieve error. Locating PAIO Std log for a given problem number. Error reason = new log manager component return code.

Problem determination: Call your next level of support.

E25E0802 E25E0802

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_retrieve error. Locating Service History logs for given problem number. Error reason = new log manager component return code.

Problem determination: Call your next level of support.

E25E0803 E25E0803

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_retrieve error. Locating Service History logs for given problem number. Error reason = new log manager component return code.

Problem determination: Call your next level of support.

E25E0804 E25E0804

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: did not find the given problem in the logs. Error reason = none

Problem determination: Call your next level of support.

E25E0805 E25E0805

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: no data in data_block given problem number. Error reason = none

Problem determination: Call your next level of support.

E25E0806 E25E0806

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_free error. Error freeing up log mgr data Error reason = new log manager component return code.

Problem determination: Call your next level of support.

E25E0807 E25E0807

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_free error. Error freeing up log mgr data Error reason = new log manager component return code.

Problem determination: Call your next level of support.

E25E0900 E25E0900

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xssi_connect error. Error reason = SSI component return code.

Problem determination: Call your next level of support.

E25E0901 E25E0901

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xssi_transmit error. Error reason = SSI component return code.

Problem determination: Call your next level of support.

E25E0902 E25E0902

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xssi_queue error. Error reason = SSI component return code.

Problem determination: Call your next level of support.

E25E0B00 E25E0B00

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xmsp error. Error reason = msp component return code.

Problem determination: Call your next level of support.

E25E0B01 E25E0B01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xmsp error. Error reason = msp component return code.

Problem determination: Call your next level of support.

E25E0C00 E25E0C00

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Problem number is in the wrong state to request service. Error reason = none

Problem determination: Call your next level of support.

E25E0C01 E25E0C01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xvpd_mgr error. Getting config data Error reason = VPD component return code.

Problem determination: Call your next level of support.

E25E0C02 E25E0C02

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_retrieve error. Locating HSENSEDATA for hecker sawmill Error reason = new log manager component return code.

Problem determination: Call your next level of support.

E25E0C03 E25E0C03

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xlog_free error. Error freeing up log mgr data Error reason = new log manager component return code.

E25E0C04 • E25E0C07

Problem determination: Call your next level of support.

E25E0C04 E25E0C04

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xsim_read error. Error calling xsim_read
Error reason = iqzsim.h component return code.

Problem determination: Call your next level of support.

E25E0C05 E25E0C05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xvpd_mgr error. Getting config data Error
reason = VPD component return code.

Problem determination: Call your next level of support.

E25E0C06 E25E0C06

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error calling xlog_create_subset function
Error reason = iqyysub.h component return code.

Problem determination: Call your next level of support.

E25E0C07 E25E0C07

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error calling xlog_record Error reason =
iqyylog.h component return code.

Problem determination: Call your next level of support.

(E26x) Reference codes

E2620001 E2620001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: pam_get_item failed

Problem determination: Call your next level of support.

E2620002 E2620002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnbCreateStringFromUTF8 failed

Problem determination: Call your next level of support.

E2620003 E2620003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnbCallStaticObjectMethod failed

Problem determination: Call your next level of support.

E2620004 E2620004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnbCallBooleanMethod failed

Problem determination: Call your next level of support.

E2620005 E2620005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnbCallVoidMethod failed

Problem determination: Call your next level of support.

E2660000 E2660000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnnn_lookup_err: Error #1-> No Known message # %4X found!!

Problem determination: Call your next level of support.

E2660001 E2660001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnnn_lookup_err: Error #2-> No Known message # %4X found!!

Problem determination: Call your next level of support.

E2660002 E2660002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnnn_lookup_err: Part number %u is incorrect. message # %4X

Problem determination: Call your next level of support.

E2660003 E2660003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnnn_lookup_err: Part number %u is incorrect for message # %4X

Problem determination: Call your next level of support.

E2663081 E2663081

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: _fmalloc failed. Requested Size was %u.

Problem determination: Call your next level of support.

E2663580 E2663580

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Message Exceeds maximum length of %u. Length is %u. Message # %4.4X.

Problem determination: Call your next level of support.

E2665080 E2665080

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnbCreateStringFromUTF8 returned %u

E2665081 • E2665085

Problem determination: Call your next level of support.

E2665081 E2665081

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnbReleaseObjectReference returned %u

Problem determination: Call your next level of support.

E2665082 E2665082

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xnbCallStaticIntMethod returned %u

Problem determination: Call your next level of support.

E2665083 E2665083

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Java returned %u from the %s method

Problem determination: Call your next level of support.

E2665084 E2665084

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Java shutdown not possible, attempting a local shutdown from 'C'."

Problem determination: Call your next level of support.

E2665085 E2665085

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: system invocation failed with errno= %u. error is: %s.

Problem determination: Call your next level of support.

(E27x) Reference codes

E27A0001 **E27A0001**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method initialize

Problem determination: Call your next level of support.

E27A0002 **E27A0002**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method enumInstanceNames

Problem determination: Call your next level of support.

E27A0003 **E27A0003**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method enumInstances

Problem determination: Call your next level of support.

E27A0004 **E27A0004**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method getInstance

Problem determination: Call your next level of support.

E27A0010 **E27A0010**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method initialize

Problem determination: Call your next level of support.

E27A0020 **E27A0020**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method associators

Problem determination: Call your next level of support.

E27A0021 **E27A0021**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method associatorNames

Problem determination: Call your next level of support.

E27A0022 **E27A0022**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method references

Problem determination: Call your next level of support.

E27A0023 **E27A0023**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in method referenceNames

Problem determination: Call your next level of support.

(E2Bx) Reference codes

E2BB1100 E2BB1100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: could not initial error reason 10 parser failure; 20 pipe failure; 40 no open

Problem determination: Call your next level of support.

E2BB1120 E2BB1120

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: could not populate errorfiles

Problem determination: Call your next level of support.

E2BB1140 E2BB1140

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: syloghmcpipe read failure

Problem determination: Call your next level of support.

E2BB1150 E2BB1150

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: could not parse error files 1 no files parsed

Problem determination: Call your next level of support.

E2BB1160 E2BB1160

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: syloghmcpipe read failure

Problem determination: Call your next level of support.

E2BB1200 E2BB1200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: could not issue a Hardware that was discovered

Problem determination: Call your next level of support.

E2BB1250 E2BB1250

Explanation: The system monitor that checks for HMC hardware failures has shutdown.

Problem determination: This is usually the result of the system syslog being shutdown. You will need to shut down and restart the HMC.

(E2Cx) Reference codes

E2C25000 E2C25000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error initializing ROUTER Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C25001 E2C25001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error calling xgid_header_info Error reason = iqzgdshi.h

Problem determination: Call your next level of support.

E2C25002 E2C25002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error building GDS Error reason = iqzgdshi.h

Problem determination: Call your next level of support.

E2C25003 E2C25003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error sending GDS Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C25004 E2C25004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error freeing RSFSERV GDS Error reason = iqzgdshi.h

Problem determination: Call your next level of support.

E2C25005 E2C25005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error freeing ROUTER data Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C25006 E2C25006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error freeing ROUTER data Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C25007 E2C25007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending response Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C25008 E2C25008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: GDS build error Error reason = iqzgdshi.h

Problem determination: Call your next level of support.

E2C25009 E2C25009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error freeing ROUTER data Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C2500A E2C2500A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending response Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C2500B • E2C25015

E2C2500B E2C2500B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error checking pointer Error reason = iqzpc.h

Problem determination: Call your next level of support.

E2C2500C E2C2500C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error getting GDS request Error reason = iqzzgdsi.h

Problem determination: Call your next level of support.

E2C2500D E2C2500D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error decoding GDS Error reason = iqzzgdsi.h

Problem determination: Call your next level of support.

E2C2500E E2C2500E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Context Identifier not correct Error reason = context id

Problem determination: Call your next level of support.

E2C2500F E2C2500F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Context Identifier not RSFSERV Error reason = NONE

Problem determination: Call your next level of support.

E2C25010 E2C25010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error freeing GDS Error reason = iqzzgdsi.h

Problem determination: Call your next level of support.

E2C25011 E2C25011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error terminating ROUTER Error reason = iqzrtr.h

Problem determination: Call your next level of support.

E2C25012 E2C25012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ptr to object invalid Error reason = xpce_chkptr

Problem determination: Call your next level of support.

E2C25013 E2C25013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ptr to unit invalid Error reason = xpce_chkptr

Problem determination: Call your next level of support.

E2C25014 E2C25014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error issuing xrtr_free Error reason = comp_rc

Problem determination: Call your next level of support.

E2C25015 E2C25015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error issuing xrtr_alloc_free Error reason = comp_rc

Problem determination: Call your next level of support.

(E2Dx) Reference codes

E2DD0001 E2DD0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory.

Problem determination: Call your next level of support.

E2DD0002 E2DD0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating memory.

Problem determination: Call your next level of support.

E2DE0010 E2DE0010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Duplicate type

Problem determination: Call your next level of support.

E2DE0011 E2DE0011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Cancel Close both specified

Problem determination: Call your next level of support.

E2DE0012 E2DE0012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Bad push button type in push button destroy event

Problem determination: Call your next level of support.

E2DE0020 E2DE0020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid type parameter

Problem determination: Call your next level of support.

E2DE0021 E2DE0021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in XPushButton::XPushButton

Problem determination: Call your next level of support.

E2DE0030 E2DE0030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was thrown and logged without an error id.

Problem determination: Call your next level of support.

E2DE0040 E2DE0040

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Incompatible XEntryField styles.

Problem determination: Call your next level of support.

E2DE0050 E2DE0050

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Duplicate type push button destroy event

Problem determination: Call your next level of support.

(E2Fx) Reference codes

E2FE0001 E2FE0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to comp rc was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0002 E2FE0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0003 E2FE0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0004 E2FE0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0005 E2FE0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0006 E2FE0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0007 E2FE0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0008 E2FE0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0009 E2FE0009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE000A E2FE000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE000B • E2FE0A04

E2FE000B E2FE000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface was passed to xpa_get_retain_file_list function. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FE0300 E2FE0300

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the RETAIN file list TRM file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FE0500 E2FE0500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the Endicott RETAIN file TRM file. Error reason is xdfc_random_read return code.

Problem determination: Call your next level of support.

E2FE0501 E2FE0501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the Endicott RETAIN file TRM file. Error reason is bytes_read.

Problem determination: Call your next level of support.

E2FE0502 E2FE0502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the Boeblingen RETAIN file TRM file. Error reason is xdfc_random_read return code.

Problem determination: Call your next level of support.

E2FE0503 E2FE0503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the Boeblingen RETAIN file TRM file. Error reason is bytes_read.

Problem determination: Call your next level of support.

E2FE0600 E2FE0600

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to find the size of the RETAIN file TRM file. Error reason is xdfc_query_file_size return code.

Problem determination: Call your next level of support.

E2FE0A00 E2FE0A00

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A01 E2FE0A01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A02 E2FE0A02

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A03 E2FE0A03

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A04 E2FE0A04

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A05 E2FE0A05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A06 E2FE0A06

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A07 E2FE0A07

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A08 E2FE0A08

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A09 E2FE0A09

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A0A E2FE0A0A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A0B E2FE0A0B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A0C E2FE0A0C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A0D E2FE0A0D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A0E E2FE0A0E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A0F E2FE0A0F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A10 E2FE0A10

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A11 E2FE0A11

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: return code.

Problem determination: Call your next level of support.

E2FE0A12 • E2FF0591

E2FE0A12 E2FE0A12

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: -01 return code.

Problem determination: Call your next level of support.

E2FF0188 E2FF0188

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to type passed to log manager. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF018A E2FF018A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer new time format passed to log manager. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF018B E2FF018B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer old time format passed to log manager. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF018D E2FF018D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to new time format passed to log manager. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF018E E2FF018E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to old time format passed to log manager. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF0280 E2FF0280

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to system event name passed to log manager. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF0281 E2FF0281

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to system event name passed to log manager. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF0384 E2FF0384

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the VNT file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF0385 E2FF0385

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the VNT file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF0590 E2FF0590

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the VNT file. Error reason is xdfc_random_read rtn code

Problem determination: Call your next level of support.

E2FF0591 E2FF0591

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the VNT file. Error reason is xdfc_random_read rtn code

Problem determination: Call your next level of support.

E2FF0685 E2FF0685

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to close the VNT file. Error reason is xdfc_close_file return code

Problem determination: Call your next level of support.

E2FF0781 E2FF0781

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is 0

Problem determination: Call your next level of support.

E2FF0801 E2FF0801

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid system event name passed to log manager. Error reason is 0

Problem determination: Call your next level of support.

E2FF1100 E2FF1100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to component return code passed to xlog_record. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF1101 E2FF1101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface block passed to xlog_record. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF1102 E2FF1102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the log data block was

passed to xlog_record. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF1103 E2FF1103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the log data was passed to xlog_record. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF1104 E2FF1104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to lock logger semaphore. Error reason is errno.

Problem determination: Call your next level of support.

E2FF1400 E2FF1400

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF1401 E2FF1401

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF1402 E2FF1402

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF1403 • E2FF1800

E2FF1403 E2FF1403

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF1404 E2FF1404

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF1405 E2FF1405

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF1406 E2FF1406

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF1407 E2FF1407

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF1408 E2FF1408

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF1409 E2FF1409

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF1500 E2FF1500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF1501 E2FF1501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF1700 E2FF1700

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is 0

Problem determination: Call your next level of support.

E2FF1701 E2FF1701

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate terse memory. Error reason is errno

Problem determination: Call your next level of support.

E2FF1800 E2FF1800

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: user is requesting to log too many data blocks. error reason is 0.

Problem determination: Call your next level of support.

E2FF1801 E2FF1801

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: user is requesting to log too much data. Error reason is 0

Problem determination: Call your next level of support.

E2FF1802 E2FF1802

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: user is requesting to log a data block that's too large Error reason is 0

Problem determination: Call your next level of support.

E2FF1901 E2FF1901

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to encode data block. Error reason is xlog_mem_encode ret code

Problem determination: Call your next level of support.

E2FF1902 E2FF1902

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to encode data block. Error reason is xlog_mem_encode ret code

Problem determination: Call your next level of support.

E2FF2100 E2FF2100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to component return code was passed to xlog_multi_retrieve.

Problem determination: Call your next level of support.

E2FF2101 E2FF2101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the interface block was passed to xlog_retrieve.

Problem determination: Call your next level of support.

E2FF2102 E2FF2102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the mask data block was passed to xlog_retrieve.

Problem determination: Call your next level of support.

E2FF2103 E2FF2103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the match data block was passed to xlog_retrieve.

Problem determination: Call your next level of support.

E2FF2104 E2FF2104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the mask data was passed to xlog_retrieve.

Problem determination: Call your next level of support.

E2FF2105 E2FF2105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the block ids was passed to xlog_retrieve.

Problem determination: Call your next level of support.

E2FF2201 E2FF2201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF2202 E2FF2202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF2203 • E2FF2507

E2FF2203 E2FF2203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is file offset.

Problem determination: Call your next level of support.

E2FF2204 E2FF2204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is file offset.

Problem determination: Call your next level of support.

E2FF2205 E2FF2205

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF2206 E2FF2206

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF2500 E2FF2500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF2501 E2FF2501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF2502 E2FF2502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF2503 E2FF2503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF2504 E2FF2504

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF2505 E2FF2505

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF2506 E2FF2506

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_read rtn code

Problem determination: Call your next level of support.

E2FF2507 E2FF2507

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF2508 E2FF2508

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF2509 E2FF2509

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF250A E2FF250A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF250B E2FF250B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF250C E2FF250C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_read rtn code

Problem determination: Call your next level of support.

E2FF250D E2FF250D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to position the log file. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2700 E2FF2700

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2701 E2FF2701

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2702 E2FF2702

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2703 E2FF2703

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2704 E2FF2704

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2705 E2FF2705

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2706 • E2FF3101

E2FF2706 E2FF2706

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2707 E2FF2707

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2708 E2FF2708

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2709 E2FF2709

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF270A E2FF270A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF270B E2FF270B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF270C E2FF270C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF270D E2FF270D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF2800 E2FF2800

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Log file corruption detected. Error reason is bad log value.

Problem determination: Call your next level of support.

E2FF2950 E2FF2950

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to lock sem. Error reason is errno

Problem determination: Call your next level of support.

E2FF3100 E2FF3100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to component return code was passed to xlog_free. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF3101 E2FF3101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the log interface block was passed to xlog_free. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF3102 E2FF3102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the log data block was passed to xlog_free. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF3103 E2FF3103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the log data was passed to xlog_free. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF3104 E2FF3104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to component return code was passed to xlog_free. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF4100 E2FF4100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to component return code passed to xlog_log_purge. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF4101 E2FF4101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid size of class delete buffer passed to xlog_log_purge. Error reason is 0.

Problem determination: Call your next level of support.

E2FF4102 E2FF4102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to class delete buffer passed to xlog_log_purge. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF4103 E2FF4103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to class delete buffer passed to xlog_log_purge. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF4201 E2FF4201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF4202 E2FF4202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF4203 E2FF4203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF4300 E2FF4300

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the log file. Error reason is xdfc_search_file_open return code

E2FF4302 • E2FF4407

Problem determination: Call your next level of support.

E2FF4302 E2FF4302

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to query the log file size. Error reason is xdfc_query_file_size return code

Problem determination: Call your next level of support.

E2FF4303 E2FF4303

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the log init file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF4304 E2FF4304

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the log file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF4305 E2FF4305

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the log file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF4400 E2FF4400

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4401 E2FF4401

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4402 E2FF4402

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4403 E2FF4403

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4404 E2FF4404

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4405 E2FF4405

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4406 E2FF4406

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4407 E2FF4407

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4408 E2FF4408

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4409 E2FF4409

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF440A E2FF440A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF440B E2FF440B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF440C E2FF440C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF440D E2FF440D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF440E E2FF440E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF440F E2FF440F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4410 E2FF4410

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4411 E2FF4411

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4412 E2FF4412

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is xdfc_write rtn code

Problem determination: Call your next level of support.

E2FF4413 E2FF4413

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

E2FF4414 • E2FF4507

Problem determination: Call your next level of support.

E2FF4414 E2FF4414

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4415 E2FF4415

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4416 E2FF4416

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4417 E2FF4417

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF4500 E2FF4500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is errno. -15

Problem determination: Call your next level of support.

E2FF4501 E2FF4501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF4502 E2FF4502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_read rtn code

Problem determination: Call your next level of support.

E2FF4503 E2FF4503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF4504 E2FF4504

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4505 E2FF4505

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF4506 E2FF4506

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to position the log file. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4507 E2FF4507

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF4508 E2FF4508

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to position the log file. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4509 E2FF4509

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF450A E2FF450A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to position the log file. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF450B E2FF450B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF450C E2FF450C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_read rtn code

Problem determination: Call your next level of support.

E2FF450D E2FF450D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF450E E2FF450E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to position the log file. Error reason is the errno value. -15

Problem determination: Call your next level of support.

E2FF450F E2FF450F

Explanation: The log manager cannot read the expected amount of data from the log file.

Problem determination: When this occurs, the log manager will copy the current log file to iqyysave.log, start a new log file, and copy the error log to the new log file. If possible, collect the iqyysave.log file with the error data for reference. There is no other action required.

E2FF4510 E2FF4510

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to position the log file. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4511 E2FF4511

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF4512 E2FF4512

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_read rtn code

Problem determination: Call your next level of support.

E2FF4513 E2FF4513

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error

E2FF4600 • E2FF4705

reason is number of bytes read

Problem determination: Call your next level of support.

E2FF4600 E2FF4600

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to close the log file. Error reason is xdfc_close_file return code

Problem determination: Call your next level of support.

E2FF4601 E2FF4601

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to close the log init file. Error reason is xdfc_close_file return code

Problem determination: Call your next level of support.

E2FF4602 E2FF4602

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to close the log init file. Error reason is xdfc_close_file return code

Problem determination: Call your next level of support.

E2FF4603 E2FF4603

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to close the log file. Error reason is xdfc_close_file return code

Problem determination: Call your next level of support.

E2FF4604 E2FF4604

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to get the size of the log file. Error reason xdfc_query_file_size return code.

Problem determination: Call your next level of support.

E2FF4605 E2FF4605

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The log file size is not correct. The error reason is the bad file size.

Problem determination: Call your next level of support.

E2FF4701 E2FF4701

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4702 E2FF4702

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4703 E2FF4703

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4704 E2FF4704

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4705 E2FF4705

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4800 E2FF4800

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: problem deleting log file. Error reason is xdfc_delete_file rtn code.

Problem determination: Call your next level of support.

E2FF4810 E2FF4810

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid target session string passed to log manager. Error reason is 0.

Problem determination: Call your next level of support.

E2FF4901 E2FF4901

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: problem locking semaphore. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4902 E2FF4902

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: problem taking log file. snapshot. Error reason is comp_rc from dfc copy -19

Problem determination: Call your next level of support.

E2FF4903 E2FF4903

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: problem taking e4 log file snapshot. Error reason is comp_rc from dfc copy -19

Problem determination: Call your next level of support.

E2FF4904 E2FF4904

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: problem taking com log file snapshot. Error reason is comp_rc from dfc copy -19

Problem determination: Call your next level of support.

E2FF4905 E2FF4905

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fflush error. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4906 E2FF4906

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fileno error. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4907 E2FF4907

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: fruncate error. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4908 E2FF4908

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: file copy error. Error reason is errno.

Problem determination: Call your next level of support.

E2FF4909 E2FF4909

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: problem deleting log file. Error reason is xdfc_delete_file rtn code.

Problem determination: Call your next level of support.

E2FF490A E2FF490A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: problem compression log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF490B E2FF490B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF490C E2FF490C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF490D E2FF490D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF490E E2FF490E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF490F E2FF490F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4910 E2FF4910

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4911 E2FF4911

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4912 E2FF4912

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error calling to allocate memory. Error reason is xdfc_query_file_location.

Problem determination: Call your next level of support.

E2FF4913 E2FF4913

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to rename file. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4914 E2FF4914

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to rename file. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF4915 E2FF4915

Explanation: A log file was corrupted while compressing an older log file.

Problem determination: The corrupted log file has been copied to the iqyysave.log. A new iqyylog.log file has been started. This refcode will not reappear after starting the new log file. No user action is required.

E2FF5101 E2FF5101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to structure for xlog_log_update.

Problem determination: Call your next level of support.

E2FF5102 E2FF5102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to structure for xlog_update_type.

Problem determination: Call your next level of support.

E2FF5103 E2FF5103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to structure for xlog_mark_log_for_delete.

Problem determination: Call your next level of support.

E2FF5201 E2FF5201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file(update_log). Error reason is 0.

Problem determination: Call your next level of support.

E2FF5202 E2FF5202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file(update_log). Error reason is 0.

Problem determination: Call your next level of support.

E2FF5203 E2FF5203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file(update_log). Error reason is 0.

Problem determination: Call your next level of support.

E2FF5204 E2FF5204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file(update_type). Error reason is 0.

Problem determination: Call your next level of support.

E2FF5205 E2FF5205

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file(mark_log). Error reason is 0.

Problem determination: Call your next level of support.

E2FF5206 E2FF5206

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file(update_type). Error reason is 0.

Problem determination: Call your next level of support.

E2FF5207 E2FF5207

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file(mark_log). Error reason is 0.

Problem determination: Call your next level of support.

E2FF5300 E2FF5300

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to lock sem. Error reason is errno

Problem determination: Call your next level of support.

E2FF5301 E2FF5301

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to lock sem. Error reason is errno

Problem determination: Call your next level of support.

E2FF5302 E2FF5302

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to lock sem. Error reason is errno

Problem determination: Call your next level of support.

E2FF5400 • E2FF5505

E2FF5400 E2FF5400

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value. -15

Problem determination: Call your next level of support.

E2FF5401 E2FF5401

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written. -15

Problem determination: Call your next level of support.

E2FF5402 E2FF5402

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value. -15

Problem determination: Call your next level of support.

E2FF5403 E2FF5403

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written. -15

Problem determination: Call your next level of support.

E2FF5404 E2FF5404

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF5405 E2FF5405

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF5500 E2FF5500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF5501 E2FF5501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF5502 E2FF5502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF5503 E2FF5503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF5504 E2FF5504

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF5505 E2FF5505

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF5506 E2FF5506

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF5507 E2FF5507

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF5508 E2FF5508

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF5509 E2FF5509

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF550A E2FF550A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_read rtn code

Problem determination: Call your next level of support.

E2FF550B E2FF550B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF5600 E2FF5600

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the log file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF5601 E2FF5601

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the log file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF5602 E2FF5602

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to open the log file. Error reason is xdfc_search_file_open return code

Problem determination: Call your next level of support.

E2FF6000 E2FF6000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to run setup. Error reason is the xpce_setup return code.

Problem determination: Call your next level of support.

E2FF6001 E2FF6001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to retrieve the message for no events. Error reason is the xmsp return code.

Problem determination: Call your next level of support.

E2FF6002 E2FF6002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to retrieve the message for no events. Error reason is the xmsp return code.

Problem determination: Call your next level of support.

E2FF6003 • E2FF600E

E2FF6003 E2FF6003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to get the size of system event file. Error reason is the xdfc_query_file_size rc.

Problem determination: Call your next level of support.

E2FF6004 E2FF6004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to open the system event file. Error reason is the xdfc_search_file_open rc.

Problem determination: Call your next level of support.

E2FF6005 E2FF6005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to read the system event file. Error reason is the xdfc_random_read ret code.

Problem determination: Call your next level of support.

E2FF6006 E2FF6006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to read the system event file. Error reason is the number of bytes read.

Problem determination: Call your next level of support.

E2FF6007 E2FF6007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to close the system event file. Error reason is the xdfc_close_file ret code.

Problem determination: Call your next level of support.

E2FF6008 E2FF6008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An undefined system event the message ID. Error reason is the xcsf_decchar2int ret code.

Problem determination: Call your next level of support.

E2FF6009 E2FF6009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to allocate memory. Error reason is 0.

Problem determination: Call your next level of support.

E2FF600A E2FF600A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to allocate memory. Error reason is 0.

Problem determination: Call your next level of support.

E2FF600B E2FF600B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to allocate memory. Error reason is 0.

Problem determination: Call your next level of support.

E2FF600C E2FF600C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to convert the message ID. Error reason is the xcsf_decchar2int ret code.

Problem determination: Call your next level of support.

E2FF600D E2FF600D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to convert the variable count. Error reason is the xcsf_decchar2int ret code.

Problem determination: Call your next level of support.

E2FF600E E2FF600E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An undefined system event was passed to the displayer. Error reason is the system event number.

Problem determination: Call your next level of support.

E2FF600F E2FF600F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An undefined system event was passed to the displayer. Error reason is the system event number.

Problem determination: Call your next level of support.

E2FF6010 E2FF6010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to retrieve the message for system event. Error reason is the xmsp return code.

Problem determination: Call your next level of support.

E2FF6011 E2FF6011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to retrieve the message for system event. Error reason is the xmsp return code.

Problem determination: Call your next level of support.

E2FF6012 E2FF6012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to convert the timestamp to old format. Error reason is the xlog_untranslate ret code.

Problem determination: Call your next level of support.

E2FF6013 E2FF6013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to convert the timestamp to old format. Error reason is the xlog_untranslate ret code.

Problem determination: Call your next level of support.

E2FF6014 E2FF6014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to convert the timestamp to old format. Error reason is the xlog_untranslate ret code.

Problem determination: Call your next level of support.

E2FF6015 E2FF6015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a DM open. Error reason is the xdm_open return code.

Problem determination: Call your next level of support.

E2FF6016 E2FF6016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a libdef. Error reason is the xdm_libdef return code.

Problem determination: Call your next level of support.

E2FF6017 E2FF6017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a panel open. Error reason is the xdm_panel_open ret code.

Problem determination: Call your next level of support.

E2FF6018 E2FF6018

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a panel open. Error reason is the xdm_panel_open ret code.

Problem determination: Call your next level of support.

E2FF6019 E2FF6019

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to display the system event panel. Error reason is the xdm_display return code.

Problem determination: Call your next level of support.

E2FF601A E2FF601A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to display the system event panel. Error reason is the xdm_display return code.

E2FF601B • E2FF7403

Problem determination: Call your next level of support.

E2FF601B E2FF601B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a DM panel close. Error reason is the xdm_panel_close ret code.

Problem determination: Call your next level of support.

E2FF601C E2FF601C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a DM panel close. Error reason is the xdm_panel_close ret code.

Problem determination: Call your next level of support.

E2FF601D E2FF601D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a DM panel close. Error reason is the xdm_panel_close ret code.

Problem determination: Call your next level of support.

E2FF601E E2FF601E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a DM panel close. Error reason is the xdm_panel_close ret code.

Problem determination: Call your next level of support.

E2FF601F E2FF601F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a DM close. Error reason is the xdm_close return code.

Problem determination: Call your next level of support.

E2FF6020 E2FF6020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error trying to do a DM close. Error reason is the xdm_close return code.

Problem determination: Call your next level of support.

E2FF7201 E2FF7201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF7202 E2FF7202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid internal pointer in the log file. Error reason is 0.

Problem determination: Call your next level of support.

E2FF7400 E2FF7400

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is xdfc_random_write rtn code

Problem determination: Call your next level of support.

E2FF7401 E2FF7401

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF7402 E2FF7402

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is xdfc_random_write rtn code

Problem determination: Call your next level of support.

E2FF7403 E2FF7403

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF7404 E2FF7404

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is xdfc_random_write rtn code

Problem determination: Call your next level of support.

E2FF7405 E2FF7405

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF7406 E2FF7406

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is xdfc_random_write rtn code

Problem determination: Call your next level of support.

E2FF7407 E2FF7407

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to write to the log file. Error reason is number of bytes written.

Problem determination: Call your next level of support.

E2FF7500 E2FF7500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read rtn code

Problem determination: Call your next level of support.

E2FF7501 E2FF7501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF7502 E2FF7502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read rtn code

Problem determination: Call your next level of support.

E2FF7503 E2FF7503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF7504 E2FF7504

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read rtn code

Problem determination: Call your next level of support.

E2FF7505 E2FF7505

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF7506 E2FF7506

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is xdfc_random_read rtn code

Problem determination: Call your next level of support.

E2FF7507 E2FF7507

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

E2FF7700 • E2FF9005

Problem determination: Call your next level of support.

E2FF7700 E2FF7700

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is 0

Problem determination: Call your next level of support.

E2FF7701 E2FF7701

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is 0

Problem determination: Call your next level of support.

E2FF7702 E2FF7702

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is 0

Problem determination: Call your next level of support.

E2FF8001 E2FF8001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to component return code passed to xlog_microcode_log. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF8002 E2FF8002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface block passed to xlog_microcode_log. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF8003 E2FF8003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to the log data block was passed to xlog_microcode_log. Error reason is xpce_chkptr return code

Problem determination: Call your next level of support.

E2FF9001 E2FF9001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating outb.codes Error reason = 0

Problem determination: Call your next level of support.

E2FF9002 E2FF9002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating hashtab Error reason = 0

Problem determination: Call your next level of support.

E2FF9003 E2FF9003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating discrim_node Error reason = 0

Problem determination: Call your next level of support.

E2FF9004 E2FF9004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating tree Error reason = 0

Problem determination: Call your next level of support.

E2FF9005 E2FF9005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating discrim Error reason = 0

Problem determination: Call your next level of support.

E2FF9006 E2FF9006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating discrima Error reason = 0

Problem determination: Call your next level of support.

E2FF9007 E2FF9007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating codequeue Error reason = 0

Problem determination: Call your next level of support.

E2FF9008 E2FF9008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating bytequeue Error reason = 0

Problem determination: Call your next level of support.

E2FF9009 E2FF9009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error allocating tree Error reason = 0

Problem determination: Call your next level of support.

E2FF9011 E2FF9011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Overwriting output buffer Error reason = 0

Problem determination: Call your next level of support.

E2FF9012 E2FF9012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Overwriting output buffer Error reason = 0

Problem determination: Call your next level of support.

E2FF9013 E2FF9013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Overwriting output buffer Error reason = 0

Problem determination: Call your next level of support.

E2FF9014 E2FF9014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Overwriting output buffer Error reason = 0

Problem determination: Call your next level of support.

E2FF9015 E2FF9015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Overwriting output buffer Error reason = 0

Problem determination: Call your next level of support.

E2FF9200 E2FF9200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to interface data structure.

Problem determination: Call your next level of support.

E2FF9201 E2FF9201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to match data structure.

Problem determination: Call your next level of support.

E2FF9202 E2FF9202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: invalid pointer to match data buffer.

Problem determination: Call your next level of support.

E2FF9203 E2FF9203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Access error reading from match data buffer.

Problem determination: Call your next level of support.

E2FF9204 • E2FF9272

E2FF9204 E2FF9204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid blockid pointer.

Problem determination: Call your next level of support.

E2FF9250 E2FF9250

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF9251 E2FF9251

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate memory. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF9252 E2FF9252

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate terse buffer. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF9253 E2FF9253

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate terse buffer. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF9254 E2FF9254

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate buffer for log data. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF9255 E2FF9255

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate buffer for log data. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF9256 E2FF9256

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to allocate buffer for log data. Error reason is the errno value.

Problem determination: Call your next level of support.

E2FF9260 E2FF9260

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to lock sem. Error reason is errno

Problem determination: Call your next level of support.

E2FF9270 E2FF9270

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF9271 E2FF9271

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF9272 E2FF9272

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF9273 E2FF9273

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

E2FF9274 E2FF9274

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is ferror return value.

Problem determination: Call your next level of support.

E2FF9275 E2FF9275

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error trying to read from the log file. Error reason is number of bytes read

Problem determination: Call your next level of support.

(E2xx) Reference codes

E2XXXXXX E2XXXXXX

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

Failing Item:

- NEXTLVL

(E302E0xx) Reference codes

E302E000 E302E000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: No component was specified in this MCF

Problem determination: Call your next level of support.

E302E001 E302E001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: processing an MCF containing an autoaccept keyword.

Problem determination: Call your next level of support.

E302E002 E302E002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to access the MCF control file

Problem determination: Call your next level of support.

E302E003 E302E003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to write the MCF control file

Problem determination: Call your next level of support.

E302E004 E302E004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to close the MCF control file

Problem determination: Call your next level of support.

E302E005 E302E005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to close

the MCF control file after writing it.

Problem determination: Call your next level of support.

E302E006 E302E006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This is a "hex patch mismatch". This means that the code on the system does not match the expected code on the system. It could be that the system has some code copied onto it directly, instead of using change management (this is called "private" code). It could also mean that the MCF is built or that the MCL contains two MCFs that alter the same file and the MCL is having the MCFs activated in the wrong sequence. The first step to resolving this problem is to verify that this is a clean system with code that matches what has been officially released. If the system has clean good code, then support must be contacted to analyze the failure. Be sure to tell support which MCF has been identified as the problem (using "analyze internal code" or "manage internal code with product engineering direction" to find the MCF(s) with the "Err" (Error) status). Before attempting to retry the operation, you may have to "undo" the last operation (such as removing the MCLs that you just tried to activate).

Problem determination: Call your next level of support.

E302E007 E302E007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While processing an MCF we did not find a file where we expected to find one.

Problem determination: Call your next level of support.

E302E008 E302E008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While executing an AFIL or EFIL in an MCF we found a file existed where we did not expect it to exist.

Problem determination: Call your next level of support.

E302E009 E302E009

E302E00A • E302E014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied before reboot. The error occurred while copying the file to the temporary staging area.

Problem determination: Call your next level of support.

E302E00A E302E00A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied before reboot. The error occurred while copying the file to its final destination.

Problem determination: Call your next level of support.

E302E00B E302E00B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied after reboot. The error occurred while backing up the old version of the file being patched.

Problem determination: Call your next level of support.

E302E00C E302E00C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied before reboot. The error occurred while backing up the old version of the file being patched.

Problem determination: Call your next level of support.

E302E00D E302E00D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied before reboot. The error occurred while deleting the temporary file used in file processing.

Problem determination: Call your next level of support.

E302E00E E302E00E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an AFILE in an MCF. This file was to be applied before reboot. The error occurred while copying the file to its final destination.

Problem determination: Call your next level of support.

E302E00F E302E00F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The command in the hex-patch file is not recognized. This is most likely caused by a corrupted hex-patch file. You will need to delete the bad MCL.

Problem determination: Call your next level of support.

E302E012 E302E012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied after reboot. The error occurred while copying the file being patched to the temporary staging area.

Problem determination: Call your next level of support.

E302E013 E302E013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or HFILE in an MCF. We were undoing a previous activate or deactivate on this MCF. This file was to be applied after reboot. The error occurred while copying the file being patched to a temporary file.

Problem determination: Call your next level of support.

E302E014 E302E014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied after reboot. The error occurred while closing the shell script file which executes during the reboot.

Problem determination: Call your next level of support.

E302E015 E302E015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or an HFILE in an MCF. This file was to be applied after reboot. The error occurred while writing to the file which does the queuing.

Problem determination: Call your next level of support.

E302E016 E302E016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an AEXEC command within an MCF.

Problem determination: Call your next level of support.

E302E017 E302E017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process a DEXEC command within an MCF.

Problem determination: Call your next level of support.

E302E01A E302E01A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while searching for the file to swap with to update this locked file. The pointers have gotten confused somehow.

Problem determination: Call your next level of support.

E302E01B E302E01B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RPM command within an MCF.

Problem determination: Call your next level of support.

E302E01C E302E01C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An I/O error occurred while attempting to process the files within an MCF.

Problem determination: Call your next level of support.

E302E01D E302E01D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A syntax error occurred while attempting to process the files within an MCF.

Problem determination: Call your next level of support.

E302E01E E302E01E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while writing the accept history file.

Problem determination: Call your next level of support.

E302E01F E302E01F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The hexpatch is missing a checksum. Check failing MCF. It says that a hexpatch file in an MCL is corrupted.

Problem determination: Call your next level of support.

E302E020 E302E020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An ACCEPT= keyword is in the MCF. The EC in the ACCEPT= keyword is not on the platform.

Problem determination: Call your next level of support.

E302E021 E302E021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An EMCF= keyword is in the MCF. The EC in the EMCF= keyword is not on the platform.

Problem determination: Call your next level of support.

E302E022 E302E022

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while getting the path of the accept history file prior to attempting to write it.

Problem determination: Call your next level of support.

E302E023 E302E023

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RPM within an MCF. The RPM was to be applied during the reboot. The error occurred while closing the shell script file which executes during the reboot.

Problem determination: Call your next level of support.

E302E024 E302E024

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RPM within an MCF. This RPM was to be applied during the reboot. The error occurred while writing to the file which does the queing.

Problem determination: Call your next level of support.

E302E025 E302E025

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to get the path of the file which stores the list of MCLs that are being automatically accepted.

Problem determination: Call your next level of support.

E302E026 E302E026

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid module type was encountered while parsing a new type MCF.

Problem determination: Call your next level of support.

E302E027 E302E027

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid keyword was encountered while parsing a new type MCF.

Problem determination: Call your next level of support.

E302E028 E302E028

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While working with a patch that requires reboot, we were attempting to add a script to process the patch to the shutdown manager, but we were unable to add the script.

Problem determination: Call your next level of support.

E302E029 E302E029

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While working with a patch that requires reboot, we were attempting to read the script file to see if the reverse of the command is there but we took an error while attempting to read the script file.

Problem determination: Call your next level of support.

E302E02A E302E02A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While working with a patch that requires reboot, we were attempting to read the script file to see if the reverse of the command is there but we took an error while attempting to close the script file.

Problem determination: Call your next level of support.

E302E02B E302E02B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While working with a patch that requires reboot, we were attempting to rewrite the script file, because we are processing a command that reverses the effect of a previous command, but we took an error while attempting to process the script file.

Problem determination: Call your next level of support.

E302E02C E302E02C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While working with a patch that requires reboot, we were attempting to rewrite the script file, because we are processing a command that reverses the effect of a previous command, but we took an error while attempting to close the script file.

Problem determination: Call your next level of support.

E302E02D E302E02D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or HFILE in an MCF. We were undoing a previous activate or deactivate on this MCF. This file was to be applied after reboot. The error occurred while replacing the file in the staging area.

Problem determination: Call your next level of support.

E302E02E E302E02E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process an RFILE or HFILE in an MCF. We were undoing a previous activate or deactivate on this MCF. This file was to be applied after reboot. The error occurred while replacing the file which is to be applied during reboot.

Problem determination: Call your next level of support.

E302E02F E302E02F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to undo a patch that requires reboot, we were attempting to read the script file to see if the command is there but we took an error while attempting to read the script file.

Problem determination: Call your next level of support.

E302E030 E302E030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to undo a patch that requires reboot, we were attempting to read the script file to see if the command is there but we took an error while attempting to close the script file.

Problem determination: Call your next level of support.

E302E031 E302E031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to undo a patch that requires reboot, we were attempting to rewrite the script file, but we took an error while attempting to process the script file.

Problem determination: Call your next level of support.

E302E032 E302E032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While attempting to undo a patch that requires reboot, we were attempting to rewrite the script file but we took an error while attempting to close the script file.

Problem determination: Call your next level of support.

E302E033 E302E033

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when we were copying a MCF module from an import directory to the staging area. This may occur with an improperly built MCF. It could also occur if the module named in the MCF was not included in the MCF because of its type (such as a file being deleted or a link). This is an informational log.

Problem determination: Call your next level of support.

E302E034 E302E034

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when we were attempting to add a new file. This error indicates that the directory that would contain the new file did not exist and could not be created. This may occur when a file exists that has the same name as the directory or one of its parent directories. The exact nature of the problem should be apparent from the trace information.

Problem determination: Call your next level of support.

E302E035 E302E035

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when we were attempting to move a patch file to the /console/mcf/patched/ directory in preparation for applying that patch to the target file. The exact nature of the problem should be apparent from the trace information.

Problem determination: Call your next level of support.

E302E036 E302E036

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when while attempting to move a temporary file that was the result of a patch operation to the /console/mcf/ directory immediately after the patch was applied. The exact nature of the problem should be apparent from the trace information.

Problem determination: Call your next level of support.

E302E037 E302E037

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when while attempting to convert a patch file that has already been applied to a 0-length file to conserve space. The error does not impact the patch operation. If the problem persists, more disk space is used than would be expected, and if MCLs are never deleted or committed, the problem could contribute to an out-of-disk-space problem. This is an informational log.

Problem determination: Call your next level of support.

E302E038 E302E038

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when while attempting to create the directory under the mcf/patched directory that we will be moving a patch file to in preparation to apply the patch. The exact nature of the problem should be apparent from the trace information.

Problem determination: Call your next level of support.

E302E039 E302E039

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to delete the MCF file while unpacking an MCF.

Problem determination: Call your next level of support.

E302E03A E302E03A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to unzip the data file for an MCF.

Problem determination: Call your next level of support.

E302E03B E302E03B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when we were attempting to hex-patch a file. The file to be patched does not exist or is queued for deletion by an earlier patch. This event would only occur if an MCL's content is incorrect. The operation will fail.

Problem determination: Call your next level of support.

E302E03C E302E03C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: More than one component keyword was specified in this MCF. The MCF will be considered invalid and will not be processable.

Problem determination: Call your next level of support.

E302E03D E302E03D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A component keyword was specified in this MCF that is not currently supported. The MCF will be considered invalid and will not be processable.

Problem determination: Call your next level of support.

E302E03E E302E03E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A keyword being processed when an MCF is parsed threw a KeywordException. This indicates some form of error in the keyword data. The MCF will be considered invalid and will not be processable.

Problem determination: Call your next level of support.

E302E03F E302E03F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A component was being processed and an error occurred. The patches cannot be applied in this situation. The patch operation is terminated with a failure. Normal patch error recovery (back out of patches) is performed.

Problem determination: Call your next level of support.

E302E040 E302E040

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A element was found inside a MCF element that should not contain an element. The MCF is considered invalid.

Problem determination: Call your next level of support.

E302E041 E302E041

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A element was found in an MCF inside an element that should not contain a element. The MCF is considered invalid.

Problem determination: Call your next level of support.

E302E042 E302E042

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An element was being processed and the correct command could not be created. The MCF is considered invalid.

Problem determination: Call your next level of support.

E302E043 E302E043

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attribute of the element was not recognized, which implies the MCF was incorrectly built. It is considered invalid.

Problem determination: Call your next level of support.

E302E044 E302E044

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: When an element was processed, one of the arguments was found to be illegal. This implies the MCF was incorrectly built. It is considered invalid.

Problem determination: Call your next level of support.

E302E045 E302E045

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were unable to delete the auto-accept data file.

Problem determination: Call your next level of support.

E302E046 E302E046

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were unable to close the auto-accept data file after adding an entry to the file.

Problem determination: Call your next level of support.

E302E047 E302E047

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Permissions were provided when creating a link in an MCF. This is not allowed. The MCF is considered incorrect.

Problem determination: Call your next level of support.

E302E048 E302E048

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The type in the XML for the MCF is not valid. It should be either "temporary" or "permanent".

Problem determination: Call your next level of support.

E302E049 E302E049

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception occurred while attempting to construct the MCF.

Problem determination: Call your next level of support.

E302E04A E302E04A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A recognized exception occurred while attempting to process the files within an MCF. Possibly the MCF is built incorrectly.

Problem determination: Call your next level of support.

E302E04B E302E04B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unrecognized exception occurred while attempting to process the files within an MCF.

Problem determination: Call your next level of support.

E302E04C E302E04C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While executing an AEXEC or DEXEC of a program during MCF processing, the AEXEC or DEXEC returned a non-zero return code, indicating that it failed.

Problem determination: Call your next level of support.

E302E04D E302E04D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While parsing an MCF, an invalid numeric value was encountered. The field will be identified in the traces attached to the log. This indicates the MCF is invalid. The MCF will not be usable. It will most likely result in an error when it is used.

Problem determination: Call your next level of support.

E302E04E E302E04E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A current or previous element was found inside a MCF that should not contain such an element. These elements should only be found inside an element. The MCF is considered invalid.

Problem determination: Call your next level of support.

E302E04F E302E04F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We have reached the minimum threshold of space available in the /console partition that consider adequate to safely perform MCL/MCF apply or remove operations. The MCL/MCF processing operation will be terminated in failure.

Problem determination: Call your next level of support.

E302E060 E302E060

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an error when creating the temporary file in which we build the hex-patched version of the new file being processed by an MCF. The patch operation will fail.

Problem determination: Call your next level of support.

E302E061 E302E061

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an error when opening files during a hex-patch operation. We were about to start building the new file from the hex-patch instructions and the old file. The file that we were unable to open will be indicated in the attached traces. The hex-patch operation will be terminated and is considered to have failed.

Problem determination: Call your next level of support.

E302E062 E302E062

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an error when closing files during a hex-patch operation. We have completed building the new file from the hex-patch instructions and the old file. The file that we were unable to close

will be indicated in the attached traces. The hex-patch operation will continue. This error is not fatal to that operation.

Problem determination: Call your next level of support.

E302E063 E302E063

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an error during hex-patch a file where we were unable to rename the newly constructed new version of the file to replace the hex-patch file. The files that were involved in this operation will be indicated in the attached traces. The hex-patch operation will be terminated and is considered to have failed.

Problem determination: Call your next level of support.

E302E064 E302E064

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an error during hex-patch a file where we found additional data in the hex-patch file after the checksum control section. This is not allowed and the file is considered corrupted. The hex-patch operation will be terminated and is considered to have failed.

Problem determination: Call your next level of support.

E302E065 E302E065

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an error during the hex-patch of a file where the version data that specifies the format of the hex-patch file is not recognized. This is not allowed and the file is considered corrupted. The hex-patch operation will be terminated and is considered to have failed.

Problem determination: Call your next level of support.

E302E066 E302E066

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an error during the hex-patch and we were trying to collect some diagnostic information. We attempted to determine the CRC32 checksum value of a file and that produced an error. The initial error will cause the hex-patch operation to be terminated.

Problem determination: Call your next level of support.

E302E070 E302E070

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted an auto-accept, but the MCF specified is neither activated nor being activated during this patch session.

Problem determination: Call your next level of support.

E302E071 E302E071

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted an auto-accept, but the set of MCFs to be autoaccepted would take a dependency check during the accept step.

Problem determination: Call your next level of support.

E302E074 E302E074

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an IO error when closing a file while attempting to calculate the file's checksum. If this was the only error, then the operation is still considered successful. This log is taken to ensure the problem gets investigated. The trace entries attached to the log will indicate the file that was being processed.

Problem determination: Call your next level of support.

E302E075 E302E075

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We encountered an IO error when opening or reading a file while attempting to calculate the file's checksum. The operation is considered a failure. The trace entries attached to the log will indicate the file that was being processed.

Problem determination: Call your next level of support.

(E302E4xx) Reference codes

E302E480 E302E480

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This error code is generated while running a script which checks the integrity of the SE after install and activate of driver 63 bundle 12. The refcode means that files are missing from the system. The extension is the return code from the script. The actual missing files are in traces. The refcode has been seen in manufacturing when loading MCLs through bundle 15 from a control level 3 AROM due to the problem where we do not reboot in the AROM process after ACTREQs. See ODT H5687

Problem determination: Call your next level of support.

E302E481 E302E481

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This error code is generated while running a script which checks the integrity of the SE after install and activate of driver 63 bundle 12. The refcode means that the iqyye4.trm is not the correct version when we are running post bundle 12. The actual data is in the traces. The refcode has been seen in manufacturing when loading MCLs through bundle 15 from a control level 3 AROM due to the problem where we do not reboot in the AROM process after ACTREQs. See ODT H5687

Problem determination: Call your next level of support.

(E302E5xx) Reference codes

E302E500 E302E500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Console Single Step MCL task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Console Single Step MCL task has been ended.

Problem determination: Call your next level of support.

E302E501 E302E501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Console Single Step MCL task action handler. The Console Single Step MCL task has been ended.

Problem determination: Call your next level of support.

E302E502 E302E502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Console Single Step MCL task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Console Single Step MCL task has been ended.

Problem determination: Call your next level of support.

E302E503 E302E503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to free the Patch Lock when the tasklet terminates. The failure may prevent other Change Management functions from running. A reboot will clear up any resulting conflict.

Problem determination: Call your next level of support.

E302E510 E302E510

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to retrieve persisted data from

the persistence manager. The default values for the class will be used.

Problem determination: Call your next level of support.

E302E511 E302E511

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid argument was passed to the setActivateOperation() method. The log is taken, and a default value of SS_NONE is used so that processing can continue.

Problem determination: Call your next level of support.

E302E512 E302E512

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid argument was passed to the setSchedopOperation() method. The log is taken, and a default value of SO_NONE is used so that processing can continue.

Problem determination: Call your next level of support.

E302E513 E302E513

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid argument was passed to the setActivateOperation() method. The log is taken, and a default value of SS_NONE is used so that processing can continue.

Problem determination: Call your next level of support.

E302E520 E302E520

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the main processing core of the Change Console Internal Code Restart Tasklet. This is the result of an exception being caught by the underlying Tasklet infrastructure. * The task has been ended.

Problem determination: Call your next level of support.

E302E521 E302E521

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to launch the Change Console Internal Code Completion Tasklet. We have waited a sufficient time for the local session to start, but it hasn't. We will not attempt to show the completion progress panel for the Change Console Internal Code operation.

Problem determination: Call your next level of support.

E302E522 E302E522

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the main processing core of the Change Console Internal Code Completion Tasklet. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E302E530 E302E530

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for the Console Single Step MCL Restart task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Console Single Step MCL Restart task has been ended.

Problem determination: Call your next level of support.

E302E531 E302E531

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for the Console Single Step MCL Restart task. This is the result unexpected saved data for which we can not determine what operation was being performed. The Console Single Step MCL Restart task has been ended.

Problem determination: Call your next level of support.

E302E532 E302E532

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the main processing core of the Console Single Step Mcl Completion Tasklet. This is the result of an exception being caught by the underlying

Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E302E533 E302E533

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Console Single Step MCL Completion task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Console Single Step MCL Completion task has been ended.

Problem determination: Call your next level of support.

E302E540 E302E540

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to write data to the data file associated with the class. This means we were not able to make a record of a file that was patched that lay outside of the directories that we backup regardless. A more precise description of the error can be had by examining the trace information.

Problem determination: Call your next level of support.

E302E550 E302E550

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to load the patch trace JNI library. Patch trace will not be able trace entries created in the Java portion of the application. These messages will instead be passed to the normal Trace.trace method.

Problem determination: Call your next level of support.

E302E551 E302E551

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform the native bridge setup. Patch trace will not be able to perform the special patch trace functions. Therefore, patch tracing on the Java side of the application is not performed and the traces messages are routed to the normal trace facility.

Problem determination: Call your next level of support.

E302E552 E302E552

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform a native bridge operation. Patch trace will continue to attempt to perform other "special" operations.

Problem determination: Call your next level of support.

E302E560 E302E560

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: When a the master shutdown processing script was run, it was not run with root authority. Because of that, some of the operations it might have to perform could fail. The operations are allowed to continue in the hopes that the lack of root authority will not impact the processing.

Problem determination: Call your next level of support.

E302E561 E302E561

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was unable to execute the file-swapping script because the script did not have execute permission and the shutdown-processing script was unable to give it execute permission. The operation is terminated and the change management subsystem is placed in a "HOZD" state. No further patch operations will be possible until PE can recover the system.

Problem determination: Call your next level of support.

E302E562 E302E562

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was attempting to resolve the path for a file using the DFC functionality provided in the hmcfuctions shell script. It was unable to locate the script where it was expected, however. It made its best guess for a path, but it is likely that the calling function will fail.

Problem determination: Call your next level of support.

E302E563 E302E563

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing has encountered a problem that has left the system in a dangerous state. The patch levels of the processor may not be the same as the levels on the system hard drive. PE intervention is required to recover this system.

Problem determination: Call your next level of support.

E302E564 E302E564

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was attempting to change permissions on one or more files. It encountered a problem, so desired file access to some files may not be possible. This unlikely situation could make patched files "invisible" to normal (non-root) processing. The effects of this situation are unpredictable.

Problem determination: Call your next level of support.

E302E565 E302E565

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was attempting to change permissions on one or more files. It encountered a file in the data that had no change operations against it. Since this represents the likelihood of an internal error, an error log was taken. Processing was allowed to continue.

Problem determination: Call your next level of support.

E302E566 E302E566

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was attempting to change links on one or more files. It encountered a problem, so the links to some files may not be correct. The effects of this situation are unpredictable.

Problem determination: Call your next level of support.

E302E567 E302E567

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was attempting to complete movement for file swapping and encountered

E302E568 • E302E592

an error. Since not all files were properly moved, some of the files may not be correct. The effects of this situation are unpredictable. This error results in Change Management becoming permanently disabled.

Problem determination: Call your next level of support.

E302E568 E302E568

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was attempting to reboot the system after moving files, and after the time allotted, the system had not yet rebooted. Normal flow continues allowing the script to exit back to its caller. The effects of this situation are unpredictable. We choose not to disable patch if this happens.

Problem determination: Call your next level of support.

E302E569 E302E569

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Shutdown processing was attempting to complete movement for updating unmounted file systems and encountered an error. Since not all files were properly moved, some of the files in the unmounted partition(s) may not be correct. The effects of this situation are unpredictable. Since none of these files can result in an UIRA (they are only SE operating files), change management is NOT permanently disabled.

Problem determination: Call your next level of support.

E302E570 E302E570

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: When the FilePermissionsChanger was attempting to write the data file that saves the deferred file permissions changes data, it encountered an error. The data was not saved, so the patch operation will fail to ensure consistent code levels are preserved.

Problem determination: Call your next level of support.

E302E578 E302E578

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: When the FileLinkChanger was attempting to write the data file that saves the deferred file link creation data, it encountered an error. The data was not saved, so the patch operation will fail to ensure

consistent code levels are preserved.

Problem determination: Call your next level of support.

E302E580 E302E580

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: When the EcVpdService class was processing a request for SYSTEM data, the count of the resulting EC streams was not 1. This indicates there is no SYSTEM EC stream or that more than one was found. In either case, that implies a fundamental problem with the set of EC streams defined.

Problem determination: Call your next level of support.

E302E590 E302E590

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ZseCduPreloadMclRestartTasklet class encountered an unexpected Exception. Tasklet operation is terminated.

Problem determination: Call your next level of support.

E302E591 E302E591

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ZselqzminacRestartTasklet class encountered an unexpected Exception. Tasklet operation is terminated. This occurs following a reboot of the SE. At this point the patch operation is complete. We were unable to perform a subsequent step, if there were more patch steps to do, or display the completion panel, but the patch state of the SE is not adversely affected by this error.

Problem determination: Call your next level of support.

E302E592 E302E592

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to recover the iqzminac process information from the XML file it was saved in. This occurs following a reboot of the SE. At this point the patch operation is complete. We were unable to perform a subsequent step, if there were more patch steps to do, or display the completion panel, but the patch state of the SE is not adversely affected by this error.

Problem determination: Call your next level of support.

E302E593 E302E593

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the main processing core of the Change Internal Code (SE) Completion Tasklet. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E302E594 E302E594

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the main processing core of the Change Internal Code (SE) Completion App. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E302E5A0 E302E5A0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ZseMcfKeywordListener class encountered an error when using BaseFileControl to determine a save file path while attempting to preserve message keywords.

Problem determination: Call your next level of support.

E302E5A1 E302E5A1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ZseMcfKeywordListener class encountered an error attempting to write the keyword message save file.

Problem determination: Call your next level of support.

E302E5A2 E302E5A2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ZseMcfKeywordListener class encountered an error when using BaseFileControl to determine a save file path while attempting to restore saved message keywords.

Problem determination: Call your next level of support.

E302E5A3 E302E5A3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ZseMcfKeywordListener class encountered an error attempting to read the keyword message save file.

Problem determination: Call your next level of support.

E302E5A4 E302E5A4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ZseMcfKeywordListener class encountered an error attempting to delete the keyword message save file after it was read.

Problem determination: Call your next level of support.

E302E5B0 E302E5B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ChangeMclToDisruptive class encountered an error when attempting to change the disruptive status of an MCL. The MCL processing was being performed at the time of the failure. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5B1 E302E5B1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ChangeMclToDisruptive class encountered an error when attempting to change the disruptive status of an MCL. The error occurred when attempting to determine the path to the data file. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5B2 E302E5B2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ChangeMclToDisruptive class encountered an error when attempting to change the disruptive status of an MCL. The error occurred when attempting to read the data file. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5B3 E302E5B3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ChangeMclToDisruptive class encountered an error when attempting to change the disruptive status of an MCL. The error occurred when attempting to delete the data file. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5B4 E302E5B4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ChangeMclToDisruptive class encountered an error when attempting to change the disruptive status of an MCL. The error occurred when attempting to close the data file. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5B8 E302E5B8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The PermanentDisabling class encountered an error when attempting write to the data file.

Problem determination: Call your next level of support.

E302E5B9 E302E5B9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The PermanentDisabling class encountered an error when attempting to close the data file.

Problem determination: Call your next level of support.

E302E5BA E302E5BA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The PermanentDisabling class is announcing that a HOZD situation has been encountered.

Problem determination: Call your next level of support.

E302E5C0 E302E5C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The performRecall method encountered an HException from the recall processing in UpdateUtilities. Single Step processing was being performed at the time of the failure. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5C1 E302E5C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The performRecall method encountered an unexpected Java exception from the recall processing in . Single Step processing was being performed at the time of the failure. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D0 E302E5D0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The loadDataFile method encountered an Exception from the UpdateUtilities.readFileToArrayList() method. FileSwapper initialization was being performed at the time of the failure. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D1 E302E5D1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The loadDataFile method encountered incorrectly formatted data when reading the existing data file. FileSwapper initialization was being performed at the time of the failure. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D2 E302E5D2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The saveDataFile method encountered an Exception from the UpdateUtilities.writeFileFromArrayList() method. The

error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D3 E302E5D3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The copyNow method encountered an Exception when copying a file during applyNow processing. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D4 E302E5D4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The eraseFile method was passed null arguments. This can not be handled. The calling code requires correction. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D5 E302E5D5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The addFile method was passed null arguments. This can not be handled. The calling code requires correction. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D6 E302E5D6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The exchangeFiles method detected that we were undo'ing a previous swap operation. Therefore, it should have removed a deferred file operation. It was unable to find the deferred file operation to remove. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D7 E302E5D7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The backup and eraseFile method detected

that we were undo'ing a previous erase operation. Therefore, it should have removed a deferred file operation. It was unable to find the deferred file operation to remove. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D8 E302E5D8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A patch operation attempted to patch a file that is in the persisted data tree. Persisted data is not allowed to be patched. Patching it will most likely cause any AROM generated subsequent to the patch being applied to be incorrect. Persisted data must be corrected directly via executable code. The error should cause the overall patch operation to fail.

Problem determination: Call your next level of support.

E302E5D9 E302E5D9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The saveDataFile method encountered an error when attempting to erase the deferred operation control file. Since the result is that the deferred operations are no longer correct, the patch session must be terminated with an error.

Problem determination: Call your next level of support.

(E302EFxx) Reference codes

E302EF01 E302EF01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Analyze Console Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Analyze Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302EF02 E302EF02

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Analyze Console Internal Code task action handler. The Analyze Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302EF03 E302EF03

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Analyze Console Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Analyze Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302EF04 E302EF04

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main "service" processing for server side of the Analyze Console Internal Code task. The Analyze Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302EF05 E302EF05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main panel handler (InternalCodeChangePanelHandler) "service" processing for server side of the Analyze Console Internal Code task. The Analyze Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302EF06 E302EF06

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for the base tower implementation of the subtasklet code that displays additional details about a selected internal code fix in the Analyze Console Internal Code server task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The subtasklet has been ended.

Problem determination: Call your next level of support.

E302EF07 E302EF07

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while accessing media to see if any MCFs are present on the media. This is the result of an exception being thrown by the media services support. Perhaps the media was removed during the operation. Perhaps an error occurred with the removable media device.

Problem determination: Call your next level of support.

E302EF08 E302EF08

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while releasing media after counting the MCFs on the media. This is the result of an exception being thrown by the media services support. Perhaps the media was removed during the operation. Perhaps an error occurred with the removable media device. The operation is allowed to continue.

Problem determination: Call your next level of support.

E302EF09 E302EF09

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

E302EF0A • E302EF11

Response: Error while examining the media for MCFs. Most likely, this is a result of the media being removed during the operation. Perhaps an error occurred with the removable media device.

Problem determination: Call your next level of support.

E302EF0A E302EF0A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error when preparing the media for MCF import. Most likely, this is a result of the media being removed after the MCFs were counted. Perhaps an error occurred with the removable media device. The application will return to the previous panel and allow the user to try again.

Problem determination: Call your next level of support.

E302EF0B E302EF0B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while releasing media after importing the MCFs on the media. This is the result of an exception being thrown by the media services support. Perhaps the media was removed during the operation. Perhaps an error occurred with the removable media device. The operation is allowed to continue.

Problem determination: Call your next level of support.

E302EF0C E302EF0C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while copying the MCF control file from the media to the staging area. This is an informational log. Processing for the MCF will stop, but any remaining MCFs will be processed.

Problem determination: Call your next level of support.

E302EF0D E302EF0D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while creating a new MCF instance. This would only happen if the MCF control file name is in error. Processing for the MCF will stop, but any remaining MCFs will be processed.

Problem determination: Call your next level of support.

E302EF0E E302EF0E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panel handler (AnalyzeConsoleIntCodePanelHandler) "service" processing for server side of the Analyze Console Internal Code task while trying to read FTP persisted data with the persistence manager. Either no FTP values have been persisted yet, or some unexpected error occurred with the persistence manager. This is an informational log. Processing continues without any prefilled values on the FTP panel.

Problem determination: Call your next level of support.

E302EF0F E302EF0F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panel handler (FtpPanelHandler) "service" processing for server side of the Analyze Console Internal Code task while trying to write FTP panel values using the persistence manager. This is an informational log. Processing continues without the FTP values being persisted.

Problem determination: Call your next level of support.

E302EF10 E302EF10

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while importing an unbundled MCF. The MCF already exists in the staging area of the system. The replacement of an MCF using import is not allowed. The MCF must be deleted before it can be imported again. This is an informational log. Processing for this MCF will stop, but any remaining MCFs will be processed.

Problem determination: Call your next level of support.

E302EF11 E302EF11

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main "service" processing for the base tower implementation of the subtasklet code that displays additional details about a selected internal code fix in the Analyze Console Internal Code server task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The subtasklet has been ended.

Problem determination: Call your next level of support.

E302EF20 E302EF20

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to write data to the IML Tracking Required file. During the write attempt to the Support Element hard drive, an IOException was caught and an HException was created and logged with the IOException embedded in it. This HException was then rethrown upward to the calling code.

Problem determination: Call your next level of support.

E302EF21 E302EF21

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to close the IML Tracking Required file. During the close attempt to the Support Element hard drive file, an IOException was caught and an HException was created and logged with the IOException embedded in it. This HException was then rethrown upward to the calling code.

Problem determination: Call your next level of support.

E302EF22 E302EF22

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to use the Disk File Controller to get the full path for the file that the "IML Tracking Required flags" for MCL/MCF processing are stored in. The DFC class threw an HException, so an error was logged with that exception embedded in it. The error was then rethrown upward to the calling code.

Problem determination: Call your next level of support.

E302EF23 E302EF23

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the add method of the ImlTrackingRequiredMgr Class. This method expects to find String objects representing the EC Stream, MCL number, and MCF number, and one of them was null. This error will be logged and rethrown.

Problem determination: Call your next level of support.

E302EF24 E302EF24

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the add method of the ImlTrackingRequiredMgr Class. This method expects to find String objects representing the EC Stream, MCL number, and MCF number, and one of them was a zero length string object. This error will be logged and rethrown.

Problem determination: Call your next level of support.

E302EF25 E302EF25

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the ImlTrackingRequiredMgr Class. During construction of an ImlTrackingEntry object, an unexpected condition occurred. Either an entry was null, or it did not contain all 4 of the expected subparts. It expects to find 4 String objects representing the operation (Apply or Remove), the EC Stream, the MCL number, and the MCF number. This error will be logged and rethrown.

Problem determination: Call your next level of support.

E302EF26 E302EF26

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the ImlTrackingRequiredMgr Class. During an attempt to read the entries that were in i390 memory for MCLs/MCFs that required tracking (because they are not yet truly Applied/Removed until the next IML), some kind of failure occurred trying to execute the Native C code in iqzmZseBridge (entry point xmcmReadI390ImlTracking). This error will be logged and rethrown.

Problem determination: Call your next level of support.

E302EF27 E302EF27

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the ImlTrackingRequiredMgr Class. A Native Bridge exception was caught trying to execute the Native C code in iqzmZseBridge (entry point xmcmReadI390ImlTracking). This error will be logged and rethrown.

Problem determination: Call your next level of support.

E302EF28 E302EF28

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the ImlTrackingRequiredMgr Class. An IOException was caught trying to execute the Native C code in iqzmZseBridge (entry point xmcmReadI390ImlTracking). This error will be logged and rethrown.

Problem determination: Call your next level of support.

E302EF29 E302EF29

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the ImlTrackingRequiredMgr Class. During an attempt to write the entries to i390 memory for MCLs/MCFs that require tracking (because they are not yet truly Applied/Removed until the next IML), a NativeBridgeException failure occurred. This error will be logged and rethrown. It originally came from the Native Bridge side in C code iqzmZseBridge.c, xmcmWriteI390ImlTracking.

Problem determination: Call your next level of support.

E302EF2A E302EF2A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the ImlTrackingRequiredMgr Class. During an attempt to write the entries to i390 memory for MCLs/MCFs that require tracking (because they are not yet truly Applied/Removed until the next IML), an IOException failure occurred. This error will be logged and rethrown. It originally came from the Native Bridge side in C code iqzmZseBridge.c, xmcmWriteI390ImlTracking.

Problem determination: Call your next level of support.

E302EF2B E302EF2B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside the ImlTrackingRequiredMgr Class. During an attempt to write the entries to i390 memory (and/or to the SE hard disk) for MCLs/MCFs that require tracking (because they are not yet truly Applied/Removed until the next IML), some kind of write failure occurred. This error will be logged and rethrown.

Problem determination: Call your next level of support.

E302EF30 E302EF30

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The value of the auto-accept data provided in an MCF is not valid. The data should be of the form "J99677.103", where the J99677 is the EC stream name of the MCL to accept and the 103 is the MCL level to accept in that EC stream. This occurrence means the MCF inside the MCL is bad and must be rebuilt. An exception will be thrown that will cause MCL processing to fail.

Problem determination: Call your next level of support.

E302EF31 E302EF31

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The value of the auto-accept data provided in an MCF specified an EC stream that is not present on the system. This is not allowed. Most likely the value of the auto-accept field in the MCF is wrong. An exception will be thrown that will cause MCL processing to fail.

Problem determination: Call your next level of support.

E302EF40 E302EF40

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected error occurred while attempting to read the data file that records the Accepted MCF data. The process is not killed and no data is displayed. A message may indicate there is no data available to the user.

Problem determination: Call your next level of support.

E302EF50 E302EF50

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to write data to the IML Log Manager file or trying to close the log file. During the write attempt to the Support Element hard drive or the close attempt, an IOException was caught. This is an informational log. Processing continues.

Problem determination: Call your next level of support.

E302EF51 E302EF51

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to add a new record to the IML log file when the path to the log file is not set. The file path should have been obtained in the constructor, and a failure at that point should have resulted in an error log. This is an informational log. Processing continues.

Problem determination: Call your next level of support.

E302EF52 E302EF52

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to read a record from the IML log file when the path to the log file is not set. The file path should have been obtained in the constructor, and a failure at that point should have resulted in an error log. This is an informational log. Processing continues. It will appear to the caller as if the log file is empty.

Problem determination: Call your next level of support.

E302EF53 E302EF53

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to use the Disk File Controller to get the full path for the file that the "IML Log Manager" entries for IML Tracking Required MCLs and completed IMLs are stored in. The DFC class threw an HException, so an error was logged with that exception embedded in it. The error was then rethrown upward to the calling code.

Problem determination: Call your next level of support.

E302EF54 E302EF54

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error instantiating a SimpleDateFormat object. This is an informational log. Processing continues.

Problem determination: Call your next level of support.

E302EF55 E302EF55

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error instantiating a SimpleDateFormat

object for formatting a date. This is an informational log. Processing continues.

Problem determination: Call your next level of support.

E302EF56 E302EF56

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error instantiating a SimpleDateFormat object for formatting time. This is an informational log. Processing continues.

Problem determination: Call your next level of support.

E302EF57 E302EF57

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading the log file. An IOException was caught. An HException is created for the error and thrown. Further reading of the log file stops.

Problem determination: Call your next level of support.

E302EF58 E302EF58

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ImlLogEntry inner class constructor receives a line of data representing a row from the IML log file. The specified data does not match expected formatting rules and therefore cannot be parsed. An HException is thrown, and processing stops.

Problem determination: Call your next level of support.

E302EF60 E302EF60

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain the RPM inventory in order to update the patched file lists. Traces should indicate the precise nature of the error. This error is fatal and will cause the MCF/MCL processing that is attempting to install the RPM to fail.

Problem determination: Call your next level of support.

E302EF61 E302EF61

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted to install an RPM on a stream where we do not support RPM MCF processing

E302EF62 • E302EF72

(initially, only the OS stream is allowed to have RPMs in an MCF). This error is fatal and will cause the MCF/MCL processing that is attempting to install the RPM to fail.

Problem determination: Call your next level of support.

E302EF62 E302EF62

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to update the patched files lists. Traces should indicate the precise nature of the error. This error is fatal and will cause the MCF/MCL processing that is attempting to install the RPM to fail.

Problem determination: Call your next level of support.

E302EF63 E302EF63

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to install the RPM. Traces should indicate the precise nature of the error. This error is fatal and will cause the MCF/MCL processing that is attempting to install the RPM to fail.

Problem determination: Call your next level of support.

E302EF70 E302EF70

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected error occurred in the BlockAutoInstallBean. The task will be terminated. The traces associated with the log entry should provide insight into the precise nature of the error.

Problem determination: Call your next level of support.

E302EF71 E302EF71

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Block Automatic Microcode Installation task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Block Automatic Microcode Installation task will be terminated.

Problem determination: Call your next level of support.

E302EF72 E302EF72

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Block Automatic Microcode Installation task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Block Automatic Microcode Installation task will be terminated.

Problem determination: Call your next level of support.

(E302Exxx) Reference codes

E302EXXX E302EXXX

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E302F0xx) Reference codes

E302F000 E302F000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to find the directory for ECC or ECD files

Problem determination: Call your next level of support.

E302F001 E302F001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to build the MCF staging area.

Problem determination: Call your next level of support.

E302F002 E302F002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to build the temporary MCF staging area.

Problem determination: Call your next level of support.

E302F003 E302F003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to build the MCL distribution staging area.

Problem determination: Call your next level of support.

E302F010 E302F010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We have a list of MCLs that we want to automatically accept, but we took an error while we were reading the file.

Problem determination: Call your next level of support.

E302F011 E302F011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We have a list of MCLs that we want to automatically accept, but we took an error while we were closing the file.

Problem determination: Call your next level of support.

E302F012 E302F012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We could not find the path where we store the list of files that are to be automatically accepted.

Problem determination: Call your next level of support.

E302F013 E302F013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We have a list of MCLs that we want to automatically accept, but we took an error while we were processing the accept.

Problem determination: Call your next level of support.

E302F014 E302F014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to run the startup processing for MCLs in the base tower.

Problem determination: Call your next level of support.

E302F020 E302F020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An I/O error occurred while attempting to import updatable components.

Problem determination: Call your next level of support.

E302F021 E302F021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A general exception error occurred while attempting to import updatable components.

E302F022 • E302F073

Problem determination: Call your next level of support.

E302F022 E302F022

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to FTP files from the HMC.

Problem determination: Call your next level of support.

E302F040 E302F040

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to access the MCF staging area

Problem determination: Call your next level of support.

E302F041 E302F041

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to read the ECC file or ECD file representing an EC stream

Problem determination: Call your next level of support.

E302F042 E302F042

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to close the ECC file or ECD file representing an EC stream

Problem determination: Call your next level of support.

E302F043 E302F043

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to read the history of accepted MCFs in this EC stream

Problem determination: Call your next level of support.

E302F044 E302F044

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to close the history of accepted MCFs in this EC stream

Problem determination: Call your next level of support.

E302F045 E302F045

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to instantiate an MCL in this EC stream

Problem determination: Call your next level of support.

E302F070 E302F070

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to establish an FCS connection to the query service on the other HMC.

Problem determination: Call your next level of support.

E302F071 E302F071

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got data from a QueryService but the data is not a class type that we support..

Problem determination: Call your next level of support.

E302F072 E302F072

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got a list of data from a QueryService, but the data within the list is not a class type that we support..

Problem determination: Call your next level of support.

E302F073 E302F073

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got an unexpected error while importing fixes from RETAIN and distributing them to other HMCs.

Problem determination: Call your next level of support.

E302F074 E302F074

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got an unexpected error while importing fixes from media and distributing them to other HMCs.

Problem determination: Call your next level of support.

E302F075 E302F075

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got an unexpected error while querying the applied fix levels on other HMCs or while pulling them from RETAIN to the staging area on this HMC.

Problem determination: Call your next level of support.

E302F076 E302F076

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got an unexpected error while querying the applied fix levels on other HMCs or while pulling them from media to the staging area on this HMC.

Problem determination: Call your next level of support.

E302F077 E302F077

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We failed while attempting to query the EC levels on an OS/2 HMC. The HMC which we could not query will not be considered when we go to RETAIN or to media to request the available MCLs.

Problem determination: Call your next level of support.

E302F078 E302F078

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got an unexpected error while attempting to distribute MCLs to an OS/2 HMC.

Problem determination: Call your next level of support.

E302F079 E302F079

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got an unexpected error while importing fixes from FTP and distributing them to other HMCs.

Problem determination: Call your next level of support.

E302F07A E302F07A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We got an unexpected error while querying the applied fix levels on other HMCs or while pulling them from FTP to the staging area on this HMC.

Problem determination: Call your next level of support.

E302F080 E302F080

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to delete an MCL.

Problem determination: Call your next level of support.

E302F081 E302F081

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to accept an MCL.

Problem determination: Call your next level of support.

E302F082 E302F082

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to install and activate an MCL.

Problem determination: Call your next level of support.

E302F083 E302F083

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to remove and activate an MCL.

E302F084 • E302F08F

Problem determination: Call your next level of support.

E302F084 E302F084

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to read the cover letter of an MCL.

Problem determination: Call your next level of support.

E302F085 E302F085

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to close the cover letter of an MCL.

Problem determination: Call your next level of support.

E302F086 E302F086

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A cover letter seems to have a dependency, but is missing a semicolon.

Problem determination: Call your next level of support.

E302F087 E302F087

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to delete the data file for the MCL while the MCL was being retrieved or initialized after reboot.

Problem determination: Call your next level of support.

E302F088 E302F088

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to unzip the data file for the MCL.

Problem determination: Call your next level of support.

E302F089 E302F089

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to create an MCF within an MCL.

Problem determination: Call your next level of support.

E302F08A E302F08A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to read the unit list of an MCL.

Problem determination: Call your next level of support.

E302F08B E302F08B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An I/O error occurred while attempting to unzip the data file for the MCL.

Problem determination: Call your next level of support.

E302F08C E302F08C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An I/O error occurred while attempting to write the latest levels to the EC file.

Problem determination: Call your next level of support.

E302F08D E302F08D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An I/O error occurred while attempting to close the EC file after writing the latest levels to it.

Problem determination: Call your next level of support.

E302F08E E302F08E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to create the distribution staging area for internal code changes.

Problem determination: Call your next level of support.

E302F08F E302F08F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A dependency was specified for an EC stream that does not exist on the system. The

dependency is illegal and the MCL is not valid.

Problem determination: Call your next level of support.

E302F090 E302F090

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: None of the dependencies supplied in a set of or-dependencies specified an EC stream that does exist on the system. The or-dependency is not valid. Thus, the MCL is not valid.

Problem determination: Call your next level of support.

E302F091 E302F091

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to re-write the MCL control file

Problem determination: Call your next level of support.

E302F092 E302F092

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The dependency information in the XML for the MCL is invalid.

Problem determination: Call your next level of support.

E302F093 E302F093

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The MCL cannot be instantiated because the control file (the .xml file) is missing from the /console/mcf subdirectory.

Problem determination: Call your next level of support.

E302F094 E302F094

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This refcode is entered when we appear to go into a recursion loop while processing through the dependency information, trying to determine if an MCL is disruptive.

Problem determination: Call your next level of support.

E302F095 E302F095

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to rename the data file (.zip file) for the MCL while the MCL was being retrieved or initialized after reboot. The rename operation was attempted to preserve the .zip file to provide diagnostic information for an earlier problem that issued refcode 0xF088

Problem determination: Call your next level of support.

E302F096 E302F096

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The MCL that was to be created already exists on the system. This can occur because of retrieve request overlaps. The error is reported, the MCL is ignored, and an info log is taken. Processing is allowed to continue.

Problem determination: Call your next level of support.

E302F097 E302F097

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The MCL that was being unpacked during retrieve processing had incorrect content. It may have contained an MCL control file for a different MCL. It may have contained 0 or more than one MCL control Files. In any case, this error is fatal to the unpacking process and an exception is thrown by the unpacking process.

Problem determination: Call your next level of support.

E302F098 E302F098

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The MCL that was being unpacked during retrieve processing contained MCFs that are already on the system. We can not allow the MCF control files that already exist to be overwritten. This MCL can not be installed until the situation is corrected. This MCL may be bad, or previously installed MCLs may have been altered to remove an MCF. In any case, this error is fatal to the unpacking process and an exception is thrown by the unpacking process.

Problem determination: Call your next level of support.

E302F099 E302F099

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The MCL that was being initially parsed during retrieve processing contained content that resulted in a parsing error. This usually indicates an improperly constructed MCL or MCF. In any case, this error is fatal to the retrieve process and an exception is thrown by the process attempting to parse the MCF contents. We will attempt to erase all files associated with this MCL.

Problem determination: Call your next level of support.

E302F0C0 E302F0C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to get the EC streams in an attempt to list all of the available MCLs on a media that can be retrieved.

Problem determination: Call your next level of support.

E302F0C1 E302F0C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to get the EC streams in an attempt to retrieve all of the available MCLs from removable media, FTP or from RETAIN.

Problem determination: Call your next level of support.

E302F0C2 E302F0C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to get the EC streams in an attempt to retrieve all of the available MCLs from retain.

Problem determination: Call your next level of support.

E302F0C3 E302F0C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to copy the files from the removable media while performing a retrieve.

Problem determination: Call your next level of support.

E302F0C4 E302F0C4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to build an MCL while performing a retrieve from removable media..

Problem determination: Call your next level of support.

E302F0C5 E302F0C5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to copy the files from the staging area while performing a retrieve from retain.

Problem determination: Call your next level of support.

E302F0C6 E302F0C6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to build an MCL while performing a retrieve from retain..

Problem determination: Call your next level of support.

E302F0C7 E302F0C7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to copy the files from the staging area to removable media while performing a retrieve from retain.

Problem determination: Call your next level of support.

E302F0C8 E302F0C8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were attempting to retrieve an MCL, but the id of the MCL we retrieved did not correspond to the next level that we could retrieve..

Problem determination: Call your next level of support.

E302F0C9 E302F0C9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were to remove an MCL, but the ID of

the MCL did not correspond to the next one to delete or the next one to accept.

Problem determination: Call your next level of support.

E302F0CA E302F0CA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While deleting an MCL, we went to remove the MCL from the list of update collections, but we couldn't find it in the list.

Problem determination: Call your next level of support.

E302F0CB E302F0CB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While accepting an MCL, we went to accept the MCL from the list of update collections, but we couldn't find it in the list.

Problem determination: Call your next level of support.

E302F0CC E302F0CC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While deleting an MCF within an MCL, we took a failure. We will continue with the delete of the MCL anyway.

Problem determination: Call your next level of support.

E302F0CD E302F0CD

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: While accepting an MCF within an MCL, we took a failure. We will continue with the delete of the MCL anyway.

Problem determination: Call your next level of support.

E302F0CE E302F0CE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to retrieve MCLs from retain. The retain code did not complete within the time allowed.

Problem determination: Call your next level of support.

E302F0CF E302F0CF

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to submit a request to retrieve MCLs from retain.

Problem determination: Call your next level of support.

E302F0D0 E302F0D0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to read the file which contains the list of on hold MCLs in retain.

Problem determination: Call your next level of support.

E302F0D1 E302F0D1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to close the list of on hold MCLs in retain.

Problem determination: Call your next level of support.

E302F0D2 E302F0D2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process the file which contains the list of on hold MCLs in retain.

Problem determination: Call your next level of support.

E302F0D3 E302F0D3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to parse a new style MCL.

Problem determination: Call your next level of support.

E302F0D4 E302F0D4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to process a node of a new style MCL.

E302F0D5 • E302F0DF

Problem determination: Call your next level of support.

E302F0D5 E302F0D5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to submit a request to retrieve MCLs from RETAIN. There were no phone servers available to handle the request.

Problem determination: Call your next level of support.

E302F0D6 E302F0D6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to submit a request to retrieve MCLs from RETAIN. RSF was disabled at the time the request was made.

Problem determination: Call your next level of support.

E302F0D7 E302F0D7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to retrieve specified MCLs from media. Some or all of the specified MCLs were not present on the media.

Problem determination: Call your next level of support.

E302F0D8 E302F0D8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred trying to read the file created by the FTP.dir.

Problem determination: Call your next level of support.

E302F0D9 E302F0D9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred trying to close the file created by the FTP.dir.

Problem determination: Call your next level of support.

E302F0DA E302F0DA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred trying to execute an FTP dir to get the list of files on a remote system.

Problem determination: Call your next level of support.

E302F0DB E302F0DB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The check for Licensed Internal Code updates at an FTP site failed when we were unable to connect to the FTP site.

Problem determination: Call your next level of support.

E302F0DC E302F0DC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The check for Licensed Internal Code updates at an FTP site failed when we were unable to login to the FTP site.

Problem determination: Call your next level of support.

E302F0DD E302F0DD

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred trying to execute an FTP get to get a file from a remote system.

Problem determination: Call your next level of support.

E302F0DE E302F0DE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The check for Licensed Internal Code updates at an FTP site failed when we were unable to change directory to the user's directory.

Problem determination: Call your next level of support.

E302F0DF E302F0DF

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We successfully contacted the specified FTP site but were unable to find any new Licensed Internal Code updates at that site.

Problem determination: Call your next level of support.

E302F0E0 E302F0E0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to write the results of a query of updatable components back to the requester of the query.

Problem determination: Call your next level of support.

E302F0F0 E302F0F0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We attempted to query the files in retain, but the query failed. We will continue on attempting a retrieve form retain.

Problem determination: Call your next level of support.

E302F0F1 E302F0F1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to query the MCLs in retain. The retain code did not complete within the time allowed.

Problem determination: Call your next level of support.

E302F0F2 E302F0F2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to submit a request to query the size and number of files to be retrieved from retain.

Problem determination: Call your next level of support.

E302F0F4 E302F0F4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were unable to remove the previous version of the on-hold data file. This unlikely condition may make impossible to retrieve MCLs in any stream that is described in the on-hold data file.

Problem determination: Call your next level of support.

E302F0F5 E302F0F5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We successfully contacted the specified FTP site but were unable to find any MCFs at that site.

Problem determination: Call your next level of support.

E302F0F6 E302F0F6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were not able to start the retain request within a reasonable amount of time. Check the queue of the phone server to see if it is on hold or if a large number of requests are scheduled to be executed at the same time.

Problem determination: Call your next level of support.

(E302F1xx) Reference codes

E302F100 E302F100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Retrieve Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Retrieve Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F101 E302F101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Retrieve Internal Code task action handler. The Retrieve Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F102 E302F102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Retrieve Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Retrieve Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F103 E302F103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main "service" processing for server side of the Retrieve Console Internal Code task. The Retrieve Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F104 E302F104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the processing performed in RetrieveInternalTargetFilter prior to the start of the

Retrieve Internal task. The user is allowed at this point to choose to retrieve just to the initially selected managed objects or to all managed objects of the same type. The Retrieve Internal Code task still starts and receives targets of just the initially selected objects.

Problem determination: Call your next level of support.

E302F105 E302F105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panel handler (RetrieveInternalCodeChgsPanelHandler) "service" processing for server side of the Retrieve Internal Code task while trying to read FTP persisted data with the persistence manager. Either no FTP values have been persisted yet, or some unexpected error occurred with the persistence manager. This is an informational log. Processing continues without any prefilled values on the FTP panel.

Problem determination: Call your next level of support.

E302F106 E302F106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panel handler (FtpPanelHandler) "service" processing for server side of the Retrieve Internal Code task while trying to write FTP panel values using the persistence manager. This is an informational log. Processing continues without the FTP values being persisted.

Problem determination: Call your next level of support.

(E302F2xx) Reference codes

E302F200 E302F200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Change Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Change Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F201 E302F201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Change Internal Code task action handler. The Change Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F202 E302F202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Change Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Change Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F203 E302F203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main "service" processing for server side of the Change Internal Code task. The Change Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F204 E302F204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main panel handler (ChangeInternalCodePanelHandler) "service" processing

for server side of the Change Internal Code task. The Change Internal Code task has been ended.

Problem determination: Call your next level of support.

E302F205 E302F205

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to process MCL alerts with the Change Internal Code task. You cannot proceed with the install and activate or the remove and activate.

Problem determination: Call your next level of support.

(E302F7xx) Reference codes

E302F700 E302F700

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An install and activate of a specific set of MCLs was requested, but an ACTREQ prevents all of the MCLs from being applied in the same pass.

Problem determination: Call your next level of support.

E302F701 E302F701

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A remove and activate of a specific set of internal code changes was requested, but an ACTREQ prevents all of the internal code changes from being applied in the same pass.

Problem determination: Call your next level of support.

E302F702 E302F702

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to create the distribution staging area for internal code changes

Problem determination: Call your next level of support.

E302F703 E302F703

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A commit of internal code changes was requested, but the set of internal code changes requested to be committed depend on other internal code changes which aren't requested to be committed.

Problem determination: Call your next level of support.

E302F704 E302F704

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An apply of internal code changes was requested, but the set of internal code changes requested to be applied depend on other internal code changes which aren't requested to be applied.

Problem determination: Call your next level of support.

E302F705 E302F705

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A reject of internal code changes was requested, but the set of internal code changes requested to be rejected depend on other internal code changes which aren't requested to be rejected.

Problem determination: Call your next level of support.

E302F706 E302F706

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A retrieve to removable media of internal code changes was requested, but the function code got an empty list of update ranges to retrieve.

Problem determination: Call your next level of support.

E302F707 E302F707

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A retrieve to removable media of internal code changes was requested, but the function code got a null list of update ranges to retrieve.

Problem determination: Call your next level of support.

E302F708 E302F708

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A retrieve to removable media of internal code changes was requested, but one of the updaters performing the retrieve did not return within the maximum wait time

Problem determination: Call your next level of support.

E302F709 E302F709

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

E302F70A • E302F713

Response: A retrieve to removable media of internal code changes has failed.

Problem determination: Call your next level of support.

E302F70A E302F70A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A shutdown was issued, but there was no deferred shutdown request.

Problem determination: Call your next level of support.

E302F70B E302F70B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A retrieve of internal code changes was requested, but one of the updaters performing the retrieve did not return within the maximum wait time

Problem determination: Call your next level of support.

E302F70C E302F70C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A retrieve of internal code changes has failed.

Problem determination: Call your next level of support.

E302F70D E302F70D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A single-step operation has failed. This may not indicate an error and results in an informational log being taken.

Problem determination: Call your next level of support.

E302F70E E302F70E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An apply of internal code changes was requested, but some unexpected code error occurred while converting the list from a list of changes to a list of concurrent changes. The operation is terminated.

Problem determination: Call your next level of support.

E302F70F E302F70F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A concurrent apply of internal code changes was requested, but the set of internal code changes requested to be applied contained one or more disruptive internal code changes. See the trace for an indication of which changes were disruptive. The operation was terminated.

Problem determination: Call your next level of support.

E302F710 E302F710

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A concurrent reject of internal code changes was requested, but the set of internal code changes requested to be rejected contained one or more disruptive internal code changes. See the trace for an indication of which changes were disruptive. The operation was terminated.

Problem determination: Call your next level of support.

E302F711 E302F711

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing the requested file after the file was read. The operation is allowed to continue.

Problem determination: Call your next level of support.

E302F712 E302F712

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling the javaConfigureCpuAlerts program in iqzmCpuAlertBridge. The call was being attempted via Native Bridge. We were attempting to either disable CPU alerts at the beginning of the file swapping phase of internal code changes or enable CPU alerts at the end of the file swapping phase of internal code changes.

Problem determination: Call your next level of support.

E302F713 E302F713

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error closing the native bridge connection after calling the javaConfigureCpuAlerts program in iqzmCpuAlertBridge.

Problem determination: Call your next level of support.

E302F780 E302F780

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to find the directory for the MCL alerts file.

Problem determination: Call your next level of support.

E302F781 E302F781

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The data in an ec_range block in the MCL alert file is incorrect. This ec_range block wither has an invalid ec tag, max_mcl tag or min_mcl tag. Please check that the tags are correct in the MCL alert file.

Problem determination: Call your next level of support.

E302F782 E302F782

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The value of the when_to_alert tag in the MCL alert file is incorrect. The value should be "install", "remove" or "both".

Problem determination: Call your next level of support.

E302F783 E302F783

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were not able to get the path of the history file for MCL alerts

Problem determination: Call your next level of support.

E302F784 E302F784

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were not able to write to the history file for MCL alerts

Problem determination: Call your next level of support.

E302F785 E302F785

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We were not able to close the history file for MCL alerts

Problem determination: Call your next level of support.

E302F786 E302F786

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We failed while attempting to display the MCL alert on the GUI.

Problem determination: Call your next level of support.

E302F787 E302F787

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to parse the MCL alerts file.

Problem determination: Call your next level of support.

E302F788 E302F788

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to pull in the MCL alerts file.

Problem determination: Call your next level of support.

E302F789 E302F789

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to install any available MCL alerts. The problem could be related to the attempted install or to the attempt to determine IF the MCLs should be installed.

Problem determination: Call your next level of support.

(E302F8xx) Reference codes

E302F800 E302F800

Explanation: An error occurred while attempting to create a provider instance of the service processor interface code as a PIHSCCECCIMClient. An exception was thrown from the PIHSCCECCIMClient createInstance code.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F801 E302F801

Explanation: An error occurred while attempting to find one of the directories used to store data for the firmware update application.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F802 E302F802

Explanation: The survey from the repository method was called, but the repository selected was not the IBM support system, the IBM Web site, the DVD, or the hard drive.

Problem determination: Use the HMC graphical user interface (GUI) to reselect the source for code updates, then retry the update. If the problem occurs again, contact your next level of support.

E302F803 E302F803

Explanation: The survey from an FTP site failed when downloading the list of files from the FTP repository failed.

Problem determination: Verify that you correctly entered valid values for the FTP site, user, password, and directory. Then repeat the operation.

E302F804 E302F804

Explanation: The request to get a list of code updates failed because the request timed out.

Problem determination: Verify that the HMC is properly configured to communicate with the support system. Verify that the support system has accepted the administrative information for your HMC, then repeat the operation.

Verify that you correctly entered valid values for the

FTP site, user, password, and directory. Then repeat the operation.

E302F805 E302F805

Explanation: The request to get a list of code updates failed with an exception.

Problem determination: Repeat the operation. If it fails, call your next level of support.

E302F806 E302F806

Explanation: The request to get a list code updates failed with an error code.

Problem determination: Repeat the operation. If it fails, call your next level of support.

E302F807 E302F807

Explanation: No phone server was available to service the request to get a list of code updates.

Problem determination: Ensure that your connection to the IBM support system is set up correctly and repeat the operation.

E302F808 E302F808

Explanation: The list of code updates was retrieved from the support system, but an I/O exception occurred when the list was written to the hard file.

Problem determination: Reboot the HMC and retry the operation. If it fails again, consider replacing the disk drive in the HMC.

E302F809 E302F809

Explanation: An error occurred while attempting to run the code to get the service processor to run a query, or set, the current IPL side or the next IPL side.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F80A E302F80A

Explanation: An invalid object was used while attempting to create an owner for the update.

Problem determination: Something is wrong with the selected target. Reboot the HMC and retry the operation. If the problem persists contact your next level of support.

E302F80B E302F80B

Explanation: Unable to get the name of the HMC while preparing to create a service processor client.

Problem determination: Reboot the HMC and retry the operation. If it fails again, contact your next level of support.

E302F80C E302F80C

Explanation: Failure when attempting to read a file.

Problem determination: Reboot the HMC and retry the operation. If it fails again, consider replacing the disk drive of the HMC.

E302F80D E302F80D

Explanation: Failure when attempting to close a file.

Problem determination: Reboot the HMC and retry the operation. If it fails again, consider replacing the disk drive of the HMC.

E302F80E E302F80E

Explanation: The list of code updates was retrieved from the support system, but an I/O exception occurred when closing the list that was written to the hard file.

Problem determination: Reboot the HMC and retry the operation. If it fails again, consider replacing the disk drive of the HMC.

E302F80F E302F80F

Explanation: The method to import the stageable cover letter was called, but the repository selected was not the support system, the DVD, or the hard drive.

Problem determination: Use the HMC GUI to reselect the source for code updates, and then retry the update. If the problem occurs again, contact your next level of support.

E302F810 E302F810

Explanation: Unable to FTP the cover letter from the specified repository to the staging area.

Problem determination: Verify that the FTP site is still up, and then retry the operation.

E302F811 E302F811

Explanation: The request to get the cover letter from the support system timed out.

Problem determination: Verify that your connection to the IBM support system is set up correctly and is operational. Retry the operation. If the problem occurs again, contact your next level of support.

E302F812 E302F812

Explanation: The request to get information from support failed with an exception.

Problem determination: Verify that your connection to the IBM support system is set up correctly and is operational. Retry the operation. If the problem occurs again, contact your next level of support.

E302F813 E302F813

Explanation: The request to get the cover letter from the support system failed with an error code.

Problem determination: Verify that your connection to the IBM support system is set up correctly and is operational. Retry the operation. If the problem occurs again, contact your next level of support.

E302F814 E302F814

Explanation: No phone server was available to service the request to get cover letters from the support system.

Problem determination: Configure the HMC as a phone server and retry the operation.

E302F815 E302F815

Explanation: Failure when attempting to copy the information from the DVD to the staging area on the hard file.

Problem determination: The CD or DVD may be faulty. Try another one.

E302F816 E302F816

Explanation: An error occurred when attempting to get the service processor to run a query of its state.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F817 E302F817

Explanation: A query of the current IPL side returned a null.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F818 E302F818

Explanation: A query of the next IPL side returned a null.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F819 E302F819

Explanation: A query of the current IPL side failed.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F81A E302F81A

Explanation: An exception occurred during a query of the current IPL side.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F81B E302F81B

Explanation: A query of the next IPL side failed.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F81C E302F81C

Explanation: An exception occurred during a query of the next IPL side.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation.

E302F81D E302F81D

Explanation: Failure during an attempt to copy the cover letter information from the support Web site to the staging area on the hard file.

Problem determination: Reboot the HMC. Verify that your LAN connection is set up properly. Then retry the operation.

E302F81E E302F81E

Explanation: Failure of a survey from an FTP site occurred when a connection to the site was unavailable.

Problem determination: Ensure that the FTP site is reachable on the network from the HMC and that the site is up and running properly. Ensure that all firewall authentications are successfully performed if needed, and then retry the operation.

E302F81F E302F81F

Explanation: Failure of a survey from an FTP site occurred when logging into the site was unsuccessful.

Problem determination: Ensure that the login parameters are correct, and then retry the operation.

E302F820 E302F820

Explanation: An error occurred while attempting to read the common marker firmware update file from flash memory to the hard file.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). Then repeat the operation. If the problem occurs again contact your next level of support.

E302F821 E302F821

Explanation: An error occurred while attempting to read the common marker firmware update file from the hard file into memory.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again contact your next level of support.

E302F822 E302F822

Explanation: An error occurred while attempting to find one of the directories used to store data for the firmware update application.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F823 E302F823

Explanation: HMC Version checks were skipped due to the presence of the override file.

Problem determination: Informational message.

E302F824 E302F824

Explanation: Firmware Version checks were skipped due to the presence of the override file.

Problem determination: Informational message.

E302F825 E302F825

Explanation: The LID file does not contain the correct identifier in the FIPS header.

Problem determination: Contact your next level of support.

E302F826 E302F826

Explanation: The LID file contains an unknown version in the FIPS header.

Problem determination: Contact your next level of support.

E302F827 E302F827

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F828 E302F828

Explanation: An error occurred while attempting to read the master firmware update file from flash memory to the hard drive.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F829 E302F829

Explanation: An error occurred while attempting to read the master firmware update file from the hard drive into memory.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F82A E302F82A

Explanation: An error occurred while attempting to read the header of the master firmware update file from flash memory to the hard file.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F82B E302F82B

Explanation: An error occurred while attempting to find one of the directories used to store data for the firmware update application.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F82C E302F82C

Explanation: An error occurred while attempting to create a provider instance of the secondary service processor interface code as a PIHSCCECCIMClient. An exception was thrown from the PIHSCCECCIMClient createInstance code.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure that the system is in a good state (power off, standby, or power on). Then repeat the operation.

E302F82D E302F82D

Explanation: An error occurred while attempting to read the header of the common marker firmware update file from flash memory to the hard drive.

Problem determination: This error code will be posted under either of the following set of conditions:

- After a service processor failover, the HMC attempted to read the P1 marker LID from the new primary service processor. If the P1 marker LID on the previously-primary service processor had not been synchronized with the P1 marker LID on the now-primary service processor before the failover, this error code will be posted. It indicates that the P1 marker LID file was not found on the now-primary service processor.

This error is not critical; it only effect the HMC's ability to determine whether or not deferred firmware updates have been applied.

- The files needed to create the P1 marker LID are not available because the HMC is in the process of writing one of them to the service processor. This can happen when a P-side restore runs because a "Do not accept" choice was selected on the advanced features panels. Currently, the HMC will issue an "Islic" command during problem analysis by Inventory Scout scripts. If the P-side common marker LID file is being written to at the time that Inventory Scout script issues the "Islic" command, the E302F82D will be posted.

Action: Install the latest HMC code package, then install the latest system firmware.

E302F82E E302F82E

Explanation: The requested operation cannot be performed because a Licensed Internal Code update operation is currently running on one or more components.

Problem determination: Wait for all running LIC update operations to complete on all sessions on both HMCs. Repeat the operation after they are finished. If there is no LIC update/upgrade running in any session on either HMC, contact your next level of support.

E302F82F E302F82F

Explanation: An exception occurred while trying to determine code update status.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F830 E302F830

Explanation: An error occurred while attempting to read a flash firmware update file from the hard file into memory.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, consider replacing the disk drive of the HMC.

E302F831 E302F831

Explanation: A file that was supposed to be a firmware update file either does not exist or is too small to contain a valid header.

Problem determination: If you are using nondisruptive microcode, verify that your test firmware update files are correct. Otherwise contact your next level of support.

E302F832 E302F832

Explanation: An error occurred while trying to create a private staging area directory for firmware update files on the HMC disk drive.

Problem determination: Follow the HMC procedures to remove dump files from the HMC disk drive. (The HMC disk drive is used for the private staging area and it may be full.) Then reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F833 E302F833

Explanation: An error occurred while trying to change file permissions in the private staging area directory for firmware update files.

Problem determination: This error might indicate that the files in the private staging area were not created, especially if this error occurs with E302F832. Follow the procedures for E302F832.

E302F834 E302F834

Explanation: An error occurred while enabling failover during a cleanup operation. The code update was otherwise successful.

Problem determination: Check the status of the service processor failover state and readiness. If the failover is disabled and there are no readiness error conditions, take the steps necessary to enable failover. If there is a failover readiness error condition, contact your next level of support.

E302F835 E302F835

Explanation: An error occurred while trying to release the BPC Frame locks during a cleanup operation. The code update was otherwise successful.

Problem determination: Do the following as applicable:

1. Allow all currently running code update processes to end successfully on all of the associated HMCs.
2. Ensure that all frame numbering, frame initialization, and repair and verify processes that also use BPA locking end successfully on all of the associated HMCs.
3. After all the operations are finished and a retargeting to one of the managed systems still results in this error, remove the BPA lock. To remove the BPA lock, use the following command from the HMC: `rmlock -e Frame*MTMS` where *Frame*MTMS* is the machine-type, model, and serial number of the affected BPA.
4. Retry the operation. If the error occurs again, contact your next level of support.

E302F836 E302F836

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F837 E302F837

Explanation: An error occurred while stopping the Refresh Power Lock thread during cleanup operations. The code update was otherwise successful.

E302F838 • E302F845

Problem determination: Reboot the HMC to terminate the Refresh Power Lock thread. If this error occurs during other code update operations on this HMC, then contact your next level of support.

E302F838 E302F838

Explanation: An error occurred while attempting to read the information about the code update out of the cover letter.

Problem determination: Verify that the cover letter is correct and has not been corrupted. Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F839 E302F839

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F83A E302F83A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F83B E302F83B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F83C E302F83C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F83D E302F83D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F83E E302F83E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F83F E302F83F

Explanation: An error occurred during delete LID processing. The update will continue.

Problem determination: Informational message.

E302F840 E302F840

Explanation: An error occurred while attempting to get the engineering change streams in order to retrieve all of the updates from removable media.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F841 E302F841

Explanation: An error occurred while attempting to issue a start code update command to the master service processor.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F842 E302F842

Explanation: An error occurred while attempting to issue a write firmware update file command to the master service processor.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F843 E302F843

Explanation: An error occurred while attempting to issue a "code update complete" action to the master service processor.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F844 E302F844

Explanation: An error occurred while attempting to reboot the service processor

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F845 E302F845

Explanation: The "import from a remote repository" code routine was called, but the repository selected was not the support system or the Web site.

Problem determination: Use the HMC GUI to reselect the source for code updates. If the problem occurs

again, contact your next level of support.

E302F846 E302F846

Explanation: An error occurred while attempting to swap the T and P sides of the service processor.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F847 E302F847

Explanation: An engineering change stream was passed between components, but no such engineering change stream exists for the targeted object.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F848 E302F848

Explanation: A request to import the code updates and information timed out.

Problem determination: Verify that your connection to the support system is set up correctly and is operational. Retry the operation. If the problem reoccurs, contact your next level of support.

E302F849 E302F849

Explanation: A request to import the code updates and information failed.

Problem determination: Verify that your connection to the IBM support system is set up correctly and is operational. Retry the operation. If the problem reoccurs, contact your next level of support.

E302F84A E302F84A

Explanation: Failure during an attempt to read the surveyed list of code updates .

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, consider replacing the disk drive of your HMC.

E302F84B E302F84B

Explanation: Failure during an attempt to close the surveyed list of code updates .

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, consider replacing the disk drive of your HMC.

E302F84C E302F84C

Explanation: An error occurred while attempting to get the engineering change streams in order to list all of the updates available on the removable media.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F84D E302F84D

Explanation: An error occurred while trying to copy the RPM files from the media repository to the hard file.

Problem determination: The CD or DVD may be faulty. Try another one.

E302F84E E302F84E

Explanation: An error occurred in a removable media code routine because the file types were null.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F84F E302F84F

Explanation: An error occurred in a method because one of the file arrays had a length of zero.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F850 E302F850

Explanation: A failure occurred while trying to unpack the RPM file in the "complete concurrently" code routine.

Problem determination: Reboot the HMC and try the operation again. In the HMC code released before August 2004, there was a problem that can be corrected with commands from the Linux command line as follows:

ls -l /opt/ccfw/data/*.rpm rpm -qp *rpmfilename* (where *rpmfilename* is the name of the file returned by the **ls** command)

rpm -e rpm *packagename* (where *packagename* is the name of the package returned by the **rpm -e** command)

E302F851 E302F851

Explanation: The request to retrieve code updates from the support system failed with an error code.

Problem determination: Verify that your connection to the support system is set up correctly and is operational. Retry the operation. If the problem occurs

E302F852 • E302F85C

again, contact your next level of support.

E302F852 E302F852

Explanation: No phone server was available to serve the request to retrieve code updates.

Problem determination: Configure the HMC as a phone server and retry the operation.

E302F853 E302F853

Explanation: An error occurred while attempting to find the directory where firmware update files are stored for testing with the non disruptive application panel.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F854 E302F854

Explanation: An error occurred while attempting to issue a read firmware update file command to a service processor

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F855 E302F855

Explanation: Importing from an FTP site failed when the files from the FTP repository were not retrieved.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F856 E302F856

Explanation: A failure occurred when trying to query the name of the image in the RPM file.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F857 E302F857

Explanation: A failure occurred while attempting to issue the runact API.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded into the partition firmware. Verify the activated level through System Information. To support concurrent updates, ensure that the appropriate service and productivity tools (RSCT and RMC) are installed and running correctly on the AIX or Linux partitions. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S"

to attempt to reapply partition firmware concurrently OR schedule a time to restart the partitions to apply disruptively. If the activated level is NOT what is expected, run the code update again.

E302F858 E302F858

Explanation: An exception occurred while attempting to issue the runact API.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded into the partition firmware. Verify the activated level through System Information. To support concurrent updates, ensure that the appropriate service and productivity tools (RSCT and RMC) are installed and running correctly on the AIX or Linux partitions. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply partition firmware concurrently OR schedule a time to restart the partitions to apply disruptively. If the activated level is NOT what is expected, run the code update again.

E302F859 E302F859

Explanation: An exception occurred while trying to query the name of the image in the RPM file.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F85A E302F85A

Explanation: An exception occurred while trying to unpack the RPM file in the "complete concurrently" code routine.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F85B E302F85B

Explanation: An exception occurred while trying to import updates from the DVD.

Problem determination: The CD or DVD may be faulty. Try another one.

E302F85C E302F85C

Explanation: An error occurred while attempting to copy the T side to the P side.

Problem determination: In the Licensed Internal Code Update panels, choose *Select advanced features*, and then choose *Accept* to copy the T side to the P side. If the problem occurs again, contact your next level of support.

E302F85D **E302F85D**

Explanation: An error occurred while attempting to IPL the system unit.

Problem determination: The level of code requested is most likely activated on the targeted system. Verify the activated level through System Information. Then IPL the system unit if desired.

E302F85E **E302F85E**

Explanation: An error occurred while attempting to power on the system unit.

Problem determination: The level of code requested is most likely activated on the targeted system. Verify the activated level through System Information. Then power on the system unit if desired.

E302F85F **E302F85F**

Explanation: An error occurred while attempting to power off the system unit.

Problem determination: Try powering off the system unit manually and doing the code update while the system is in the platform standby state.

E302F860 **E302F860**

Explanation: An error occurred while trying to import updates to the DVD during an export command.

Problem determination: The CD or DVD may be faulty. Try another one.

E302F861 **E302F861**

Explanation: An error occurred while attempting to open the hypervisor diff file prior to writing.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F862 **E302F862**

Explanation: An error occurred while attempting to write the hypervisor diff file to the hypervisor.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command

"updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F863 **E302F863**

Explanation: An error occurred while attempting to close the hypervisor firmware diff file after writing it to the server firmware.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F864 **E302F864**

Explanation: An exception occurred during the query to see if a hypervisor firmware update has completed.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F865 **E302F865**

Explanation: A failure occurred while querying the status after a firmware update.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F866 **E302F866**

Explanation: The hypervisor firmware update timed out.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated

level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F867 E302F867

Explanation: An interruption occurred while waiting for the hypervisor firmware update.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F868 E302F868

Explanation: An error occurred while issuing a start code update command to the secondary service processor.

Problem determination:

- For systems using HMC firmware before V5R1.1, the secondary service processor will be synchronized in the next code update. If this does not occur, contact your next level of support.
- For systems using V5R1.1 (or newer) HMC firmware, follow the appropriate replace and verify procedure to synchronize the secondary service processor firmware to the primary firmware. Ensure that you set up the service processor failover feature as desired after you complete the replace and verify procedure.

E302F869 E302F869

Explanation: An error occurred while issuing a write firmware update file command to the secondary service processor.

Problem determination:

- For systems using HMC firmware before V5R1.1, the secondary service processor will be synchronized in the next code update. If this does not occur, contact your next level of support.
- For systems using V5R1.1 (or newer) HMC firmware, follow the appropriate replace and verify procedure to synchronize the secondary service processor firmware to the primary firmware. Ensure that you set up the service processor failover feature as desired after you complete the replace and verify procedure.

E302F86A E302F86A

Explanation: An error occurred issuing a code update complete command to the secondary service processor.

Problem determination:

- For systems using HMC firmware before V5R1.1, the secondary service processor will be synchronized in the next code update. If this does not occur, contact your next level of support.
- For systems using V5R1.1 (or newer) HMC firmware, follow the appropriate replace and verify procedure to synchronize the secondary service processor firmware to the primary firmware. Ensure that you set up the service processor failover feature as desired after you complete the replace and verify procedure.

E302F86B E302F86B

Explanation: A failure occurred while issuing a runact API to query the partitions and their status.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded into the partition firmware. Verify the activated level through System Information. To support concurrent updates, ensure that the appropriate service and productivity tools (RSCT and RMC) are installed and running correctly on the AIX or Linux partitions. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply partition firmware concurrently OR schedule a time to restart the partitions to apply disruptively. If the activated level is NOT what is expected, run the code update again.

E302F86C E302F86C

Explanation: An exception occurred while issuing a runact API to query the partitions and their status.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded into the partition firmware. Verify the activated level through System Information. To support concurrent updates, ensure that the appropriate service and productivity tools (RSCT and RMC) are installed and running correctly on the AIX or Linux partitions. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply partition firmware concurrently OR schedule a time to restart the partitions to apply disruptively. If the activated level is NOT what is expected, run the code update again.

E302F86D E302F86D

Explanation: A code update did not contain a diff firmware update file, or no diff firmware update file was found in the firmware update file directory, for nondisruptive firmware application.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F86E E302F86E

Explanation: An error occurred during a call to a code module while preparing to write the hypervisor firmware diff file to flash memory.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F86F E302F86F

Explanation: An error occurred during a call to a code module while attempting to write the hypervisor firmware diff file to flash memory.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F870 E302F870

Explanation: An error occurred during a call to a code module after writing the hypervisor firmware diff file to flash memory.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F871 E302F871

Explanation: An error occurred during the call to start firmware update to concurrently patch firmware.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F872 E302F872

Explanation: Querying status after a firmware update did not return the proper number of elements in the vector.

Problem determination: The level of code requested is most likely activated on the targeted system, but not loaded in the hypervisor firmware. Verify the activated level through system information. If the activated level is what is expected, use the command-line command "updlic -o v -m Your_MTM*S" to attempt to reapply hypervisor and partition firmware concurrently, OR schedule a time to IPL the system to apply it disruptively. If the activated level is NOT what is expected, run the code update again.

E302F873 E302F873

Explanation: Rebooting the service processor was executed, but the system unit did not return to the state where the T side was active within a reasonable amount of time. This generally means that the system was not successful when coming up with the new code level and went back to the older code level.

Problem determination: Retry the operation. To do this, select **Select Advanced Features** and then select **Install And Activate** . If the code update fails again, contact your next level of support.

E302F874 E302F874

Explanation: Rebooting the service processor was executed, but the system unit did not return to its original state within a reasonable amount of time.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). If it is not in a good state, then take the necessary steps to put it in a good state. After it is in a good state, check System Information to ensure the code update was applied. If it is now in a good state but the update is not applied, repeat the operation.

E302F875 • E302F87F

E302F875 E302F875

Explanation: An error occurred while attempting to query (at standby) in an attempt to retrieve all of the updates from the removable media.

Problem determination: The CD or DVD may be faulty. Try another one.

E302F876 E302F876

Explanation: A failure occurred while trying to query the name of the image in the RPM file.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F877 E302F877

Explanation: An exception occurred while trying to query the name of the image in the RPM file.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F878 E302F878

Explanation: A failure occurred trying to erase an RPM file.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F879 E302F879

Explanation: An exception occurred trying to erase an RPM file.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F87A E302F87A

Explanation: A failure occurred while trying to change the permissions of an image file after it had been pulled from an RPM package.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F87B E302F87B

Explanation: An exception occurred while trying to change the permissions of an image file after it had been pulled from an RPM package.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F87C E302F87C

Explanation: After the flash write to the primary service processor was complete, the secondary service processor did not complete operations within half an hour.

Problem determination:

- For systems using HMC firmware before V5R1.1, the secondary service processor will be synchronized in the next code update. If this does not occur, contact your next level of support.
 - For systems using V5R1.1 (or newer) HMC firmware, follow the appropriate replace and verify procedure to synchronize the secondary service processor firmware to the primary firmware. Ensure that you set up the service processor failover feature as desired after you complete the replace and verify procedure.
-

E302F87D E302F87D

Explanation: A failure occurred importing I/O microcode.

Problem determination: Try the operation again. If the problem occurs again, contact your next level of support.

E302F87E E302F87E

Explanation: An IPL of the service processor was executed as part of a disruptive firmware update, but it did not put the system in its original state within a reasonable amount of time.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). If it is not in a good state, take the necessary steps to put it in a good state. After it is in a good state, check System Information to ensure the code update was applied.

E302F87F E302F87F

Explanation: Powering off the service processor was executed as part of a disruptive firmware update, but it did not put the service processor in a powered off state within a reasonable amount of time.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). If it is not in a good state, take the necessary steps to put it in a good state. After it is in a good state, repeat the code update operation.

E302F880 **E302F880**

Explanation: Powering on the service processor was executed as part of a disruptive firmware update, but it did not put the service processor in a powered on state within a reasonable amount of time.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). If it is not in a good state, take the necessary steps to put it in a good state. After it is in a good state, check System Information to ensure the code update was applied.

E302F881 **E302F881**

Explanation: An IPL was executed as part of a disruptive firmware update, but the managed system was placed in an error state.

Problem determination: If this message occurs, contact your next level of support.

E302F882 **E302F882**

Explanation: A power off was executed as part of a disruptive firmware update, but the managed system was placed in an error state.

Problem determination: If this message occurs, contact your next level of support.

E302F883 **E302F883**

Explanation: A power on was executed as part of a disruptive firmware update, but the managed system was placed in an error state.

Problem determination: If this message occurs, contact your next level of support.

E302F884 **E302F884**

Explanation: The service processor was rebooted during a firmware update, but it did not put the service processor in a "not connected" state within a reasonable amount of time.

Problem determination: Go to the Server and Partition display, refresh the screen and ensure the system is in a good state (for example, power off, standby, or operating). If it is not in a good state, take the necessary steps to put it in a good state. When in a good state, check System Information to ensure the code update was applied. If it is now in a good state but the update is not applied, then repeat the operation.

E302F885 **E302F885**

Explanation: The service processor was rebooted during a firmware update, which put the service processor in a "not connected" state. However, this action did not clear the "not connected" state within a reasonable amount of time.

Problem determination: Contact the next level of support for assistance in getting the HMC to communicate with the service processor again.

E302F886 **E302F886**

Explanation: A retrieve from the code repository was issued, but no available code updates were found.

Problem determination: If this message occurs, contact your next level of support.

E302F887 **E302F887**

Explanation: An exception occurred during execution of the synchronous apply staged updates program while applying code from the hard file staging area.

Problem determination: If this message occurs, contact your next level of support.

E302F888 **E302F888**

Explanation: A `chsyscfg` command was issued to change the next IPL side, but it failed.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F889 **E302F889**

Explanation: An exception occurred after a `chsyscfg` command was issued to change the next IPL side.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F88A **E302F88A**

Explanation: Powering off the system unit has started.

E302F88B **E302F88B**

Explanation: Reading of the firmware update files has started.

E302F88C **E302F88C**

Explanation: Writing of the firmware update files has started.

E302F88D • E302F89A

E302F88D E302F88D

Explanation: Rebooting the service processor has started.

E302F88E E302F88E

Explanation: Powering on the system unit has started.

E302F88F E302F88F

Explanation: Restoring of the firmware update files to the P side has started.

E302F890 E302F890

Explanation: An error occurred while attempting to find the directory used as temporary storage.

Problem determination: Reboot the HMC and try the operation again. If the problem occurs again, contact your next level of support.

E302F891 E302F891

Explanation: Failure when attempting to import an RPM package from the Web site.

Problem determination: Verify that your LAN connections are set up properly and retry the operation. If the problem occurs again, contact your next level of support.

E302F892 E302F892

Explanation: A request was received to take the service processor back to an earlier level, but it was a concurrent request. This operation can only be performed disruptively.

Problem determination: Reboot the HMC and schedule time for a disruptive update. Retry the operation during that scheduled time. If the problem occurs again, contact your next level of support.

E302F893 E302F893

Explanation: A general error occurred while applying code.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F894 E302F894

Explanation: A general error occurred while processing a hardware upgrade.

Problem determination: If another error occurs before this message, follow the action for that error. If this

message occurs by itself, contact your next level of support.

E302F895 E302F895

Explanation: A general error occurred while committing code.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F896 E302F896

Explanation: A general error occurred while exporting code to the DVD.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F897 E302F897

Explanation: A general error occurred while importing code.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F898 E302F898

Explanation: A general error occurred while rejecting code.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F899 E302F899

Explanation: An attempt was made to update the hypervisor firmware, but the hypervisor reported that it is already at that level.

E302F89A E302F89A

Explanation: A general error occurred while updating the flash on a service processor.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F89B E302F89B

Explanation: An error occurred while swapping the T and P sides of the secondary service processor.

Problem determination:

- For systems using HMC firmware before V5R1.1, the secondary service processor will be synchronized in the next code update. If this does not occur, contact your next level of support.
- For systems using V5R1.1 (or newer) HMC firmware, follow the appropriate replace and verify procedure to synchronize the secondary service processor firmware to the primary firmware. Ensure that you set up the service processor failover feature as desired after you complete the replace and verify procedure.

E302F89C E302F89C

Explanation: An error occurred while copying the T to the P side on the secondary service processor.

Problem determination:

- For systems using HMC firmware before V5R1.1, the secondary service processor will be synchronized in the next code update. If this does not occur, contact your next level of support.
- For systems using V5R1.1 (or newer) HMC firmware, follow the appropriate replace and verify procedure to synchronize the secondary service processor firmware to the primary firmware. Ensure that you set up the service processor failover feature as desired after you complete the replace and verify procedure.

E302F89D E302F89D

Explanation: A failure occurred either writing the firmware to the bulk power assemblies (BPAs), or rebooting them after writing the firmware.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F89E E302F89E

Explanation: A failure occurred while trying to erase a file.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F89F E302F89F

Explanation: An attempt to set a lock on a BPA frame failed. The BPA is locked by another process.

Problem determination: Do the following as applicable:

1. Make sure that you do not select multiple managed systems (that are associated with the same power frame) for simultaneous managed system and power code update or upgrade.
2. Allow all currently running code update processes to end successfully on all of the associated HMCs.
3. Ensure that all frame numbering, frame initialization, and repair and verify processes that also use BPA locking end successfully on all of the associated HMCs.
4. After all the operations are finished and a retargeting to one of the managed systems still results in this error, remove the BPA lock. To remove the BPA lock, use the following command from the HMC: `rmlock -e Frame*MTMS` where *Frame*MTMS* is the machine-type, model, and serial number of the affected BPA.
5. Retry the operation. If the error occurs again, contact your next level of support.

E302F8A0 E302F8A0

Explanation: An error occurred while trying to read the list of code updates that was surveyed.

Problem determination: If you are using an ftp server, first make sure the fixpack files are the only ones listed in the source directory. If that is not the problem, reboot the HMC and retry the operation. If the problem occurs again, consider replacing the disk drive of the HMC.

E302F8A1 E302F8A1

Explanation: An error occurred while trying to close the list of code updates that was surveyed.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, consider replacing the disk drive of the HMC.

E302F8A2 E302F8A2

Explanation: An error occurred while attempting to update the server firmware.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8A3 • E302F8B1

E302F8A3 E302F8A3

Explanation: An error occurred while querying to see if the server firmware diff file is in memory.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8A4 E302F8A4

Explanation: An exception occurred while querying to see if the server firmware diff file is in memory.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8A5 E302F8A5

Explanation: An exception occurred while querying to see if the HMC is the code update owner.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8A6 E302F8A6

Explanation: An exception occurred while setting the HMC to be the code update owner.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8A7 E302F8A7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8A8 E302F8A8

Explanation: Querying to see if the service firmware diff file is in memory did not return the proper number of elements in the vector.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8A9 E302F8A9

Explanation: A general error occurred while rebooting.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F8AA E302F8AA

Explanation: An error occurred when attempting to copy the P-side flash memory to the T-side on the master service processor.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8AB E302F8AB

Explanation: An error occurred when attempting to copy the P-side flash memory to the T-side on the secondary service processor.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8AC E302F8AC

Explanation: A failure occurred importing or applying I/O microcode.

Problem determination: Try the operation again. If the error occurs again, contact your next level of support.

E302F8AD E302F8AD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8AE E302F8AE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8AF E302F8AF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B0 E302F8B0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B1 E302F8B1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B2 E302F8B2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B3 E302F8B3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B4 E302F8B4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B5 E302F8B5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B6 E302F8B6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B7 E302F8B7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B8 E302F8B8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8B9 E302F8B9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8BA E302F8BA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8BB E302F8BB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8BC E302F8BC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8BD E302F8BD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8BE E302F8BE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8BF E302F8BF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C0 E302F8C0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C1 E302F8C1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C2 • E302F8D1

E302F8C2 E302F8C2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C3 E302F8C3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C4 E302F8C4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C5 E302F8C5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C6 E302F8C6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C7 E302F8C7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C8 E302F8C8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8C9 E302F8C9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8CA E302F8CA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8CB E302F8CB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8CC E302F8CC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8CD E302F8CD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8CE E302F8CE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8CF E302F8CF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D0 E302F8D0

Explanation: An I/O error occurred while reading the fixpack or code update image.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, consider replacing the disk drive in the HMC.

E302F8D1 E302F8D1

Explanation: An error occurred while writing a firmware update file that was read from a fixpack or code update to disk.

Problem determination: Reboot the HMC and retry

the operation. If the problem occurs again, contact your next level of support.

E302F8D2 E302F8D2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D3 E302F8D3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D4 E302F8D4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D5 E302F8D5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D6 E302F8D6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D7 E302F8D7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D8 E302F8D8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8D9 E302F8D9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8DA E302F8DA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8DB E302F8DB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8DC E302F8DC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8DD E302F8DD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8DE E302F8DE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8DF E302F8DF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E0 E302F8E0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E1 • E302F8F0

E302F8E1 E302F8E1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E2 E302F8E2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E3 E302F8E3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E4 E302F8E4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E5 E302F8E5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E6 E302F8E6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E7 E302F8E7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E8 E302F8E8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8E9 E302F8E9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8EA E302F8EA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8EB E302F8EB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8EC E302F8EC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8ED E302F8ED

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8EE E302F8EE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8EF E302F8EF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8F0 E302F8F0

Explanation: An error occurred while surveying the Web site.

Problem determination: Verify that your LAN connections are set up properly and retry the operation.

If the problem occurs again, contact your next level of support.

E302F8F1 E302F8F1

Explanation: An exception occurred while surveying the Web site.

Problem determination: Verify that your LAN connections are set up properly and retry the operation. If the problem occurs again, contact your next level of support.

E302F8F2 E302F8F2

Explanation: An exception occurred while copying the XML file to the cover letter during importation from the Web site.

Problem determination: Verify that your LAN connections are set up properly and retry the operation. If the problem occurs again, contact your next level of support.

E302F8F3 E302F8F3

Explanation: Two hour wait period was exceeded for the updating of firmware.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F8F4 E302F8F4

Explanation: An error occurred while surveying the Web site. The file was not found at the Web site.

Problem determination: Verify that the HMC connection to the support Web site is working. Contact the network administrator for your installation to determine if a firewall or other network security process must be opened for the HMC to access the Internet. If the HMC is on a private network, the support Web site will not be available as a repository. Retry the operation again after you successfully access the support Web site. If the error occurs again, contact your next level of support.

E302F8F5 E302F8F5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8F6 E302F8F6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8F7 E302F8F7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8F8 E302F8F8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8F9 E302F8F9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8FA E302F8FA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8FB E302F8FB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8FC E302F8FC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8FD E302F8FD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8FE • E302F8FF

E302F8FE E302F8FE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F8FF E302F8FF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E302F9xx) Reference codes

E302F900 E302F900

Explanation: The survey from an FTP site failed when the control program was not able to change the directory to that of the user.

Problem determination: Verify that the FTP site directory specified is correct and that any firewall authentications were completed, if necessary, before performing the update. Try the operation again. If the problem occurs again, contact your next level of support.

E302F901 E302F901

Explanation: A query of the current boot side of the secondary processor returned a null.

Problem determination: Verify that the authentication passwords for the service processors are synchronized and that the TCP/IP addresses of the service processors are not in the HMC DHCP server's removed list. Use the Update Managed System Password field under the Server and Partition panels to reset the password if necessary. Use the restricted shell "mksysconn -o auto" command to reset the HMC DHCP server's removed list and reconnect the affected service processors. If the problem occurs again, contact your next level of support.

E302F902 E302F902

Explanation: A query of the next boot side of the secondary processor returned a null.

Problem determination: Verify that the authentication passwords for the service processors are synchronized and that the TCP/IP addresses of the service processors are not in the HMC DHCP server's removed list. Use the Update Managed System Password pulldown under the Server and Partition panels to reset the password if necessary. Use the restricted shell "mksysconn -o auto" command to reset the HMC DHCP server's removed list and reconnect the affected service processors. If the problem occurs again, contact your next level of support.

E302F903 E302F903

Explanation: Unable to determine Power Frame Information.

Problem determination: Check that all of the Power Frames are connected to the HMC and that they are properly authenticated. If not, take the appropriate actions to achieve this. Retry the operation. If the

problem occurs again, contact your next level of support.

E302F904 E302F904

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F905 E302F905

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F906 E302F906

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F907 E302F907

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F908 E302F908

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F909 E302F909

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F90A E302F90A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F90B E302F90B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F90C E302F90C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F90D E302F90D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F90E E302F90E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F90F E302F90F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F910 E302F910

Explanation: An exception occurred when querying to find out if the bulk power assembly was N-mode.

Problem determination: Verify that both the primary and secondary service processors for the bulk power assembly (or assemblies) are configured properly and available for communication with the HMC. This is a requirement. Retry the operation. If the problem occurs again, contact your next level of support.

E302F911 E302F911

Explanation: A failure occurred when querying to find out if the bulk power assembly was N-mode.

Problem determination: Verify that both the primary and secondary service processors for the bulk power assembly (or assemblies) are configured properly and available for communication with the HMC. This is a requirement. Retry the operation. If the problem occurs again, contact your next level of support.

E302F912 E302F912

Explanation: One of the bulk power assemblies targeted for firmware update has N-mode power.

Problem determination: Verify that both the primary and secondary service processors for the bulk power assembly (or assemblies) are configured properly and available for communication with the HMC. This is a requirement. Retry the operation. If the problem occurs again, contact your next level of support.

E302F913 E302F913

Explanation: One of the bulk power assemblies targeted for firmware update has an auto-code download (ACDL) pending.

Problem determination: A code update cannot be performed while a service processor in the bulk power assembly is running an auto-code download process. Depending on the number of FRUs being loaded, this process might take a significantly long time. After two hours, try the original operation again. If the failure occurs again, wait two hours and manually point the next re-IPL of the service processor to the "P" side by using the Flash Side Selection panels. Perform a "Disruptive Activate" using the Select advanced features panels. Wait two hours for that auto-code download to complete, then try the original operation again. If the problem occurs again, contact your next level of support.

E302F914 E302F914

Explanation: An exception occurred when attempting to start the auto-code download (ACDL) on a bulk power assembly.

Problem determination:

- For systems using HMC firmware before V5R2, contact your next level of support.
- For systems using V5R2 (or newer) HMC firmware, do the following:
 1. Choose **Select advanced features** .
 2. Perform an **Install and activate (implied Retrieve) Specific Level update** to the current level of power firmware on the hard drive repository. (Choose **Automatically Accept** .)
 3. Click **Change Levels** , and change **None** to the current level of power firmware.
 4. Leave the Managed System code level as **None** , and then finish the code update.

If the problem occurs again, contact your next level of support.

E302F915 **E302F915**

Explanation: A failure occurred when attempting to start the auto-code download (ACDL) on a bulk power assembly.

Problem determination:

- For systems using HMC firmware before V5R2, contact your next level of support.
- For systems using V5R2 (or newer) HMC firmware, do the following:
 1. Choose **Select advanced features** .
 2. Perform an **Install and activate (implied Retrieve) Specific Level update** to the current level of power firmware on the hard drive repository. (Choose **Automatically Accept** .)
 3. Click **Change Levels** , and change **None** to the current level of power firmware.
 4. Leave the Managed System code level as **None** , and then finish the code update.

If the problem occurs again, contact your next level of support.

E302F916 **E302F916**

Explanation: An exception occurred when attempting to determine how many FRUs were completed during an auto-code download (ACDL).

Problem determination:

- For systems using HMC firmware before V5R2, contact your next level of support.
- For systems using V5R2 (or newer) HMC firmware, do the following:
 1. Choose **Select advanced features** .
 2. Perform an **Install and activate (implied Retrieve) Specific Level update** to the current level of power firmware on the hard drive repository. (Choose **Automatically Accept** .)
 3. Click **Change Levels** , and change **None** to the current level of power firmware.
 4. Leave the Managed System code level as **None** , and then finish the code update.

If the problem occurs again, contact your next level of support.

E302F917 **E302F917**

Explanation: A failure occurred when attempting to determine how many FRUs were completed during an auto-code download (ACDL).

Problem determination:

- For systems using HMC firmware before V5R2, contact your next level of support.
- For systems using V5R2 (or newer) HMC firmware, do the following:

1. Choose **Select advanced features** .
2. Perform an **Install and activate (implied Retrieve) Specific Level update** to the current level of power firmware on the hard drive repository. (Choose **Automatically Accept** .)
3. Click **Change Levels** , and change **None** to the current level of power firmware.
4. Leave the Managed System code level as **None** , and then finish the code update.

If the problem occurs again, contact your next level of support.

E302F918 **E302F918**

Explanation: The auto-code download (ACDL) took too long on one side of the bulk power assembly.

Problem determination:

- For systems using HMC firmware before V5R2, contact your next level of support.
- For systems using V5R2 (or newer) HMC firmware, do the following:
 1. Choose **Select advanced features** .
 2. Perform an **Install and activate (implied Retrieve) Specific Level update** to the current level of power firmware on the hard drive repository. (Choose **Automatically Accept** .)
 3. Click **Change Levels** , and change **None** to the current level of power firmware.
 4. Leave the Managed System code level as **None** , and then finish the code update.

If the problem occurs again, contact your next level of support.

E302F919 **E302F919**

Explanation: The auto-code download (ACDL) began but did not complete successfully.

Problem determination: Follow the actions listed for E302F918.

E302F91A **E302F91A**

Explanation: An error occurred in the service processor support code during a query of the state of a service processor for a frame.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F91B **E302F91B**

Explanation: A failure occurred when attempting to query the state of the system unit after receiving an asynchronous report that the state had changed.

Problem determination: Reboot the HMC and retry

E302F91C • E302F924

the operation. If the error occurs again, contact your next level of support.

E302F91C E302F91C

Explanation: A failure occurred while copying the firmware from the T side to the P side after a successful update of the bulk power controller code.

Problem determination: Perform an "Accept" operation using the Select advanced features panels. This operation also accepts the system unit code. If the problem occurs again, contact your next level of support.

E302F91D E302F91D

Explanation: A failure occurred when trying to deactivate a bulk power assembly.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F91E E302F91E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F91F E302F91F

Explanation: An exception occurred when trying to deactivate a bulk power assembly.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F920 E302F920

Explanation: An I/O error occurred when attempting to write the power FRU code levels to a file.

Problem determination: Ensure the following:

- That ample space exists in the file system that contains the /opt/ccfw directory
- For HMCs before V7, that a user with root authority executes the following command: `dlslic -e`

Note: The `dlslic` command is a diagnostic aid that obtains ACDL status and creates the `bpa.frus.lst` file in /opt/ccfw/data directory.

For HMC V7 firmware the `bpa.frus.lst` file is created when the Power FRU selection is made on the View System Information panel. The `dlslic` command is no longer implemented. For command-line commands, the new `-t powerfru` parameter of the `lslic` command now

provides information for Power FRU code levels in the command line environment.

After you clear the file space (root privilege required), if necessary, execute the `dlslic` command again as a user with root authority (HMC before V7) or select the Power FRU choice in View System Information (HMC V7+). If the error occurs again, contact your next level of support.

E302F921 E302F921

Explanation: An I/O error occurred when attempting to close the file containing the Power FRU code levels.

Problem determination: Perform the actions for error code E302 F920. If the error occurs again, contact your next level of support.

E302F922 E302F922

Explanation: An exception occurred when attempting to set or release a lock on a bulk power adapter frame.

Problem determination: Perform the actions for error code E302 F89F. If the error occurs again, contact your next level of support.

E302F923 E302F923

Explanation: A failure occurred during a query of the current service processor failover state.

Problem determination:

- If another error occurs before this message, follow the action for that error.
- If this message occurs during a code update Health Check, correct the condition that caused the Health Check to fail and retry the operation.
- If this message occurs by itself, contact your next level of support.

E302F924 E302F924

Explanation: An exception occurred during the query of the current service processor failover state.

Problem determination:

- If another error occurs before this message, follow the action for that error.
- If this message occurs during a code update Health Check, correct the condition that caused the Health Check to fail and retry the operation.
- If this message occurs by itself, contact your next level of support.

E302F925 E302F925

Explanation: A failure occurred when attempting to set the service processor failover state with the `chsyscfg` command.

Problem determination:

- If another error occurs before this message, follow the action for that error.
- If this message occurs during a code update Health Check, correct the condition that caused the Health Check to fail and retry the operation.
- If this message occurs by itself, contact your next level of support.

E302F926 E302F926

Explanation: An exception occurred when attempting to set the service processor failover state with the `chsyscfg` command.

Problem determination: Follow the actions listed for E302F925.

E302F927 E302F927

Explanation: An error occurred when attempting to acquire the service processor lock.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F928 E302F928

Explanation: A timeout error occurred when attempting to acquire the service processor lock.

Problem determination: Check to see if a long running DLPAR operation is in progress to the same managed system. If there is, wait for that operation to complete and then perform a Disruptive Activate. If the error occurs again, contact your next level of support.

E302F929 E302F929

Explanation: An error occurred when attempting to release the service processor lock.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F92A E302F92A

Explanation: Dynamic service processor failover has been disabled.

Problem determination: Informational message.

E302F92B E302F92B

Explanation: Dynamic service processor failover has been enabled.

Problem determination: Informational message.

E302F92C E302F92C

Explanation: A firmware update reboot of the secondary service processor placed it into a not connected state, but it did not clear that state in a reasonable amount of time.

Problem determination: Contact the next level of support for assistance in getting the HMC to talk to the service processor again.

E302F92D E302F92D

Explanation: During readiness checking, an exception occurred in the `readBPAPowerStatus()` method when attempting to determine the status of the power subsystem.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F92E E302F92E

Explanation: During readiness checking, a null value was returned by the `readBPAPowerStatus()` method when attempting to determine the status of the power subsystem.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F92F E302F92F

Explanation: During readiness checking, an exception occurred in the `getConnectionStatus()` method when attempting to determine the status of power subsystem connections.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F930 E302F930

Explanation: During readiness checking, a null value was returned by the `getConnectionStatus()` method when attempting to determine the status of power subsystem connections.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F931 E302F931

Explanation: During readiness checking, an exception occurred in the getState() method when attempting to determine the state of the power subsystem.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F932 E302F932

Explanation: During readiness checking, an exception occurred in the isNModePower() method when attempting to determine the state of the power subsystem.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F933 E302F933

Explanation: An exception occurred in the getRedundantFspInfoExt() method to the primary service processor when attempting to determine the state of the secondary service processor.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F934 E302F934

Explanation: A null value was returned by the getRedundantFspInfoExt() method to the primary service processor when attempting to determine the state of the secondary service processor.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F935 E302F935

Explanation: During readiness checking, an exception occurred in the getState() method when attempting to determine the state of the managed system.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F936 E302F936

Explanation: During readiness checking, an exception occurred in the getConnectionStatus() method when attempting to determine the status of service processor connections.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F937 E302F937

Explanation: During readiness checking, a null value was returned by the getConnectionStatus() method when attempting to determine the status of service processor connections.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F938 E302F938

Explanation: An exception occurred while querying the Original Platform IPL Side.

Problem determination: Verify that the primary service processor is properly connected to the HMC and authenticated. Take the appropriate steps to achieve this. Retry the operation. If the error occurs again, contact your next level of support.

E302F939 E302F939

Explanation: A reboot of the primary service processor for a code update did not return that processor to a stable state in a reasonable amount of time.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F93A E302F93A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F93B E302F93B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F93C E302F93C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F93D E302F93D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F93E **E302F93E**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F93F **E302F93F**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F940 **E302F940**

Explanation: A reboot of the secondary service processor for a code update did not return that processor to a stable state in a reasonable amount of time.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F941 **E302F941**

Explanation: An internal error occurred during LIC update Readiness Checking. An exception occurred in the `getCodeUpdateStatus()` method while trying to determine the status of the service processors.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F942 **E302F942**

Explanation: An internal error occurred during LIC update Readiness Checking. An exception occurred in the `getCodeUpdateStatus()` method while trying to determine the status of the power subsystem.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F943 **E302F943**

Explanation: An exception occurred while trying to execute `GetCodeUpdateStatus` to the primary service processor.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F944 **E302F944**

Explanation: An exception occurred while trying to execute `GetCodeUpdateStatus` to the secondary service processor.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F945 **E302F945**

Explanation: An internal error occurred during LIC update Readiness Checking. An exception occurred while trying to determine if the half-genesis condition exists.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F946 **E302F946**

Explanation: An internal error occurred during Licensed Internal Code readiness checking. An error occurred in the `checkFrameHealth()` method while trying to determine the status of the Power Subsystem.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F947 • E302F955

E302F947 E302F947

Explanation: An internal error occurred during Licensed Internal Code readiness checking. An exception occurred in the checkFrameHealth() method while trying to determine the status of the Power Subsystem.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Try the operation again. Reboot the HMC if the error occurs again. Retry the operation. If the error still occurs, contact your next level of support.

E302F948 E302F948

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F949 E302F949

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F94A E302F94A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F94B E302F94B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F94C E302F94C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F94D E302F94D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F94E E302F94E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F94F E302F94F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F950 E302F950

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F951 E302F951

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F952 E302F952

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F953 E302F953

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F954 E302F954

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F955 E302F955

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F956 **E302F956**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F957 **E302F957**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F958 **E302F958**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F959 **E302F959**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F95A **E302F95A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F95B **E302F95B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F95C **E302F95C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F95D **E302F95D**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F95E **E302F95E**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F95F **E302F95F**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F960 **E302F960**

Explanation: The operation was cancelled.

Problem determination: Informational message.

E302F961 **E302F961**

Explanation: An error occurred while releasing the service processor lock. This error occurred during cleanup. The code update operation was successful.

Problem determination: Reboot the HMC to disconnect it from the service processor. Take steps to assure that all managed system and power frame service processors reconnect properly with good authentication. Contact your next level of support if this error occurs on a subsequent LIC update to the managed system.

E302F962 **E302F962**

Explanation: A power on was executed as a part of a disruptive firmware update, but it put the CEC into a recovery state.

Problem determination: Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Rebuild the managed system environment using the HMC GUI or the command-line command. If this is not successful, contact your next level of support.

E302F963 **E302F963**

Explanation: A service processor failover was initiated as part of a code update.

Problem determination: Informational message.

E302F964 **E302F964**

Explanation: An exception occurred while trying to initiate failover during a firmware update.

Problem determination: Reboot the HMC and retry

E302F965 • E302F970

the operation. If the error occurs again, contact your next level of support.

E302F965 E302F965

Explanation: A failover was executed as a part of a firmware update, and it did put the primary service processor into a not connected state, but the primary service processor did not reconnect within a reasonable amount of time.

Problem determination: Contact your next level of support.

E302F966 E302F966

Explanation: A failover was executed as a part of a firmware update, but the service processors did not change roles.

Problem determination: Retry the operation. If the error occurs again, contact your next level of support.

E302F967 E302F967

Explanation: A failover was executed as a part of a firmware update, and it did put the secondary service processor into a not connected state, but the secondary service processor did not reconnect within a reasonable amount of time.

Problem determination: Contact your next level of support.

E302F968 E302F968

Explanation: A PIUpdateableComponent object does not exist for the selected object.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F969 E302F969

Explanation: Redundancy is enabled, but failover is not allowed due to an error condition on the service processors.

Problem determination: If another error occurs before this message, follow the action for that error. If this message occurs by itself, contact your next level of support.

E302F96A E302F96A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F96B E302F96B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F96C E302F96C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F96D E302F96D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F96E E302F96E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F96F E302F96F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F970 E302F970

Explanation: Failover was initiated as part of the code update process, but the managed system state did not return to a usable, connected state.

Problem determination: If the system continues to run, schedule a time for disruptive operations. During that time take appropriate action to get to Power Off state. Verify that all of the managed system and power frame service processors are connected and properly authenticated to the HMC. Take appropriate action to achieve this. Perform a Disruptive Activate and verify that service processor failover is enabled and ready. If failover is not ready due to an error condition, contact your next level of support. Otherwise, enable failover and power on the system.

E302F971 E302F971

Explanation: The synchronize function was invoked to copy from the secondary service processor to the primary with redundancy enabled. This is not allowed.

Problem determination: Contact your next level of support for a procedure to handle Secondary to Primary synchronization during the time of a scheduled disruptive operation.

E302F972 E302F972

Explanation: An exception occurred while managing the task lock.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F973 E302F973

Explanation: The requested operation cannot be performed. The task lock is already locked by another task.

Problem determination: Allow the other task to complete. If there is no other session or command line operations performing this task, then reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F974 E302F974

Explanation: The firmware level is not compatible with the current HMC level.

Problem determination: Update the code level of the HMC itself to the level required for this Managed System or Power Subsystem firmware. Repeat the operation after all systems have reconnected and are properly authenticated. Retry the operation. If the problem occurs again, contact your next level of support.

E302F975 E302F975

Explanation: The Managed System firmware level is not compatible with the Power Subsystem firmware level.

Problem determination: Check the firmware requisites to assure that the Managed System and Power Subsystem firmware are compatible and change one or both firmware levels to compatible ones. Repeat the operation. If the problem occurs again and you are certain that the firmware is compatible, contact your next level of support. Otherwise, review the firmware requisites again to assure that they are compatible and take the appropriate action to achieve compatibility.

E302F976 E302F976

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F977 E302F977

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F978 E302F978

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F979 E302F979

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F97A E302F97A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F97B E302F97B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F97C E302F97C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F97D E302F97D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F97E • E302F98D

E302F97E E302F97E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F97F E302F97F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F980 E302F980

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F981 E302F981

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F982 E302F982

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F983 E302F983

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F984 E302F984

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F985 E302F985

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F986 E302F986

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F987 E302F987

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F988 E302F988

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F989 E302F989

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F98A E302F98A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F98B E302F98B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F98C E302F98C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F98D E302F98D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F98E E302F98E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F98F E302F98F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F990 E302F990

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F991 E302F991

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F992 E302F992

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F993 E302F993

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F994 E302F994

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F995 E302F995

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F996 E302F996

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F997 E302F997

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F998 E302F998

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F999 E302F999

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F99A E302F99A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F99B E302F99B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F99C E302F99C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F99D E302F99D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F99E • E302F9AA

E302F99E E302F99E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302F99F E302F99F

Explanation: Error during processing of the License Agreement panel.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9A0 E302F9A0

Explanation: Error during the main processing for the server side of the IOSurveyResults task. This could be the result of an Exception being caught by the underlying Tasklet infrastructure.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9A1 E302F9A1

Explanation: Readiness check has attempted to repair the error condition on the secondary service processor by rebooting it.

Problem determination: Informational message.

E302F9A2 E302F9A2

Explanation: Readiness check errors were ignored due to the presence of the override file /opt/ccfw/data/IgnoreLICErrors. The file has since been removed as a normal part of processing.

Problem determination: Informational message.

E302F9A3 E302F9A3

Explanation: Readiness checks were skipped due to the presence of the override file /opt/ccfw/data/DisableLICChecks. The file has since been removed as a normal part of processing.

Problem determination: Informational message.

E302F9A4 E302F9A4

Explanation: Error during the actual processing for Readiness Check task.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9A5 E302F9A5

Explanation: Error during the main processing for the server side of the Readiness Check task. This could be the result of an Exception being caught by the underlying Tasklet infrastructure.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9A6 E302F9A6

Explanation: Error trying to do the main processing for client side of the Readiness Check task. This is the result of an Exception being caught by the underlying Tasklet infrastructure. The Readiness Check task has been ended.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9A7 E302F9A7

Explanation: Error during processing in the handling of the license agreement or confirmation panel in the AdvFeaturesTasklet. The task is terminated.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9A8 E302F9A8

Explanation: Error during processing in the powerControlPanelHandler in the AdvFeaturesTasklet. The task is terminated.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9A9 E302F9A9

Explanation: Error trying to perform some processing in the Power Control Bean. The bean attempts to close the panel.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9AA E302F9AA

Explanation: Error during processing in the powerControlPanelHandler in the MesUpgradeTasklet. The task is terminated.

Problem determination: Reboot the HMC and try the operation again. If the error occurs again, contact your next level of support.

E302F9AB E302F9AB

Explanation: An error occurred during the processing for the update licensed internal code MES select level panel handler.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F9AC E302F9AC

Explanation: An error occurred during the processing for the update licensed internal code main repository panel handler.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F9AD E302F9AD

Explanation: An error occurred during the processing for the update licensed internal code FTPpanel panel handler.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F9AE E302F9AE

Explanation: An error occurred during the processing for the update licensed internal code changeFTP panel handler.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F9AF E302F9AF

Explanation: An error occurred during the processing for the advanced features task when trying to run a tasklet exit on the client to display the license panel. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F9B0 E302F9B0

Explanation: An error occurred during the processing for the MES upgrade task when trying to run a tasklet exit on the client to display the license panel. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F9B1 E302F9B1

Explanation: An error occurred during the processing for the change internal code wizard when trying to run a tasklet exit on the client to display the license panel. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the error occurs again, contact your next level of support.

E302F9B2 E302F9B2

Explanation: Error during processing for the Change Internal Code Wizard

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9B3 E302F9B3

Explanation: Error during processing for an internal code method.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9B4 E302F9B4

Explanation: Error during processing for an internal panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9B5 E302F9B5

Explanation: Error during processing for an internal panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9B6 E302F9B6

Explanation: Error during processing for an internal panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9B7 E302F9B7

Explanation: Error during processing of the server side of the scheduleable update task.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9B8 E302F9B8

Explanation: Error trying to perform processing in a hardware upgrade code path.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9B9 E302F9B9

Explanation: Error during the main "service" processing for the server side of the hardware upgrade task. The task has been terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9BA E302F9BA

Explanation: Error during the main processing for the client side of the hardware upgrade task. The task has been terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9BB E302F9BB

Explanation: Error during the main processing for the server side of the hardware upgrade task.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9BC E302F9BC

Explanation: Error during the processing of the actual non disruptive firmware update task. The progress panel for the affected target is updated with error message. The task continues to execute.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9BD E302F9BD

Explanation: Error during the main "service" processing for the server side of the change internal code wizard subtasklet.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9BE E302F9BE

Explanation: Error during the main "service" processing for the server side of the change internal code wizard1 panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9BF E302F9BF

Explanation: Error during the main "service" processing for the server side of the change internal code wizard2 panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C0 E302F9C0

Explanation: Error during the main "service" processing for the server side of the change internal code wizard3 panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C1 E302F9C1

Explanation: Error during the main "service" processing for the server side of the change internal code wizard4 panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C2 E302F9C2

Explanation: Error during the main "service" processing for the server side of the change internal code wizard ceconcurrency panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C3 E302F9C3

Explanation: Error during the main "service" processing for the server side of the change internal code wizard cecdetails panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C4 E302F9C4

Explanation: Error during the main "service" processing for the server side of the change internal code wizard fix details panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C5 E302F9C5

Explanation: Error during the main "service" processing for the server side of the change internal code wizard license panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C6 E302F9C6

Explanation: Error during the main "service" processing for the server side of the change internal code wizard leveldetails panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C7 E302F9C7

Explanation: Error during the main processing for the server side of the flash side selection task.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C8 E302F9C8

Explanation: Error during the main "service" processing for the server side of the advanced features subtasklet.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9C9 E302F9C9

Explanation: Error during processing for the advanced features panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9CA E302F9CA

Explanation: Error during processing for the advanced features retrieve panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9CB E302F9CB

Explanation: Error during processing for the advanced features implied retrieve panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9CC E302F9CC

Explanation: Error during processing for the advanced features change levels panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9CD E302F9CD

Explanation: Error during processing for the advanced features select change levels panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9CE E302F9CE

Explanation: Error during processing for the advanced features install type panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9CF E302F9CF

Explanation: Error during processing for the advanced features fix details panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D0 E302F9D0

Explanation: Error during processing for the advanced features confirm panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D1 • E302F9DE

E302F9D1 E302F9D1

Explanation: Error during processing for the advanced features level details panel handler.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D2 E302F9D2

Explanation: Error during the main "service" processing for the server side of the change internal code task. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D3 E302F9D3

Explanation: Error during processing change internal code MainPanel panel handler. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D4 E302F9D4

Explanation: Error during processing change internal code MainRepos panel handler. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D5 E302F9D5

Explanation: Error during processing change internal code InbandMessage panel handler. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D6 E302F9D6

Explanation: Error during processing change internal code FtpPanel panel handler. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D7 E302F9D7

Explanation: Error during processing change internal code ChangeFTP panel handler. The task is terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D8 E302F9D8

Explanation: Error trying to assign values from a SysInfoEcInternalCodeData object.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9D9 E302F9D9

Explanation: Error during the main processing for the server side of the system information task.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9DA E302F9DA

Explanation: Error from getting null presentation task parameters in the system information task.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9DB E302F9DB

Explanation: Error during the processing for the server side SysInfoEcTasklet system information subtask.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9DC E302F9DC

Explanation: Error trying to do the main processing for the client side of the change internal code task. The task has been terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9DD E302F9DD

Explanation: Error trying to do the main processing for the client side of the flash side selection task. The task has been terminated.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9DE E302F9DE

Explanation: Error trying to do the main processing for the client side of the non disruptive firmware update task. The task has been terminated.

Problem determination: Reboot the HMC and retry

the operation. If the problem occurs again, contact your next level of support.

E302F9DF E302F9DF

Explanation: Error during the main processing for the server side of the advanced features subtask.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E0 E302F9E0

Explanation: Error during the main processing for the server side of the advanced targeting subtask.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E1 E302F9E1

Explanation: Error during the main processing for the server side of the Change Internal Code task. This could be the result of an exception being caught by the underlying tasklet infrastructure.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E2 E302F9E2

Explanation: Error during the main processing for the server side of the Nondisruptive Firmware Update task. This could be the result of an exception being caught by the underlying tasklet infrastructure.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E3 E302F9E3

Explanation: Error during the main processing for the server side of the Change Internal Code Wizard subtask. This could be the result of an exception being caught by the underlying tasklet infrastructure.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E4 E302F9E4

Explanation: Error trying to perform some processing in the Advanced Features Bean `panelAction()` method. The bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E5 E302F9E5

Explanation: Error trying to perform some processing in the Advanced Targeting for Frames Bean `panelAction()` method. The bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E6 E302F9E6

Explanation: Error trying to perform some processing in the Advanced Targeting for System Bean `panelAction()` method. The bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E7 E302F9E7

Explanation: Error in the select advanced targeting type bean `panelAction` method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E8 E302F9E8

Explanation: Error in the CEC/power concurrency bean `panelAction` method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9E9 E302F9E9

Explanation: Error in the CEC/power level details bean `panelAction` method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9EA E302F9EA

Explanation: Error in the change FTP directory bean `panelAction` method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9EB E302F9EB

Explanation: Error in the specify levels bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9EC E302F9EC

Explanation: Error in the advanced features confirm bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9ED E302F9ED

Explanation: Error in the LIC details bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9EE E302F9EE

Explanation: Error in the flash side selection bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9EF E302F9EF

Explanation: Error in the FTP site access bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F0 E302F9F0

Explanation: Error in the advanced features install and activate (implied retrieval) bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F1 E302F9F1

Explanation: Error in the inband configuration detected bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F2 E302F9F2

Explanation: Error in the advanced features select installation type bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F3 E302F9F3

Explanation: Error in the confirmation level details bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F4 E302F9F4

Explanation: Error in the license agreement bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F5 E302F9F5

Explanation: Error in the change internal code main bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F6 E302F9F6

Explanation: Error in the change internal code main repos bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F7 E302F9F7

Explanation: Error in the nondisruptive firmware update bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F8 E302F9F8

Explanation: Error in the advanced features retrieve bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9F9 E302F9F9

Explanation: Error in the select advanced targeting frame choice bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9FA E302F9FA

Explanation: Error in the advanced features select level bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9FB E302F9FB

Explanation: Error in the system information bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9FC E302F9FC

Explanation: Error in the change internal code wizard1 bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9FD E302F9FD

Explanation: Error in the change internal code wizard2 bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9FE E302F9FE

Explanation: Error in the change internal code wizard3 bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

E302F9FF E302F9FF

Explanation: Error in the change internal code wizard4 bean panelAction method. This bean attempts to close the panel.

Problem determination: Reboot the HMC and retry the operation. If the problem occurs again, contact your next level of support.

(E302FAxx) Reference codes

E302FA00 **E302FA00**

Explanation: An error occurred while attempting to synchronize one service processor to the other during a repair and verify operation.

Problem determination: Ensure that the entire repair and verify procedure executed correctly and that the new service processor is communicating properly. If the error continues to occur, contact your next level of support.

E302FA01 **E302FA01**

Explanation: An error occurred while attempting to determine which service processor is the source and which one is the destination for a repair and verify operation.

Problem determination: Ensure that the entire repair and verify procedure executed correctly and that the new service processor is communicating properly. If the error continues to occur, contact your next level of support.

E302FA02 **E302FA02**

Explanation: An error occurred while attempting to create a targeted service processor object during a repair and verify operation.

Problem determination: Ensure that the entire repair and verify procedure executed correctly and that the new service processor is communicating properly. If the error continues to occur, contact your next level of support.

E302FA03 **E302FA03**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA04 **E302FA04**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA05 **E302FA05**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA06 **E302FA06**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA07 **E302FA07**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA08 **E302FA08**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA09 **E302FA09**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA0A **E302FA0A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA0B **E302FA0B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA0C **E302FA0C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA0D • E302FA1C

E302FA0D E302FA0D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA0E E302FA0E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA0F E302FA0F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA10 E302FA10

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA11 E302FA11

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA12 E302FA12

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA13 E302FA13

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA14 E302FA14

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA15 E302FA15

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA16 E302FA16

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA17 E302FA17

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA18 E302FA18

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA19 E302FA19

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA1A E302FA1A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA1B E302FA1B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA1C E302FA1C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA1D E302FA1D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA1E E302FA1E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA1F E302FA1F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA20 E302FA20

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA21 E302FA21

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA22 E302FA22

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA23 E302FA23

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA24 E302FA24

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA25 E302FA25

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA26 E302FA26

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA27 E302FA27

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA28 E302FA28

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA29 E302FA29

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA2A E302FA2A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA2B E302FA2B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA2C E302FA2C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA2D • E302FA3C

E302FA2D E302FA2D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA2E E302FA2E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA2F E302FA2F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA30 E302FA30

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA31 E302FA31

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA32 E302FA32

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA33 E302FA33

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA34 E302FA34

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA35 E302FA35

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA36 E302FA36

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA37 E302FA37

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA38 E302FA38

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA39 E302FA39

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA3A E302FA3A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA3B E302FA3B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA3C E302FA3C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA3D E302FA3D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA3E E302FA3E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA3F E302FA3F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA40 E302FA40

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA41 E302FA41

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA42 E302FA42

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA43 E302FA43

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA44 E302FA44

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA45 E302FA45

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA46 E302FA46

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA47 E302FA47

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA48 E302FA48

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA49 E302FA49

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA4A E302FA4A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA4B E302FA4B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA4C E302FA4C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA4D • E302FA5C

E302FA4D E302FA4D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA4E E302FA4E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA4F E302FA4F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA50 E302FA50

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA51 E302FA51

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA52 E302FA52

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA53 E302FA53

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA54 E302FA54

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA55 E302FA55

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA56 E302FA56

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA57 E302FA57

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA58 E302FA58

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA59 E302FA59

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA5A E302FA5A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA5B E302FA5B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA5C E302FA5C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA5D E302FA5D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA5E E302FA5E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA5F E302FA5F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA60 E302FA60

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA61 E302FA61

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA62 E302FA62

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA63 E302FA63

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA64 E302FA64

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA65 E302FA65

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA66 E302FA66

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA67 E302FA67

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA68 E302FA68

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA69 E302FA69

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA6A E302FA6A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA6B E302FA6B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA6C E302FA6C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA6D • E302FA7C

E302FA6D E302FA6D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA6E E302FA6E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA6F E302FA6F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA70 E302FA70

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA71 E302FA71

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA72 E302FA72

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA73 E302FA73

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA74 E302FA74

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA75 E302FA75

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA76 E302FA76

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA77 E302FA77

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA78 E302FA78

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA79 E302FA79

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA7A E302FA7A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA7B E302FA7B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA7C E302FA7C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA7D E302FA7D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA7E E302FA7E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA7F E302FA7F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA80 E302FA80

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA81 E302FA81

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA82 E302FA82

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA83 E302FA83

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA84 E302FA84

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA85 E302FA85

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA86 E302FA86

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA87 E302FA87

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA88 E302FA88

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA89 E302FA89

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA8A E302FA8A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA8B E302FA8B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA8C E302FA8C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA8D • E302FA9C

E302FA8D E302FA8D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA8E E302FA8E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA8F E302FA8F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA90 E302FA90

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA91 E302FA91

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA92 E302FA92

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA93 E302FA93

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA94 E302FA94

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA95 E302FA95

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA96 E302FA96

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA97 E302FA97

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA98 E302FA98

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA99 E302FA99

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA9A E302FA9A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA9B E302FA9B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA9C E302FA9C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA9D E302FA9D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA9E E302FA9E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FA9F E302FA9F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA0 E302FAA0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA1 E302FAA1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA2 E302FAA2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA3 E302FAA3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA4 E302FAA4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA5 E302FAA5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA6 E302FAA6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA7 E302FAA7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA8 E302FAA8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAA9 E302FAA9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAAA E302FAAA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAAB E302FAAB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAAC E302FAAC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAAD • E302FABC

E302FAAD E302FAAD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAAE E302FAAE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAAF E302FAAF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB0 E302FAB0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB1 E302FAB1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB2 E302FAB2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB3 E302FAB3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB4 E302FAB4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB5 E302FAB5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB6 E302FAB6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB7 E302FAB7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB8 E302FAB8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAB9 E302FAB9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FABA E302FABA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FABB E302FABB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FABC E302FABC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FABD E302FABD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FABE E302FABE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FABF E302FABF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC0 E302FAC0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC1 E302FAC1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC2 E302FAC2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC3 E302FAC3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC4 E302FAC4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC5 E302FAC5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC6 E302FAC6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC7 E302FAC7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC8 E302FAC8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAC9 E302FAC9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FACA E302FACA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FACB E302FACB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FACC E302FACC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FACD • E302FADC

E302FACD E302FACD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FACE E302FACE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FACF E302FACF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD0 E302FAD0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD1 E302FAD1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD2 E302FAD2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD3 E302FAD3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD4 E302FAD4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD5 E302FAD5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD6 E302FAD6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD7 E302FAD7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD8 E302FAD8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAD9 E302FAD9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FADA E302FADA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FADB E302FADB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FADC E302FADC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FADD E302FADD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FADE E302FADE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FADF E302FADF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE0 E302FAE0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE1 E302FAE1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE2 E302FAE2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE3 E302FAE3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE4 E302FAE4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE5 E302FAE5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE6 E302FAE6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE7 E302FAE7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE8 E302FAE8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAE9 E302FAE9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAEA E302FAEA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAEB E302FAEB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAEC E302FAEC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAED • E302FAFC

E302FAED E302FAED

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAEE E302FAEE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAEF E302FAEF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF0 E302FAF0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF1 E302FAF1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF2 E302FAF2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF3 E302FAF3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF4 E302FAF4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF5 E302FAF5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF6 E302FAF6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF7 E302FAF7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF8 E302FAF8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAF9 E302FAF9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAFA E302FAFA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAFB E302FAFB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAFC E302FAFC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAFD E302FAFD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAFE E302FAFE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FAFF E302FAFF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E302FBxx) Reference codes

E302FB00 **E302FB00**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB01 **E302FB01**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB02 **E302FB02**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB03 **E302FB03**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB04 **E302FB04**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB05 **E302FB05**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB06 **E302FB06**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB07 **E302FB07**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB08 **E302FB08**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB09 **E302FB09**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB0A **E302FB0A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB0B **E302FB0B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB0C **E302FB0C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB0D **E302FB0D**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB0E **E302FB0E**

Explanation: Licensed Internal Code failure on the HMC.

E302FB0F • E302FB1D

Problem determination: Contact your service provider.

E302FB0F E302FB0F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB10 E302FB10

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB11 E302FB11

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB12 E302FB12

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB13 E302FB13

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB14 E302FB14

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB15 E302FB15

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB16 E302FB16

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB17 E302FB17

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB18 E302FB18

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB19 E302FB19

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB1A E302FB1A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB1B E302FB1B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB1C E302FB1C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB1D E302FB1D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB1E E302FB1E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB1F E302FB1F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB20 E302FB20

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB21 E302FB21

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB22 E302FB22

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB23 E302FB23

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB24 E302FB24

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB25 E302FB25

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB26 E302FB26

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB27 E302FB27

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB28 E302FB28

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB29 E302FB29

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB2A E302FB2A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB2B E302FB2B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB2C E302FB2C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB2D E302FB2D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB2E • E302FB3D

E302FB2E E302FB2E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB2F E302FB2F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB30 E302FB30

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB31 E302FB31

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB32 E302FB32

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB33 E302FB33

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB34 E302FB34

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB35 E302FB35

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB36 E302FB36

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB37 E302FB37

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB38 E302FB38

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB39 E302FB39

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB3A E302FB3A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB3B E302FB3B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB3C E302FB3C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB3D E302FB3D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB3E E302FB3E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB3F E302FB3F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB40 E302FB40

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB41 E302FB41

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB42 E302FB42

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB43 E302FB43

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB44 E302FB44

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB45 E302FB45

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB46 E302FB46

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB47 E302FB47

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB48 E302FB48

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB49 E302FB49

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB4A E302FB4A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB4B E302FB4B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB4C E302FB4C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB4D E302FB4D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB4E • E302FB5D

E302FB4E E302FB4E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB4F E302FB4F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB50 E302FB50

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB51 E302FB51

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB52 E302FB52

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB53 E302FB53

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB54 E302FB54

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB55 E302FB55

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB56 E302FB56

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB57 E302FB57

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB58 E302FB58

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB59 E302FB59

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB5A E302FB5A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB5B E302FB5B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB5C E302FB5C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB5D E302FB5D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB5E E302FB5E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB5F E302FB5F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB60 E302FB60

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB61 E302FB61

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB62 E302FB62

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB63 E302FB63

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB64 E302FB64

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB65 E302FB65

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB66 E302FB66

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB67 E302FB67

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB68 E302FB68

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB69 E302FB69

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB6A E302FB6A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB6B E302FB6B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB6C E302FB6C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB6D E302FB6D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB6E • E302FB7D

E302FB6E E302FB6E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB6F E302FB6F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB70 E302FB70

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB71 E302FB71

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB72 E302FB72

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB73 E302FB73

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB74 E302FB74

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB75 E302FB75

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB76 E302FB76

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB77 E302FB77

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB78 E302FB78

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB79 E302FB79

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB7A E302FB7A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB7B E302FB7B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB7C E302FB7C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB7D E302FB7D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB7E E302FB7E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB7F E302FB7F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB80 E302FB80

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB81 E302FB81

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB82 E302FB82

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB83 E302FB83

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB84 E302FB84

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB85 E302FB85

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB86 E302FB86

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB87 E302FB87

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB88 E302FB88

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB89 E302FB89

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB8A E302FB8A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB8B E302FB8B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB8C E302FB8C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB8D E302FB8D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB8E • E302FB9D

E302FB8E E302FB8E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB8F E302FB8F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB90 E302FB90

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB91 E302FB91

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB92 E302FB92

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB93 E302FB93

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB94 E302FB94

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB95 E302FB95

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB96 E302FB96

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB97 E302FB97

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB98 E302FB98

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB99 E302FB99

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB9A E302FB9A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB9B E302FB9B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB9C E302FB9C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB9D E302FB9D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB9E E302FB9E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FB9F E302FB9F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA0 E302FBA0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA1 E302FBA1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA2 E302FBA2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA3 E302FBA3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA4 E302FBA4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA5 E302FBA5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA6 E302FBA6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA7 E302FBA7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA8 E302FBA8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBA9 E302FBA9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBAA E302FBAA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBAB E302FBAB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBAC E302FBAC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBAD E302FBAD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBAE • E302FBB0

E302FBAE E302FBAE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBAF E302FBAF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB0 E302FBB0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB1 E302FBB1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB2 E302FBB2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB3 E302FBB3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB4 E302FBB4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB5 E302FBB5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB6 E302FBB6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB7 E302FBB7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB8 E302FBB8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBB9 E302FBB9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBBA E302FBBA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBBB E302FBBB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBBC E302FBBC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBBD E302FBBD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBBE E302FBBE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBBF E302FBBF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC0 E302FBC0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC1 E302FBC1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC2 E302FBC2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC3 E302FBC3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC4 E302FBC4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC5 E302FBC5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC6 E302FBC6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC7 E302FBC7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC8 E302FBC8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBC9 E302FBC9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBCA E302FBCA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBCB E302FBCB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBCC E302FBCC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBCD E302FBCD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBCE • E302FBDD

E302FBCE E302FBCE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBCF E302FBCF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD0 E302FBD0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD1 E302FBD1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD2 E302FBD2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD3 E302FBD3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD4 E302FBD4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD5 E302FBD5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD6 E302FBD6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD7 E302FBD7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD8 E302FBD8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBD9 E302FBD9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBDA E302FBDA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBDB E302FBDB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBDC E302FBDC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBDD E302FBDD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBDE E302FBDE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBDF E302FBDF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE0 E302FBE0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE1 E302FBE1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE2 E302FBE2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE3 E302FBE3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE4 E302FBE4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE5 E302FBE5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE6 E302FBE6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE7 E302FBE7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE8 E302FBE8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBE9 E302FBE9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBEA E302FBEA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBEB E302FBEB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBEC E302FBEC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBED E302FBED

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBEE • E302FBFD

E302FBEE E302FBEE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBEF E302FBEF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF0 E302FBF0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF1 E302FBF1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF2 E302FBF2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF3 E302FBF3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF4 E302FBF4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF5 E302FBF5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF6 E302FBF6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF7 E302FBF7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF8 E302FBF8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBF9 E302FBF9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBFA E302FBFA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBFB E302FBFB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBFC E302FBFC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBFD E302FBFD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBFE E302FBFE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FBFF E302FBFF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E302FCxx) Reference codes

E302FC00 E302FC00

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC01 E302FC01

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC02 E302FC02

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC03 E302FC03

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC04 E302FC04

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC05 E302FC05

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC06 E302FC06

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC07 E302FC07

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC08 E302FC08

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC09 E302FC09

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC0A E302FC0A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC0B E302FC0B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC0C E302FC0C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC0D E302FC0D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC0E E302FC0E

Explanation: Licensed Internal Code failure on the HMC.

E302FC0F • E302FC1D

Problem determination: Contact your service provider.

E302FC0F E302FC0F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC10 E302FC10

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC11 E302FC11

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC12 E302FC12

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC13 E302FC13

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC14 E302FC14

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC15 E302FC15

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC16 E302FC16

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC17 E302FC17

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC18 E302FC18

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC19 E302FC19

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC1A E302FC1A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC1B E302FC1B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC1C E302FC1C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC1D E302FC1D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC1E E302FC1E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC1F E302FC1F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC20 E302FC20

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC21 E302FC21

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC22 E302FC22

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC23 E302FC23

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC24 E302FC24

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC25 E302FC25

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC26 E302FC26

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC27 E302FC27

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC28 E302FC28

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC29 E302FC29

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC2A E302FC2A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC2B E302FC2B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC2C E302FC2C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC2D E302FC2D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC2E • E302FC3D

E302FC2E E302FC2E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC2F E302FC2F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC30 E302FC30

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC31 E302FC31

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC32 E302FC32

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC33 E302FC33

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC34 E302FC34

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC35 E302FC35

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC36 E302FC36

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC37 E302FC37

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC38 E302FC38

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC39 E302FC39

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC3A E302FC3A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC3B E302FC3B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC3C E302FC3C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC3D E302FC3D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC3E E302FC3E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC3F E302FC3F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC40 E302FC40

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC41 E302FC41

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC42 E302FC42

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC43 E302FC43

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC44 E302FC44

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC45 E302FC45

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC46 E302FC46

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC47 E302FC47

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC48 E302FC48

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC49 E302FC49

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC4A E302FC4A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC4B E302FC4B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC4C E302FC4C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC4D E302FC4D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC4E • E302FC5D

E302FC4E E302FC4E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC4F E302FC4F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC50 E302FC50

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC51 E302FC51

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC52 E302FC52

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC53 E302FC53

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC54 E302FC54

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC55 E302FC55

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC56 E302FC56

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC57 E302FC57

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC58 E302FC58

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC59 E302FC59

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC5A E302FC5A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC5B E302FC5B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC5C E302FC5C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC5D E302FC5D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC5E E302FC5E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC5F E302FC5F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC60 E302FC60

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC61 E302FC61

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC62 E302FC62

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC63 E302FC63

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC64 E302FC64

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC65 E302FC65

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC66 E302FC66

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC67 E302FC67

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC68 E302FC68

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC69 E302FC69

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC6A E302FC6A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC6B E302FC6B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC6C E302FC6C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC6D E302FC6D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC6E • E302FC7D

E302FC6E E302FC6E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC6F E302FC6F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC70 E302FC70

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC71 E302FC71

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC72 E302FC72

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC73 E302FC73

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC74 E302FC74

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC75 E302FC75

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC76 E302FC76

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC77 E302FC77

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC78 E302FC78

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC79 E302FC79

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC7A E302FC7A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC7B E302FC7B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC7C E302FC7C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC7D E302FC7D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC7E E302FC7E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC7F E302FC7F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC80 E302FC80

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC81 E302FC81

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC82 E302FC82

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC83 E302FC83

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC84 E302FC84

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC85 E302FC85

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC86 E302FC86

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC87 E302FC87

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC88 E302FC88

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC89 E302FC89

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC8A E302FC8A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC8B E302FC8B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC8C E302FC8C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC8D E302FC8D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC8E • E302FC9D

E302FC8E E302FC8E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC8F E302FC8F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC90 E302FC90

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC91 E302FC91

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC92 E302FC92

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC93 E302FC93

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC94 E302FC94

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC95 E302FC95

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC96 E302FC96

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC97 E302FC97

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC98 E302FC98

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC99 E302FC99

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC9A E302FC9A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC9B E302FC9B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC9C E302FC9C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC9D E302FC9D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC9E E302FC9E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FC9F E302FC9F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA0 E302FCA0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA1 E302FCA1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA2 E302FCA2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA3 E302FCA3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA4 E302FCA4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA5 E302FCA5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA6 E302FCA6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA7 E302FCA7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA8 E302FCA8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCA9 E302FCA9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCAA E302FCAA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCAB E302FCAB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCAC E302FCAC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCAD E302FCAD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCAE • E302FCBD

E302FCAE E302FCAE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCAF E302FCAF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB0 E302FCB0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB1 E302FCB1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB2 E302FCB2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB3 E302FCB3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB4 E302FCB4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB5 E302FCB5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB6 E302FCB6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB7 E302FCB7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB8 E302FCB8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCB9 E302FCB9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCBA E302FCBA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCBB E302FCBB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCBC E302FCBC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCBD E302FCBD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCBE E302FCBE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCBF E302FCBF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC0 E302FCC0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC1 E302FCC1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC2 E302FCC2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC3 E302FCC3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC4 E302FCC4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC5 E302FCC5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC6 E302FCC6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC7 E302FCC7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC8 E302FCC8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCC9 E302FCC9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCCA E302FCCA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCCB E302FCCB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCCC E302FCCC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCCD E302FCCD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCCE • E302FCDD

E302FCCE E302FCCE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCCF E302FCCF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD0 E302FCD0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD1 E302FCD1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD2 E302FCD2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD3 E302FCD3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD4 E302FCD4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD5 E302FCD5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD6 E302FCD6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD7 E302FCD7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD8 E302FCD8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCD9 E302FCD9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCDA E302FCDA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCDB E302FCDB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCDC E302FCDC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCDD E302FCDD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCDE E302FCDE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCDF E302FCDF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE0 E302FCE0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE1 E302FCE1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE2 E302FCE2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE3 E302FCE3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE4 E302FCE4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE5 E302FCE5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE6 E302FCE6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE7 E302FCE7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE8 E302FCE8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCE9 E302FCE9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCEA E302FCEA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCEB E302FCEB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCEC E302FCEC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCED E302FCED

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCEE • E302FCFD

E302FCEE E302FCEE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCEF E302FCEF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF0 E302FCF0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF1 E302FCF1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF2 E302FCF2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF3 E302FCF3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF4 E302FCF4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF5 E302FCF5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF6 E302FCF6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF7 E302FCF7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF8 E302FCF8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCF9 E302FCF9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCFA E302FCFA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCFB E302FCFB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCFC E302FCFC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCFD E302FCFD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCFE E302FCFE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FCFF E302FCFF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E302FDxx) Reference codes

E302FD00 E302FD00

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD01 E302FD01

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD02 E302FD02

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD03 E302FD03

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD04 E302FD04

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD05 E302FD05

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD06 E302FD06

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD07 E302FD07

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD08 E302FD08

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD09 E302FD09

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD0A E302FD0A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD0B E302FD0B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD0C E302FD0C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD0D E302FD0D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD0E E302FD0E

Explanation: Licensed Internal Code failure on the HMC.

E302FD0F • E302FD1D

Problem determination: Contact your service provider.

E302FD0F **E302FD0F**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD10 **E302FD10**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD11 **E302FD11**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD12 **E302FD12**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD13 **E302FD13**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD14 **E302FD14**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD15 **E302FD15**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD16 **E302FD16**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD17 **E302FD17**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD18 **E302FD18**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD19 **E302FD19**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD1A **E302FD1A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD1B **E302FD1B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD1C **E302FD1C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD1D **E302FD1D**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD1E E302FD1E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD1F E302FD1F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD20 E302FD20

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD21 E302FD21

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD22 E302FD22

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD23 E302FD23

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD24 E302FD24

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD25 E302FD25

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD26 E302FD26

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD27 E302FD27

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD28 E302FD28

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD29 E302FD29

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD2A E302FD2A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD2B E302FD2B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD2C E302FD2C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD2D E302FD2D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD2E • E302FD3D

E302FD2E E302FD2E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD2F E302FD2F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD30 E302FD30

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD31 E302FD31

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD32 E302FD32

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD33 E302FD33

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD34 E302FD34

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD35 E302FD35

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD36 E302FD36

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD37 E302FD37

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD38 E302FD38

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD39 E302FD39

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD3A E302FD3A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD3B E302FD3B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD3C E302FD3C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD3D E302FD3D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD3E E302FD3E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD3F E302FD3F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD40 E302FD40

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD41 E302FD41

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD42 E302FD42

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD43 E302FD43

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD44 E302FD44

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD45 E302FD45

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD46 E302FD46

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD47 E302FD47

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD48 E302FD48

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD49 E302FD49

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD4A E302FD4A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD4B E302FD4B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD4C E302FD4C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD4D E302FD4D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD4E • E302FD5D

E302FD4E E302FD4E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD4F E302FD4F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD50 E302FD50

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD51 E302FD51

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD52 E302FD52

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD53 E302FD53

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD54 E302FD54

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD55 E302FD55

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD56 E302FD56

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD57 E302FD57

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD58 E302FD58

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD59 E302FD59

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD5A E302FD5A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD5B E302FD5B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD5C E302FD5C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD5D E302FD5D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD5E E302FD5E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD5F E302FD5F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD60 E302FD60

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD61 E302FD61

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD62 E302FD62

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD63 E302FD63

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD64 E302FD64

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD65 E302FD65

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD66 E302FD66

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD67 E302FD67

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD68 E302FD68

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD69 E302FD69

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD6A E302FD6A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD6B E302FD6B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD6C E302FD6C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD6D E302FD6D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD6E • E302FD7D

E302FD6E E302FD6E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD6F E302FD6F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD70 E302FD70

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD71 E302FD71

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD72 E302FD72

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD73 E302FD73

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD74 E302FD74

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD75 E302FD75

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD76 E302FD76

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD77 E302FD77

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD78 E302FD78

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD79 E302FD79

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD7A E302FD7A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD7B E302FD7B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD7C E302FD7C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD7D E302FD7D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD7E E302FD7E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD7F E302FD7F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD80 E302FD80

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD81 E302FD81

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD82 E302FD82

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD83 E302FD83

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD84 E302FD84

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD85 E302FD85

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD86 E302FD86

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD87 E302FD87

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD88 E302FD88

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD89 E302FD89

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD8A E302FD8A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD8B E302FD8B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD8C E302FD8C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD8D E302FD8D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD8E • E302FD9D

E302FD8E E302FD8E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD8F E302FD8F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD90 E302FD90

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD91 E302FD91

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD92 E302FD92

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD93 E302FD93

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD94 E302FD94

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD95 E302FD95

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD96 E302FD96

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD97 E302FD97

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD98 E302FD98

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD99 E302FD99

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD9A E302FD9A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD9B E302FD9B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD9C E302FD9C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD9D E302FD9D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD9E E302FD9E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD9F E302FD9F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA0 E302FDA0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA1 E302FDA1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA2 E302FDA2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA3 E302FDA3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA4 E302FDA4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA5 E302FDA5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA6 E302FDA6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA7 E302FDA7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA8 E302FDA8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDA9 E302FDA9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDAA E302FDAA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDAB E302FDAB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDAC E302FDAC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDAD E302FDAD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDAE • E302FDBD

E302FDAE E302FDAE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDAF E302FDAF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB0 E302FDB0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB1 E302FDB1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB2 E302FDB2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB3 E302FDB3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB4 E302FDB4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB5 E302FDB5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB6 E302FDB6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB7 E302FDB7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB8 E302FDB8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDB9 E302FDB9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDDBA E302FDDBA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDBBB E302FDBBB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDBCB E302FDBCB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDBDB E302FDBDB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDBE E302FDBE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDBF E302FDBF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC0 E302FDC0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC1 E302FDC1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC2 E302FDC2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC3 E302FDC3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC4 E302FDC4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC5 E302FDC5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC6 E302FDC6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC7 E302FDC7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC8 E302FDC8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDC9 E302FDC9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDCA E302FDCA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDCB E302FDCB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDCC E302FDCC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDCD E302FDCD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDCE • E302FDDD

E302FDCE E302FDCE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDCF E302FDCF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD0 E302FDD0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD1 E302FDD1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD2 E302FDD2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD3 E302FDD3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD4 E302FDD4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD5 E302FDD5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD6 E302FDD6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD7 E302FDD7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD8 E302FDD8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDD9 E302FDD9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDDA E302FDDA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDDB E302FDDB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDDC E302FDDC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDDD E302FDDD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDDE E302FDDE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDDE E302FDDE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE0 E302FDE0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE1 E302FDE1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE2 E302FDE2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE3 E302FDE3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE4 E302FDE4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE5 E302FDE5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE6 E302FDE6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE7 E302FDE7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE8 E302FDE8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDE9 E302FDE9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDEA E302FDEA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDEB E302FDEB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDEC E302FDEC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDED E302FDED

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDEE • E302FDFD

E302FDEE **E302FDEE**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDEF **E302FDEF**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF0 **E302FDF0**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF1 **E302FDF1**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF2 **E302FDF2**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF3 **E302FDF3**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF4 **E302FDF4**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF5 **E302FDF5**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF6 **E302FDF6**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF7 **E302FDF7**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF8 **E302FDF8**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDF9 **E302FDF9**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDFA **E302FDFA**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDFB **E302FDFB**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDFC **E302FDFC**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FDFD **E302FDFD**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD FE E302FD FE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FD FF E302FD FF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E302FExx) Reference codes

E302FE00 E302FE00

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE01 E302FE01

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE02 E302FE02

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE03 E302FE03

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE04 E302FE04

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE05 E302FE05

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE06 E302FE06

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE07 E302FE07

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE08 E302FE08

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE09 E302FE09

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE0A E302FE0A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE0B E302FE0B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE0C E302FE0C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE0D E302FE0D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE0E E302FE0E

Explanation: Licensed Internal Code failure on the HMC.

E302FE0F • E302FE1D

Problem determination: Contact your service provider.

E302FE0F E302FE0F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE10 E302FE10

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE11 E302FE11

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE12 E302FE12

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE13 E302FE13

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE14 E302FE14

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE15 E302FE15

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE16 E302FE16

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE17 E302FE17

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE18 E302FE18

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE19 E302FE19

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE1A E302FE1A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE1B E302FE1B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE1C E302FE1C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE1D E302FE1D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE1E E302FE1E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE1F E302FE1F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE20 E302FE20

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE21 E302FE21

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE22 E302FE22

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE23 E302FE23

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE24 E302FE24

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE25 E302FE25

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE26 E302FE26

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE27 E302FE27

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE28 E302FE28

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE29 E302FE29

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE2A E302FE2A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE2B E302FE2B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE2C E302FE2C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE2D E302FE2D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE2E • E302FE3D

E302FE2E E302FE2E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE2F E302FE2F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE30 E302FE30

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE31 E302FE31

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE32 E302FE32

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE33 E302FE33

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE34 E302FE34

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE35 E302FE35

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE36 E302FE36

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE37 E302FE37

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE38 E302FE38

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE39 E302FE39

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE3A E302FE3A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE3B E302FE3B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE3C E302FE3C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE3D E302FE3D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE3E E302FE3E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE3F E302FE3F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE40 E302FE40

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE41 E302FE41

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE42 E302FE42

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE43 E302FE43

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE44 E302FE44

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE45 E302FE45

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE46 E302FE46

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE47 E302FE47

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE48 E302FE48

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE49 E302FE49

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE4A E302FE4A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE4B E302FE4B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE4C E302FE4C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE4D E302FE4D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE4E • E302FE5D

E302FE4E E302FE4E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE4F E302FE4F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE50 E302FE50

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE51 E302FE51

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE52 E302FE52

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE53 E302FE53

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE54 E302FE54

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE55 E302FE55

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE56 E302FE56

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE57 E302FE57

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE58 E302FE58

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE59 E302FE59

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE5A E302FE5A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE5B E302FE5B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE5C E302FE5C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE5D E302FE5D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE5E E302FE5E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE5F E302FE5F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE60 E302FE60

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE61 E302FE61

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE62 E302FE62

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE63 E302FE63

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE64 E302FE64

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE65 E302FE65

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE66 E302FE66

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE67 E302FE67

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE68 E302FE68

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE69 E302FE69

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE6A E302FE6A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE6B E302FE6B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE6C E302FE6C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE6D E302FE6D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE6E • E302FE7D

E302FE6E **E302FE6E**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE6F **E302FE6F**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE70 **E302FE70**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE71 **E302FE71**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE72 **E302FE72**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE73 **E302FE73**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE74 **E302FE74**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE75 **E302FE75**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE76 **E302FE76**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE77 **E302FE77**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE78 **E302FE78**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE79 **E302FE79**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE7A **E302FE7A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE7B **E302FE7B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE7C **E302FE7C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE7D **E302FE7D**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE7E E302FE7E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE7F E302FE7F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE80 E302FE80

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE81 E302FE81

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE82 E302FE82

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE83 E302FE83

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE84 E302FE84

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE85 E302FE85

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE86 E302FE86

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE87 E302FE87

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE88 E302FE88

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE89 E302FE89

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE8A E302FE8A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE8B E302FE8B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE8C E302FE8C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE8D E302FE8D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE8E • E302FE9D

E302FE8E **E302FE8E**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE8F **E302FE8F**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE90 **E302FE90**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE91 **E302FE91**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE92 **E302FE92**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE93 **E302FE93**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE94 **E302FE94**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE95 **E302FE95**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE96 **E302FE96**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE97 **E302FE97**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE98 **E302FE98**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE99 **E302FE99**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE9A **E302FE9A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE9B **E302FE9B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE9C **E302FE9C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE9D **E302FE9D**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE9E E302FE9E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FE9F E302FE9F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA0 E302FEA0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA1 E302FEA1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA2 E302FEA2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA3 E302FEA3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA4 E302FEA4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA5 E302FEA5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA6 E302FEA6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA7 E302FEA7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA8 E302FEA8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEA9 E302FEA9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEAA E302FEAA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEAB E302FEAB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEAC E302FEAC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEAD E302FEAD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEAE • E302FEBD

E302FEAE E302FEAE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEAF E302FEAF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB0 E302FEB0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB1 E302FEB1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB2 E302FEB2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB3 E302FEB3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB4 E302FEB4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB5 E302FEB5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB6 E302FEB6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB7 E302FEB7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB8 E302FEB8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEB9 E302FEB9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEBA E302FEBA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEBB E302FEBB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEBC E302FEBC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEBD E302FEBD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEBE E302FEBE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEBF E302FEBF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC0 E302FEC0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC1 E302FEC1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC2 E302FEC2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC3 E302FEC3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC4 E302FEC4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC5 E302FEC5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC6 E302FEC6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC7 E302FEC7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC8 E302FEC8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEC9 E302FEC9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FECA E302FECA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FECB E302FECB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FECC E302FECC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FECD E302FECD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FECE • E302FEDD

E302FECE E302FECE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FECE E302FECE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED0 E302FED0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED1 E302FED1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED2 E302FED2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED3 E302FED3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED4 E302FED4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED5 E302FED5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED6 E302FED6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED7 E302FED7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED8 E302FED8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FED9 E302FED9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEDA E302FEDA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEDB E302FEDB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEDC E302FEDC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEDD E302FEDD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEDE E302FEDE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEDF E302FEDF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE0 E302FEE0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE1 E302FEE1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE2 E302FEE2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE3 E302FEE3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE4 E302FEE4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE5 E302FEE5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE6 E302FEE6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE7 E302FEE7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE8 E302FEE8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEE9 E302FEE9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEEA E302FEEA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEEB E302FEEB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEEC E302FEEC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEED E302FEED

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEEE • E302FEFD

E302FEEE E302FEEE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEFF E302FEFF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF0 E302FEF0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF1 E302FEF1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF2 E302FEF2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF3 E302FEF3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF4 E302FEF4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF5 E302FEF5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF6 E302FEF6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF7 E302FEF7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF8 E302FEF8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEF9 E302FEF9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEFA E302FEFA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEFB E302FEFB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEFC E302FEFC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEFD E302FEFD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEFE E302FEFE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FEFF E302FEFF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E302FFxx) Reference codes

E302FF00 E302FF00

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF01 E302FF01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Change Console Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Change Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302FF02 E302FF02

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Change Console Internal Code task action handler. The Change Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302FF03 E302FF03

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Change Console Internal Code task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Change Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302FF04 E302FF04

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main "service" processing for server side of the Change Console Internal Code task. The Change Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302FF05 E302FF05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main panel handler (ChgIntCodePanelHandler) "service" processing for server side of the Change Console Internal Code task. The Change Console Internal Code task has been ended.

Problem determination: Call your next level of support.

E302FF06 E302FF06

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF07 E302FF07

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF08 E302FF08

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panel handler (RetrieveIntCodePanelHandler) "service" processing for server side of the Change Console Internal Code task while trying to read FTP persisted data with the persistence manager. Either no FTP values have been persisted yet, or some unexpected error occurred with the persistence manager. This is an informational log. Processing continues without any prefilled values on the FTP panel.

Problem determination: Call your next level of support.

E302FF09 E302FF09

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panel handler (FtpPanelHandler) "service" processing for server side

E302FF0A • E302FF17

of the Change Console Internal Code task while trying to write FTP panel values using the persistence manager. This is an informational log. Processing continues without the FTP values being persisted.

Problem determination: Call your next level of support.

E302FF0A E302FF0A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while processing MCL alerts prior to an install and activate.

Problem determination: Call your next level of support.

E302FF0B E302FF0B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while processing MCL alerts prior to an install and activate.

Problem determination: Call your next level of support.

E302FF0C E302FF0C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF0D E302FF0D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF0E E302FF0E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF0F E302FF0F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF10 E302FF10

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF11 E302FF11

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF12 E302FF12

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF13 E302FF13

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF14 E302FF14

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF15 E302FF15

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF16 E302FF16

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF17 E302FF17

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF18 **E302FF18**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF19 **E302FF19**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF1A **E302FF1A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF1B **E302FF1B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF1C **E302FF1C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF1D **E302FF1D**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF1E **E302FF1E**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF1F **E302FF1F**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF20 **E302FF20**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Change Console Internal Code subtasklet for handling configuration specific internal code fixes. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Change Console Config Specific subtasklet has been ended.

Problem determination: Call your next level of support.

E302FF21 **E302FF21**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the main "service" processing for server side of the Change Console Internal Code subtasklet for handling configuration specific internal code fixes. The Change Console Config Specific subtasklet has been ended.

Problem determination: Call your next level of support.

E302FF22 **E302FF22**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panelAction processing for common code of the ChangeFTPDirectoryBean for handling configuration specific internal code fixes.

Problem determination: Call your next level of support.

E302FF23 **E302FF23**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the panelAction processing for common code of the FTPSiteBean for handling configuration specific internal code fixes.

Problem determination: Call your next level of support.

E302FF24 **E302FF24**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF25 • E302FF34

E302FF25 E302FF25

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF26 E302FF26

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF27 E302FF27

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF28 E302FF28

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF29 E302FF29

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF2A E302FF2A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF2B E302FF2B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF2C E302FF2C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF2D E302FF2D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF2E E302FF2E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF2F E302FF2F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF30 E302FF30

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF31 E302FF31

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF32 E302FF32

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF33 E302FF33

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF34 E302FF34

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF35 E302FF35

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF36 E302FF36

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF37 E302FF37

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF38 E302FF38

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF39 E302FF39

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF3A E302FF3A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF3B E302FF3B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF3C E302FF3C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF3D E302FF3D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF3E E302FF3E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF3F E302FF3F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF40 E302FF40

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF41 E302FF41

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF42 E302FF42

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF43 E302FF43

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF44 E302FF44

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF45 • E302FF54

E302FF45 **E302FF45**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF46 **E302FF46**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF47 **E302FF47**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF48 **E302FF48**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF49 **E302FF49**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF4A **E302FF4A**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF4B **E302FF4B**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF4C **E302FF4C**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF4D **E302FF4D**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF4E **E302FF4E**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF4F **E302FF4F**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF50 **E302FF50**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF51 **E302FF51**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF52 **E302FF52**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF53 **E302FF53**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF54 **E302FF54**

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF55 E302FF55

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF56 E302FF56

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF57 E302FF57

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF58 E302FF58

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF59 E302FF59

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF5A E302FF5A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF5B E302FF5B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF5C E302FF5C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF5D E302FF5D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF5E E302FF5E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF5F E302FF5F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF60 E302FF60

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF61 E302FF61

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF62 E302FF62

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF63 E302FF63

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF64 E302FF64

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF65 • E302FF74

E302FF65 E302FF65

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF66 E302FF66

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF67 E302FF67

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF68 E302FF68

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF69 E302FF69

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF6A E302FF6A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF6B E302FF6B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF6C E302FF6C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF6D E302FF6D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF6E E302FF6E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF6F E302FF6F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF70 E302FF70

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF71 E302FF71

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF72 E302FF72

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF73 E302FF73

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF74 E302FF74

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF75 E302FF75

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF76 E302FF76

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF77 E302FF77

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF78 E302FF78

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF79 E302FF79

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF7A E302FF7A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF7B E302FF7B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF7C E302FF7C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF7D E302FF7D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF7E E302FF7E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF7F E302FF7F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF80 E302FF80

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF81 E302FF81

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF82 E302FF82

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF83 E302FF83

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF84 E302FF84

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF85 • E302FF94

E302FF85 E302FF85

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF86 E302FF86

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF87 E302FF87

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF88 E302FF88

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF89 E302FF89

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF8A E302FF8A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF8B E302FF8B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF8C E302FF8C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF8D E302FF8D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF8E E302FF8E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF8F E302FF8F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF90 E302FF90

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF91 E302FF91

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF92 E302FF92

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF93 E302FF93

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF94 E302FF94

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF95 E302FF95

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF96 E302FF96

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF97 E302FF97

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF98 E302FF98

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF99 E302FF99

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF9A E302FF9A

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF9B E302FF9B

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF9C E302FF9C

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF9D E302FF9D

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF9E E302FF9E

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FF9F E302FF9F

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA0 E302FFA0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA1 E302FFA1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA2 E302FFA2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA3 E302FFA3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA4 E302FFA4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA5 • E302FFB4

E302FFA5 E302FFA5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA6 E302FFA6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA7 E302FFA7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA8 E302FFA8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFA9 E302FFA9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFAA E302FFAA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFAB E302FFAB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFAC E302FFAC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFAD E302FFAD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFAE E302FFAE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFAF E302FFAF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB0 E302FFB0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB1 E302FFB1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB2 E302FFB2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB3 E302FFB3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB4 E302FFB4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB5 E302FFB5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB6 E302FFB6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB7 E302FFB7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB8 E302FFB8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFB9 E302FFB9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFBA E302FFBA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFBB E302FFBB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFBC E302FFBC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFBD E302FFBD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFBE E302FFBE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFBF E302FFBF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC0 E302FFC0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC1 E302FFC1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC2 E302FFC2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC3 E302FFC3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC4 E302FFC4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC5 • E302FFD4

E302FFC5 E302FFC5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC6 E302FFC6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC7 E302FFC7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC8 E302FFC8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFC9 E302FFC9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFCA E302FFCA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFCB E302FFCB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFCC E302FFCC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFCD E302FFCD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFCE E302FFCE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFCF E302FFCF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD0 E302FFD0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD1 E302FFD1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD2 E302FFD2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD3 E302FFD3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD4 E302FFD4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD5 E302FFD5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD6 E302FFD6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD7 E302FFD7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD8 E302FFD8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFD9 E302FFD9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFDA E302FFDA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFDB E302FFDB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFDC E302FFDC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFDD E302FFDD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFDE E302FFDE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFDF E302FFDF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE0 E302FFE0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE1 E302FFE1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE2 E302FFE2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE3 E302FFE3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE4 E302FFE4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE5 • E302FFF4

E302FFE5 E302FFE5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE6 E302FFE6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE7 E302FFE7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE8 E302FFE8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFE9 E302FFE9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFEA E302FFEA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFEB E302FFEB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFEC E302FFEC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFED E302FFED

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFEE E302FFEE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFEF E302FFEF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF0 E302FFF0

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF1 E302FFF1

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF2 E302FFF2

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF3 E302FFF3

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF4 E302FFF4

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF5 E302FFF5

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF6 E302FFF6

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF7 E302FFF7

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF8 E302FFF8

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFF9 E302FFF9

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFFA E302FFFA

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFFB E302FFFB

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFFC E302FFFC

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFFD E302FFFD

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFFE E302FFFE

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

E302FFFF E302FFFF

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

(E303) Reference codes

E3033001 E3033001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught from FormatMediaApp

Problem determination: Call your next level of support.

E303300A E303300A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from FormatMediaTasklet displaying main panel

Problem determination: Call your next level of support.

E303300B E303300B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from FormatMediaTasklet log exception handler

Problem determination: Call your next level of support.

E303300C E303300C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unknown message "int" from formatMeiaMessages(int message)

Problem determination: Call your next level of support.

E303300D E303300D

Explanation: Format Media application had an error trying to display a format message panel on the screen.

Problem determination: Perform the following steps:

1. Exit or Cancel the Format Media application.
 2. Retry the operation
-

E303300E E303300E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Illegal Argument Exception caught from FormatMediaTasklet.mountMedia().

Problem determination: Call your next level of support.

E303300F E303300F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown MediaDevice Exception caught from DVD button FormatMediaTasklet.mountMedia().

Problem determination: Call your next level of support.

E3033010 E3033010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown MediaDevice Exception caught from diskette button FormatMediaTasklet.mountMedia().

Problem determination: Call your next level of support.

E3033011 E3033011

Explanation: Format Media encountered a problem accessing the removable media it is trying to format.

Problem determination: Perform the following steps:

1. Check the media to see if it is inserted correctly.
 2. Retry the operation
 3. If it still fails, the media being formatted may be defective. Try a different media.
-

E3033012 E3033012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from FormatMediaTasklet.mountMedia().

Problem determination: Call your next level of support.

E3033013 E3033013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from FormatMediaTasklet.isLocalMediaAvailable().

Problem determination: Call your next level of support.

E3033014 E3033014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from FormatMediaTasklet.isLocalMediaAvailable().

Problem determination: Call your next level of support.

E3033015 E3033015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown MediaDevice Exception caught from Memory format FormatMediaTasklet.

Problem determination: Call your next level of support.

E3034001 E3034001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Note: This error id needs to be managed by the code owner to not conflict with their existing error locations. Exception caught from SaveUpgradeApp

Problem determination: Call your next level of support.

E303400A E303400A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from UpgradeDataTasklet displaying main panel

Problem determination: Call your next level of support.

E303400B E303400B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from UpgradeDataTasklet log exception handler

Problem determination: Call your next level of support.

E303400C E303400C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unknown message "int" from saveupgradeMessages(int message)

Problem determination: Call your next level of support.

E303400D E303400D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from saveupgradeMessages(int message)

Problem determination: Call your next level of support.

E303400E E303400E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Illegal Argument Exception caught from SaveUpgradeHarddrive.mountHardDrive().

Problem determination: Call your next level of support.

E3034010 E3034010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Illegal Argument Exception caught from SaveUpgradeHarddrive.mountDVD().

Problem determination: Call your next level of support.

E3034011 E3034011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unknown MediaDevice Exception caught from SaveUpgradeHarddrive.mountHardDrive().

Problem determination: Call your next level of support.

E3034012 E3034012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unknown MediaDevice Exception caught from SaveUpgradeHarddrive.mountDVD().

Problem determination: Call your next level of support.

E3034013 E3034013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Exception caught from SaveUpgradeHarddrive.mountDVD().

Problem determination: Call your next level of support.

E3034014 E3034014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Write Protected Exception caught from SaveUpgradeHarddrive.mountHD().

Problem determination: Call your next level of support.

E3034015 E3034015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A No Media Present Exception caught from SaveUpgradeHarddrive.mountHD().

Problem determination: Call your next level of support.

E3034016 E3034016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Exception caught from SaveUpgradeHarddrive.mountHD().

Problem determination: Call your next level of support.

E3034017 E3034017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An HException caught from SaveUpgradeHarddrive()

Problem determination: Call your next level of support.

E3034018 E3034018

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from SaveUpgradeHarddrive()

Problem determination: Call your next level of support.

E3034019 E3034019

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException caught from SaveUpgradeHarddrive()

Problem determination: Call your next level of support.

E303401A E303401A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Class Not Found Exception caught from SaveUpgradeHarddrive()

Problem determination: Call your next level of support.

E303401B E303401B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A UpgradeData Exception caught from SaveUpgradeHarddrive().saveUpgradeData()

Problem determination: Call your next level of support.

E303401C E303401C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A UpgradeData Exception caught from SaveUpgradeHarddrive().getUpgradeDataVersion()

Problem determination: Call your next level of support.

E303401D E303401D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A IOException caught when writing data to DVD

Problem determination: Call your next level of support.

E303401E E303401E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Illegal Argument Exception caught from writeRestoreIstDOS().

Problem determination: Call your next level of support.

E303401F E303401F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unknown MediaDevice Exception caught from writeRestoreIstDOS().

Problem determination: Call your next level of support.

E3034020 • E3034039

E3034020 E3034020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Write Protected Exception caught from writeRestoreIstDOS().

Problem determination: Call your next level of support.

E3034021 E3034021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A No Media Present Exception caught from writeRestoreIstDOS().

Problem determination: Call your next level of support.

E3034022 E3034022

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Exception caught from writeRestoreIstDOS().

Problem determination: Call your next level of support.

E3034031 E3034031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when getting pathing of table file used to find user class name in saveUpgradeData

Problem determination: Call your next level of support.

E3034032 E3034032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected Exception caught when running saveUpgradeData in UpgradeDataBImpl.

Problem determination: Call your next level of support.

E3034033 E3034033

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when running saveUpgradeData in UpgradeDataBImpl.

Problem determination: Call your next level of support.

E3034034 E3034034

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected NoSuchElementException caught when running saveUpgradeData in UpgradeDataBImpl.

Problem determination: Call your next level of support.

E3034035 E3034035

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: UpgradeData Exception caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034036 E3034036

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034037 E3034037

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: HException caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034038 E3034038

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ClassNotFoundException Exception caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034039 E3034039

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: NoSuchMethod Exception caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E303403A E303403A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Instantiation Exception caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E303403B E303403B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IllegalAccess Exception caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E303403C E303403C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: InvocationTarget Exception caught when running through table list for saveUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034041 E3034041

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when getting pathing of table file used to find user class name in restoreUpgradeData

Problem determination: Call your next level of support.

E3034042 E3034042

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected Exception caught when running restoreUpgradeData in UpgradeDataBImpl.

Problem determination: Call your next level of support.

E3034043 E3034043

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when running restoreUpgradeData in UpgradeDataBImpl.

Problem determination: Call your next level of support.

E3034044 E3034044

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected NoSuchElementException caught when running restoreUpgradeData in UpgradeDataBImpl.

Problem determination: Call your next level of support.

E3034045 E3034045

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: UpgradeData Exception caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034046 E3034046

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034047 E3034047

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: HException caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034048 E3034048

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ClassNotFoundException Exception caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

E3034049 • E3034056

Problem determination: Call your next level of support.

E3034049 E3034049

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: NoSuchMethod Exception caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E303404A E303404A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Instantiation Exception caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E303404B E303404B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IllegalAccessException Exception caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E303404C E303404C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: InvocationTargetException Exception caught when running through table list for restoreUpgradeData in upgradeDataBImpl.

Problem determination: Call your next level of support.

E3034050 E3034050

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Note: This error id needs to be managed by the code owner to not conflict with their existing error locations. Exception caught from RestoreUpgradeApp

Problem determination: Call your next level of support.

E3034051 E3034051

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from UpgradeDataRestoreTasklet log exception handler

Problem determination: Call your next level of support.

E3034052 E3034052

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from UpgradeDataRestoreTasklet log exception handler

Problem determination: Call your next level of support.

E3034053 E3034053

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unknown message "int" from restoreupgradeMessages(int message)

Problem determination: Call your next level of support.

E3034054 E3034054

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught from restoreupgradeMessages(int message)

Problem determination: Call your next level of support.

E3034055 E3034055

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Illegal Argument Exception caught from RestoreTasklet.mountHardDrive().

Problem determination: Call your next level of support.

E3034056 E3034056

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unknown MediaDevice Exception caught from mountHardDrive().

Problem determination: Call your next level of support.

E3034057 E3034057

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Write Protected Exception caught from mountHardDrive().

Problem determination: Call your next level of support.

E3034058 E3034058

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A No Media Present Exception caught from mountHardDrive().

Problem determination: Call your next level of support.

E3034059 E3034059

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Exception caught from mountHardDrive().

Problem determination: Call your next level of support.

E303405A E303405A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Illegal Argument Exception caught from mountDVD().

Problem determination: Call your next level of support.

E303405B E303405B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unknown MediaDevice Exception caught from mountDVD().

Problem determination: Call your next level of support.

E303405C E303405C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Exception caught from mountDVD().

Problem determination: Call your next level of support.

E303405D E303405D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Illegal Argument Exception caught from RestoreTasklet.mountHardDriveDOS().

Problem determination: Call your next level of support.

E303405E E303405E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unknown MediaDevice Exception caught from mountHardDriveDOS().

Problem determination: Call your next level of support.

E303405F E303405F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Write Protected Exception caught from mountHardDriveDOS().

Problem determination: Call your next level of support.

E3034060 E3034060

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A No Media Present Exception caught from mountHardDriveDOS().

Problem determination: Call your next level of support.

E3034061 E3034061

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Exception caught from mountHardDriveDOS().

Problem determination: Call your next level of support.

E3034062 E3034062

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A IOException caught when writing data to DVD in restoreUpgradeDataTasklet()

Problem determination: Call your next level of support.

E3034063 E3034063

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception caught in restoreUpgradeDataTasklet() mounting partitions

Problem determination: Call your next level of support.

E3034064 E3034064

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Error in restoreUpgradeDataTasklet() mounting the DOS partition

Problem determination: Call your next level of support.

E3034065 E3034065

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A UpgradeData Exception caught from restoreUpgradeDataHarddrive()

Problem determination: Call your next level of support.

E3034066 E3034066

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Class Not Found Exception caught from restoreUpgradeDataHarddrive()

Problem determination: Call your next level of support.

E3034067 E3034067

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException caught from restoreUpgradeDataHarddrive()

Problem determination: Call your next level of support.

E3034068 E3034068

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An HException caught from restoreUpgradeDataHarddrive()

Problem determination: Call your next level of support.

E3034069 E3034069

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A IOException caught when writing restore.lst to Dos partition

Problem determination: Call your next level of support.

E303406A E303406A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A IOException caught when writing restore.lst to Dos partition

Problem determination: Call your next level of support.

E3034081 E3034081

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when creating a file to save user data.

Problem determination: Call your next level of support.

E3034082 E3034082

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when restoring user data.

Problem determination: Call your next level of support.

E3034086 E3034086

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when getting pathing of table file that holds the sim fields to restore.

Problem determination: Call your next level of support.

E3034087 E3034087

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException caught when zipping Sim field files.

Problem determination: Call your next level of support.

E3034088 E3034088

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: HException caught when getting file path for Sim field files to save.

Problem determination: Call your next level of support.

E3034089 E3034089

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when saving Sim field files.

Problem determination: Call your next level of support.

E303408A E303408A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException caught when restoring Sim field files.

Problem determination: Call your next level of support.

E303408B E303408B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when restoring Sim field files.

Problem determination: Call your next level of support.

E303408C E303408C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught in get_field_s method.

Problem determination: Call your next level of support.

E3034091 E3034091

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when creating a file to save user data.

Problem determination: Call your next level of support.

E3034092 E3034092

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when restoring user data.

Problem determination: Call your next level of support.

E3034096 E3034096

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when getting pathing of table file that holds the file names to save.

Problem determination: Call your next level of support.

E3034097 E3034097

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected NoSuchElementException caught when running saveUpgradeData in UpgradeZNativeData

Problem determination: Call your next level of support.

E3034098 E3034098

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException caught when running through table list for saveUpgradeData in UpgradeZNative.

Problem determination: Call your next level of support.

E3034099 E3034099

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: HException caught when running through table list for saveUpgradeData in UpgradeZNativeData.

Problem determination: Call your next level of support.

E303409A E303409A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException caught when zipping files.

Problem determination: Call your next level of support.

E303409B E303409B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when saving files.

Problem determination: Call your next level of support.

E303409C E303409C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when restoring files.

Problem determination: Call your next level of support.

E303409D E303409D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException caught when restoring files.

Problem determination: Call your next level of support.

E30340B0 E30340B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when getting pathing of table file used to find user class name.

Problem determination: Call your next level of support.

E30340B1 E30340B1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: UpgradeData Exception caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B2 E30340B2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: UpgradeData Exception caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B3 E30340B3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IllegalAccess Exception caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B4 E30340B4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: InvocationTargetException caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B5 E30340B5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Instantiation Exception caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B6 E30340B6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: NoSuchMethod Exception caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B7 E30340B7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ClassNotFoundException Exception caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B8 E30340B8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected NoSuchElementException caught when running restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340B9 E30340B9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340BA E30340BA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: HException caught when running through table list for restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340BB E30340BB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ClassNotFoundException caught when running restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340BC E30340BC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when running restoreOS2UpgradeData().

Problem determination: Call your next level of support.

E30340BD E30340BD

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException caught when running restoreUpgradeData().

Problem determination: Call your next level of support.

E30340C0 E30340C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when getting pathing of table file that holds the sim fields to restore.

Problem determination: Call your next level of support.

E30340C1 E30340C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException caught when zipping Sim field files.

Problem determination: Call your next level of support.

E30340C2 E30340C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: HException caught when getting file path for Sim field files to save.

Problem determination: Call your next level of support.

E30340C3 E30340C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when saving Sim field files.

Problem determination: Call your next level of support.

E30340C4 E30340C4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException caught when restoring Sim field files.

Problem determination: Call your next level of support.

E30340C5 E30340C5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when restoring Sim field files.

Problem determination: Call your next level of support.

E30340C6 E30340C6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught in get_field_s method.

Problem determination: Call your next level of support.

E30340D0 • E30340E3

E30340D0 E30340D0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when getting pathing of table files that holds the sim fields to restore.

Problem determination: Call your next level of support.

E30340D1 E30340D1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException caught when restoring Sim field files.

Problem determination: Call your next level of support.

E30340D2 E30340D2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught when restoring Sim field files.

Problem determination: Call your next level of support.

E30340D3 E30340D3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected IOException caught in get_field_s method.

Problem determination: Call your next level of support.

E30340D4 E30340D4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: ClassNotFoundException Exception caught when running through table list2 for sim field restore.

Problem determination: Call your next level of support.

E30340D5 E30340D5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: NoSuchMethod Exception caught when running through table list2 for sim field restore.

Problem determination: Call your next level of support.

E30340D6 E30340D6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Instantiation Exception caught when running through table list2 for sim field restore.

Problem determination: Call your next level of support.

E30340D7 E30340D7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IllegalAccess Exception caught when running through table list2 for sim field restore.

Problem determination: Call your next level of support.

E30340D8 E30340D8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: InvocationTargetException caught when running through table list2 for sim field restore.

Problem determination: Call your next level of support.

E30340E1 E30340E1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A HException caught

Problem determination: Call your next level of support.

E30340E2 E30340E2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception caught

Problem determination: Call your next level of support.

E30340E3 E30340E3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception caught

Problem determination: Call your next level of support.

E30340E4 E30340E4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception caught

Problem determination: Call your next level of support.

E30340E5 E30340E5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception caught

Problem determination: Call your next level of support.

(E316) Reference codes

E3160001 E3160001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when instantiating the data bean or when instantiating the panel renderer. Look at the nested exception for details about this error. The error reason is 0.

Problem determination: Call your next level of support.

Action for the the SimDebug task. The SimDebug task has been ended.

Problem determination: Call your next level of support.

E3160002 E3160002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when the panel was displayed or SIM data is being retrieved. Look at the nested exception for details about this error. The error reason is 0.

Problem determination: Call your next level of support.

E3160003 E3160003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when instantiating the data bean or when instantiating the panel renderer. Look at the nested exception for details about this error. The error reason is 0.

Problem determination: Call your next level of support.

E3160004 E3160004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the SimDebug task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The SimDebug task has been ended.

Problem determination: Call your next level of support.

E3160005 E3160005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying processing request in panel

(E325) Reference codes

E3250001 E3250001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the save restore task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The save restore task has been ended.

Problem determination: Call your next level of support.

E3250002 E3250002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the save restore task. The save restore task has been ended.

Problem determination: Call your next level of support.

E3250003 E3250003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the save restore task. The save restore task has been ended.

Problem determination: Call your next level of support.

E3250004 E3250004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the save restore task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The save restore task has been ended.

Problem determination: Call your next level of support.

E3250005 E3250005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the save restore task action handler. The save restore task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3250006 E3250006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform a save of a specific file in a CustomizableFileData object. The task will continue to run, but this particular file will not be saved.

Problem determination: Call your next level of support.

E3250007 E3250007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform a restore of a specific file in a CustomizableFileData object. The task will continue to run, but this particular file will not be restored.

Problem determination: Call your next level of support.

E3250008 E3250008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the data replication configuration tasklet. This is the result of an exception being caught by the underlying Tasklet infrastructure. The configuration tasklet has been ended.

Problem determination: Call your next level of support.

E3250009 E3250009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the customizable data replication warning tasklet. This is the result of an exception being caught by the underlying Tasklet infrastructure. The configuration tasklet has been ended.

Problem determination: Call your next level of support.

E3250101 E3250101

E3250102 • E3250109

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the cloning task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The cloning task has been ended.

Problem determination: Call your next level of support.

E3250102 E3250102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the cloning task. The cloning task has been ended.

Problem determination: Call your next level of support.

E3250103 E3250103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the cloning task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The cloning task has been ended.

Problem determination: Call your next level of support.

E3250104 E3250104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the cloning task action handler. The cloning task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3250105 E3250105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the cloning task HMC to HMC communications handler.

Problem determination: Call your next level of support.

E3250106 E3250106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the cloning bean's prepare() method. The cloning task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3250107 E3250107

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the handling of the "save" button processing for server side of the cloning task. The cloning task has been ended.

Problem determination: Call your next level of support.

E3250108 E3250108

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the handling of the "save" button processing for server side of the cloning task. The cloning task has been ended.

Problem determination: Call your next level of support.

E3250109 E3250109

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the handling of the "restore" button processing for server side of the cloning task. The cloning task has been ended.

Problem determination: Call your next level of support.

(E332) Reference codes

E3320001 E3320001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error getting the problem manager - CommonProblem

Problem determination: Call your next level of support.

E332040B E332040B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ZMicroCodeBaseAnalysisRoutine. PA must handle a permanent process trap and reboot the console if possible.

Problem determination: Call your next level of support.

E332040C E332040C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ZseMicroCodeAnalysisRoutine. PA must handle a permanent process trap and reboot the SE if possible.

Problem determination: Call your next level of support.

E332040D E332040D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ServiceDataProviderImpl. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3320671 E3320671

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The managed systems dump directory is full. No more dumps can be extracted from any managed system until dumps are delted from the /dump directory. Dumps can be deleted via the Manage Dumps Task.

Problem determination: Call your next level of support.

E3321001 E3321001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error parsing MANPAI GDS - Z manual pa service data provider

Problem determination: Call your next level of support.

E3321002 E3321002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: GDS router error - Z manual pa service data provider

Problem determination: Call your next level of support.

E3321003 E3321003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error reading VPD information - HMCIncident

Problem determination: Call your next level of support.

E3321004 E3321004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error resolving FRU list in CommonProblem

Problem determination: Call your next level of support.

E3321005 E3321005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error recording service history in Journaled problem

Problem determination: Call your next level of support.

E3321006 E3321006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

E3321007 • E3321012

Response: error recording service history in Common problem

Problem determination: Call your next level of support.

E3321007 E3321007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error recording service history in Common problem listener

Problem determination: Call your next level of support.

E3321008 E3321008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error getting VPD data in CriticalProblem

Problem determination: Call your next level of support.

E3321009 E3321009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: couldn't retrieve the log in the CommonLogGenerator. It wasn't there.

Problem determination: Call your next level of support.

E332100A E332100A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: couldn't build the event to pass to the event manager

Problem determination: Call your next level of support.

E332100B E332100B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception from the log manager.

Problem determination: Call your next level of support.

E332100C E332100C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception reading delayed files from drive

Problem determination: Call your next level of support.

E332100D E332100D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception getting the problem manager in the primaryanalysis tasklet

Problem determination: Call your next level of support.

E332100E E332100E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception reporting the problem

Problem determination: Call your next level of support.

E332100F E332100F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception on the addPropertyChangeListener in InitServices

Problem determination: Call your next level of support.

E3321010 E3321010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception getting the FFDC factory common problem listener

Problem determination: Call your next level of support.

E3321011 E3321011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception putting data in virtual retain

Problem determination: Call your next level of support.

E3321012 E3321012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while on timer thread

Problem determination: Call your next level of support.

E3321013 E3321013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while on timer thread

Problem determination: Call your next level of support.

E3321014 E3321014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while on timer thread

Problem determination: Call your next level of support.

E3321015 E3321015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception creating IPL error problem

Problem determination: Call your next level of support.

E3321016 E3321016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception clearing XP11_CHANNEL_DATA in Z SIM

Problem determination: Call your next level of support.

E3321017 E3321017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while trying to display a problem in PrimaryProblemAnalysisServerTasklet

Problem determination: Call your next level of support.

E3321018 E3321018

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while trying to open a problem in Manual PA

Problem determination: Call your next level of support.

E3321019 E3321019

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while trying to call the problem home

Problem determination: Call your next level of support.

E332101A E332101A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while trying to call the problem manager in the channel ar

Problem determination: Call your next level of support.

E332101B E332101B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while trying to serialize the problem in ManualPaServiceDataProvider on a Channel Error

Problem determination: Call your next level of support.

E332101C E332101C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while trying to serialize the problem in ManualPaServiceDataProvider on a CEC Error

Problem determination: Call your next level of support.

E332101D E332101D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while trying to handle recoverable functions

Problem determination: Call your next level of support.

E332101E E332101E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while waiting for HOM to be initialized

E332101F • E332102A

Problem determination: Call your next level of support.

E332101F E332101F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while getting problem in PrimaryProblemTasklet

Problem determination: Call your next level of support.

E3321020 E3321020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while getting problem in RSFCompleFailServerTasklet

Problem determination: Call your next level of support.

E3321021 E3321021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an exception while getting problem in RSFCompleteOkServerTasklet

Problem determination: Call your next level of support.

E3321022 E3321022

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an error get the channel refcode

Problem determination: Call your next level of support.

E3321023 E3321023

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an error get the channel extension

Problem determination: Call your next level of support.

E3321024 E3321024

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: got an error in the CommonProblemListenWorkThread

Problem determination: Call your next level of support.

E3321025 E3321025

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error while opening a reboot PA problem

Problem determination: Call your next level of support.

E3321026 E3321026

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error while get the threshold info in ProblemOpenAnalysisRoutine

Problem determination: Call your next level of support.

E3321027 E3321027

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ManualPaWorkThread

Problem determination: Call your next level of support.

E3321028 E3321028

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ProblemAnalysisManager

Problem determination: Call your next level of support.

E3321029 E3321029

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ProblemAnalysisManager building the problem data base. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E332102A E332102A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in DefaultProblemPersistence removing a problem. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E332102B E332102B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in DefaultProblemPersistence adding a problem. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E332102C E332102C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ServiceHistory while processing the data. The trace back will show the details of what failed.

Problem determination: Call your next level of support.

E332102D E332102D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in Encodign the call home data for Link Incidents. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E332102E E332102E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ZipdirManager. The // -xx exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E332102F E332102F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in MessagingTasklet. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321030 E3321030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ZConsoleProblemReporter. The

exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321031 E3321031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in DataPortListner. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321032 E3321032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in DistributedProblemReplicator. Peer systems could not replicate information to each other. The exception contained in the log that created this message will have the details of what the problem was. This may be caused by varying code levels between the two peer systems.

Problem determination: Call your next level of support.

E3321033 E3321033

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in FEDCExecutable. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321034 E3321034

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in CommonServiceAnalysisRoutine. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321035 E3321035

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in LogListener. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321036 **E3321036**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in DistributedAnalysisDomain. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321037 **E3321037**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in RemoteEntityThread. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321038 **E3321038**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ManualPaGdsHandler. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3321039 **E3321039**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in CloseAllProblems. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E332103A **E332103A**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in GetProblemData. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E332103B **E332103B**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in ReferenceCodeDescriptionTask. The exception will have the details of what the problem was.

Problem determination: Call your next level of support.

E3322D1E **E3322D1E**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An SE process has demanded a reboot of SE. This SRC forces PA to reboot SE.

Problem determination: Call your next level of support.

E3325000 **E3325000**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DumpInfoManager no dump file exists for dump.properties file. The dump.properties file has been removed.

Problem determination: Call your next level of support.

E3325005 **E3325005**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DumpInfoManager has added a new DumpManagerInfo for a new dump file

Problem determination: Call your next level of support.

E3326601 **E3326601**

Explanation: The HMC failed to retrieve a platform system dump from the managed system. For details, refer to reference code B3036601.

E3326604 **E3326604**

Explanation: The HMC failed to retrieve a power subsystem dump from the managed system. For details, refer to reference code B3036604.

E332FFFF **E332FFFF**

Explanation: This error occurs when the HMC receives notification that a particular Java code string is corrupted.

Problem determination: If you have the call home feature enabled, the failure information (including the JavaCore) will be transmitted to service and support. The support organization will examine the JavaCore file. Otherwise, you can retry the task.

(E333) Reference codes

E33326602 E33326602

Explanation: The HMC failed to retrieve a dump from the service processor. For details, refer to reference code B3036601.

(E338) Reference codes

E3380001 E3380001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An HException was caught during InitServices initialization.

Problem determination: Call your next level of support.

E3380002 E3380002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Exception (non-HException) was caught during InitServices initialization.

Problem determination: Call your next level of support.

E3380003 E3380003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An HException was caught by PerformConsoleRepairActionTasklet.

Problem determination: Call your next level of support.

E3380004 E3380004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception (non-HException) was caught by PerformConsoleRepairActionTasklet.

Problem determination: Call your next level of support.

E3381200 E3381200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381201 E3381201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel.

Problem determination: Call your next level of support.

E3381202 E3381202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381203 E3381203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel.

Problem determination: Call your next level of support.

E3381204 E3381204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381205 E3381205

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381206 E3381206

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381207 E3381207

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

E3381208 • E33812B7

Problem determination: Call your next level of support.

E3381208 E3381208

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying repair.

Problem determination: Call your next level of support.

E3381240 E3381240

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E338124D E338124D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E338124E E338124E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel.

Problem determination: Call your next level of support.

E338124F E338124F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E33812B0 E33812B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaCheckBatteryEnbldIndicator10.

Problem determination: Call your next level of support.

E33812B1 E33812B1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel
PBZBpaCheckBatteryEnbldIndicator10.

Problem determination: Call your next level of support.

E33812B2 E33812B2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaSetIbfCircuitBreakerOff.

Problem determination: Call your next level of support.

E33812B3 E33812B3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel
PBZBpaSetIbfCircuitBreakerOff.

Problem determination: Call your next level of support.

E33812B5 E33812B5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaSetIbfCircuitBreakerOn.

Problem determination: Call your next level of support.

E33812B6 E33812B6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBDelaySupportRequired.

Problem determination: Call your next level of support.

E33812B7 E33812B7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying repair.

Problem determination: Call your next level of support.

E33812C0 E33812C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaCheckBatteryEnbldIndicator10.

Problem determination: Call your next level of support.

E33812C1 E33812C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel
PBZBpaCheckBatteryEnbldIndicator10.

Problem determination: Call your next level of support.

E33812C2 E33812C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaSetIbfCircuitBreakerOff.

Problem determination: Call your next level of support.

E33812C3 E33812C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel
PBZBpaSetIbfCircuitBreakerOff.

Problem determination: Call your next level of support.

E33812C5 E33812C5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaSetIbfCircuitBreakerOn.

Problem determination: Call your next level of support.

E33812C6 E33812C6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBDelaySupportRequired.

Problem determination: Call your next level of support.

E33812C7 E33812C7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying repair.

Problem determination: Call your next level of support.

E3381300 E3381300

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaCheckBatteryEnbldIndicator10.

Problem determination: Call your next level of support.

E3381301 E3381301

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel
PBZBpaCheckBatteryEnbldIndicator10.

Problem determination: Call your next level of support.

E3381302 E3381302

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaSetIbfCircuitBreakerOff.

Problem determination: Call your next level of support.

E3381303 E3381303

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel
PBZBpaSetIbfCircuitBreakerOff.

Problem determination: Call your next level of support.

E3381305 E3381305

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBZBpaSetIbfCircuitBreakerOn.

Problem determination: Call your next level of support.

E3381307 • E33813CA

E3381307 E3381307

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel
PBDelaySupportRequired.

Problem determination: Call your next level of support.

E3381308 E3381308

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying repair.

Problem determination: Call your next level of support.

E33813C0 E33813C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813C1 E33813C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying a panel.

Problem determination: Call your next level of support.

E33813C2 E33813C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813C3 E33813C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the BPA interface.

Problem determination: Call your next level of support.

E33813C4 E33813C4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying a panel.

Problem determination: Call your next level of support.

E33813C5 E33813C5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying a panel.

Problem determination: Call your next level of support.

E33813C6 E33813C6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813C7 E33813C7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813C8 E33813C8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813C9 E33813C9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813CA E33813CA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813CB E33813CB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying a repair.

Problem determination: Call your next level of support.

E33813CC E33813CC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the VPD interface.

Problem determination: Call your next level of support.

E33813D0 E33813D0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E33813D1 E33813D1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel.

Problem determination: Call your next level of support.

E33813D2 E33813D2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E33813D3 E33813D3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel.

Problem determination: Call your next level of support.

E33813D4 E33813D4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E33813D5 E33813D5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E33813D6 E33813D6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E33813D7 E33813D7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E33813D8 E33813D8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error delaying repair.

Problem determination: Call your next level of support.

E3381400 E3381400

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381401 E3381401

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel.

E3381402 • E3382504

Problem determination: Call your next level of support.

E3381402 E3381402

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381403 E3381403

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid selection from panel.

Problem determination: Call your next level of support.

E3381404 E3381404

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381405 E3381405

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381406 E3381406

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381410 E3381410

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3381420 E3381420

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error displaying panel.

Problem determination: Call your next level of support.

E3382500 E3382500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Cage location information was not found in reference code extension one.

Problem determination: Call your next level of support.

E3382501 E3382501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error machineType is null

Problem determination: Call your next level of support.

E3382502 E3382502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating the factory

Problem determination: Call your next level of support.

E3382503 E3382503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Expected reference code not found error.

Problem determination: Call your next level of support.

E3382504 E3382504

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error refCode is null

Problem determination: Call your next level of support.

E3382505 E3382505

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error refCodeExtension1 is null

Problem determination: Call your next level of support.

E3382506 E3382506

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error I or P series cage location not found

Problem determination: Call your next level of support.

E3382520 E3382520

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reference code not found.

Problem determination: Call your next level of support.

E3382521 E3382521

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: samerefcode error

Problem determination: Call your next level of support.

E3382522 E3382522

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error BPC activate exception

Problem determination: Call your next level of support.

E3382523 E3382523

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Factory Creation

Problem determination: Call your next level of support.

E3382524 E3382524

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error BPC Fru not found

Problem determination: Call your next level of support.

E3382525 E3382525

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error BPR Fru not found

Problem determination: Call your next level of support.

E3382526 E3382526

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error BPE Fru not found

Problem determination: Call your next level of support.

E3382527 E3382527

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error BPA Line Cord Fru not found

Problem determination: Call your next level of support.

E3382528 E3382528

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Default Fru not found

Problem determination: Call your next level of support.

E3382529 E3382529

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error Default Fru not found

Problem determination: Call your next level of support.

E338253A E338253A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: BPC Fru side not found

Problem determination: Call your next level of support.

E338253B • E3383551

E338253B E338253B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating factory

Problem determination: Call your next level of support.

E338253C E338253C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with redundancy

Problem determination: Call your next level of support.

E338253D E338253D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: element level activate failed

Problem determination: Call your next level of support.

E338254A E338254A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid FRU list.

Problem determination: Call your next level of support.

E338254B E338254B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Not enough BPDs in the FRU list.

Problem determination: Call your next level of support.

E338254C E338254C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception from displayServiceEffect.

Problem determination: Call your next level of support.

E338254D E338254D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception deactivating FRU.

Problem determination: Call your next level of support.

E338254E E338254E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating the factory

Problem determination: Call your next level of support.

E338254F E338254F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error activating bpcFru

Problem determination: Call your next level of support.

E3383500 E3383500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Display error.

Problem determination: Call your next level of support.

E3383501 E3383501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Display error.

Problem determination: Call your next level of support.

E3383550 E3383550

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: No FRU list for the problem.

Problem determination: Call your next level of support.

E3383551 E3383551

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The BPR, BPI, or BPE was not found in the FRU list.

Problem determination: Call your next level of support.

E3383554 E3383554

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid next step.

Problem determination: Call your next level of support.

E3383555 E3383555

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Display error.

Problem determination: Call your next level of support.

E3383556 E3383556

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Display error.

Problem determination: Call your next level of support.

E3383591 E3383591

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid next step.

Problem determination: Call your next level of support.

E3383592 E3383592

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Either the MDA or the thermistor cable is missing from the FRU list.

Problem determination: Call your next level of support.

E3383593 E3383593

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: No FRU list for problem.

Problem determination: Call your next level of support.

E3383594 E3383594

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid cage location.

Problem determination: Call your next level of support.

E3383595 E3383595

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception updating FRU list.

Problem determination: Call your next level of support.

E3383596 E3383596

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception activating FRU.

Problem determination: Call your next level of support.

E3383597 E3383597

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception activating FRU.

Problem determination: Call your next level of support.

E3383598 E3383598

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception PSXML error.

Problem determination: Call your next level of support.

E3383599 E3383599

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception Isolation Factory Creation error.

Problem determination: Call your next level of support.

E33835B0 E33835B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: No FRU list for problem.

E33835B1 • E33835C4

Problem determination: Call your next level of support.

E33835B1 E33835B1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating factory

Problem determination: Call your next level of support.

E33835B2 E33835B2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error ZHECecPuBookFru not found in Fru list

Problem determination: Call your next level of support.

E33835B3 E33835B3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error ZHeCecEvaporatorFru not found in Fru list

Problem determination: Call your next level of support.

E33835B4 E33835B4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reference code is null

Problem determination: Call your next level of support.

E33835B5 E33835B5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reference code extension1 is null

Problem determination: Call your next level of support.

E33835B6 E33835B6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reference code extension2 is null

Problem determination: Call your next level of support.

E33835B7 E33835B7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error evaporator FRU not found

Problem determination: Call your next level of support.

E33835C0 E33835C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating the factory

Problem determination: Call your next level of support.

E33835C1 E33835C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error EPO no FRU List

Problem determination: Call your next level of support.

E33835C2 E33835C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error BPC not found

Problem determination: Call your next level of support.

E33835C3 E33835C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error UEPO not found

Problem determination: Call your next level of support.

E33835C4 E33835C4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error UEPO not found

Problem determination: Call your next level of support.

(E33A) Reference codes

E33A0001 E33A0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the main processing for server side of the SOO task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The SOO task has been ended.

Problem determination: Call your next level of support.

E33A0002 E33A0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the "service" processing for server side of the SOO task. The SOO task has been ended.

Problem determination: Call your next level of support.

E33A0003 E33A0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the "run" processing for client side of the SOO task. The SOO task has been ended.

Problem determination: Call your next level of support.

E33A0004 E33A0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An communication error occurred attempting to contact the SE. The SOO task ended.

Problem determination: Call your next level of support.

E33A0005 E33A0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An I/O error occurred while communicating. The SOO task ended.

Problem determination: Call your next level of support.

E33A0006 E33A0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected infrastructure error occurred while communicating. The SOO task ended.

Problem determination: Call your next level of support.

E33A0007 E33A0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A communication protocol error occurred while managing connection to the SE. The SOO task ended.

Problem determination: Call your next level of support.

(E341) Reference codes

E3410001 E3410001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error reading the event monitor persistent data.

Problem determination: Call your next level of support.

E3410002 E3410002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error writing the event monitor persistent data.

Problem determination: Call your next level of support.

E3410003 E3410003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt was made to restore event monitor data while the Monitor System Events task was running.

Problem determination: Call your next level of support.

E3410004 E3410004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error processing the event definitions.

Problem determination: Call your next level of support.

E3410005 E3410005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error sending an email notification.

Problem determination: Call your next level of support.

E3410006 E3410006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was some unspecified general error. Should try not to use this.

Problem determination: Call your next level of support.

E3410007 E3410007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error while handling the initial tasklet request.

Problem determination: Call your next level of support.

E3410008 E3410008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error in the event summary panel handler.

Problem determination: Call your next level of support.

E341000A E341000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error in the event editor panel handler.

Problem determination: Call your next level of support.

E341000B E341000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error in the event test panel handler.

Problem determination: Call your next level of support.

E341000C E341000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error in the event test results panel handler.

Problem determination: Call your next level of support.

E341000D • E341000F

E341000D E341000D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error in the client side task.

Problem determination: Call your next level of support.

E341000E E341000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error while an event monitor was attempting to start listening to a monitored object.

Problem determination: Call your next level of support.

E341000F E341000F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an error while an event monitor was attempting to stop listening to a monitored object.

Problem determination: Call your next level of support.

(E35500xx) Reference codes

E3550010 E3550010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in the native code while retrieving log entries.

Problem determination: Call your next level of support.

E3550011 E3550011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in the native code when updating a modify block.

Problem determination: Call your next level of support.

E3550012 E3550012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in tasklet processing.

Problem determination: Call your next level of support.

E3550013 E3550013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred trying to read the persistent data for the security log options settings. Everything will continue to run, but the security log options settings will revert to the default values.

Problem determination: Call your next level of support.

E3550014 E3550014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred trying to write the persistent data for the security log options settings. Everything will continue to run, but the security log options settings currently in effect will be lost when the console is restarted.

Problem determination: Call your next level of support.

E3550030 E3550030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to create a new TaskLauncher or thread. This error is logged when the `com.ibm.hwmca.fw.task.TaskLauncher#startTask(PresentationTaskParms,String)` `startTask` method is invoked and there is a problem either creating a new instance of a TaskLauncher or a Thread for it to execute in.

Problem determination: Call your next level of support.

E3550031 E3550031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error detected in the `invoke()` method of `CommonMsgApp`. It is caught and logged by `PanelDisplayer`.

Problem determination: Call your next level of support.

E3550032 E3550032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling the `com.ibm.hwmca.fw.managed.Task#updateTasksPerformed(PresentationTaskParms)` `updateTasksPerformed()` method. While this error is not critical to the operations of the console this log is taken since it is most likely due to a more fundamental underlying condition that should be fixed.

Problem determination: Call your next level of support.

E3550033 E3550033

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to update the elapsed time in the progress window. While this error is not critical to the operations of the console this log is taken since it is most likely due to a more fundamental underlying condition that should be fixed.

Problem determination: Call your next level of support.

E3550034 E3550034

E3550035 • E355003D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to display a busy dialog to the user. The only adverse side effect of this error is that the user will not see the busy dialog. This error does not affect the task that requested the busy dialog to be displayed.

Problem determination: Call your next level of support.

E3550035 E3550035

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to display a message box to display the details for a progress window entry. The only adverse side effect of this error is that the user will not see the message box. This error does not affect the task that associated the details with the progress window entry.

Problem determination: Call your next level of support.

E3550036 E3550036

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform the common up front task processing. If the task this processing is being performed for is a PanelTask, then the task has been ended. Otherwise, the task will continue without this up front processing.

Problem determination: Call your next level of support.

E3550037 E3550037

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to initialize and/or run a task. Depending on the type of exception, this error may or may not cause the execution of the task to terminate.

Problem determination: Call your next level of support.

E3550038 E3550038

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the tasklet used to perform the common up front task processing. The task was never really started in this case.

Problem determination: Call your next level of support.

E3550039 E3550039

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to display a message telling the user to select an object on the single target object selection panel. This error does not affect the task in any way, since the user is left on the single target selection panel where hopefully they will get the idea that they need to select something.

Problem determination: Call your next level of support.

E355003A E355003A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to process a user action event on one of the common task panels (i.e. confirmation, etc.). This error more than likely means that the user will not be able to successfully start the task.

Problem determination: Call your next level of support.

E355003B E355003B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to an update request to execute a class on the local client during startup. This error means that there is probably a configuration problem with the name of the class or the class itself that is to be executed. Startup will continue without any problems.

Problem determination: Call your next level of support.

E355003C E355003C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to an action event on the Logo panel during startup of the client. The logo panel does not expect any action events so this error should not be critical to the startup of the client. Startup will continue without any problems.

Problem determination: Call your next level of support.

E355003D E355003D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the tasklet used to perform the client startup processing. The client startup will

continue, but no further startup hooks will be processed.

Problem determination: Call your next level of support.

E355003E E355003E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the tasklet used to perform the client startup processing. The had to do with the creation of a tower specified startup hook. The client startup will continue, without processing the startup hook in error and processing will continue with the next startup hook.

Problem determination: Call your next level of support.

E355003F E355003F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform the common client startup processing. The client will continue to start, but the startup hook processing has been terminated.

Problem determination: Call your next level of support.

E3550040 E3550040

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to process a user action event on the target filtering panels . This error more than likely means that the user will not be able to successfully end the task.

Problem determination: Call your next level of support.

E3550041 E3550041

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to notify a ShutdownListener about a shutdown request that is about to be processed. This error occurred in the thread that was calling the register listener. An attempt will be made to notify the remainder of the registered listeners and the shutdown request will proceed as requested. The only problem is that this particular register listener may not receive notification of the shutdown request. Note: this is an INFORMATIONAL log.

Problem determination: Call your next level of support.

E3550042 E3550042

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to notify a ShutdownListener about a shutdown request that is about to be processed. This error occurred in while trying to retrieve a specific listener from the list and a thread was being created to call the specific listener. An attempt will be made to notify the remainder of the registered listeners and the shutdown request will proceed as requested. The only problem is that this particular register listener may not receive notification of the shutdown request. Note: this is an INFORMATIONAL log.

Problem determination: Call your next level of support.

E3550043 E3550043

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to notify the set of ShutdownListeners about a shutdown request that is about to be processed. This error occurred in while trying to retrieve list of registered listeners and obtain an iterator for the list. An attempt will be made to notify the remainder of the registered listeners and the shutdown request will proceed as requested. The only problem is that this particular register listener may not receive notification of the shutdown request.

Problem determination: Call your next level of support.

E3550044 E3550044

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform a shutdown/restart request. At this point a graceful shutdown of the framework and towers is not possible, so a last ditch attempt will be made to honor the request by shutting down and potentially restarting the underlying operating system platform. Information about the shutdown request being performed is included in the log.

Problem determination: Call your next level of support.

E3550045 E3550045

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A shutdown request was made and the framework is about to be terminated. This INFORMATIONAL log is used to track the requesting application for audit trail purposes. This is not an error.

E3550046 • E355004E

Problem determination: Call your next level of support.

E3550046 E3550046

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An uncaught exception has been caught by the thread group. This should never occur, so an error log is taken to determine which code failed to handle the exception. The secondary data block with id "81" should be analyzed to determine the code that really is in error.

Problem determination: Call your next level of support.

E3550047 E3550047

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while trying to write the one of the shutdown scripts. The script did not get written and will not be able to be executed during an upcoming shutdown/startup.

Problem determination: Call your next level of support.

E3550048 E3550048

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An uncaught exception occurred while rendering a task panel as HTML. An attempt will be made to terminate the task, but it may or may not be successful.

The secondary data block with id 81 should be examined to see the exception traceback, including root cause exceptions.

Problem determination: Call your next level of support.

E3550049 E3550049

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform the common up front task processing. If the task this processing is being performed for is a PanelTask, then the task has been ended. Otherwise, the task will continue without this up front processing.

Problem determination: Call your next level of support.

E355004A E355004A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the execution of a program based task. The task will continue executing.

Problem determination: Call your next level of support.

E355004B E355004B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: /** Error in the tasklet used to perform the cleanup of temporary files from the Hard Drive. The task was never really started in this case.

Problem determination: Call your next level of support.

E355004C E355004C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A memory threshold has been exceeded for the Java Virtual Machine (JVM). It is possible that memory for the is becoming exhausted and will soon run out. It is also possible that this is a spike in the memory usage of the JVM and things could return to a normal operational state. In addition to the log being taken, a dump of the JVM has been forced for this condition as well.

Problem determination: Call your next level of support.

E355004D E355004D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An out of memory exception has been caught in the Java Virtual Machine (JVM). In addition to the log being taken, a dump of the JVM has been forced for this condition as well. Although it is possible the out of memory condition will correct itself, the console application will be restarted by problem analysis when this problem is analyzed.

Problem determination: Call your next level of support.

E355004E E355004E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An ill-formed HTTP request was detected by the task interface servlet. The servlet responded with content telling the user that an ill-formed request was received. This informational log is taken to allow

for debugging after the fact.

Problem determination: Call your next level of support.

E355004F E355004F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A Javascript error occurred on the client which we are logging and the client browser window location (URL) will be reloaded

Problem determination: Call your next level of support.

E3550060 E3550060

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when trying to instantiate a new LogonApp.

Problem determination: Call your next level of support.

E3550061 E3550061

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in the process of constructing the logon panel tasklet or starting the logon panel

Problem determination: Call your next level of support.

E3550062 E3550062

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while trying to logon via the non-panel logon.

Problem determination: Call your next level of support.

E3550063 E3550063

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside the logon bean.

Problem determination: Call your next level of support.

E3550064 E3550064

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside the panel logon tasklet

Problem determination: Call your next level of support.

E3550065 E3550065

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred creating the client user context.

Problem determination: Call your next level of support.

E35500C1 E35500C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while reading the file

Problem determination: Call your next level of support.

E35500C2 E35500C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while writing the file

Problem determination: Call your next level of support.

E35500C3 E35500C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The file did not exist, and we were instructed not to create it.

Problem determination: Call your next level of support.

E35500C4 E35500C4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while establishing client connections

Problem determination: Call your next level of support.

E35500C5 • E35500E9

E35500C5 E35500C5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during tasklet processing

Problem determination: Call your next level of support.

E35500C6 E35500C6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during client processing

Problem determination: Call your next level of support.

E35500E0 E35500E0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred creating the ClassId tasklet client.

Problem determination: Call your next level of support.

E35500E8 E35500E8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred looking up the specified class name.

Problem determination: Call your next level of support.

E35500E9 E35500E9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in tasklet processing.

Problem determination: Call your next level of support.

(E35501xx) Reference codes

E3550100 E3550100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating new Console Tasks file actzuict.dat ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550101 E3550101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating new Console Tasks back up file actzuict.org ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550102 E3550102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating new BufferedReader for read Console Tasks file actzuict.dat ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550103 E3550103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating new BufferedWriter to write backup Console Tasks file actzuict.org ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550104 E3550104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading a line from Console Tasks file actzuict.dat ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550105 E3550105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing a line to Console Tasks back up file actzuict.org ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550106 E3550106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error deleting Console Tasks file actzuict.dat ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550107 E3550107

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating new BufferedWriter for new updated Console Tasks file actzuict.dat ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550108 E3550108

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error writing a line to the new updated Console Tasks file actzuict.dat ConsoleTasks service task will not continue to run.

Problem determination: Call your next level of support.

E3550110 E3550110

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the ViewConsoleTasks task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The ViewConsoleTasks task has been ended.

E3550111 • E3550172

Problem determination: Call your next level of support.

E3550111 E3550111

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the ViewConsoleTasks task. The ViewConsoleTasks task has been ended.

Problem determination: Call your next level of support.

E3550112 E3550112

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the ViewConsoleTasks task. The ViewConsoleTasks task has been ended.

Problem determination: Call your next level of support.

E3550113 E3550113

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the ViewConsoleTasks task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The ViewConsoleTasks task has been ended.

Problem determination: Call your next level of support.

E3550114 E3550114

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the ViewConsoleTasks task action handler. The ViewConsoleTasks task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3550115 E3550115

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to initialize data in the ViewConsoleTasksBean method load(). The ViewConsoleTasks task will not continue to run.

Problem determination: Call your next level of support.

E3550116 E3550116

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to initialize data in the ViewConsoleTasksBean method prepare(). The ViewConsoleTasks task will not continue to run.

Problem determination: Call your next level of support.

E3550117 E3550117

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational component log used to track task invocations.

Problem determination: Call your next level of support.

E3550160 E3550160

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to initialize and/or run a Logoff.

Problem determination: Call your next level of support.

E3550170 E3550170

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while reconstructing a persisted framework object.

Problem determination: Call your next level of support.

E3550171 E3550171

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while reading the list of persisted object names.

Problem determination: Call your next level of support.

E3550172 E3550172

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Issue a message stating that I am waiting for the towers to start.

Problem determination: Call your next level of support.

E3550173 E3550173

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Issue message that towers have finished, get to work.

Problem determination: Call your next level of support.

E3550174 E3550174

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: During startup objects are unpersisted and added to the inventory (MOM). An object was unpersisted that already exists in MOM. The duplicate object is deleted and an error log is taken with information about the duplicate object.

Problem determination: Call your next level of support.

E3550175 E3550175

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: During startup objects are unpersisted and added to the inventory (MOM). An object was unpersisted that has already been unpersisted (duplicate object). The duplicate object is deleted and an error log is taken with information about the duplicate object.

Problem determination: Call your next level of support.

E3550190 E3550190

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred on the client side and was caught by the task infrastructure.

Problem determination: Call your next level of support.

E35501F4 E35501F4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error processing the Event Log Summary App.

Problem determination: Call your next level of support.

(E35502xx) Reference codes

E3550280 E3550280

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Either a class listed in an ini control file could not be loaded, or an exception occurred when running it.

Problem determination: Call your next level of support.

E3550281 E3550281

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Either the requested ini file could not be found, or there was an error parsing class file names from the ini file.

Problem determination: Call your next level of support.

E3550290 E3550290

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred creating a class in the CIMOM.

Problem determination: Call your next level of support.

(E35504xx) Reference codes

E3550410 E3550410

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DFC query file path table not found.

Problem determination: Call your next level of support.

E3550411 E3550411

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error reading DFC query file path table.

Problem determination: Call your next level of support.

E3550412 E3550412

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: In the DFC query file path table, there was at least one line where the path was not specified.

Problem determination: Call your next level of support.

E3550413 E3550413

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: More than one path specified for a given mask in the DFC query file path table.

Problem determination: Call your next level of support.

E3550414 E3550414

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The path extracted from the DFC query file path table contained an "*" in the first character. In this case, the path is to be taken from the DFC query file path file name that was an input from the caller. However, there was no path specified.

Problem determination: Call your next level of support.

E3550415 E3550415

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was no path found in the DFC query file path table for the file name that was input.

Problem determination: Call your next level of support.

E3550420 E3550420

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error encoding an object.

Problem determination: Call your next level of support.

E3550421 E3550421

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error decoding an object.

Problem determination: Call your next level of support.

E3550422 E3550422

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error constructing an object.

Problem determination: Call your next level of support.

E3550423 E3550423

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error uncaught by an application.

Problem determination: Call your next level of support.

E3550424 E3550424

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the protocol between machines.

Problem determination: Call your next level of support.

E3550425 E3550425

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

E3550426 • E3550451

Response: Error persisting an object.

Problem determination: Call your next level of support.

E3550426 E3550426

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The results of request brokering.

Problem determination: Call your next level of support.

E3550427 E3550427

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A request has been submitted for brokering.

Problem determination: Call your next level of support.

E3550430 E3550430

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.autologon.
CustomizeAutomaticLogonApp
CustomizeAutomaticLogonApp

Problem determination: Call your next level of support.

E3550431 E3550431

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.autologon.
CustomizeAutomaticLogonBean
CustomizeAutomaticLogonBean

Problem determination: Call your next level of support.

E3550432 E3550432

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.autologon.
CustomizeAutomaticLogonTasklet
CustomizeAutomaticLogonTasklet

Problem determination: Call your next level of support.

E3550440 E3550440

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.peaccess.
ProductEngineeringAccessApp
ProductEngineeringAccessApp

Problem determination: Call your next level of support.

E3550441 E3550441

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.peaccess.
ProductEngineeringAccessBean
ProductEngineeringAccessBean

Problem determination: Call your next level of support.

E3550442 E3550442

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.peaccess.
ProductEngineeringAccessTasklet
ProductEngineeringAccessTasklet

Problem determination: Call your next level of support.

E3550450 E3550450

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.grouping.GroupingApp
GroupingApp

Problem determination: Call your next level of support.

E3550451 E3550451

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in createGroup(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550452 **E3550452**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in modifyGroup(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550453 **E3550453**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.grouping.GroupingServerTasklet GroupingServerTasklet

Problem determination: Call your next level of support.

E3550454 **E3550454**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in starting patternmatching(). No isgroupable managedobjects exist.

Problem determination: Call your next level of support.

E3550455 **E3550455**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in modifyGroup(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550460 **E3550460**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to retrieve persisted data from the persistence manager. The default values for teh class will be used. This may result in classes that have made requests to be restarted not being restarted.

Problem determination: Call your next level of support.

E3550470 **E3550470**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in configuration.

Problem determination: Call your next level of support.

E3550471 **E3550471**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error constructing an object.

Problem determination: Call your next level of support.

E3550472 **E3550472**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error persisting an object.

Problem determination: Call your next level of support.

E3550473 **E3550473**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a task.

Problem determination: Call your next level of support.

E3550474 **E3550474**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a tasklet.

Problem determination: Call your next level of support.

E3550475 **E3550475**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a bean.

Problem determination: Call your next level of support.

E3550480 **E3550480**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was caught in the BaseTower

E3550481 • E3550489

constructor. This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550481 E3550481

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was thrown by VPD. This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550482 E3550482

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was thrown by NetworkSettings most likely because a program could not run as root. This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550483 E3550483

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was caught while initializing BaseTower.startTower(). This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550484 E3550484

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was caught processing the INI files in the BaseTower.startTower(). This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550485 E3550485

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An UnsatisfiedLinkError was caught processing the INI files in the BaseTower.startTower(). This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550486 E3550486

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was caught processing the INI files in the BaseTower.stopTower(). This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550487 E3550487

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An HException was caught trying to start CIMOM. This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550488 E3550488

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught in BaseTower.setHostNameInSim(). This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550489 E3550489

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught in the base tower constructor when trying to create the marker file used to determine if non-upgradable persistent data should be used. The base tower will continue to run, but will default to using non-upgradable persistent data.

Problem determination: Call your next level of support.

E355048A E355048A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught in the base tower constructor when trying to determine the location of the marker file used to determine if non-upgradable persistent data should be used. The base tower will continue to run, but will default to using non-upgradable persistent data.

Problem determination: Call your next level of support.

E355048B E355048B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught in the base tower constructor when trying to re-persist the data after resetting the non-upgradable persistent data to default values. The base tower will continue to run, but the persistent data for these non-upgradable items is incorrect.

Problem determination: Call your next level of support.

E355048C E355048C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught while trying to initialize the default name for the console. This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E355049E E355049E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught trying to create a task object. The console will continue to operate, but the task will not be available to any users.

Problem determination: Call your next level of support.

E355049F E355049F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in updateChildrenOfGroup(). This is an internal error that could be caused by incorrect tower definition XML (see the XML files in data/plugins/tower/). Possibly the task group was not created or the task group was not added to the object repository. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

(E35505xx) Reference codes

E3550511 E3550511

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the event log summary panel. Error in panelAction().

Problem determination: Call your next level of support.

E3550512 E3550512

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the block id panel. Error in panelAction().

Problem determination: Call your next level of support.

E3550513 E3550513

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the secondary block id panel. Error in panelAction().

Problem determination: Call your next level of support.

E3550514 E3550514

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the text expander panel. Error in panelAction().

Problem determination: Call your next level of support.

E3550515 E3550515

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the hex expander panel. Error in panelAction().

Problem determination: Call your next level of support.

E3550516 E3550516

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the standard expander panel. Error in panelAction().

Problem determination: Call your next level of support.

E355051A E355051A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the event log summary panel retrieving event log data.

Problem determination: Call your next level of support.

E355051C E355051C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while searching the log event data.

Problem determination: Call your next level of support.

E355051D E355051D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while displaying message for the search function

Problem determination: Call your next level of support.

E355051E E355051E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the expander data panel. Error in panelAction().

Problem determination: Call your next level of support.

E3550550 E3550550

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the EventSummary tasklet.

Problem determination: Call your next level of support.

E3550551 • E355055C

E3550551 E3550551

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading the log file.

Problem determination: Call your next level of support.

E3550552 E3550552

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the HexExpanderTasklet.

Problem determination: Call your next level of support.

E3550553 E3550553

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the SystemEventTasklet.

Problem determination: Call your next level of support.

E3550554 E3550554

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the TextExpanderTasklet.

Problem determination: Call your next level of support.

E3550555 E3550555

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the StandardExpanderTasklet.

Problem determination: Call your next level of support.

E3550556 E3550556

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the FileFn.

Problem determination: Call your next level of support.

E3550557 E3550557

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the FileFn.

Problem determination: Call your next level of support.

E3550558 E3550558

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the TextExpanderTasklet.

Problem determination: Call your next level of support.

E3550559 E3550559

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the DllExpanderTasklet.

Problem determination: Call your next level of support.

E355055A E355055A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading the log block.

Problem determination: Call your next level of support.

E355055B E355055B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the SystemEventTasklet. Unable to find the resource bundle.

Problem determination: Call your next level of support.

E355055C E355055C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the NativeE4ExpanderTasklet.

Problem determination: Call your next level of support.

E355055E **E355055E**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Null text in E4 log detected in the NativeE4ExpanderTasklet. This is an informational log, not an error log.

Problem determination: Call your next level of support.

(E35507xx) Reference codes

E3550700 E3550700

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The user interface was started in an unauthenticated user context. Look at the log for information about the user context.

Problem determination: Call your next level of support.

E3550701 E3550701

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught by a tasklet class and passed to UIEventTasklet.logException(). Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550702 E3550702

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A TaskletException was caught when instantiating LauncherUtils for a client session. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550703 E3550703

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception or Error was caught in UIClient#EventClient. This is the thread that receives property changes from the manager and passes the property changes to the user interface. The thread will continue processing property changes but will not log again if another error is detected. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550704 E3550704

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was caught in the constructor

of UIObjects. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550705 E3550705

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught trying to close the temporary file that contains user interface data for the displayed objects. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550706 E3550706

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught trying reading a temporary file that contains the identifiers of a managed object group. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550707 E3550707

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught trying reading a temporary file that contains the identifiers of a task group. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550708 E3550708

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught trying reading the temporary file that contains the identifiers of managed objects in an unacceptable state. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550709 E3550709

E355070B • E3550713

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught trying reading the temporary file that contains the identifiers of all root objects. Look at the log for information about the error.

Problem determination: Call your next level of support.

E355070B E355070B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught trying reading the temporary file that contains user interface data for the displayed objects. This failing method is trying to find all tasks that have an attention. Look at the log for information about the error.

Problem determination: Call your next level of support.

E355070C E355070C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception was caught instantiating the UIObjectsWriter singleton. This object is responsible for notifying user interfaces of objects added/removed from the Managed Object Manager and of changes to objects in the Managed Object Manager. Look at the log for information about the error.

Problem determination: Call your next level of support.

E355070D E355070D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: UIObjectsWriter was notified of a change to an unknown object. The event is ignored and an informational log is taken. Look at the log for information about the error.

Problem determination: Call your next level of support.

E355070E E355070E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An Exception or Error was caught processing a property change event. Look at the log for information about the error.

Problem determination: Call your next level of support.

E355070F E355070F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: UIObjectsWriter was not able to write the property to the temporary objects file because the property was too long. The record size must be increased to handle the size of the property. The property is truncated and an informational log is taken. Look at the log to determine the property name and size.

Problem determination: Call your next level of support.

E3550710 E3550710

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught by a tasklet class and passed to UIQueryTasklet.logException(). Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550711 E3550711

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught reading the user interface styles. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550712 E3550712

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught while reading the temporary file that contains user interface data for the displayed objects. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550713 E3550713

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught reading the user interface styles. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550714 E3550714

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught trying to close the properties file that defines the default style or the default style class file. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550715 E3550715

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught while processing an inventory event from the Managed Object Manager. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550716 E3550716

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The worker thread in UIObjectsWriter detected an exception. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550717 E3550717

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A property changes was received from an object that is not in the temporary objects file. Probably an error log was previously taken for this same object. The event is ignored and an informational log is taken. Look at the log for information about the error.

Problem determination: Call your next level of support.

E3550718 E3550718

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Caught an exception instantiating UIObjectsReader. Look at the log for more information about the error.

Problem determination: Call your next level of support.

E3550719 E3550719

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Caught an exception trying to get the list of tasks allowed for a managed object. Look at the log for more information about the error.

Problem determination: Call your next level of support.

E355071A E355071A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was caught trying reading a temporary file that contains the identifiers of a group. Look at the log for information about the error.

Problem determination: Call your next level of support.

E355071B E355071B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown Status was passed to UIObjectsWriter. The log contains information about the unknown Status as well as a dump of all known Status.

Problem determination: Call your next level of support.

E355071C E355071C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The size of the Status to shortId map is not equal to the size of the shortId to Status map. The log contains a dump of both maps.

Problem determination: Call your next level of support.

E355071D E355071D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Caught an exception trying to get the map of tasks and the permitted target classes. Look at the log for more information about the error.

Problem determination: Call your next level of support.

E355071E E355071E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Caught an exception trying to instantiate a pluggable user interface style object. A log is taken with information about the failure and the next pluggable user interface style is processed. Look at the log for more information about the error.

Problem determination: Call your next level of support.

E355071F E355071F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOExecution was caught trying read the file that contains all the short identifiers of tasks that are allowed to be launched against a managed object. Look at the log for more information about the error.

Problem determination: Call your next level of support.

E3550720 E3550720

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This informational log is taken when a group contains duplicate short identifiers. The Managed Object Framework allows duplicate identifiers in a group but the zSeries tower does not. The log will contain the children of the group before adding the duplicates and the identifiers to be added.

Problem determination: Call your next level of support.

E3550721 E3550721

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Class ShortIdManager could not create a short identifier from an ObjectId because there are too many short identifiers or, more likely, a code bug.

Problem determination: Call your next level of support.

E3550722 E3550722

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not determine the task to be launched. Look at the log for more information about the error.

Problem determination: Call your next level of support.

E3550723 E3550723

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Could not get the task object to be launched from the object repository. Look at the log for more information about the error.

Problem determination: Call your next level of support.

E3550790 E3550790

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with configuration data.

Problem determination: Call your next level of support.

E3550791 E3550791

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error constructing an object.

Problem determination: Call your next level of support.

E3550792 E3550792

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error persisting an object.

Problem determination: Call your next level of support.

E3550793 E3550793

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a task.

Problem determination: Call your next level of support.

E3550794 E3550794

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a tasklet.

Problem determination: Call your next level of support.

E3550795 E3550795

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a bean.

Problem determination: Call your next level of support.

E3550796 E3550796

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error uncaught.

Problem determination: Call your next level of support.

E3550797 E3550797

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: General Error ID for RCS Callhome Errors.

Problem determination: Call your next level of support.

E3550798 E3550798

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Indicates that the model MT5600BA-V92 modem associated with the system has back level firmware installed.

Problem determination: Call your next level of support.

E35507B0 E35507B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was logged while trying to perform a function in the network Diagnostics console action.

Problem determination: Call your next level of support.

E35507C0 E35507C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught trying to save the original settings to a file. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C1 E35507C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught was reading file data/defaultuserdef.properties. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C2 E35507C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught persisting object ObjectLockingSettings.Persist. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C3 E35507C3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught in the object locking tasklet. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C4 E35507C4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught trying to save the object locking settings. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C5 E35507C5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught instantiating DefaultUserSettings. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C6 E35507C6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: PersistenceManager threw an exception while saving the default user settings. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C7 E35507C7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the tasklet and method ObjectControlsTasklet.logException() was called to log the error. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C8 E35507C8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the tasklet and method ConfirmationSettingsTasklet.logException() was called to log the error. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507C9 E35507C9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the tasklet and method ObjectBackgroundSettingsTasklet.logException() was called to log the error. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507CA E35507CA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the tasklet and method UIStylesTasklet.logException() was called to log the error. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507CB E35507CB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the tasklet and method UserSettingsTasklet.logException() was called to log the error. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507CC E35507CC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the tasklet and method ToggleViewsTasklet.logException() was called to log the error. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507CD E35507CD

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the tasklet and method UserSettingsTask.logException() was called to log the error. Look at the log for details about the exception.

Problem determination: Call your next level of support.

E35507CE E35507CE

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error was detected by the bean used to display the colors and patterns pane in the User Settings task. These settings are written to an informational log just before this error log is taken. Look at the informational log to debug the settings.

Problem determination: Call your next level of support.

E35507CF E35507CF

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An information log taken when the User Settings task detects and error. The displayed user settings are written to the log.

Problem determination: Call your next level of support.

E35507D0 E35507D0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An uncaught error occurred that resulted in the termination of the manager process.

Problem determination: Call your next level of support.

E35507D1 E35507D1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during manager initialization.

Problem determination: Call your next level of support.

E35507D2 E35507D2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during manager termination.

Problem determination: Call your next level of support.

E35507D3 E35507D3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the static initialization of the Manager class.

Problem determination: Call your next level of support.

E35507D4 E35507D4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Information log taken because a file in the tower subdirectory does not have a numeric extension. The file name is in the log.

Problem determination: Call your next level of support.

E35507D5 E35507D5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Information log taken because a file in the tower subdirectory does not have a valid file name. The file name is in the log.

Problem determination: Call your next level of support.

E35507D6 E35507D6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to add a tower to the Managed Object Manager.

Problem determination: Call your next level of support.

E35507D7 E35507D7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating a tower. The tower file name is in the log.

Problem determination: Call your next level of support.

E35507D8 E35507D8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Information log taken if a tower startup fails.

Problem determination: Call your next level of support.

E35507D9 E35507D9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Information log taken if a tower shutdown fails.

Problem determination: Call your next level of support.

E35507DA E35507DA

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error processing the tower file that contains the class name. The tower file name is in the log.

Problem determination: Call your next level of support.

E35507DB E35507DB

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational log taken to indicate that the manager has completed its startup processing.

E35507DC

Problem determination: Call your next level of support.

E35507DC E35507DC

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to start the PCE server program.

Problem determination: Call your next level of support.

(E35508xx) Reference codes

E3550800 E3550800

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error code for errors occurring in the Prelogin Monitor Task - Logged when an exception is thrown in Tasklet.

Problem determination: Call your next level of support.

E3550810 E3550810

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with configuration data.

Problem determination: Call your next level of support.

E3550811 E3550811

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error constructing an object.

Problem determination: Call your next level of support.

E3550812 E3550812

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error persisting an object or creating an object from persistence.

Problem determination: Call your next level of support.

E3550813 E3550813

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a task.

Problem determination: Call your next level of support.

E3550814 E3550814

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a tasklet.

Problem determination: Call your next level of support.

E3550815 E3550815

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a bean.

Problem determination: Call your next level of support.

E3550816 E3550816

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a protocol such as a communication protocol.

Problem determination: Call your next level of support.

E3550830 E3550830

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected internal error occurred. Examine the actual exception to determine the source and severity of the problem.

Problem determination: Call your next level of support.

E3550831 E3550831

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was thrown in the connection server accept loop due to a problem with the accept itself, or the connection handler thread threw an exception. Examine the actual exception to determine the source and severity of the problem.

Problem determination: Call your next level of support.

E3550832 E3550832

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There was an IO exception on the socket communication between a client and the manager. Anything that causes a socket communication exception can cause this log entry. The client or manager

E3550840 • E3550861

programs may have ended abruptly or the connection between the two may have been physically broken. Examine the actual IO exception and the environment in which it occurred to determine the source and severity of the exception.

Problem determination: Call your next level of support.

E3550840 E3550840

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the shutdown task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3550841 E3550841

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the shutdown task. The task has been ended.

Problem determination: Call your next level of support.

E3550843 E3550843

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the shutdown task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3550850 E3550850

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.snmp.SnmpApp SnmpApp

Problem determination: Call your next level of support.

E3550851 E3550851

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside

com.ibm.hwmca.base.settings.snmp.SnmpBean SnmpBean

Problem determination: Call your next level of support.

E3550852 E3550852

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.settings.snmp.SnmpTasklet SnmpTasklet

Problem determination: Call your next level of support.

E3550853 E3550853

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while trying to start the SNMP daemon in com.ibm.hwmca.base.settings.snmp.Snmpd Snmpd

Problem determination: Call your next level of support.

E3550854 E3550854

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while trying to stop the SNMP daemon in com.ibm.hwmca.base.settings.snmp.Snmpd Snmpd

Problem determination: Call your next level of support.

E3550860 E3550860

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during startup. The base tower was not yet initialized.

Problem determination: Call your next level of support.

E3550861 E3550861

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in obtaining the network interface information. The local machine only had loopback addresses for IPs (127.0.0.1).

Problem determination: Call your next level of support.

E3550862 E3550862

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the processConnection() method of a FCS service

Problem determination: Call your next level of support.

E3550880 E3550880

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when processing the data for a log event.

Problem determination: Call your next level of support.

E3550881 E3550881

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to display the log data.

Problem determination: Call your next level of support.

E3550882 E3550882

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the log file

Problem determination: Call your next level of support.

E3550883 E3550883

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to display the log data.

Problem determination: Call your next level of support.

E3550884 E3550884

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to retrieve the log block data.

Problem determination: Call your next level of support.

E3550885 E3550885

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to read the log block data.

Problem determination: Call your next level of support.

E3550886 E3550886

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to retrieve the list of log classes and their descriptions.

Problem determination: Call your next level of support.

E3550887 E3550887

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to purge logs.

Problem determination: Call your next level of support.

E3550888 E3550888

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to retrieve the log block data for the View Data file list function.

Problem determination: Call your next level of support.

E3550889 E3550889

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to create/close a new file.

Problem determination: Call your next level of support.

E355088A E355088A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to get the list of FEDC files. from LogCollectionAgent.getFileList()

Problem determination: Call your next level of support.

E355088B • E3550896

E355088B E355088B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to close the file.

Problem determination: Call your next level of support.

E355088C E355088C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the log after a purge.

Problem determination: Call your next level of support.

E355088D E355088D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the log for a list of selected classes

Problem determination: Call your next level of support.

E355088E E355088E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the log for a list of all classes

Problem determination: Call your next level of support.

E355088F E355088F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the log for a refresh

Problem determination: Call your next level of support.

E3550890 E3550890

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the log file specified by the user

Problem determination: Call your next level of support.

E3550891 E3550891

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to get the environment var CONSOLE_PATH

Problem determination: Call your next level of support.

E3550892 E3550892

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to get the next window of log summary data

Problem determination: Call your next level of support.

E3550893 E3550893

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the log map key file

Problem determination: Call your next level of support.

E3550894 E3550894

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to load the log map key file

Problem determination: Call your next level of support.

E3550895 E3550895

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to read the component logs that the user selected

Problem determination: Call your next level of support.

E3550896 E3550896

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught when trying to purge the component logs that the user selected

Problem determination: Call your next level of support.

(E35509xx) Reference codes

E3550911 E3550911

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.userprof.UserProfTasklet UserProfTasklet

Problem determination: Call your next level of support.

E3550912 E3550912

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.userprof.UserProfApp UserProfApp

Problem determination: Call your next level of support.

E3550913 E3550913

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in getUIInfo(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550914 E3550914

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UpgradeUserProfData.saveUpgradeData(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550915 E3550915

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UpgradeUserProfData.restoreUpgradeData(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550916 E3550916

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Information message to indicate the UserProfSaveRestore.getSaveableData method has been invoked.

Problem determination: Call your next level of support.

E3550917 E3550917

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Number of roles being saved in UserProfSaveRestore.getSaveableData.

Problem determination: Call your next level of support.

E3550918 E3550918

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Number of users being saved in UserProfSaveRestore.getSaveableData.

Problem determination: Call your next level of support.

E3550919 E3550919

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Ending UserProfSaveRestore.getSaveableData function.

Problem determination: Call your next level of support.

E355091A E355091A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Initial start of UserProfSaveRestore.restoreData function.

Problem determination: Call your next level of support.

E355091B E355091B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

E355091C • E355092A

Response: Number of roles being restored in UserProfSaveRestore.restoreData function.

Problem determination: Call your next level of support.

E355091C E355091C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Number of users being restored in UserProfSaveRestore.restoreData function.

Problem determination: Call your next level of support.

E355091D E355091D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Ending UserProfSaveRestore.restoreData function.

Problem determination: Call your next level of support.

E355091E E355091E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UserProfSaveRestore.processUsers.

Problem determination: Call your next level of support.

E355091F E355091F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UserProfSaveRestore.oldProcessUsers.

Problem determination: Call your next level of support.

E3550920 E3550920

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UserProfSaveRestore.processRoles.

Problem determination: Call your next level of support.

E3550921 E3550921

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UserProfilesPluginImpl.

Problem determination: Call your next level of support.

E3550922 E3550922

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UserProfilesTasklet.

Problem determination: Call your next level of support.

E3550923 E3550923

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Number of userdefinedtaskgroups being restored in UserProfSaveRestore.restoreData function.

Problem determination: Call your next level of support.

E3550925 E3550925

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in NewUserBean class.

Problem determination: Call your next level of support.

E3550926 E3550926

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in AddUserBean class.

Problem determination: Call your next level of support.

E355092A E355092A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.userrole.UserRole UserRoleTasklet

Problem determination: Call your next level of support.

E355092B E355092B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.userrole.UserRoleApp UserRoleApp

Problem determination: Call your next level of support.

E355092C E355092C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in getUIInfo(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E355092D E355092D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in AddRoleBean(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E355092E E355092E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in AddRoleBean(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550930 E3550930

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error on the client trying to run the "Task List" task.

Problem determination: Call your next level of support.

E3550931 E3550931

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error on the manager trying to serve the "Task List" task.

Problem determination: Call your next level of support.

E3550932 E3550932

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error on the client trying to run the "Change Password" task.

Problem determination: Call your next level of support.

E3550934 E3550934

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to run the Reauthentication task.

Problem determination: Call your next level of support.

E3550950 E3550950

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the settings task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The settings task has been ended.

Problem determination: Call your next level of support.

E3550951 E3550951

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the settings task. The settings task has been ended.

Problem determination: Call your next level of support.

E3550952 E3550952

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the settings task. The settings task has been ended.

Problem determination: Call your next level of support.

E3550953 **E3550953**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the instantiation of a tower class, a tab on the settings task. The settings task should continue

Problem determination: Call your next level of support.

E3550954 **E3550954**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the file name validity check of a tower class, a tab on the settings task. The settings task should continue

Problem determination: Call your next level of support.

E3550955 **E3550955**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the settings task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The settings task has been ended.

Problem determination: Call your next level of support.

E3550956 **E3550956**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the network settings task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The network settings task has been ended.

Problem determination: Call your next level of support.

E3550957 **E3550957**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the account information settings task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The account information settings task has been ended.

Problem determination: Call your next level of support.

E3550958 **E3550958**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the settings task action handler. The settings task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3550959 **E3550959**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the network settings task action handler. The network settings task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E355095A **E355095A**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the account info settings task action handler. The account info settings task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E355095B **E355095B**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some internet address processing in the network settings task action handler. The network settings task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E355095C **E355095C**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some firewall operation.

Problem determination: Call your next level of support.

E355095D E355095D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception occurred during the restore of Account Info Settings. The task has been ended.

Problem determination: Call your next level of support.

E355095E E355095E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception occurred during the restore of Network Settings. The task has been ended.

Problem determination: Call your next level of support.

E355095F E355095F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception occurred during the restore of Network Settings. The task has been ended.

Problem determination: Call your next level of support.

E3550960 E3550960

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational event. Network Settings have been updated.

Problem determination: Call your next level of support.

E3550961 E3550961

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational event. IP/Netmask set by matching MAC addresses.

Problem determination: Call your next level of support.

E3550970 E3550970

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error uncaught by a listener. Command execution continues.

Problem determination: Call your next level of support.

E3550990 E3550990

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The WorkEvent associated with the work completed in the WorkThread contains an Exception. This exception is logged as an HException in a FrameworkLog. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3550991 E3550991

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when attempting to persist an HwmcaObject.

Problem determination: Call your next level of support.

E3550992 E3550992

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A registered interface implementation class name does not exist.

Problem determination: Call your next level of support.

E3550993 E3550993

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while processing a property change event.

Problem determination: Call your next level of support.

E3550994 E3550994

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while processing a property change event.

Problem determination: Call your next level of support.

E3550995 E3550995

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A registered interface implementation class name does not exist.

E3550996 • E35509A1

Problem determination: Call your next level of support.

E3550996 E3550996

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred when updating the console tasks performed information.

Problem determination: Call your next level of support.

E3550997 E3550997

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid hashing algorithm identifier was used.

Problem determination: Call your next level of support.

E3550998 E3550998

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while processing a property change event.

Problem determination: Call your next level of support.

E3550999 E3550999

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A ClassNotFoundException occurred in myGetInventoryObjects().

Problem determination: Call your next level of support.

E355099A E355099A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A ClassNotFoundException occurred in myGetInventoryObjects().

Problem determination: Call your next level of support.

E355099B E355099B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A ClassNotFoundException occurred in myGetInventoryObjects().

Problem determination: Call your next level of support.

E355099C E355099C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while calling getProperties on an object or a provider.

Problem determination: Call your next level of support.

E355099D E355099D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while calling setProperties on an object or a provider.

Problem determination: Call your next level of support.

E355099E E355099E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while calling Tower.getUIBooks().

Problem determination: Call your next level of support.

E355099F E355099F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in UnacceptableManagedObjects.Worker.performWork().

Problem determination: Call your next level of support.

E35509A0 E35509A0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in RootObjects.Worker.performWork().

Problem determination: Call your next level of support.

E35509A1 E35509A1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: getUIInfo() was called but the UIInfo object is null. This log is only taken once for each object in the Managed Object Manager.

Problem determination: Call your next level of support.

E35509A2 E35509A2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to update the root user's login password.

Problem determination: Call your next level of support.

E35509A3 E35509A3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to establish a timer to update the root user's login password each night.

Problem determination: Call your next level of support.

E35509A4 E35509A4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The User Settings for a user were changed. The changed settings are logged.

Problem determination: Call your next level of support.

E35509A5 E35509A5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught in GroupSummary.Worker.performWork(). Look at the log and the trace block for more information about the error.

Problem determination: Call your next level of support.

E35509B0 E35509B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Tasklet panel manager general abnormal tasklet failure. Often generated when an exception is caught while handling a users request.

Problem determination: Call your next level of support.

E35509B1 E35509B1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Tasklet manager general failure. Often generated when an exception is caught while handling a users service request.

Problem determination: Call your next level of support.

E35509B2 E35509B2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Several user actions can result in warnings being issued. These warnings, although not always fatal, may indicate a problem with the task logic.

Problem determination: Call your next level of support.

(E35510xx) Reference codes

E3551010 E3551010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside `com.ibm.hwmca.base.Password.PasswordPasswordTasklet`

Problem determination: Call your next level of support.

E3551011 E3551011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside `com.ibm.hwmca.base.Password.PasswordAppPasswordApp`

Problem determination: Call your next level of support.

E3551012 E3551012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in `getUIInfo()`. Look at the logged `HException` for information about the error.

Problem determination: Call your next level of support.

E3551013 E3551013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in `UpgradePassProfData.saveUpgradeData()`. Look at the logged `HException` for information about the error.

Problem determination: Call your next level of support.

E3551014 E3551014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in `UpgradePassProfData.restoreUpgradeData()`. Look at the logged `HException` for information about the error.

Problem determination: Call your next level of support.

E3551015 E3551015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in `UpgradePassProfData.getPasswordRules()`. Look at the logged `HException` for information about the error.

Problem determination: Call your next level of support.

E3551016 E3551016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in `PasswordRuleBean` class. Look at the logged `HException` for information about the error.

Problem determination: Call your next level of support.

E3551030 E3551030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error instantiating the `LicenseManager` implementation.

Problem determination: Call your next level of support.

E3551031 E3551031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error running the "View License Agreements" task.

Problem determination: Call your next level of support.

E3551032 E3551032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling `BaseFileControl.getFilePath()` for file control nickname "licenseDefinitions".

Problem determination: Call your next level of support.

E3551033 E3551033

Explanation: Licensed Internal Code failure on the

E3551040 • E3551047

Hardware Management Console (HMC).

Response: Error reading or parsing one of the XML files defining what licenses are available for viewing.

Problem determination: Call your next level of support.

E3551040 E3551040

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred while processing a property change event for a tree node representing a managed object or group. The error is logged and ignored, most likely causing the client to be out of sync with the back-end data.

Problem determination: Call your next level of support.

E3551041 E3551041

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred that prevented displaying a message to the user. The error is logged and ignored.

Problem determination: Call your next level of support.

E3551042 E3551042

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred while attempting to launch a task at the user's request. The task is most likely not running, and the error is logged and ignored.

Problem determination: Call your next level of support.

E3551043 E3551043

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred while distributing a property change event to a listener. Other listeners will still be notified of the event, but the listener who originated the exception most likely has out-of-date data. The error is logged and ignored.

Problem determination: Call your next level of support.

E3551044 E3551044

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred while notifying listeners of an event that was placed on an event queue. This exception most likely originated during the event handling of one of the listeners. This will cause 1 to n listeners' data to be out of sync. The error is logged and ignored.

Problem determination: Call your next level of support.

E3551045 E3551045

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred while notifying listeners of an event queue becoming empty. This exception most likely originated during the event handling of one of the listeners. Because queue empty listeners usually use this event to refresh the client, the client is most likely now out of sync. The error is logged and ignored.

Problem determination: Call your next level of support.

E3551046 E3551046

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred causing the thread death of an event queue. This is a serious error, because it means that no more notifications of events will be sent to listeners, and thus clients will no longer receive any updates, and the console will most likely have to be restarted. The error is logged and ignored.

Problem determination: Call your next level of support.

E3551047 E3551047

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A unknown host error has occurred during the initialization of the controller servlet. This is a serious error, because it means that the tree-style UI will be entirely un-usable until fixed. It is incredibly unlikely for this to occur, because it means that the UI was the first to use the system user context, causing its creation. This creation failed due to an `UnknownHostException`, which is what this error is logging.

Problem determination: Call your next level of support.

E3551048 E3551048

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A configuration error has occurred during the initialization of the controller servlet. This is a serious error, because it means that the tree-style UI will be entirely un-usable until fixed. It is assumed these will only occur in test. The error is logged and an error page will be displayed to the client.

Problem determination: Call your next level of support.

E3551049 E3551049

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred preventing the initialization of the tree-style UI session data for a newly logged in user. The error is logged and an error page is displayed to the user. However, retrying the request will cause another attempt at initialization of the session data, which may or may not work.

Problem determination: Call your next level of support.

E355104A E355104A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error has occurred preventing the initialization of the tree-style UI per-session facade data. The error is logged and an error page is displayed to the user. However, retrying the request will cause another attempt at initialization of the facade data, which may or may not work.

Problem determination: Call your next level of support.

E355104B E355104B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error has occurred while attempting to render requested output for some aspect of the tree-style UI. The error is logged and the request is ignored by setting "no content" in the response. This most likely means that the client is out of sync. Further requests may or may not work.

Problem determination: Call your next level of support.

E355104C E355104C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error has occurred while allowing WCL to handle a request they said they could handle. The error is logged and the request is ignored by setting "no content" in the response. This most likely means that the client is out of sync. Further requests will most likely work.

Problem determination: Call your next level of support.

E355104D E355104D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown error, other than the other "SERVLET" errors, has occurred during the processing of a request. The error is logged and an error page is displayed to the user. Further requests may or may not work.

Problem determination: Call your next level of support.

E3551050 E3551050

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Successfully retrieved file from remote system.

Problem determination: Call your next level of support.

E3551051 E3551051

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Successfully transferred file to remote system.

Problem determination: Call your next level of support.

E3551052 E3551052

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Successfully deleted remote file.

Problem determination: Call your next level of support.

E3551060 E3551060

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Uncaught exception encountered in servlet processing.

Problem determination: Call your next level of support.

E3551061 E3551061

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred parsing the web app extension xml files.

These files reside in the "extensions" directory, a peer to the Tomcat "webapps" directory.

The DTDs defining the proper syntax of each type of file also reside in that directory.

Problem determination: Call your next level of support.

E3551062 E3551062

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The context directory configured for an extension web application does not exist or the name is not a directory.

Problem determination: Call your next level of support.

E3551063 E3551063

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred attempting to instantiate the customer role provider associated with an extension web application.

Problem determination: Call your next level of support.

E3551070 E3551070

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown exception was caught by the object locking task. Look at the log for information about the exception.

Problem determination: Call your next level of support.

E3551071 E3551071

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown exception was caught by the object locking tasklet. Look at the log for information about the exception.

Problem determination: Call your next level of support.

E3551080 E3551080

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the remote console task. This is the result of an exception being caught by the underlying infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3551081 E3551081

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to start a new task for the remote console session. The remote sessions was not started.

Problem determination: Call your next level of support.

E3551082 E3551082

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the runTask method. The remote console task has been ended.

Problem determination: Call your next level of support.

E3551090 E3551090

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This info log is intended to document the most recent key events that occurred in the data replication task. They may be simply informational or may indicate a warning condition.

Problem determination: Call your next level of support.

E35510A0 E35510A0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to determine the file path to use for the system log monitor rule definitions XML file. The system log monitor will continue to run, but it will not be using any of the rules defined in the XML file. This will result in no system log messages being processed in the correct manner. The system should be checked to make sure the rules definition XML file exists in the expected location and has the correct permissions.

Problem determination: Call your next level of support.

E35510A1 E35510A1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to determine the path to use for the pipe for reading system log messages. The system log monitor will continue to run and will attempt to use a default, hard coded path for this named pipe. If the default pipe name is correct, the system log monitor will be able to continue processing system log messages. If the default pipe name is not correct, the system log monitor will not be able to process messages from the system log.

Problem determination: Call your next level of support.

E35510A2 E35510A2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected error occurred trying to process system log messages. The system log monitor has ended and will no longer process messages from the system log. The console application will need to be restarted in order to restart the system log monitor.

Problem determination: Call your next level of support.

E35510A3 E35510A3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to read the system log monitor rules definition XML file. The system log monitor will continue to run, but it will not be using any of the rules defined in the XML file. This will result in no system log messages being processed in the correct manner. The system should be checked to make sure the rules definition XML file exists in the expected location and has the correct permissions.

Problem determination: Call your next level of support.

E35510A4 E35510A4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to call a handler defined in the system log monitor rules definition XML. The system log monitor determined that a system log message occurred that matched a defined rule, but the handler defined for that rule had an error processing the system log message. The system log monitor will continue to process system log messages like before the error, but the next level of support should be contacted to determine why there was an error processing the message by the handler.

Problem determination: Call your next level of support.

E35510B0 E35510B0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: General info log indication for users of the PseqTrace facility. This info log is taken when an odd circumstance occurs while processing a sequence or a group-sequence.

Problem determination: Call your next level of support.

E35510C0 E35510C0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the tip task. This is the result of an exception being caught by the underlying infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E35510C1 E35510C1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the runTask method. The tip task has been ended.

Problem determination: Call your next level of support.

E35510C2 E35510C2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred trying to start the tip task when a user logged on to the console. The console application will continue to run normally, but the tip task was not automatically run for the user when they logged on.

Problem determination: Call your next level of support.

E35510D0 E35510D0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An application has requested all subsequent shutdown requests to be blocked. This INFORMATIONAL log is used to track the requesting application for audit trail purposes. This is not an error.

Problem determination: Call your next level of support.

E35510D1 E35510D1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An application has requested to no longer block all subsequent shutdown requests. This INFORMATIONAL log is used to track the requesting application for audit trail purposes. This is not an error.

Problem determination: Call your next level of support.

E35510D2 E35510D2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational component log used to track common message invocations.

Problem determination: Call your next level of support.

E35510D3 E35510D3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Informational component log used to track task starting and ending.

Problem determination: Call your next level of support.

E35510D4 E35510D4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the subtasklet used to perform the client startup processing. The client startup will continue.

Problem determination: Call your next level of support.

E35510E0 E35510E0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.ldapservers.LdapServerTasklet

Problem determination: Call your next level of support.

E35510E1 E35510E1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.ldapservers.LdapServerApp LdapServerApp

Problem determination: Call your next level of support.

E35510E2 E35510E2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in implClass loading process(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510E3 E35510E3

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UpgradeLdapServerData.saveUpgradeData(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510E4 E35510E4

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UpgradeLdapServerData.restoreUpgradeData(). Look at

the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510E5 E35510E5

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in UpgradeLdapServerData.getLdapServers(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510E6 E35510E6

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in LdapServerTasklet.getUsedServers(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510E7 E35510E7

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in LdapServerData initialization code. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510E8 E35510E8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in LdapServerData persisting the definition data. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510E9 E35510E9

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in LdapServerData updating the definitions data. Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E35510F1 E35510F1

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response:

Problem determination: Call your next level of support.

E35510F2 E35510F2

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response:

Problem determination: Call your next level of support.

(E35511xx) Reference codes

E3551101 E3551101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response:

Problem determination: Call your next level of support.

E3551103 E3551103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response:

Problem determination: Call your next level of support.

E3551110 E3551110

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.userprof.UserProfTasklet UserProfTasklet

Problem determination: Call your next level of support.

E3551111 E3551111

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside com.ibm.hwmca.base.wizard.WizardApp WizardApp

Problem determination: Call your next level of support.

E3551112 E3551112

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in refreshing password rules. HException for information about the error.

Problem determination: Call your next level of support.

E3551113 E3551113

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in

UpgradeUserProfData.saveUpgradeData(). Look at the logged HException for information about the error.

Problem determination: Call your next level of support.

E3551120 E3551120

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a task.

Problem determination: Call your next level of support.

E3551121 E3551121

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a tasklet.

Problem determination: Call your next level of support.

E3551122 E3551122

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a bean.

Problem determination: Call your next level of support.

E3551130 E3551130

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Callhome Report results.

Problem determination: Call your next level of support.

E3551131 E3551131

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with configuration file data/callhome/hosts.xml. The method readHostXml() was not able to parse the hosts.xml file.

Problem determination: Call your next level of support.

(E35A) Reference codes

E35A0001 E35A0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception occurred constructing a monitor condition class. The error reason is 0.

Problem determination: Call your next level of support.

E35A0002 E35A0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception occurred constructing a monitor action class. The error reason is 0.

Problem determination: Call your next level of support.

E35A0003 E35A0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A throwable was thrown while running the monitor. The error reason is 0.

Problem determination: Call your next level of support.

E35A0004 E35A0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The logException() method of the Ping tasklet was called with a throwable as a parameter. The error reason is 0.

Problem determination: Call your next level of support.

E35A0005 E35A0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unknown event was received by the service() method of a monitor tasklet. The error reason is 0.

Problem determination: Call your next level of support.

(E35B) Reference codes

E35B0001 **E35B0001**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The hostname of the HMC can not be determined. The error reason is 0.

Problem determination: Call your next level of support.

E35B0002 **E35B0002**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unknown event received in service() of PanelTasklet subclass.. The error reason is 0.

Problem determination: Call your next level of support.

E35B0003 **E35B0003**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected throwable thrown in service() method of PanelTasklet subclass. The error reason is 0.

Problem determination: Call your next level of support.

E35B0004 **E35B0004**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected TaskletException thrown while trying to show a message box to the user. The error reason is 0.

Problem determination: Call your next level of support.

E35B0005 **E35B0005**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected throwable thrown during function of the PanelTasklet subclass. The error reason is 0.

Problem determination: Call your next level of support.

E35B0006 **E35B0006**

Explanation: Licensed Internal Code failure on the

Hardware Management Console (HMC).

Response: Unexpected HException thrown while constructing a CertMgtBean. The error reason is 0.

Problem determination: Call your next level of support.

E35B0007 **E35B0007**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unknown event received in panelAction() of PanelBean subclass. The error reason is 0.

Problem determination: Call your next level of support.

E35B0008 **E35B0008**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException thrown retrieving values from DDFC. The error reason is 0.

Problem determination: Call your next level of support.

E35B0009 **E35B0009**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A CertificateParsingException was thrown while constructing a SubjectAltNames object. The error reason is 0.

Problem determination: Call your next level of support.

E35B000A **E35B000A**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected throwable thrown during function of the PanelTask subclass. The error reason is 0.

Problem determination: Call your next level of support.

E35B000B **E35B000B**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

E35B000C • E35B0016

Response: HException thrown parsing a certificate. The error reason is 0.

Problem determination: Call your next level of support.

E35B000C E35B000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IOException thrown creating a temporary file. The error reason is 0.

Problem determination: Call your next level of support.

E35B000D E35B000D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException thrown while constructing a ArchivedServerCertBean. The error reason is 0.

Problem determination: Call your next level of support.

E35B000E E35B000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected choice made from the SigningChoicePanel. The error reason is 0.

Problem determination: Call your next level of support.

E35B000F E35B000F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: There is no removable media type devices available. The error reason is 0.

Problem determination: Call your next level of support.

E35B0010 E35B0010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected choice made from the RemovableMediaChoicePanel. Not used anymore. The error reason is 0.

Problem determination: Call your next level of support.

E35B0011 E35B0011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected exception getting list of removable media devices. The error reason is 0.

Problem determination: Call your next level of support.

E35B0012 E35B0012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The certificate is null which is unexpected. The error reason is 0.

Problem determination: Call your next level of support.

E35B0013 E35B0013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected HException thrown. The error reason is 0.

Problem determination: Call your next level of support.

E35B0014 E35B0014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected removable media related Exception thrown. The error reason is 0.

Problem determination: Call your next level of support.

E35B0015 E35B0015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected null returned from DDFC. The error reason is 0.

Problem determination: Call your next level of support.

E35B0016 E35B0016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception while installing the certificate. The error reason is 0.

Problem determination: Call your next level of support.

E35B0017 E35B0017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception while pushing information to the alternate SE. The error reason is 0.

Problem determination: Call your next level of support.

E35B0018 E35B0018

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected condition. The error reason is 0.

Problem determination: Call your next level of support.

E35B0019 E35B0019

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: File download to browser failed. The error reason is 0.

Problem determination: Call your next level of support.

E35B001A E35B001A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: File download to browser returned an unexpected return code. The error reason is 0.

Problem determination: Call your next level of support.

E35B001B E35B001B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: File download to browser returned an unexpected return code of not completed. The error reason is 0.

Problem determination: Call your next level of support.

E35B001C E35B001C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: File(s) upload from browser failed. The error reason is 0.

Problem determination: Call your next level of support.

E35B001D E35B001D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: File(s) upload from browser returned an unexpected return code. The error reason is 0.

Problem determination: Call your next level of support.

E35B001E E35B001E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: File(s) upload from browser returned an unexpected return code of not completed. The error reason is 0.

Problem determination: Call your next level of support.

E35B001F E35B001F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unexpected Throwable thrown. The error reason is 0.

Problem determination: Call your next level of support.

E35B0020 E35B0020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unable to connect to remote ssl server The error reason is 0.

Problem determination: Call your next level of support.

(E35C) Reference codes

E35C0000 E35C0000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: no Error - HardwareAnalysisFailure 0x0000

Problem determination: Call your next level of support.

E35C0001 E35C0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log out refcode - HardwareAnalysisFailure 0x0001

Problem determination: Call your next level of support.

E35C0002 E35C0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log outdata extension - HardwareAnalysisFailure 0x0002

Problem determination: Call your next level of support.

E35C0003 E35C0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log out panel id - HardwareAnalysisFailure 0x0003

Problem determination: Call your next level of support.

E35C0004 E35C0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log panel lib - HardwareAnalysisFailure 0x0004

Problem determination: Call your next level of support.

E35C0005 E35C0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log outdata priority

- HardwareAnalysisFailure 0x0005

Problem determination: Call your next level of support.

E35C0006 E35C0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log text field - HardwareAnalysisFailure 0x0006

Problem determination: Call your next level of support.

E35C0007 E35C0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log service - HardwareAnalysisFailure 0x0007

Problem determination: Call your next level of support.

E35C0008 E35C0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: adept failure hardware log transmit - HardwareAnalysisFailure 0x0008

Problem determination: Call your next level of support.

E35C0401 E35C0401

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid poshorter to the comp_rc was passed in by the PA Shell. The error reason is the return code from xpce_ckptr. 0x0401

Problem determination: Call your next level of support.

E35C0402 E35C0402

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid poshorter to the shorterface was passed in by the PA Shell. The error reason is the return code from xpce_ckptr. 0x0402

E35C0403 • E35C0417

Problem determination: Call your next level of support.

E35C0403 E35C0403

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid poshorter to the Results File block was passed in by the PA Shell. The error reason is the return code from xpce_ckptr. 0x0403

Problem determination: Call your next level of support.

E35C0404 E35C0404

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid poshorter to the log shorterface control block was passed in by the PA Shell. The error reason is the return code from xpce_ckptr. 0x0404

Problem determination: Call your next level of support.

E35C0405 E35C0405

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An ff value error log undefined to IQYP3304 was passed in for analysis. The error reason is the ff value of the error log passed shorto IQYP3304* for analysis. 0x0405

Problem determination: Call your next level of support.

E35C0410 E35C0410

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xsim_read error. Error reason is the xsim_read rc. 0x0410

Problem determination: Call your next level of support.

E35C0411 E35C0411

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: xsim_read error. Error reason is the xsim_read rc. 0x0411

Problem determination: Call your next level of support.

E35C0412 E35C0412

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xdm_open. The error reason is the return code from xdm_open. 0x0412

Problem determination: Call your next level of support.

E35C0413 E35C0413

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xdm_libdef. The error reason is the return code from xdm_libdef. 0x0413

Problem determination: Call your next level of support.

E35C0414 E35C0414

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xdm_panel_open. The error reason is the return code from xdm_panel_open. 0x0414

Problem determination: Call your next level of support.

E35C0415 E35C0415

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xdm_display. The error reason is the return code from xdm_display. 0x0415

Problem determination: Call your next level of support.

E35C0416 E35C0416

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xdm_panel_close. The error reason is the return code from xdm_panel_close. 0x0416

Problem determination: Call your next level of support.

E35C0417 E35C0417

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xdm_close. The error reason is the return code from xdm_close. 0x0417

Problem determination: Call your next level of support.

E35C0418 E35C0418

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xp46_logchk. The error reason is the return code from xp46_logchk. 0x0418

Problem determination: Call your next level of support.

E35C0419 E35C0419

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xp41_create_rtsl. The error reason is the return code from xp41_create_rtsl. 0x0419

Problem determination: Call your next level of support.

E35C041A E35C041A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: SSI completed a successful queued PA Send Service request. The PA Shell comp_rc is set to this value for PA Shell use. No results file is created, Results Analysis is not called. 0x041A

Problem determination: Call your next level of support.

E35C0420 E35C0420

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xvpd_mgr. The error reason is the return code from xvpd_mgr. 0x0420

Problem determination: Call your next level of support.

E35C0450 E35C0450

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An undefined Comm Mgr message was logged. The message type is not ACS or MACH. The PD routine is not able to recognize or analyze this error log. The error reason is 0 or 1, depending upon the location in the code module where the failure was detected. 0x0450

Problem determination: Call your next level of support.

E35C0451 E35C0451

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adinvoke for IQYP33CM or IQYP33CA rules base. The error reason is the return code from xadi_adinvoke. 0x0451

Problem determination: Call your next level of support.

E35C0452 E35C0452

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid data was returned from the ADEPT rules base. The rules base called is IQYP33CM or IQYP33CA. The error reason is set to the ADEPT outdata class which contained the invalid data. 0x0452

Problem determination: Call your next level of support.

E35C0453 E35C0453

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ADEPT rules base determined an undefined Communications Manager message log was taken. The message type is either ACS or MACH but the message number is not included in the rules base. The error reason is always 0. 0x0453

Problem determination: Call your next level of support.

E35C0454 E35C0454

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adfree for IQYP33CA or IQYP33CM rules base. The error reason is the return code from xadi_adfree. 0x0454

Problem determination: Call your next level of support.

E35C0455 E35C0455

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Communications Manager logged a message for which there is no PA panel to display. These CM messages*inform the user that other messages have been logged, and it is not necessary to display these. The PA Shell comp_rc is set to this value for PA Shell use. No results file is created, Results Analysis is not * called. 0x0455

E35C0461 • E35C0484

Problem determination: Call your next level of support.

E35C0461 E35C0461

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An undefined autodial error_id was logged. The PD routine is not able to recognize or analyze this error log. The error reason is set to the autodial error_id. 0x0461

Problem determination: Call your next level of support.

E35C0462 E35C0462

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adinvoke for IQYP33AD rules base. The error reason is the return code from xadi_adinvoke. 0x0462

Problem determination: Call your next level of support.

E35C0463 E35C0463

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid data was returned from the ADEPT rules base IQYP33AD. The error reason is set to the ADEPT outdata class which contained the invalid data. 0x0463

Problem determination: Call your next level of support.

E35C0464 E35C0464

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ADEPT rules base determined an undefined autodial error_id log was taken. The error_id is not included in the rules base. The error reason is always 0. 0x0464

Problem determination: Call your next level of support.

E35C0465 E35C0465

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adfree for IQYP33AD rules base. The error reason is the return code from xadi_adfree. 0x0465

Problem determination: Call your next level of support.

E35C0480 E35C0480

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An undefined TPI tpsretc was logged. The PD routine is not able to recognize or analyze this error log. The error reason is set to the TPI tpsretc error log value. 0x0480

Problem determination: Call your next level of support.

E35C0481 E35C0481

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adinvoke for IQYP33TP rules base. The error reason is the return code from xadi_adinvoke. 0x0481

Problem determination: Call your next level of support.

E35C0482 E35C0482

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid data was returned from the ADEPT rules base IQYP33TP. The error reason is set to the ADEPT outdata class which contained the invalid data. 0x0482

Problem determination: Call your next level of support.

E35C0483 E35C0483

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ADEPT rules base determined an undefined TPI tpsretc error log was taken. The tpsretc is not included in the rules base. The error reason is always 0. 0x0483

Problem determination: Call your next level of support.

E35C0484 E35C0484

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adfree for IQYP33TP rules base. The error reason is the return code from xadi_adfree. 0x0484

Problem determination: Call your next level of support.

E35C0D01 E35C0D01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid pointer to the comp_rc was passed in by the PA Shell. The error reason is the return code from xpce_ckptr. 0x0D01

Problem determination: Call your next level of support.

E35C0D02 E35C0D02

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid pointer to the interface was passed in by the PA Shell. The error reason is the return code from xpce_ckptr. 0x0D02

Problem determination: Call your next level of support.

E35C0D03 E35C0D03

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid pointer to the Results File block was passed in by the PA Shell. The error reason is the return code f; /* An invalid pointer to the log interface control block was passed in by the PA Shell. The error reason is the return code from xpce_ckptr. 0x0D03

Problem determination: Call your next level of support.

E35C0D05 E35C0D05

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adinvoke for IQYP330D rules base. The error reason is the return code from xadi_adinvoke. 0x0D05

Problem determination: Call your next level of support.

E35C0D06 E35C0D06

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Invalid data was returned from the ADEPT rules base IQYP330D. The error reason is set to the ADEPT outdata class which contained the invalid data. 0x0D06

Problem determination: Call your next level of support.

E35C0D07 E35C0D07

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The ADEPT rules base determined an undefined pc hardware ff value log was taken. The ff value of the log is not included in the rules base. The error reason is always 0. 0x0D07

Problem determination: Call your next level of support.

E35C0D08 E35C0D08

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error calling xadi_adfree for IQYP330D rules base. The error reason is the return code from adi_adfree. 0x0D08

Problem determination: Call your next level of support.

E35C0D09 E35C0D09

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An invalid ROF error log was taken. The primary block data field pccaddr3" of the 0D0C log contains invalid data. The error reason is always 0.0x0D09

Problem determination: Call your next level of support.

E35C0D0A E35C0D0A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred accessing SIM data. The error reason is the return code from XSIM_READ. 0x0D0A

Problem determination: Call your next level of support.

(E35F) Reference codes

E35F0000 E35F0000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to create a new PersistenceManager. This error is logged when the constructor of the PersistenceManager is called but the PersistenceManager object could not be initialized correctly (e.g. because the path to the persistent data store could not be created). The object is invalidated and subsequent calls are rejected (that is: an exception is thrown for any following calls to the PersistenceManager).

Problem determination: Call your next level of support.

E35F0010 E35F0010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to read an object by the PersistenceManager. This error is logged when during the read of an object an error occurs. The PersistenceManager cannot reconstitute an object from the persistent data store.

Problem determination: Call your next level of support.

E35F0011 E35F0011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to decode an object by the PersistenceManager. This error is logged when during the decoding of an object an error occurs (the error is usually an IOException). The PersistenceManager cannot reconstitute an object from the persistent data store.

Problem determination: Call your next level of support.

E35F0012 E35F0012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to reconstitute an object by the PersistenceManager. This error is logged when during the reconstitution a class object was not found. The class object that was not found is the object describing the stored PersistentData or Persistable. The PersistenceManager cannot reconstitute an object from the persistent data store.

Problem determination: Call your next level of support.

E35F0013 E35F0013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to reconstitute an object by the PersistenceManager. This error is logged when during the reconstitution the required constructor to create a Persistable from a PersistentData was not found. The PersistenceManager cannot reconstitute an object from the persistent data store.

Problem determination: Call your next level of support.

E35F0014 E35F0014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to reconstitute an object by the PersistenceManager. This error is logged when during the reconstitution an unsupported version of the PersistenceManager code was detected. The object to be reconstituted was written by a different version of the PersistenceManager. The current code does not support this version. The PersistenceManager cannot reconstitute an object from the persistent data store.

Problem determination: Call your next level of support.

E35F0020 E35F0020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to write an object by the PersistenceManager. This error is logged when during the write of an object an error occurs. The PersistenceManager cannot reconstitute an object from the persistent data store.

Problem determination: Call your next level of support.

E35F0021 E35F0021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to encode an object by the PersistenceManager. This error is logged when during the encoding of an object an error occurs (the error is usually an IOException). The PersistenceManager cannot create the encoded form for an object.

E35F0030 • E35F0032

Problem determination: Call your next level of support.

E35F0030 E35F0030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform the saveUpgradeData method. This error is logged when during the saveUpgradeData task an error in the PersistenceManager occurs. The log contains additional information on the error.

Problem determination: Call your next level of support.

E35F0031 E35F0031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform the restoreUpgradeData method. This error is logged when during the restoreUpgradeData task an error in the PersistenceManager occurs. The log contains additional information on the error.

Problem determination: Call your next level of support.

E35F0032 E35F0032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A parsing error occurred trying to parse the xml files representing deployment preferences. The parsing occurs the first time a call is made to Deployment.getPreferences().

Look in the trace for a description of the parsing error that occurred.

The xml files reside in the directory named by the "deploymentPrefs" file control nickname.

Problem determination: Call your next level of support.

(E361) Reference codes

E3610201 **E3610201**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the HMC Configuration task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The HMC Configuration task has been ended.

Problem determination: Call your next level of support.

E3610202 **E3610202**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the HMC Configuration task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The HMC Configuration task has been ended.

Problem determination: Call your next level of support.

E3610203 **E3610203**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the HMC Configuration task action handler. The task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3610204 **E3610204**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to gather the VPD information during the Hmc Configuration task. The task has been ended.

Problem determination: Call your next level of support.

E3610205 **E3610205**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to update the VPD during the

Hmc Configuration task. The task has been ended.

Problem determination: Call your next level of support.

E3610C01 **E3610C01**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for the client side of the update hom/vpd task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3610C02 **E3610C02**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for the server side of the update hom/vpd task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3617001 **E3617001**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the reassignHmc task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The cpc details task has been ended.

Problem determination: Call your next level of support.

E3617002 **E3617002**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the reassignHmc task. The reassignHmc task has been ended.

Problem determination: Call your next level of support.

E3617003 **E3617003**

Explanation: Licensed Internal Code failure on the

E3617004 • E3617106

Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the reassignHmc task. The reassignHmc task has been ended.

Problem determination: Call your next level of support.

E3617004 E3617004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing of the reassignHmc task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The reassignHmc task has been ended.

Problem determination: Call your next level of support.

E3617005 E3617005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the reassignHmc task action handler. The reassignHmc task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3617006 E3617006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to read the diskette file BBPUTVPD.TRM.

Problem determination: Call your next level of support.

E3617007 E3617007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Data on diskette file not valid.

Problem determination: Call your next level of support.

E3617008 E3617008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Serial number from diskette does not match.

Problem determination: Call your next level of support.

E3617009 E3617009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Update Machine Configuration data failed.

Problem determination: Call your next level of support.

E3617010 E3617010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Rebuild Vpd failed.

Problem determination: Call your next level of support.

E3617011 E3617011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Transmit to RETAIN failed.

Problem determination: Call your next level of support.

E3617012 E3617012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Main processing Reassign HMC failed.

Problem determination: Call your next level of support.

E3617013 E3617013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Diskette drive not available.

Problem determination: Call your next level of support.

E3617106 E3617106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to read the diskette file BBPUTVPD.TRM.

Problem determination: Call your next level of support.

E3617801 **E3617801**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Transmit Vital Product Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Vital Product Data task has been ended.

Problem determination: Call your next level of support.

E3617802 **E3617802**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Transmit Vital Product Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Vital Product Data task has been ended.

Problem determination: Call your next level of support.

E3617803 **E3617803**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Transmit Vital Product Data task. The Transmit Vital Product Data task has been ended.

Problem determination: Call your next level of support.

E3617804 **E3617804**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in panelAction method of Transmit Vital Product Data bean. Failing to catch this exception would cause it to be caught by the AUIML thread and the panel would stay up, ignoring the error. Transmit Vital Product Data task has been ended.

Problem determination: Call your next level of support.

E3617901 **E3617901**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Rebuild Vital Product Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Rebuild Vital Product Data task has been ended.

Problem determination: Call your next level of support.

E3617902 **E3617902**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Rebuild Vital Product Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Rebuild Vital Product Data task has been ended.

Problem determination: Call your next level of support.

E3617903 **E3617903**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Rebuild Vital Product Data task. The Rebuild Vital Product Data task has been ended.

Problem determination: Call your next level of support.

E3617910 **E3617910**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to get the ECs for the HMC in getSystemEcNumber().

Problem determination: Call your next level of support.

E3617911 **E3617911**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to find the System EC for the HMC in getSystemEcNumber().

Problem determination: Call your next level of support.

E3617912 **E3617912**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling the VPD Manager during updateMicrocodeVpd(). the Rebuild Vital Product Data task.

Problem determination: Call your next level of support.

E3617913 E3617913

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred during general processing in rebuildVpd()

Problem determination: Call your next level of support.

E3617914 E3617914

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred during general processing in rebuildVpd().

Problem determination: Call your next level of support.

E3617915 E3617915

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred during general processing in rebuildVpd()

Problem determination: Call your next level of support.

E3617916 E3617916

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred during general processing in rebuildVpd().

Problem determination: Call your next level of support.

E3617917 E3617917

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred transmit of actvhmca.dat file to retain.

Problem determination: Call your next level of support.

E3617918 E3617918

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error (IOException) occurred calling native bridge code.

Problem determination: Call your next level of support.

E3617919 E3617919

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error (NativeBridgeException) occurred calling native bridge code.

Problem determination: Call your next level of support.

E361791A E361791A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in xp33_35n C function.

Problem determination: Call your next level of support.

E361791B E361791B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred writing data out during writeFileHeader().

Problem determination: Call your next level of support.

E361791C E361791C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred reading file during readFileContent().

Problem determination: Call your next level of support.

E361791D E361791D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred writing file to diskette during transmitToDiskette().

Problem determination: Call your next level of support.

E361791E E361791E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred calling rsf to transmit file to retain.

Problem determination: Call your next level of support.

E361791F E361791F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred reading partial file content.

Problem determination: Call your next level of support.

E3617920 E3617920

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred using Media Services to get Diskette - id returned was null

Problem determination: Call your next level of support.

E3617921 E3617921

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred getting lock from Media Services for Diskette

Problem determination: Call your next level of support.

E3617922 E3617922

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in iqyvsein main C function.

Problem determination: Call your next level of support.

E3617923 E3617923

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in in constructor determining platform information.

Problem determination: Call your next level of support.

E3617924 E3617924

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to get the AROM data for the HMC in getSystemEcNumber().

Problem determination: Call your next level of support.

E3617925 E3617925

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error transmitting VPD after a rebuild of VPD..

Problem determination: Call your next level of support.

E3617926 E3617926

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred writing file to USB during transmitToUsb().

Problem determination: Call your next level of support.

(E369) Reference codes

E3690001 E3690001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the main processing of the client side of the Customize Console Date/Time task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Customize Console Date/Time task has been ended.

Problem determination: Call your next level of support.

E3690002 E3690002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when the Customize Console Date/Time tasklet catches an error. An error occurred during the "service" processing for server side of the Customize Console Date/Time task. The Customize Console Date/Time task has been ended.

Problem determination: Call your next level of support.

E3690003 E3690003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in the TimeManager constructor when attempting to get the Class object for the MasterTimeSource interface.

Problem determination: Call your next level of support.

E3690004 E3690004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unrecognized action command was passed from the client side to the server side of the Customize Console Date/Time task.

Problem determination: Call your next level of support.

E3690005 E3690005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected error was encountered while parsing an internally constructed Date object. The

Customize Console Date/Time task has been terminated.

Problem determination: Call your next level of support.

E3690006 E3690006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: No valid master time source was found after a request from a master time source to have the console sync to it. The console time was not set.

Problem determination: Call your next level of support.

E3690007 E3690007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An unexpected error was encountered while attempting to sync the console time to that of a managed object. The console time was not set.

Problem determination: Call your next level of support.

E3690008 E3690008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was encountered while attempting to invoke the program to set the console time. The console time was not set.

Problem determination: Call your next level of support.

E3690009 E3690009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The program to set the console time failed. The console time was not set.

Problem determination: Call your next level of support.

E369000A E369000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when the Customize Console Date/Time tasklet catches an error. An error occurred

E369000B • E3690015

during the "service" processing for server side of the Customize Console Date/Time task. The Customize Console Date/Time task has been ended.

Problem determination: Call your next level of support.

E369000B E369000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was encountered while attempting to invoke the program to set the time zone. The time zone was not set.

Problem determination: Call your next level of support.

E369000C E369000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The program to set the time zone failed. The console time was not set.

Problem determination: Call your next level of support.

E369000D E369000D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The creation of a temporary time zone file was unsuccessful.

Problem determination: Call your next level of support.

E369000E E369000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Closing an opened temporary time zone file was unsuccessful.

Problem determination: Call your next level of support.

E369000F E369000F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The deletion of a temporary time zone file was unsuccessful.

Problem determination: Call your next level of support.

E3690010 E3690010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Closing an opened /etc/sysconfig/clock was unsuccessful.

Problem determination: Call your next level of support.

E3690011 E3690011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error opening or reading /etc/sysconfig/clock file to extract current time zone.

Problem determination: Call your next level of support.

E3690012 E3690012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Closing an opened /etc/sysconfig/clock after extracting current time zone was unsuccessful.

Problem determination: Call your next level of support.

E3690013 E3690013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught reading initial time zone.

Problem determination: Call your next level of support.

E3690014 E3690014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An exception was caught reading initial time zone.

Problem determination: Call your next level of support.

E3690015 E3690015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IOException was encountered while attempting to invoke the program to restart the window manager. The window manager will have the wrong time displayed, but task driver can continue without a problem.

Problem determination: Call your next level of support.

E3690016 E3690016

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The program to restart the window manager failed. The window manager will have the wrong time displayed, but task driver can continue without a problem.

Problem determination: Call your next level of support.

E3690017 E3690017

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The attempt to extract the Linux Time Zone by reading its symbolic link was not a success. The time displayed may be incorrect but task driver can continue.

Problem determination: Call your next level of support.

E3690018 E3690018

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The Linux Time Zone extracted from the operating system resulted in a null string. The time displayed may be incorrect but task driver can continue.

Problem determination: Call your next level of support.

E3690019 E3690019

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The Linux Time Zone extracted from the operating system did not contain the expected end delimiter inserted by the Read Time Zone shell script. The time displayed may be incorrect but task driver can continue.

Problem determination: Call your next level of support.

E369001A E369001A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The Linux Time Zone extracted from the operating system did not start with the expected time zone path. The time displayed may be incorrect but task driver can continue.

Problem determination: Call your next level of support.

E3690101 E3690101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An attempt to determine the location of the trace file failed. Time of Day can continue as is, but an internal trace file cannot be created.

Problem determination: Call your next level of support.

E3690102 E3690102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Was told that a brand new trace file cannot be created. Time of Day can continue as is, but an internal trace file cannot be created.

Problem determination: Call your next level of support.

E3690103 E3690103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: I/O Error writing to the brand new trace file. Time of Day can continue as is, but an internal trace file cannot be created.

Problem determination: Call your next level of support.

E3690104 E3690104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: I/O Error closing brand new trace file after attempt to write to it. Time of Day can continue as is, but an internal trace file cannot be created.

Problem determination: Call your next level of support.

E3690105 E3690105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: I/O Error interacting with trace file. Time of Day can continue as is, but an internal trace file cannot be created.

Problem determination: Call your next level of support.

E3690106 • E3690202

E3690106 E3690106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: I/O Error closing brand new trace file after attempt to read it. Time of Day can continue as is, but an internal trace file cannot be created.

Problem determination: Call your next level of support.

E3690107 E3690107

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: I/O Error closing brand new trace file after attempt to write to it. Time of Day can continue as is, but an internal trace file cannot be created.

Problem determination: Call your next level of support.

E3690201 E3690201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An info log entry indicating that a null has been detected inside CustManObjDateTimeBean when trying to translate the timezone to the desired language.

Problem determination: Call your next level of support.

E3690202 E3690202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An info log entry indicating that a null has been detected inside CustManObjDateTimeBean when trying to translate the timezone from the desired language.

Problem determination: Call your next level of support.

(E36A) Reference codes

E36A4700 **E36A4700**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when the Activation application catches an error.

Problem determination: Call your next level of support.

E36A4701 **E36A4701**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the name of the class that implements the Activation Interface for the targetted object type

Problem determination: Call your next level of support.

E36A4702 **E36A4702**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling getInvalidActivateTargets() or getInvalidDeactivateTargets()

Problem determination: Call your next level of support.

E36A4703 **E36A4703**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: We could not obtain the com.ibm.hwmca.base.activate.Activation Activation implementation for the class of managed object specified

Problem determination: Call your next level of support.

E36A4704 **E36A4704**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error inside of getGoodBadTargets()

Problem determination: Call your next level of support.

E36A4705 **E36A4705**

Explanation: Licensed Internal Code failure on the

Hardware Management Console (HMC).

Response: Error inside of getGoodBadTargets()

Problem determination: Call your next level of support.

E36A4706 **E36A4706**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling getActivateConfirmationData() or getDeactivateConfirmationData()

Problem determination: Call your next level of support.

E36A4707 **E36A4707**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the data we saved earlier back.

Problem determination: Call your next level of support.

E36A4710 **E36A4710**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in ActivationTasklet

Problem determination: Call your next level of support.

E36A4711 **E36A4711**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in ActivationTasklet while trying to prepare for the in-progress panel

Problem determination: Call your next level of support.

E36A4712 **E36A4712**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in ActivationTasklet while starting up our threads.

Problem determination: Call your next level of support.

E36A4713 • E36A47F8

E36A4713 E36A4713

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in ActivationTasklet while starting up our threads (in the synchronized part)

Problem determination: Call your next level of support.

E36A4714 E36A4714

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in ins service()

Problem determination: Call your next level of support.

E36A4715 E36A4715

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in ActivationTasklet while trying to display an error message.

Problem determination: Call your next level of support.

E36A4716 E36A4716

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: RuntimeException caught in ActivationTasklet while destroying the busy dialog.

Problem determination: Call your next level of support.

E36A4720 E36A4720

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in panelAction() when trying to handle the panel's action (eg YES, NO, Show details, etc.)

Problem determination: Call your next level of support.

E36A47F0 E36A47F0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling a activate method

Problem determination: Call your next level of support.

E36A47F8 E36A47F8

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling a deactivate method

Problem determination: Call your next level of support.

(E36B) Reference codes

E36BA500 E36BA500

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the activation profile list (actproflist). This is the result of an exception being caught by the underlying Tasklet infrastructure. The actproflist task has been ended.

Problem determination: Call your next level of support.

E36BA501 E36BA501

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the actproflist task. The actproflist task has been ended.

Problem determination: Call your next level of support.

E36BA502 E36BA502

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the actproflist task. The actproflist task has been ended.

Problem determination: Call your next level of support.

E36BA503 E36BA503

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the actproflist task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The actproflist task has been ended.

Problem determination: Call your next level of support.

E36BA504 E36BA504

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the actproflist task action handler. The task will most

likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E36BA505 E36BA505

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error calling the "Delete" method in the tasklet.

Problem determination: Call your next level of support.

E36BA506 E36BA506

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with retrieving needed data such as the owning impl within the Tasklet.

Problem determination: Call your next level of support.

E36BA507 E36BA507

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with retrieving needed data, null owning impl was returned.

Problem determination: Call your next level of support.

E36BA508 E36BA508

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with retrieving needed data, such as the object for the profile within the Tasklet.

Problem determination: Call your next level of support.

E36BA509 E36BA509

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with retrieving needed data, null object for profile was returned.

Problem determination: Call your next level of support.

E36BA50A

E36BA50A E36BA50A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: RuntimeException caught. Perhaps tasklet was killed?

Problem determination: Call your next level of support.

(E36C) Reference codes

E36C0100 E36C0100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during task processing.

Problem determination: Call your next level of support.

E36C0101 E36C0101

Explanation: An error occurred during tasklet processing.

Problem determination: Contact your next level of support.

E36C0102 E36C0102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred trying to remove a scheduled operation.

Problem determination: Call your next level of support.

E36C0103 E36C0103

Explanation: An error occurred while working with persisted scheduled operations.

Problem determination: Contact your next level of support.

E36C0104 E36C0104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to restore a scheduled operation.

Problem determination: Call your next level of support.

E36C0105 E36C0105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in StartHMC.

Problem determination: Call your next level of support.

E36C0106 E36C0106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A scheduler error occurred.

Problem determination: Call your next level of support.

E36C0107 E36C0107

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Collecting FFDC miscellaneous data for Scheduled Operations.

Problem determination: Call your next level of support.

E36C0108 E36C0108

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Collecting FFDC miscellaneous data for Scheduled Operations.

Problem determination: Call your next level of support.

E36C0109 E36C0109

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during Scheduled Operations initialization.

Problem determination: Call your next level of support.

(E372) Reference codes

E3721000 E3721000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Load task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Load task has been ended.

Problem determination: Call your next level of support.

E3721001 E3721001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught in the DomainSecurityTasklet.service method.

Problem determination: Call your next level of support.

(E392) Reference codes

E3920001 E3920001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a task.

Problem determination: Call your next level of support.

E3920002 E3920002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a tasklet.

Problem determination: Call your next level of support.

E3920003 E3920003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in a bean.

Problem determination: Call your next level of support.

E3920004 E3920004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error persisting an object or creating an object from persistence.

Problem determination: Call your next level of support.

(E39F) Reference codes

E39F0001 **E39F0001**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred processing an incoming EMP GDS.

Problem determination: Call your next level of support.

E39F0002 **E39F0002**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during processing of the AttentionPanelTask.

Problem determination: Call your next level of support.

E39F0003 **E39F0003**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during processing of the AttentionPanelTasklet.

Problem determination: Call your next level of support.

E39F0004 **E39F0004**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while persisting an Attention.

Problem determination: Call your next level of support.

E39F0005 **E39F0005**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while unpersisting an Attention.

Problem determination: Call your next level of support.

E39F0006 **E39F0006**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while reading all persisted Attentions.

Problem determination: Call your next level of support.

E39F0007 **E39F0007**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while trying to add a generic console attention. The console will continue to run, but the attention (hardware message) that was trying to be created will not be seen by any users.

Problem determination: Call your next level of support.

E39F0008 **E39F0008**

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while trying to display the details for a generic attention. The console will continue to run, but the attention (hardware message) details being displayed were not be seen by the user.

Problem determination: Call your next level of support.

(E3A2) Reference codes

E3A2000E E3A2000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An event was requested to be logged but the event type was not recognized.

Problem determination: Call your next level of support.

E3A2000F E3A2000F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: This is an informational log that logAvailableTraceInfo creates when a Service Exception is thrown.

Problem determination: Call your next level of support.

(E3A3) Reference codes

E3A30001 E3A30001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Config 3270 task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Config 3270 task has been ended.

Problem determination: Call your next level of support.

E3A30002 E3A30002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the Config 3270 task. The Config 3270 task has been ended.

Problem determination: Call your next level of support.

E3A30003 E3A30003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Config 3270 task. The Config 3270 task has been ended.

Problem determination: Call your next level of support.

E3A30004 E3A30004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Config 3270 task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Config 3270 task has been ended.

Problem determination: Call your next level of support.

E3A30005 E3A30005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Config 3270 task action handler. The Config 3270 task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3A30010 E3A30010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to start 3270 emulators

Problem determination: Call your next level of support.

E3A30020 E3A30020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Config 3270 startupHook. The emulators probably are not started, but could have been.

Problem determination: Call your next level of support.

(E3CA) Reference codes

E3CA0260 E3CA0260

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to create the temporary directories needed by MediaServices during the construction of the MediaServices singleton class

Problem determination: Call your next level of support.

E3CA0261 E3CA0261

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to find the DOS drive letter for the media device.

Problem determination: Call your next level of support.

E3CA0262 E3CA0262

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to detect the devices supported by Media Services

Problem determination: Call your next level of support.

E3CA0265 E3CA0265

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to instantiate the hard drive devices supported by Media Services

Problem determination: Call your next level of support.

E3CA0268 E3CA0268

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to get the label from the media

Problem determination: Call your next level of support.

E3CA0269 E3CA0269

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to tokenize the output from the Linux df command

Problem determination: Call your next level of support.

E3CA026A E3CA026A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to invoke the Linux df command

Problem determination: Call your next level of support.

E3CA026B E3CA026B

Explanation: An error occurred mounting a media device for one of the cases below.

Problem determination:

- An unknown reason.
- The device is mounted and cannot be unmounted.
- The mount command reported an incorrect major or minor number

Perform the following steps:

1. Try to determine which media device reported this failure.
2. Determine what specific task was being performed when the error occurred. If necessary, check the logs.
3. Check for entries in the /tmp/console/mediasvc/mediasvc.log or for .mount files in /tmp/console/mediasvc to determine which device failed and for which of the reasons previously listed reasons. If tracing was also running, there are also XMDA entries in the iqzdrac.trm file.
4. When you know which media device failed, determine whether there were problems with the removable media, including diskette, DVD, CD, or memory stick.
5. Retry the task with new or reformatted media to see if that solves the problem.
6. If the problem does not appear to be with removable media, perform tests on the media device to see whether the device is defective.

Note: The media services log file is stored in the /tmp folder and is lost when the HMC is rebooted.

E3CA026C E3CA026C

E3CA026D • E3CA0274

Explanation: An error occurred while trying to unmount a media device.

Problem determination:

1. Check the console log entry to see what exception was reported for this problem. Other than unexpected Java exceptions, the media device code reports this exception when it gets a non 0 return code from running the unmount media script: if it gets rc = 203, it reports a MediaDeviceException "runAsRoot setuid error. return code = 203". This means the unmount script could not be run with root privileges. Otherwise it reports an IOException "the unmount operation failed. return code = x" where x is the return code from the unmount script.
2. Try to determine which media device reported this failure.
3. Determine what specific task was being performed when the error occurred.
4. If necessary, check the logs. Check for entries in the /tmp/console/mediasvc/mediasvcs.log or for .mount files in /tmp/console/mediasvc to determine which device failed and for which of the previously listed reasons. If tracing was also running, there are also XMDA entries in the iqzdrac.trm file.
5. When you know which media device failed, determine whether there were problems with the removable media, including diskette, DVD, CD, or memory stick.
6. Retry the task with new or reformatted media to see if that solves the problem.
7. If the problem does not appear to be with removable media, perform tests on the media device to see whether the device is defective.
8. If there is removable media in the device that cannot be removed (such as a DVD that will not eject), you might need to reboot the HMC to release that device and the media. Be sure to first save the /tmp/console/mediasvc/mediasvcs.log before rebooting.

Note: The media services log file is stored in the /tmp folder and is lost when the HMC is rebooted.

E3CA026D E3CA026D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to unlock a media device

Problem determination: Call your next level of support.

E3CA026F E3CA026F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to determine if the diskette media is present in the device

Problem determination: Call your next level of support.

E3CA0270 E3CA0270

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to format the diskette media

Problem determination: Call your next level of support.

E3CA0271 E3CA0271

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to determine if the CD-ROM or DVD-RAM media is present in the drive

Problem determination: Call your next level of support.

E3CA0272 E3CA0272

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to eject the media from the CD-ROM or DVD-RAM device

Problem determination: Call your next level of support.

E3CA0273 E3CA0273

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to either lock or unlock the door of the CD-ROM or DVD-RAM device

Problem determination: Call your next level of support.

E3CA0274 E3CA0274

Explanation: An error occurred formatting a DVD.

Problem determination: Perform the following steps:

1. Check the console log entry to see if an exception was reported for this problem. Other than unexpected Java exceptions, the media device code reports this exception when it gets an error running

the format dvd script and will report a MediaDeviceException "Failure to format media, unknown error occurred."

2. Check for entries in the /tmp/console/mediasvc/mediasvcs.log to show details on how the format failed. If tracing was also running, there are also XMDA entries in the iqzdtrac.trm file.
3. Try the format operation with a new or different DVD to see if the problem is due to the DVD media itself. Ensure that the new or different DVD is the same type of DVD as the one that failed to format.
4. If the problem does not appear to be with DVD media, perform tests on the media device to see whether the device is defective.
5. If there is DVD media in the DVD device that cannot be ejected, you might need to reboot the HMC to release that device and the media. Be sure to first save the /tmp/console/mediasvc/mediasvcs.log before rebooting.

Note: The media services log file is stored in the /tmp folder and is lost when the HMC is rebooted.

E3CA0275 E3CA0275

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to display a message box within MediaServicesUtil

Problem determination: Call your next level of support.

E3CA0276 E3CA0276

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: within the C code interface that uses Media Services via the Native Bridge support

Problem determination: Call your next level of support.

E3CA0277 E3CA0277

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: within the C code interface that uses Media Services via the Native Bridge support

Problem determination: Call your next level of support.

E3CA0278 E3CA0278

Explanation: An error occurred formatting a USB flash memory drive, most likely a USB memory stick.

Problem determination: Perform the following steps:

1. Check the console log entry to see what exception was reported for this problem. Other than unexpected Java exceptions, the media device code reports this exception when it gets an error running the format USB script and will report a MediaDeviceException "Failure to format media, unknown error occurred."
2. Check for entries in the /tmp/console/mediasvc/mediasvcs.log for details on how the format failed. If tracing was also running, there are also XMDA entries in the iqzdtrac.trm file.
3. Format a new or different USB memory stick to see if the problem is due to the media itself.
4. If the problem does not appear to be with the USB media itself, proceed with whatever the existing protocol is for performing tests on the specific media device itself to see whether the device itself is defective.

Note: The media services log file is stored in the /tmp folder and is lost when the HMC is rebooted.

E3CA0279 E3CA0279

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to determine if the USB flash memory drive is present.

Problem determination: Call your next level of support.

E3CA027D E3CA027D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to mount a media device

Problem determination: Call your next level of support.

E3CA027E E3CA027E

Explanation: An error occurred mounting a media device for one of the cases below.

Problem determination:

- An unknown reason
- The device is mounted and cannot be unmounted
- The mount command reported an incorrect major or minor number

Perform the following steps:

1. Try to determine which media device reported this failure.
2. Determine what specific task was being performed when the error occurred. If necessary, check the logs.

E3CA027F • E3CA0920

3. Check for entries in the /tmp/console/mediasvc/mediascvs.log or for .mount files in /tmp/console/mediasvc to determine which device failed and for which of the previously listed reasons. If tracing was also running, there are also XMDA entries in the iqzdrac.trm file.
4. When you know which media device failed, determine whether there were problems with the removable media, including diskette, DVD, CD, or memory stick.
5. Retry the task with new or reformatted media to see if that solves the problem.
6. If the problem does not appear to be with removable media, perform tests on the media device to see whether the device is defective.

Note: The media services log file is stored in the /tmp folder and is lost when the HMC is rebooted.

E3CA027F E3CA027F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error while trying to mount a media device

Problem determination: Call your next level of support.

E3CA0900 E3CA0900

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Authorize Internal Code Change task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Authorize Internal Code Change task has been ended.

Problem determination: Call your next level of support.

E3CA0902 E3CA0902

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Authorize Internal Code Change task action handler.

Problem determination: Call your next level of support.

E3CA0910 E3CA0910

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Authorize Internal Code Change task. This is the result of an exception being caught by the

underlying Tasklet infrastructure. The Authorize Internal Code Change task has been ended.

Problem determination: Call your next level of support.

E3CA0911 E3CA0911

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response:

Problem determination: Call your next level of support.

E3CA0912 E3CA0912

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error was caught in the AuthInternalCodeChangeTasklet.ExecuteSave.run() thread when doing postRequest().

Problem determination: Call your next level of support.

E3CA0913 E3CA0913

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception was caught in the AuthInternalCodeChangeTasklet.ExecuteSave.run() thread.

Problem determination: Call your next level of support.

E3CA0920 E3CA0920

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: PanelTasklet.updateProgress() TaskletException was caught in BaseAuthInternalCodeChangeImpl.execute()

Problem determination: Call your next level of support.

(E3CB) Reference codes

E3CB0018 E3CB0018

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught during the processing of the client side operations for the System Information Task. This is the result of an exception being caught by the underlying PanelTask infrastructure. The System Information task has ended.

Problem determination: Call your next level of support.

E3CB0020 E3CB0020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error processing a TaskActionEvent in the panelAction method The task will terminate

Problem determination: Call your next level of support.

E3CB0028 E3CB0028

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error processing a TaskActionEvent in the panelAction method The task will terminate.

Problem determination: Call your next level of support.

E3CB0029 E3CB0029

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error retrieving data while building system information data fields for the target pane

Problem determination: Call your next level of support.

E3CB0030 E3CB0030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error processing a TaskActionEvent in the panelAction method The task will terminate.

Problem determination: Call your next level of support.

E3CB0038 E3CB0038

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the sysinfo task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The sysinfo task has been ended.

Problem determination: Call your next level of support.

E3CB0039 E3CB0039

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught trying to get the PresentationTasksParms object Processing will terminate.

Problem determination: Call your next level of support.

E3CB003A E3CB003A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught from getInterfaceImpl(Class.forName(SYSINFO)) trying to determine target Tower class implementing the SysInfo interface Processing will terminate for the target tower.

Problem determination: Call your next level of support.

E3CB003B E3CB003B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught when trying to determine target Tower's subtasklet via the target's SysInfo implementation of the getSysInfoTaskletName() method Processing will terminate for the target tower.

Problem determination: Call your next level of support.

E3CB003C E3CB003C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught from getInterfaceImpl(Class.forName(SYSINFO)) trying to determine target ManagedObject class implementing the SysInfo interface Processing will terminate for the target .

E3CB003D • E3CB0051

Problem determination: Call your next level of support.

E3CB003D E3CB003D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught when trying to determine target Tower's subtasklet via the target's SysInfo implementation of the getSysInfoTaskletName() method. Processing will terminate for the target tower.

Problem determination: Call your next level of support.

E3CB0048 E3CB0048

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Exception caught calling the target object's implementation of the getSysInfoData() method. Processing will terminate.

Problem determination: Call your next level of support.

E3CB0050 E3CB0050

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating BufferedReader or FileReader for reading driver.name file. Processing will not terminate.

Problem determination: Call your next level of support.

E3CB0051 E3CB0051

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reading line from driver.name file. Processing will not terminate.

Problem determination: Call your next level of support.

(E3CD) Reference codes

E3CD0001 E3CD0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the HMC Services panel. This is the result of an exception being caught by the underlying Tasklet infrastructure. The HMC Services panel has been ended.

Problem determination: Call your next level of support.

E3CD0002 E3CD0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the HMC Services panel. The HMC Services panel has been ended.

Problem determination: Call your next level of support.

E3CD0003 E3CD0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the HMC Services task. The HMC Services task has been ended.

Problem determination: Call your next level of support.

E3CD0004 E3CD0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the HMC Services task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The HMC Services task has been ended.

Problem determination: Call your next level of support.

E3CD0005 E3CD0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the HMC Services task action handler. The HMC Services task will most likely continue to run, but it

may not function as expected.

Problem determination: Call your next level of support.

E3CD0006 E3CD0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing during the initialization of the data. This may cause any tasks that rely upon the HMC Services data to fail.

Problem determination: Call your next level of support.

E3CD0007 E3CD0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to persist the HMC Service data. Everything will still function as normally but the HMC Services data will be lost when the server shuts down.

Problem determination: Call your next level of support.

E3CD0008 E3CD0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to set the perform optical analysis indicator on the towers that support it.

Problem determination: Call your next level of support.

E3CD0009 E3CD0009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to query exclusive control using the Reserve interface.

Problem determination: Call your next level of support.

E3CD000A E3CD000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to obtain or release exclusive control using the Reserve interface.

Problem determination: Call your next level of support.

(E3CE) Reference codes

E3CE0000 E3CE0000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the restore application. This error is logged when the `com.ibm.hwmca.base.critdata.RestoreApp#logException()` `logException()` is invoked.

Problem determination: Call your next level of support.

E3CE0001 E3CE0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the restore application. This error is logged when the `com.ibm.hwmca.base.critdata.RestoreTasklet#service()` `service()` is invoked.

Problem determination: Call your next level of support.

E3CE0002 E3CE0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response:

Problem determination: Call your next level of support.

E3CE0003 E3CE0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the main restore tasklet. This error is logged when the targeted `ManagedObject`'s implementation of `ManagedObjectBackupRestore` does not return a valid name of a restore tasklet.

Problem determination: Call your next level of support.

E3CE0004 E3CE0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the main restore tasklet. This error is logged when the targeted `ManagedObject`'s does not implement the `ManagedObjectBackupRestore` interface.

Problem determination: Call your next level of support.

E3CE0005 E3CE0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the backup task. This error is logged when the `com.ibm.hwmca.base.critdata.BackupTask#logException()` `logException()` is invoked.

Problem determination: Call your next level of support.

E3CE0006 E3CE0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the backup application. This error is logged when the `com.ibm.hwmca.base.critdata.BackupTasklet#service()` `service()` is invoked.

Problem determination: Call your next level of support.

E3CE0007 E3CE0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response:

Problem determination: Call your next level of support.

E3CE0008 E3CE0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the main backup tasklet. This error is logged when the targeted `ManagedObject`'s implementation of `ManagedObjectBackupRestore` does not return a valid name of a backup tasklet.

Problem determination: Call your next level of support.

E3CE0009 E3CE0009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error caught in the main backup tasklet. This error is logged when the targeted `ManagedObject`'s

E3CE0100 • E3CE0202

does not implement the ManagedObjectBackupRestore interface.

Problem determination: Call your next level of support.

E3CE0100 E3CE0100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Backup task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Backup task has been ended.

Problem determination: Call your next level of support.

E3CE0101 E3CE0101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the Backup task. The Backup task has been ended.

Problem determination: Call your next level of support.

E3CE0102 E3CE0102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Backup task. The Backup task has been ended.

Problem determination: Call your next level of support.

E3CE0103 E3CE0103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Backup task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Backup task has been ended.

Problem determination: Call your next level of support.

E3CE0104 E3CE0104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Backup task action handler. The Backup task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3CE0105 E3CE0105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Backup task handler.

Problem determination: Call your next level of support.

E3CE0106 E3CE0106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Backup task handler. This is an IO error, please check the media DVD.

Problem determination: Call your next level of support.

E3CE0200 E3CE0200

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Restore task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Restore task has been ended.

Problem determination: Call your next level of support.

E3CE0201 E3CE0201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the Restore task. The Restore task has been ended.

Problem determination: Call your next level of support.

E3CE0202 E3CE0202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Restore task. The Restore task has been ended.

Problem determination: Call your next level of support.

E3CE0203 E3CE0203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Restore task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Restore task has been ended.

Problem determination: Call your next level of support.

E3CE0204 E3CE0204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Restore task action handler. The Restore task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3CE0205 E3CE0205

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Restore task handler.

Problem determination: Call your next level of support.

E3CE0206 E3CE0206

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error in the Restore Tasklet while trying to read information from the upgrade partition.

Problem determination: Call your next level of support.

E3CE0207 E3CE0207

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error performing a tar command from the backup DVD file. The system may not be totally restored.

Problem determination: Call your next level of support.

(E3D3) Reference codes

E3D30001 E3D30001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in Service Agent

Problem determination: Call your next level of support.

E3D30002 E3D30002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: error in Service Agent

Problem determination: Call your next level of support.

(E3D4) Reference codes

E3D40001 E3D40001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when the CONSOLE_PATH, which contains the path for the DFC control file, was null at startup.

Problem determination: Call your next level of support.

E3D40031 E3D40031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A file-not-found error has occurred when trying to read a data file. This error is logged when the com.ibm.hwmca.rsfcnn.data.ShadowedFile#getData() method is invoked and the data file to be read does not exist.

Problem determination: Call your next level of support.

E3D40032 E3D40032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IO error has occurred when trying to open a data file to read it. This error is logged when the com.ibm.hwmca.rsfcnn.data.ShadowedFile#getData() method encounters an IO exception while opening a data file. This error might occur because access to the file is denied for some unexpected reason.

Problem determination: Call your next level of support.

E3D40033 E3D40033

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IO error has occurred when trying to read a data file. This error is logged when the com.ibm.hwmca.rsfcnn.data.ShadowedFile#getData() method encounters an IO exception while reading a data file. This error might occur because access to the file is denied for some unexpected reason.

Problem determination: Call your next level of support.

E3D40034 E3D40034

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IO error has occurred when trying to open a data file to create it. This error is logged when the com.ibm.hwmca.rsfcnn.data.ShadowedFile#promote() method encounters an IO exception while opening the data file to create/overwrite it. This error might occur because access to the file is denied for some unexpected reason.

Problem determination: Call your next level of support.

E3D40035 E3D40035

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IO error has occurred when trying to write to a data file. This error is logged when the com.ibm.hwmca.rsfcnn.data.ShadowedFile#promote() method encounters an IO exception while writing to the data file. This error might occur because access to the file is denied for some unexpected reason.

Problem determination: Call your next level of support.

E3D40036 E3D40036

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A file-not-found error has occurred when trying to read a staging file. This error is logged when the com.ibm.hwmca.rsfcnn.data.ShadowedFile#promote() method is invoked and the staging file to be read does not exist.

Problem determination: Call your next level of support.

E3D40037 E3D40037

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IO error has occurred when trying to open a staging file to read it. This error is logged when the com.ibm.hwmca.rsfcnn.data.ShadowedFile#promote() method encounters an IO exception while opening a data file. This error might occur because access to the file is denied for some unexpected reason.

E3D40038 • E3D41003

Problem determination: Call your next level of support.

E3D40038 E3D40038

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An IO error has occurred when trying to read a staging file. This error is logged when the `com.ibm.hwmca.rsfcnndata.ShadowedFile#promote()` `promote()` method encounters an IO exception while reading a staging file. This error might occur because access to the file is denied for some unexpected reason.

Problem determination: Call your next level of support.

E3D40039 E3D40039

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Data read from the file containing ip addresses and ports for connections to Retain contained an IP address that was considered invalid by the constructor for the `TcpConnectionInfo` class. This error is logged when the `com.ibm.hwmca.rsfcnndata.RetainTcpConnectionInfo#getConnectionInfo(String,String)` `getConnectionInfo()` method encounters an exception while creating new `TcpConnectionInfo` objects. This error indicates that the data file may contain invalid records. Processing will continue. The bad data is ignored. If no good data is found, the HMC may not be able to contact Retain.

Problem determination: Call your next level of support.

E3D4003A E3D4003A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: A phone number that is currently configured is not listed in the file of valid phone numbers. This error is logged when the `com.ibm.hwmca.rsfcnndata.DialConfigInfo#validatePhoneNumbers()` `validatePhoneNumbers()` method finds a number in the configuration data that is not in the new data file that has just been downloaded from RETAIN.

Problem determination: Call your next level of support.

E3D4003B E3D4003B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to load `DialConfigInfo` persistable data from the `PersistenceManger`. This error is logged when the

`com.ibm.hwmca.rsfcnndata.DialConfigInfo#loadPersistentData()` `loadPersistentData()` method receives a `PersistenceException` (other than a `PersistenceClassNotFoundException`) from the `PersistenceManager.read()` call.

Problem determination: Call your next level of support.

E3D4003C E3D4003C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to save `DialConfigInfo` persistable data to the `PersistenceManger`. This error is logged when the `com.ibm.hwmca.rsfcnndata.DialConfigInfo#savePersistentData()` `savePersistentData()` method receives a `PersistenceException` from the `PersistenceManager.write()` call.

Problem determination: Call your next level of support.

E3D41001 E3D41001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Dial Configuration. This is the result of an exception being caught by the underlying Tasklet infrastructure. The HMC Services task has been ended.

Problem determination: Call your next level of support.

E3D41002 E3D41002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the Dial Configuration task. The Dial Configuration task has been ended.

Problem determination: Call your next level of support.

E3D41003 E3D41003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Dial Configuration task. The Dial Configuration task has been ended.

Problem determination: Call your next level of support.

E3D41004 E3D41004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Dial Configuration task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Dial Configuration task has been ended.

Problem determination: Call your next level of support.

E3D41005 E3D41005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Dial Add bean action handler. The Dial Configuration bean will attempt to shut down the panel.

Problem determination: Call your next level of support.

E3D41006 E3D41006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Dial Configuration bean action handler. The Dial Configuration bean will attempt to shut down the panel.

Problem determination: Call your next level of support.

E3D41007 E3D41007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform an update in the Dial Configuration bean. The Dial Configuration bean will attempt to shut down the panel.

Problem determination: Call your next level of support.

E3D43100 E3D43100

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while trying to obtain from call home request all data required for RETAIN

Problem determination: Call your next level of support.

E3D43101 E3D43101

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while trying to build the RETAIN login info for the call home request

Problem determination: Call your next level of support.

E3D43102 E3D43102

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unsupported encoding error occurred while trying to build the RETAIN login info for the call home request

Problem determination: Call your next level of support.

E3D43103 E3D43103

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while trying to return result for the call home request

Problem determination: Call your next level of support.

E3D43104 E3D43104

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while trying to obtain credentials for the call home request

Problem determination: Call your next level of support.

E3D43105 E3D43105

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while trying to obtain data needed for credentials for the call home request

Problem determination: Call your next level of support.

E3D43106 E3D43106

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Successful credential password update operation

Problem determination: Call your next level of support.

E3D43107 E3D43107

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Successful system credential update operation

Problem determination: Call your next level of support.

E3D43108 E3D43108

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Successful new credential operation

Problem determination: Call your next level of support.

E3D43109 E3D43109

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Successful call home progress update

Problem determination: Call your next level of support.

E3D4310A E3D4310A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred during submission of rsf request

Problem determination: Call your next level of support.

E3D4310B E3D4310B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred during file transfer associated with the rsf request

Problem determination: Call your next level of support.

E3D4310C E3D4310C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred during remote program execution associated with the rsf request

Problem determination: Call your next level of support.

E3D4310D E3D4310D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with adding the rsfStatusListener for the call home request

Problem determination: Call your next level of support.

E3D4310E E3D4310E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error getting the credentials from persistence for the call home request

Problem determination: Call your next level of support.

E3D4310F E3D4310F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Need to update the credentials with new machine information

Problem determination: Call your next level of support.

E3D43201 E3D43201

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when there is a problem reading or writing to persistence.

Problem determination: Call your next level of support.

E3D43202 E3D43202

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when there is a problem reading or writing to sim data.

Problem determination: Call your next level of support.

E3D43203 E3D43203

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when there is a problem executing a remote Java method at the target.

Problem determination: Call your next level of support.

E3D43204 E3D43204

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Logged when there is a problem reading/parsing configuration parms.

Problem determination: Call your next level of support.

E3D45060 E3D45060

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Transmit Service Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3D45061 E3D45061

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Transmit Service Data task action handler. The Transmit Service Data task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3D45062 E3D45062

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the Transmit Service Data task. The task has been ended.

Problem determination: Call your next level of support.

E3D45063 E3D45063

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Transmit Services Data task. The task has been ended.

Problem determination: Call your next level of support.

E3D45064 E3D45064

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Transmit Service Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3D45065 E3D45065

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do IO with the TSD XML file or with BaseFileControl. This is the result of an HException being caught. Null has been returned to invoker.

Problem determination: Call your next level of support.

E3D45066 E3D45066

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to parse TSD XML file. Null has been returned to invoker.

Problem determination: Call your next level of support.

E3D45067 E3D45067

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the diskette copy for server side of the Transmit Service Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3D45068 E3D45068

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the diskette copy for server side of the Transmit Service Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3D45069 E3D45069

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to send data to RSF for server side of the Transmit Service Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3D4506A E3D4506A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The tasklet has been forced to terminate by the user or some other external indication. The Transmit Service Data will stop any gathering of data, release media locks, and the task will be ended.

Problem determination: Call your next level of support.

E3D4506B E3D4506B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: The tasklet has some processing information to be logged.

Problem determination: Call your next level of support.

E3D45070 E3D45070

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to preprocess or postprocess files to be transmitted. This is the result of an error in the execution of the program to process the files. This is an informational log and will be passed to the calling program to handle

Problem determination: Call your next level of support.

E3D45071 E3D45071

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to create the TransmitSvcDataUtils class from the TSD XML file.

Problem determination: Call your next level of support.

E3D45072 E3D45072

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to execute the TransmitSvcDataUtils method for a particular selection.

Problem determination: Call your next level of support.

E3D45073 E3D45073

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to collect and initiate send of the service data.

Problem determination: Call your next level of support.

E3D45074 E3D45074

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to collect and initiate write to diskette or dvd of the service data.

Problem determination: Call your next level of support.

E3D45075 E3D45075

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to collect and initiate write to diskette or dvd of the service data.

Problem determination: Call your next level of support.

E3D45076 E3D45076

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to collect and initiate write to diskette or dvd of the service data. This is a user-recoverable error.

Problem determination: Call your next level of support.

E3D45077 E3D45077

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to collect and initiate write to diskette or dvd of the service data. This is a user-recoverable error.

Problem determination: Call your next level of support.

E3D45078 E3D45078

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An application-issued TSD was unable to transmit the data to the remote system because the remote system was not configured. This is a user-recoverable error.

Problem determination: Call your next level of support.

E3D45079 E3D45079

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the device copy for server side of the Transmit Service Data task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3D46F01 E3D46F01

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while formatting the request parameters for RETAIN

Problem determination: Call your next level of support.

E3D46F10 E3D46F10

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Information RETAIN call home progressing

Problem determination: Call your next level of support.

E3D46F21 E3D46F21

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred retrieving a file to send to RETAIN

Problem determination: Call your next level of support.

E3D46F22 E3D46F22

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred compacting a file to be sent to RETAIN

Problem determination: Call your next level of support.

E3D46F23 E3D46F23

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while performing local file path query

Problem determination: Call your next level of support.

E3D46F25 E3D46F25

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred reading a file to be sent to RETAIN

Problem determination: Call your next level of support.

E3D46F2D E3D46F2D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred writing a file sent from RETAIN

Problem determination: Call your next level of support.

E3D46F2E E3D46F2E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred executing a command issued from RETAIN

Problem determination: Call your next level of support.

E3D46F2F E3D46F2F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred writing a file sent from RETAIN

Problem determination: Call your next level of support.

E3D46F40 • E3D46FFF

E3D46F40 E3D46F40

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred getting the call home authentication token using system credentials

Problem determination: Call your next level of support.

E3D46F41 E3D46F41

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with system authentication using system credentials

Problem determination: Call your next level of support.

E3D46F42 E3D46F42

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred communicating with service data receiver

Problem determination: Call your next level of support.

E3D46F43 E3D46F43

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Information SDR communication progressing

Problem determination: Call your next level of support.

E3D46F46 E3D46F46

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred connecting to RETAIN

Problem determination: Call your next level of support.

E3D46F71 E3D46F71

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred while parsing the command from RETAIN for the call home request.

Problem determination: Call your next level of support.

E3D46F72 E3D46F72

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error reported from RETAIN for the call home request

Problem determination: Call your next level of support.

E3D46FB0 E3D46FB0

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred sending/receiving from RETAIN

Problem determination: Call your next level of support.

E3D46FFF E3D46FFF

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Internal error occurred while calling home - remote connection services may have returned an error

Problem determination: Call your next level of support.

(E3D7) Reference codes

E3D71000 E3D71000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Bad variable length in packet

Problem determination: Call your next level of support.

E3D71001 E3D71001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending packet

Problem determination: Call your next level of support.

E3D71002 E3D71002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unmatched packet id on incoming response packet

Problem determination: Call your next level of support.

E3D71003 E3D71003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Unsupported packet type in incoming packet

Problem determination: Call your next level of support.

E3D71004 E3D71004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: IO error in PacketHandler thread

Problem determination: Call your next level of support.

E3D71005 E3D71005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: General error in PacketHandler thread

Problem determination: Call your next level of support.

E3D72000 E3D72000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error establishing the DPI connection

Problem determination: Call your next level of support.

E3D72001 E3D72001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending register request to DPI agent

Problem determination: Call your next level of support.

E3D72002 E3D72002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: DPI agent reported error in register request

Problem determination: Call your next level of support.

E3D72003 E3D72003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending trap

Problem determination: Call your next level of support.

E3D72004 E3D72004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error creating datagram socket

Problem determination: Call your next level of support.

(E3E4) Reference codes

E3E40001 E3E40001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Archieve Security logs task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3E40002 E3E40002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Archieve Security Logs task action handler. The task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3E40003 E3E40003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the Archieve Security Logs task. The task has been ended.

Problem determination: Call your next level of support.

E3E40004 E3E40004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Archieve Security Logs task. The task has been ended.

Problem determination: Call your next level of support.

E3E40005 E3E40005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Archieve Security Logs task. This is the result of an exception being caught by the

underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3E40006 E3E40006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the disk copy for server side of the Archieve Security Logs task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3E40007 E3E40007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the DVD copy for server side of the Archieve Security Logs task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Transmit Service Data task has been ended.

Problem determination: Call your next level of support.

E3E40511 E3E40511

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the event log summary panel. Error in panelAction().

Problem determination: Call your next level of support.

E3E40514 E3E40514

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error occurred in bean for the text expander panel. Error in panelAction().

Problem determination: Call your next level of support.

E3E40515 E3E40515

Explanation: Licensed Internal Code failure on the

E3E40554 • E3E4A015

Hardware Management Console (HMC).

Response: Error occurred in bean for the hex expander panel. Error in panelAction().

Problem determination: Call your next level of support.

E3E40554 E3E40554

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error found in the TextExpanderTasklet.

Problem determination: Call your next level of support.

E3E4A011 E3E4A011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the View Security (E4) Logs task. This is the result of an exception being caught by the underlying Tasklet infrastructure.

Problem determination: Call your next level of support.

E3E4A012 E3E4A012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "init" processing for server side of the View Security (E4) Logs task. The task has been ended.

Problem determination: Call your next level of support.

E3E4A013 E3E4A013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the View Security (E4) Logs task. The task has been ended.

Problem determination: Call your next level of support.

E3E4A014 E3E4A014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the View Security (E4) Logs task. This is the result of an exception being caught by the underlying Tasklet infrastructure.

Problem determination: Call your next level of support.

E3E4A015 E3E4A015

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the getLogs processing for server side of the View Security (E4) Logs task. This is the result of an exception being caught by the underlying Tasklet infrastructure.

Problem determination: Call your next level of support.

(E3E9) Reference codes

E3E90000 E3E90000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the client side of the Add Fiber Saver task.

Problem determination: Call your next level of support.

E3E90001 E3E90001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside the Find Fiber Saver Bean for the Add Fiber Saver task.

Problem determination: Call your next level of support.

E3E90002 E3E90002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside the Manual Add Fiber Saver Bean for the Add Fiber Saver task.

Problem determination: Call your next level of support.

E3E90003 E3E90003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the server side of the Add Fiber Saver task.

Problem determination: Call your next level of support.

E3E90004 E3E90004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the client side of the Remove Fiber Saver task.

Problem determination: Call your next level of support.

E3E90005 E3E90005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the server side of the Remove Fiber Saver task.

Problem determination: Call your next level of support.

E3E90010 E3E90010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the construction of the Fiber Saver Tower.

Problem determination: Call your next level of support.

E3E90011 E3E90011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred in compiling the regular expression class that is used by the Fiber Saver Tower.

Problem determination: Call your next level of support.

E3E90012 E3E90012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while instantiating a new instance of a SNMP socket class that is used by the Fiber Saver Tower.

Problem determination: Call your next level of support.

E3E90013 E3E90013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred while attempting to restore the Defined Fiber Saver objects for console.

Problem determination: Call your next level of support.

E3E90020 E3E90020

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the client side of the Fiber Saver Alert Details task.

E3E90021 • E3E90032

Problem determination: Call your next level of support.

E3E90021 E3E90021

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside the bean of the Fiber Saver Alert Details task.

Problem determination: Call your next level of support.

E3E90022 E3E90022

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the server side of the Fiber Saver Alert Details task.

Problem determination: Call your next level of support.

E3E90030 E3E90030

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the client side of the Fiber Saver Details task.

Problem determination: Call your next level of support.

E3E90031 E3E90031

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred inside the bean of the Fiber Saver Details task.

Problem determination: Call your next level of support.

E3E90032 E3E90032

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred on the server side of the Fiber Saver Details task.

Problem determination: Call your next level of support.

(E3EA) Reference codes

E3EA0000 E3EA0000

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with the listening server. The auto-discovery thread will be taken down.

Problem determination: Call your next level of support.

E3EA0001 E3EA0001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error sending the multicast to D/T consoles. No action will be taken, and we will try again on the next heart beat.

Problem determination: Call your next level of support.

E3EA0002 E3EA0002

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying get and parse a response. The response has been ignored.

Problem determination: Call your next level of support.

E3EA0003 E3EA0003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error with the server socket. The server has been brought down and the exception can be retrieved via the `getException()` method.

Problem determination: Call your next level of support.

E3EA0004 E3EA0004

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of a Director/Timer add obj def task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3EA0005 E3EA0005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Director/Timer add obj def task. The task has been ended.

Problem determination: Call your next level of support.

E3EA0006 E3EA0006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Director/Timer add obj def task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3EA0007 E3EA0007

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of a Director/Timer remove obj def task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3EA0008 E3EA0008

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Director/Timer remove obj def task. The task has been ended.

Problem determination: Call your next level of support.

E3EA0009 E3EA0009

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Director/Timer remove obj def task.

E3EA000A • E3EA0012

This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3EA000A E3EA000A

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of a Director/Timer change obj def task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3EA000B E3EA000B

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Director/Timer change obj def task. The task has been ended.

Problem determination: Call your next level of support.

E3EA000C E3EA000C

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Director/Timer change obj def task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The task has been ended.

Problem determination: Call your next level of support.

E3EA000D E3EA000D

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Director/Timer obj def task action handler. The task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3EA000E E3EA000E

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Director/Timer Details task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Directors/Timers Details task has been ended.

Problem determination: Call your next level of support.

E3EA000F E3EA000F

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Director/Timer Details task. The Director/Timer details task has been ended.

Problem determination: Call your next level of support.

E3EA0010 E3EA0010

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for client side of the Director/Timer Details task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Director/Timer Details task has been ended.

Problem determination: Call your next level of support.

E3EA0011 E3EA0011

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Director/Timer Details task action handler. The Director/Timer Details task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3EA0012 E3EA0012

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the main processing for server side of the SOO task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The SOO task has been ended.

Problem determination: Call your next level of support.

E3EA0013 E3EA0013

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the "service" processing for server side of the SOO task. The SOO task has been ended.

Problem determination: Call your next level of support.

E3EA0014 E3EA0014

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: An error occurred during the "run" processing for client side of the SOO task. The SOO task has been ended.

Problem determination: Call your next level of support.

(E3F0) Reference codes

E3F00001 E3F00001

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to do the main processing for server side of the Console Trace task. This is the result of an exception being caught by the underlying Tasklet infrastructure. The Console Trace task has been ended.

Problem determination: Call your next level of support.

Response: Error trying to perform some processing in Console Trace prepare(). The Console Trace task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3F00003 E3F00003

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error during the "service" processing for server side of the Console Trace task. The Console Trace task has been ended.

Problem determination: Call your next level of support.

E3F00004 E3F00004

Explanation: The 'Perform Console Trace' task located in Console Actions encountered an error that caused it to end.

Problem determination: Perform the following steps:

1. Retry the task.

Note: Do not interrupt the task while it is running.

2. If the problem persists, send the iqyylog.log to your next level of support for analysis.

Note: To use the 'Perform Console Trace' task, you must be a member of the service representative role.

E3F00005 E3F00005

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

Response: Error trying to perform some processing in the Console Trace task action handler. The Console Trace task will most likely continue to run, but it may not function as expected.

Problem determination: Call your next level of support.

E3F00006 E3F00006

Explanation: Licensed Internal Code failure on the Hardware Management Console (HMC).

(E3xx) Reference codes

E3XXXXXX E3XXXXXX

Explanation: Licensed Internal Code failure on the HMC.

Problem determination: Contact your service provider.

Failing Item:

- NEXTLVL

(EFxx) Reference codes

EF000001 EF000001

Explanation: A disk has failed or is not responding and needs to be replaced.

Response: Use MAP5000

Failing Item:

- IO_DEV

EF000002 EF000002

Explanation: There is not enough available spare space to re-establish full redundancy in a declustered array.

Response: Use MAP5001

(0xxxxx) Reference codes

If the HMC displays a state of No Connection in the managed system state column, or if the Systems Director Management Console (SDMC) displays a state of Not available in the managed system state column, it means that the management console is unable to establish a connection to the managed system. There are several reasons why the management console fails to establish a connection, and often it is due to network issues. It is important to first check the network setting on both the management console and the managed system. However, there are times a no connection state or a not available state is caused by another problem unrelated to network settings.

0X0000 **0X0000**

Explanation: Connecting

0X0001 **0X0001**

Explanation: Connecting

Problem determination: If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0002 **0X0002**

Explanation: Connecting

Problem determination: If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0003 **0X0003**

Explanation: Connecting

Problem determination: A reset connection of the managed system was initiated on the management console. If the management console does not recover automatically within a few minutes, contact your next level of support or your hardware service provider. The managed system should not stay in this state for long. The management console will re-establish connection to the system, and change to another state.

0X0004 **0X0004**

Explanation: Temporary disconnection

0X0005 **0X0005**

Explanation: Permanent disconnection

0X0006 **0X0006**

Explanation: Forced disconnection

Problem determination: If you no longer want your server to be management console-managed, you must reset the server to a nonpartitioned server before removing the management console.

0X0007 **0X0007**

Explanation: Connecting

Problem determination: If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0008 **0X0008**

Explanation: Duplicate IP

Problem determination: There is another managed system with the same IP address. Check whether there is an IP conflict. Reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0009 **0X0009**

Explanation: Connection not allowed.

0X00FF **0X00FF**

Explanation: Connecting

Problem determination: Reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0101 **0X0101**

0X0102 • 0X0404

Explanation: DNS failure

Problem determination: The management console is unable to resolve the host name entered for the managed system through the domain name server. Check whether the DNS is down. If the failure continues, remove the managed system connection and add it back using the IP address. Leaving a connection in the DNS failed state might cause performance problems for other management console connections.

0X0102 0X0102

Explanation: Connecting

Problem determination: The management console is unable to establish a network connection to the managed system. Ensure that the managed system network is configured correctly.

0X0103 0X0103

Explanation: Connecting

Problem determination: The target IP address of the managed system is refusing a connection from the management console. Ensure that the IP specified is a valid managed system IP and that the managed system's network is configured correctly. A connection might also be refused if the service processor firewall is configured to block this management console IP address. Check the network configuration setting of your managed system to ensure that the management console IP is not being blocked.

0X0104 0X0104

Explanation: IP unreachable

Problem determination: The management console is unable to establish a network connection to the managed system. Ensure the management console and managed system are not on either side of a firewall, or if a firewall exists, ensure that the firewall is configured correctly. Ensure that the managed system network is configured correctly. A common cause for this might be an invalid IP configuration on the management console (for example, bad routing tables or default gateway).

0X01FF 0X01FF

Explanation: Connecting

Problem determination: The management console is unable to establish a network connection to the managed system. Ensure that the managed system network is configured correctly.

0X02FF 0X02FF

Explanation: Connecting

Problem determination: The management console is unable to establish a secure network connection to the managed system. Reset the connection from the management console. If the problem persists, contact your next level of support or your hardware service provider.

0X0401 0X0401

Explanation: Interface version timed out

Problem determination: If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0402 0X0402

Explanation: Already connected

Problem determination: The managed system already has a connection established from the same management console. If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection, then restart the management console. If the problem persists, contact your next level of support or your hardware service provider.

0X0403 0X0403

Explanation: All connections in use

Problem determination: All connections available for management consoles are already in use. Determine what other management consoles are connected to the managed system, and remove the managed system connections from the other management consoles. Contact your administrator to find out which management consoles can connect to the managed system.

0X0404 0X0404

Explanation: Version mismatch

Problem determination: This version of management console is unable to manage the system. Update the management console image.

0X0405 **0X0405**
Explanation: Duplicate MTMS**Problem determination:** There is already a managed system with the same machine type, model, and serial number. Contact your next level of support or your hardware service provider.

0X0406 **0X0406**
Explanation: Firmware not ready**Problem determination:** If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X04FF **0X04FF**
Explanation: Connecting**Problem determination:** If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your hardware service provider.

0X0801 **0X0801**
Explanation: Authentication timed out**Problem determination:** Reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0802 **0X0802**
Explanation: Incorrect password**Problem determination:** The password entered for the managed system is not correct. Check with your administrator to ensure that the password is correct and update the managed system password that the management console is sending to the managed system.

0X0803 **0X0803**
Explanation: Firmware password locked**Problem determination:** There have been too many unsuccessful login attempts to the same managed system and the password is locked. Wait for five minutes, and reset the connection from the management console. If the problem persists, contact

your next level of support or your hardware service provider.

0X08FF **0X08FF**
Explanation: Connecting.**Problem determination:** If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X0BFF **0X0BFF**
Explanation: Connecting.**Problem determination:** If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X1001 **0X1001**
Explanation: Command timed out.**Problem determination:** If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

0X10FF **0X10FF**
Explanation: Connecting.**Problem determination:** If the management console does not recover automatically within a few minutes, reset the managed system connection from the management console. If the managed system is still showing No Connection on the management console, contact your next level of support or your hardware service provider.

(HSCE) Reference codes

HSCE2001 HSCE2001

Explanation: New managed system created.

Problem determination: No action required

HSCE2002 HSCE2002

Explanation: Logical Partition has been created in managed system.

Problem determination: No action required

HSCE2003 HSCE2003

Explanation: Logical Partition failed to be created in managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2004 HSCE2004

Explanation: Profile data of managed system has been backed up to file.

Problem determination: No action required

HSCE2005 HSCE2005

Explanation: Profile data of managed system failed to backup to file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2006 HSCE2006

Explanation: Backup file has been restored to managed system.

Problem determination: No action required

HSCE2007 HSCE2007

Explanation: Backup file failed to restore to managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2008 HSCE2008

Explanation: Backup file of managed system has been removed.

Problem determination: No action required

HSCE2009 HSCE2009

Explanation: Backup file of managed system failed to be removed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2010 HSCE2010

Explanation: Logical Partition has been deleted from managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2011 HSCE2011

Explanation: Logical Partition failed to be deleted in managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2012 HSCE2012

Explanation: A reset has been executed on partition of managed system.

Problem determination: No action required

HSCE2013 HSCE2013

Explanation: A reset failed to be executed on partition of managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2014 HSCE2014

Explanation: Virtual terminal has been open on partition of managed system.

Problem determination: No action required

HSCE2015 HSCE2015

Explanation: Virtual terminal failed to be opened on partition of managed system.

Problem determination: If the problem persists,

HSCE2016 • HSCE2032

contact your next level of support or your service provider.

HSCE2016 HSCE2016

Explanation: Logical Partition of managed system has been activated with profile.

Problem determination: No action required

HSCE2017 HSCE2017

Explanation: Failed to activate logical partition of managed system using profile.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2018 HSCE2018

Explanation: System profile has been deleted from managed system.

Problem determination: No action required

HSCE2019 HSCE2019

Explanation: System profile failed to be deleted from managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2020 HSCE2020

Explanation: System profile has been successfully copied in managed system.

Problem determination: No action required

HSCE2021 HSCE2021

Explanation: System profile copy failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2022 HSCE2022

Explanation: Unit ID slot of managed system has been freed from LPAR.

Problem determination: No action required

HSCE2023 HSCE2023

Explanation: Unit ID slot of managed system has been assigned to LPAR.

Problem determination: No action required

HSCE2024 HSCE2024

Explanation: Processor of managed system has been freed from LPAR.

Problem determination: No action required

HSCE2025 HSCE2025

Explanation: Processor of managed system has been assigned to LPAR.

Problem determination: No action required

HSCE2026 HSCE2026

Explanation: Requested memory from managed system has been assigned to LPAR.

Problem determination: No action required

HSCE2027 HSCE2027

Explanation: New Profile created in managed system.

Problem determination: No action required

HSCE2028 HSCE2028

Explanation: New Profile creation failed in managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2029 HSCE2029

Explanation: Profile modified in managed system.

Problem determination: No action required

HSCE2030 HSCE2030

Explanation: Profile modification failed in managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2031 HSCE2031

Explanation: New System Profile created in managed system.

Problem determination: No action required

HSCE2032 HSCE2032

Explanation: New System Profile creation failed in managed system.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCE2033 HSCE2033

Explanation: System Profile modified in managed system.

Problem determination: No action required

HSCE2034 HSCE2034

Explanation: System Profile modification failed in managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2035 HSCE2035

Explanation: Failed to Power On.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2036 HSCE2036

Explanation: Powering On.

Problem determination: No action required

HSCE2037 HSCE2037

Explanation: Failed to Power Off.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2038 HSCE2038

Explanation: Powering Off.

Problem determination: No action required

HSCE2039 HSCE2039

Explanation: Failed to delete managed system from CIMOM.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2040 HSCE2040

Explanation: Deleted managed system.

Problem determination: No action required

HSCE2041 HSCE2041

Explanation: Boot error of logical partition at managed system is cleared during process.

Problem determination: No action required

HSCE2042 HSCE2042

Explanation: Activated System Profile on managed system.

Problem determination: No action required

HSCE2043 HSCE2043

Explanation: Failed to Activate System Profile on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2044 HSCE2044

Explanation: Modified property on managed system.

Problem determination: to

HSCE2066 HSCE2066

Explanation: A scheduled backup of critical console data failed.

Problem determination: The possible return code values are: A 4 indicates that the removable media could not be mounted. Verify that the media is inserted correctly in the drive and try the operation again. A 5 indicates that the removable media is write protected. Remove write protection and try the operation again. Any value except 4 or 5 is an internal HMC error. Back up critical HMC data. If the problem persists, contact your next level of support or your service provider.

HSCE2101 HSCE2101

Explanation: Created user with specified role.

Problem determination: No action required

HSCE2102 HSCE2102

Explanation: Failed to create user with specified role.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2103 HSCE2103

Explanation: Changed property of user.

Problem determination: No action required

HSCE2104 • HSCE2120

HSCE2104 HSCE2104

Explanation: Failed to change user property.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2105 HSCE2105

Explanation: Changed password for user.

Problem determination: No action required

HSCE2106 HSCE2106

Explanation: Failed to change password for user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2107 HSCE2107

Explanation: Removed user.

Problem determination: No action required

HSCE2108 HSCE2108

Explanation: Failed to remove user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2109 HSCE2109

Explanation: Modified remote execution settings to ssh.

Problem determination: No action required

HSCE2110 HSCE2110

Explanation: Modified DNS Server search order.

Problem determination: No action required

HSCE2111 HSCE2111

Explanation: Modified Domain Suffix search order.

Problem determination: No action required

HSCE2112 HSCE2112

Explanation: Modified network settings of interface.

Problem determination: No action required

HSCE2113 HSCE2113

Explanation: Modified network settings successfully.

Problem determination: No action required

HSCE2114 HSCE2114

Explanation: Failed to modify network settings.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2115 HSCE2115

Explanation: Change default profile on partition on managed system succeeded.

Problem determination: No action required

HSCE2116 HSCE2116

Explanation: Failed to change default profile to on partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2117 HSCE2117

Explanation: Rebuilt managed system.

Problem determination: No action required

HSCE2118 HSCE2118

Explanation: Failed to rebuild managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2119 HSCE2119

Explanation: Reboot executed successfully on partition on the managed system.

Problem determination: No action required

HSCE2120 HSCE2120

Explanation: Reboot failed on partition on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2121 HSCE2121

Explanation: Shut down executed successfully on partition on the managed system.

Problem determination: No action required

HSCE2122 HSCE2122

Explanation: Shut down failed on partition on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2123 HSCE2123

Explanation: Command was executed successfully.

Problem determination: No action required

HSCE2124 HSCE2124

Explanation: Command failed.

Problem determination: Run the rebuild managed system operation, then try the command again. If the problem persists, contact your next level of support or your service provider.

HSCE2127 HSCE2127

Explanation: Deleting managed system failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2128 HSCE2128

Explanation: Deleting managed system succeeded.

Problem determination: No action required

HSCE2129 HSCE2129

Explanation: Virtual I/O server command for partition failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2130 HSCE2130

Explanation: Virtual I/O server command for partition executed successfully.

Problem determination: No action required

HSCE2131 HSCE2131

Explanation: HMC date/time changed.

Problem determination: No action required

HSCE2132 HSCE2132

Explanation: VPD collection was successful from managed system.

Problem determination: No action required

HSCE2133 HSCE2133

Explanation: VPD collection was only partially successful from managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2134 HSCE2134

Explanation: VPD collection failed from managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2135 HSCE2135

Explanation: The NTP service was successfully changed.

Problem determination: No action required

HSCE2145 HSCE2145

Explanation: Events in the event log were deleted.

Problem determination: No action required

HSCE2146 HSCE2146

Explanation: Due to event log space limitations, obsolete events were deleted.

Problem determination: No action required

HSCE2147 HSCE2147

Explanation: DLPAR: Finished retrieving slot data.

Problem determination: No action required

HSCE2148 HSCE2148

Explanation: DLPAR: Finished getting processor data.

Problem determination: No action required

HSCE2149 • HSCE2167

HSCE2149 HSCE2149

Explanation: DLPAR: Finished getting memory data.

Problem determination: No action required

HSCE2150 HSCE2150

Explanation: LED: Finished getting list of LEDs.

Problem determination: No action required

HSCE2151 HSCE2151

Explanation: LED: Finished setting LED state.

Problem determination: No action required

HSCE2152 HSCE2152

Explanation: LED: Finished getting LED state.

Problem determination: No action required

HSCE2153 HSCE2153

Explanation: DLPAR: Finished retrieving data for all the I/O devices in the system.

Problem determination: No action required

HSCE2154 HSCE2154

Explanation: DLPAR: Completed adding CPUs to the partition.

Problem determination: No action required

HSCE2155 HSCE2155

Explanation: DLPAR: Completed removing CPUs from the partition.

Problem determination: No action required

HSCE2156 HSCE2156

Explanation: DLPAR: Completed moving CPUs.

Problem determination: No action required

HSCE2157 HSCE2157

Explanation: DLPAR: Completed adding memory to the partition.

Problem determination: No action required

HSCE2158 HSCE2158

Explanation: DLPAR: Completed removing memory from the partition.

Problem determination: No action required

HSCE2159 HSCE2159

Explanation: DLPAR: Completed moving memory.

Problem determination: No action required

HSCE2160 HSCE2160

Explanation: DLPAR: Completed adding slots to the partition.

Problem determination: No action required

HSCE2161 HSCE2161

Explanation: DLPAR: Completed removing slots from the partition.

Problem determination: No action required

HSCE2162 HSCE2162

Explanation: DLPAR: Completed moving slots from the partition.

Problem determination: No action required

HSCE2163 HSCE2163

Explanation: Completed activating the partition.

Problem determination: No action required

HSCE2164 HSCE2164

Explanation: SMA adapter assigned.

Problem determination: No action required

HSCE2165 HSCE2165

Explanation: SMA adapter freed.

Problem determination: No action required

HSCE2166 HSCE2166

Explanation: Forced Virtual Terminal Session on managed system to close.

Problem determination: No action required

HSCE2167 HSCE2167

Explanation: Forced Virtual Terminal Session on logical partition in managed system to close.

Problem determination: No action required

HSCE2168 HSCE2168

Explanation: Failed to force Virtual Terminal Session on managed system to close.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2169 HSCE2169

Explanation: Failed to force Virtual Terminal Session on logical partition in managed system to close.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2174 HSCE2174

Explanation: Login from remote host was successful.

Problem determination: No action required

HSCE2175 HSCE2175

Explanation: Login from remote host failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2176 HSCE2176

Explanation: Local login was successful.

Problem determination: No action required

HSCE2177 HSCE2177

Explanation: Modified remote websm settings.

Problem determination: No action required

HSCE2178 HSCE2178

Explanation: Modified web server settings.

Problem determination: No action required

HSCE2179 HSCE2179

Explanation: Modified syslog server settings.

Problem determination: No action required

HSCE2180 HSCE2180

Explanation: Modified remote access.

Problem determination: No action required

HSCE2181 HSCE2181

Explanation: Installed LIC on managed system.

Problem determination: No action required

HSCE2182 HSCE2182

Explanation: Installed and activated LIC on managed system.

Problem determination: No action required

HSCE2183 HSCE2183

Explanation: Removed LIC on managed system.

Problem determination: No action required

HSCE2184 HSCE2184

Explanation: AcmAPI User Op.

Problem determination: No action required

HSCE2185 HSCE2185

Explanation: AcmAPI Role Op.

Problem determination: No action required

HSCE2186 HSCE2186

Explanation: AcmAPI Group Op.

Problem determination: No action required

HSCE2187 HSCE2187

Explanation: AcmAPI Purge Op.

Problem determination: No action required

HSCE2188 HSCE2188

Explanation: Added firewall rule for interfaces.

Problem determination: No action required

HSCE2189 HSCE2189

Explanation: Removed firewall rule for interfaces.

Problem determination: No action required

HSCE2190 HSCE2190

Explanation: Guided Setup Wizard Message.

Problem determination: No action required

HSCE2191 • HSCE2206

HSCE2191 HSCE2191

Explanation: Modified xntp server settings.

Problem determination: No action required

HSCE2192 HSCE2192

Explanation: Modified xntp server settings.

Problem determination: No action required

HSCE2193 HSCE2193

Explanation: Modified xntp server settings.

Problem determination: No action required

HSCE2194 HSCE2194

Explanation: Dump was manually initiated.

Problem determination: No action required

HSCE2195 HSCE2195

Explanation: Power On manually initiated.

Problem determination: No action required

HSCE2196 HSCE2196

Explanation: Power Off manually initiated.

Problem determination: No action required

HSCE2197 HSCE2197

Explanation: Service Processor failover successfully completed on selected system.

Problem determination: No action required

HSCE2198 HSCE2198

Explanation: Service Processor failover command failed on selected system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2199 HSCE2199

Explanation: Service Processor failover call took an exception for selected system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2200 HSCE2200

Explanation: Service Processor failover enablement command completed successfully on selected system.

Problem determination: No action required

HSCE2201 HSCE2201

Explanation: Service Processor failover enablement command failed on selected system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2202 HSCE2202

Explanation: Service Processor failover enablement call took an exception for selected system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2203 HSCE2203

Explanation: DLPAR Add memory resources to partition succeeded on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2204 HSCE2204

Explanation: DLPAR Add memory resources to partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2205 HSCE2205

Explanation: DLPAR Remove memory resources from partition succeeded on managed system.

Problem determination: No action required

HSCE2206 HSCE2206

Explanation: DLPAR Remove memory resources from partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2207 HSCE2207

Explanation: DLPAR Move memory resources from one partition to another partition succeeded on the managed system.

Problem determination: No action required.

HSCE2208 HSCE2208

Explanation: DLPAR Move memory resources from one partition to another partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2209 HSCE2209

Explanation: DLPAR Add processor resources to partition succeeded on managed system.

Problem determination: No action required

HSCE2210 HSCE2210

Explanation: DLPAR Add processor resources to partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2211 HSCE2211

Explanation: DLPAR Remove processor resources from partition succeeded on managed system.

Problem determination: No action required

HSCE2212 HSCE2212

Explanation: DLPAR Remove processor resources from partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2213 HSCE2213

Explanation: DLPAR Move processor resources from one partition to another partition succeeded on managed system.

Problem determination: No action required

HSCE2214 HSCE2214

Explanation: DLPAR Move processor resources from one partition to another partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2215 HSCE2215

Explanation: DLPAR Add I/O resources to partition succeeded on managed system.

Problem determination: No action required

HSCE2216 HSCE2216

Explanation: DLPAR Add I/O resources to partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2217 HSCE2217

Explanation: DLPAR Remove I/O resources from partition succeeded on managed system.

Problem determination: No action required

HSCE2218 HSCE2218

Explanation: DLPAR Remove I/O resources from partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2219 HSCE2219

Explanation: DLPAR Move I/O resources from one partition to another partition succeeded on managed system.

Problem determination: No action required

HSCE2220 HSCE2220

Explanation: DLPAR Move I/O resources from one partition to another partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2221 HSCE2221

Explanation: DLPAR Add Virtual I/O resources to partition succeeded on managed system.

Problem determination: No action required

HSCE2222 HSCE2222

Explanation: DLPAR Add Virtual I/O resources to partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2223 HSCE2223

Explanation: DLPAR Remove Virtual I/O resources from partition succeeded on managed system.

Problem determination: No action required

HSCE2224 HSCE2224

Explanation: DLPAR Remove Virtual I/O resources from partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2225 HSCE2225

Explanation: launching ASM.

Problem determination: No action required

HSCE2226 HSCE2226

Explanation: Validation of system profile succeeded on managed system.

Problem determination: No action required

HSCE2227 HSCE2227

Explanation: Validation of system profile failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2228 HSCE2228

Explanation: Reset operation on managed system succeeded.

Problem determination: No action required

HSCE2229 HSCE2229

Explanation: Reset operation on managed system failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2230 HSCE2230

Explanation: Operation to change managed system name succeeded.

Problem determination: No action required

HSCE2231 HSCE2231

Explanation: Operation to change managed system name failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2232 HSCE2232

Explanation: New managed frame created.

Problem determination: No action required

HSCE2233 HSCE2233

Explanation: Rebuilt managed frame.

Problem determination: No action required

HSCE2234 HSCE2234

Explanation: Failed to rebuild managed frame.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2235 HSCE2235

Explanation: Reset operation on managed frame succeeded.

Problem determination: No action required

HSCE2236 HSCE2236

Explanation: Reset operation on managed frame failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2237 HSCE2237

Explanation: Deleting managed frame succeeded.

Problem determination: No action required

HSCE2238 HSCE2238

Explanation: Deleting managed frame failed.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCE2239 HSCE2239

Explanation: Changed password for managed frame.

Problem determination: No action required

HSCE2240 HSCE2240

Explanation: Failed to change password for managed frame.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2241 HSCE2241

Explanation: OS shutdown for partition succeeded on managed system.

Problem determination: No action required

HSCE2242 HSCE2242

Explanation: Failed to shutdown the partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2243 HSCE2243

Explanation: Powering on the managed system with options succeeded.

Problem determination: No action required

HSCE2244 HSCE2244

Explanation: Failed to power on the partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2245 HSCE2245

Explanation: Activating the partition succeeded on managed system.

Problem determination: No action required

HSCE2246 HSCE2246

Explanation: Failed to activate the partition on managed system.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCE2247 HSCE2247

Explanation: Virtual TTY request for partition succeeded on managed system.

Problem determination: No action required

HSCE2248 HSCE2248

Explanation: Failed to send Virtual TTY request for partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2249 HSCE2249

Explanation: Powering on the partition succeeded on managed system.

Problem determination: No action required

HSCE2250 HSCE2250

Explanation: Failed to power on the partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2251 HSCE2251

Explanation: Powering off the partition succeeded on managed system.

Problem determination: No action required

HSCE2252 HSCE2252

Explanation: Failed to power off the partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2253 HSCE2253

Explanation: Rebuilt managed system.

Problem determination: No action required

HSCE2254 HSCE2254

Explanation: Dump to load source for partition succeeded on managed system.

Problem determination: No action required

HSCE2255 • HSCE2272

HSCE2255 HSCE2255

Explanation: Dump to load source for partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2256 HSCE2256

Explanation: Modified partition property for partition.

Problem determination: No action required

HSCE2257 HSCE2257

Explanation: Changed password on managed system.

Problem determination: No action required

HSCE2258 HSCE2258

Explanation: Failed to changed password on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2259 HSCE2259

Explanation: Changed HMC locale.

Problem determination: No action required

HSCE2260 HSCE2260

Explanation: Changing HMC locale failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2261 HSCE2261

Explanation: CoD activation code entered for managed system.

Problem determination: No action required

HSCE2262 HSCE2262

Explanation: Virtual Engine Technologies activation code entered for managed system.

Problem determination: No action required

HSCE2263 HSCE2263

Explanation: Request to manage On/Off CoD processors on managed system received.

Problem determination: No action required

HSCE2264 HSCE2264

Explanation: Request to manage On/Off CoD memory on managed system received.

Problem determination: No action required

HSCE2265 HSCE2265

Explanation: Request to manage Reserve CoD processors on managed system received.

Problem determination: No action required

HSCE2266 HSCE2266

Explanation: Request to stop Trial CoD processors on managed system received.

Problem determination: No action required

HSCE2267 HSCE2267

Explanation: Request to stop Trial CoD memory on managed system received.

Problem determination: No action required

HSCE2268 HSCE2268

Explanation: Configured Object Managed Security for management console.

Problem determination: No action required

HSCE2269 HSCE2269

Explanation: Configured a Web-based System Manager Certificate Authority.

Problem determination: No action required

HSCE2270 HSCE2270

Explanation: Configured a Web-based System Manager Certificate Authority failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2271 HSCE2271

Explanation: Unconfigured a Web-based System Manager Certificate Authority.

Problem determination: No action required

HSCE2272 HSCE2272

Explanation: Unconfigured a Web-based System Manager Certificate Authority failed.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCE2273 HSCE2273

Explanation: Generated Certificate Authority Servers Private Key Ring Files for management console.

Problem determination: No action required

HSCE2274 HSCE2274

Explanation: Generated Certificate Authority Servers Private Key Ring Files for HMC failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2275 HSCE2275

Explanation: Copied Servers Private Key Ring Files for HMC to Removable Media.

Problem determination: No action required

HSCE2276 HSCE2276

Explanation: Copied this Certificate Authority Public Key Ring Files for HMC to Removable Media.

Problem determination: No action required

HSCE2277 HSCE2277

Explanation: Copied another Certificate Authority Public Key Ring Files from Removable Media to management console.

Problem determination: No action required

HSCE2278 HSCE2278

Explanation: Installed Servers Private Key Ring Files for management console.

Problem determination: No action required

HSCE2279 HSCE2279

Explanation: Installed Servers Private Key Ring Files for HMC failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2280 HSCE2280

Explanation: Configured a Secure Web-based System Manager Server.

Problem determination: No action required

HSCE2281 HSCE2281

Explanation: Configured a Secure Web-based System Manager Server failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2282 HSCE2282

Explanation: Recover partition data succeeded on managed system.

Problem determination: No action required

HSCE2283 HSCE2283

Explanation: Failed to recover partition data for managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2284 HSCE2284

Explanation: Changed startup from alternate disk partition.

Problem determination: No action required

HSCE2285 HSCE2285

Explanation: Changed startup from network.

Problem determination: No action required

HSCE2286 HSCE2286

Explanation: Failed to change startup from alternate disk partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2287 HSCE2287

Explanation: Failed to change startup from network.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2288 HSCE2288

Explanation: Modified keyboard configuration.

Problem determination: No action required

HSCE2289 HSCE2289

Explanation: HMC date/time change failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2290 HSCE2290

Explanation: Remote access connections.

Problem determination: No action required

HSCE2291 HSCE2291

Explanation: Remote access connections - failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2292 HSCE2292

Explanation: New managed system creation -failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2293 HSCE2293

Explanation: Shutdown or Restart HMC Successfull.

Problem determination: No action required

HSCE2294 HSCE2294

Explanation: Shutdown or Restart HMC Failure.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2296 HSCE2296

Explanation: User Assignment added for User.

Problem determination: No action required

HSCE2297 HSCE2297

Explanation: User redefined.

Problem determination: No action required

HSCE2298 HSCE2298

Explanation: User Assignment redefined for User.

Problem determination: No action required

HSCE2299 HSCE2299

Explanation: RegisterUser failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2300 HSCE2300

Explanation: User Assignment removed for User.

Problem determination: No action required

HSCE2301 HSCE2301

Explanation: UnregisterUser failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2302 HSCE2302

Explanation: New Role created.

Problem determination: No action required

HSCE2303 HSCE2303

Explanation: Failed to create new role.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2304 HSCE2304

Explanation: Role Deleted.

Problem determination: No action required

HSCE2305 HSCE2305

Explanation: Failed to delete role.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2306 HSCE2306

Explanation: Role Redefined.

Problem determination: No action required

HSCE2307 HSCE2307

Explanation: Failed to redefine role.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2308 HSCE2308

Explanation: Group Deleted.

Problem determination: No action required

HSCE2309 HSCE2309

Explanation: Failed to delete Group.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2310 HSCE2310

Explanation: Group Modified.

Problem determination: No action required

HSCE2311 HSCE2311

Explanation: Failed to modify Group.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2312 HSCE2312

Explanation: Group redefined.

Problem determination: No action required

HSCE2313 HSCE2313

Explanation: Failed to redefine Group.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2314 HSCE2314

Explanation: Group created.

Problem determination: No action required

HSCE2315 HSCE2315

Explanation: Failed to create Group.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2316 HSCE2316

Explanation: Purge resources.

Problem determination: No action required

HSCE2317 HSCE2317

Explanation: Failed to purge resources.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2318 HSCE2318

Explanation: Failed to add UserAssignment for user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2319 HSCE2319

Explanation: Failed to Redefine User.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2320 HSCE2320

Explanation: Failed to redefine User Assignment for user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2321 HSCE2321

Explanation: Failed to remove User Assignment for user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2322 HSCE2322

Explanation: DLPAR Add Logical HEA resources to partition succeeded on managed system.

Problem determination: No action required

HSCE2323 HSCE2323

Explanation: DLPAR Add Logical HEA resources to partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2324 HSCE2324

Explanation: DLPAR Remove Logical HEA resources to partition succeeded on managed system.

Problem determination: No action required

HSCE2325 • HSCE2341

HSCE2325 HSCE2325

Explanation: DLPAR Remove Logical HEA resources to partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2326 HSCE2326

Explanation: DLPAR Move Logical HEA resources from one partition to another partition succeeded on managed system.

Problem determination: No action required

HSCE2327 HSCE2327

Explanation: DLPAR Move Logical HEA resources from one partition to another partition failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2330 HSCE2330

Explanation: A 5250 console has been opened on partition of managed system.

Problem determination: No action required

HSCE2331 HSCE2331

Explanation: A virtual terminal has been opened on partition of managed system.

Problem determination: No action required

HSCE2332 HSCE2332

Explanation: A 5250 console failed to be opened on partition of managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2333 HSCE2333

Explanation: Virtual terminal failed to be opened on partition of managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2334 HSCE2334

Explanation: Request to cha./appendRCDL.sh HSCE nge Utility CoD processor usage limit on managed system was received.

Problem determination: No action required

HSCE2335 HSCE2335

Explanation: Request to manage Utility CoD processors on managed system was received.

Problem determination: No action required

HSCE2336 HSCE2336

Explanation: Modify for shared processor pool succeeded on managed system.

Problem determination: No action required

HSCE2337 HSCE2337

Explanation: Modify for shared processor pool failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2338 HSCE2338

Explanation: Move partition to shared processor pool succeeded on managed system.

Problem determination: No action required

HSCE2339 HSCE2339

Explanation: Move partition to shared processor pool failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2340 HSCE2340

Explanation: Logical port belonging to HEA location assigned to partition on managed system.

Problem determination: No action required

HSCE2341 HSCE2341

Explanation: Logical port belonging to HEA location code failed to assign to partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2342 HSCE2342

Explanation: Logical port belonging to HEA location code unassigned from partition on managed system.

Problem determination: No action required

HSCE2343 HSCE2343

Explanation: Logical port belonging to HEA location code failed to unassigned from partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2344 HSCE2344

Explanation: Logical HEA with capability from HEA location code is assigned to partition on managed system.

Problem determination: No action required

HSCE2345 HSCE2345

Explanation: Logical HEA with capability from HEA location code has failed to be assigned to partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2346 HSCE2346

Explanation: Logical HEA from HEA location code is deleted from partition on managed system.

Problem determination: No action required

HSCE2347 HSCE2347

Explanation: Logical HEA from HEA location code failed to delete from partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2348 HSCE2348

Explanation: PendingMCSValue has been set successfully for port group belonging to HEA location code on managed system.

Problem determination: No action required

HSCE2349 HSCE2349

Explanation: PendingMCSValue has failed to set for port group belonging to HEA location code on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2350 HSCE2350

Explanation: The LHEA capability for HEA on LPAR on managed system has changed.

Problem determination: No action required

HSCE2351 HSCE2351

Explanation: The LHEA Custom capability for HEA on LPAR on managed system has changed.

Problem determination: No action required

HSCE2352 HSCE2352

Explanation: The Physical port has changed for logical port from port group belonging to HEA location code assigned to partition on managed system.

Problem determination: No action required

HSCE2353 HSCE2353

Explanation: The VLAN ID has changed for logical port from port group belonging to HEA location code assigned to partition on managed system.

Problem determination: No action required

HSCE2354 HSCE2354

Explanation: New user copied successfully.

Problem determination: No action required

HSCE2355 HSCE2355

Explanation: Set info for physical port belonging to port group and HEA succeeded on managed system.

Problem determination: No action required

HSCE2356 HSCE2356

Explanation: Set info for physical port belonging to port group and HEA failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2357 • HSCE2376

HSCE2357 HSCE2357

Explanation: Managed system code levels compatible.

Problem determination: No action required

HSCE2358 HSCE2358

Explanation: Managed system code levels not compatible. Recommended update HMC level.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2359 HSCE2359

Explanation: Managed frame code levels compatible.

Problem determination: No action required

HSCE2360 HSCE2360

Explanation: Managed frame code levels not compatible. Recommended update HMC level.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2361 HSCE2361

Explanation: New Virtual Switch created in managed system.

Problem determination: No action required

HSCE2362 HSCE2362

Explanation: Virtual Switch failed to be created in managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2363 HSCE2363

Explanation: Virtual Switch has been deleted from managed system.

Problem determination: No action required

HSCE2364 HSCE2364

Explanation: Virtual Switch failed to be deleted from managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2365 HSCE2365

Explanation: Operation to change Virtual Switch name succeeded on managed system.

Problem determination: No action required

HSCE2366 HSCE2366

Explanation: Operation to change Virtual Switch name failed on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2367 HSCE2367

Explanation: The Managed System failed to set LPAR state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2368 HSCE2368

Explanation: The Managed System failed to set LPAR pending entitled memory.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2369 HSCE2369

Explanation: The Managed System failed to set LPAR pending memory.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2370 HSCE2370

Explanation: Corrective service file was offloaded successfully.

Problem determination: No action required

HSCE2371 HSCE2371

Explanation: Installation of HMC corrective service was successful.

Problem determination: No action required

HSCE2376 HSCE2376

Explanation: Operation failed for API.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2377 HSCE2377

Explanation: Operation failed for API.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2380 HSCE2380

Explanation: Migration of Partition from Managed System.

Problem determination: No action required

HSCE2381 HSCE2381

Explanation: Remote Migration of Partition.

Problem determination: No action required

HSCE2400 HSCE2400

Explanation: LDAP managed user account has been set up.

Problem determination: No action required

HSCE2401 HSCE2401

Explanation: User does not exist locally nor defined on LDAP server.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2402 HSCE2402

Explanation: LDAP managed user login is denied due to invalid role.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2403 HSCE2403

Explanation: LDAP managed user has been updated with new roles.

Problem determination: No action required

HSCE2404 HSCE2404

Explanation: Failed to create LDAP managed user account.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCE2410 HSCE2410

Explanation: LDAP auto managed user mode is enabled.

Problem determination: No action required

HSCE2411 HSCE2411

Explanation: LDAP auto managed user mode is disabled.

Problem determination: No action required

HSCE2416 HSCE2416

Explanation: Suspend operation on Partition of Managed System succeeded.

Problem determination: No action required

HSCE2417 HSCE2417

Explanation: Suspend operation on Partition of Managed System failed.

HSCE2418 HSCE2418

Explanation: Resume operation on Partition of Managed System succeeded.

HSCE2419 HSCE2419

Explanation: Resume operation on Partition of Managed System failed.

(HSCF) Reference codes

HSCF0001 HSCF0001

Explanation: Select at least one Licensed Internal Code type to be updated.

HSCF0002 HSCF0002

Explanation: Flash side selected for next activation: t-side

Problem determination: No recovery action is needed.

HSCF0003 HSCF0003

Explanation: Flash side selected for next activation: p-side. Attention : Selecting p-side for next activation will disable concurrent LIC update. The selection is for the next activation. To make it the currently active side, the target must be activated.

Problem determination: To switch to the temporary side, refer to Working with the temporary and permanent side of the service processor.

HSCF0004 HSCF0004

Explanation: An error occurred trying to survey the target. The task will be terminated.

HSCF0005 HSCF0005

Explanation: Managed System and Power LIC is selected for updating, but no target is currently selected. Ensure that the Managed System and Power LIC checkbox is not checked, or click Advanced Options to select a target.

HSCF0006 HSCF0006

Explanation: I/O LIC is selected for updating, but no device is currently selected. Ensure that the I/O LIC checkbox is not checked, or click Advanced Options to select a device.

HSCF0007 HSCF0007

Explanation: An error was encountered while reconfiguring the target for updating through the management console. The selected action can not be performed at this time.

HSCF0008 HSCF0008

Explanation: The selected installation type indicates to install and activate concurrently, but one or more selected targets have a disruptive concurrency status.

Either select a different installation type, or ensure there are no targets selected with a concurrency status of "All must be disruptively activated."

HSCF0009 HSCF0009

Explanation: Failure importing the I/O microcode.

HSCF0010 HSCF0010

Explanation: I/O level details are not available.

HSCF0011 HSCF0011

Explanation: Select a row in the table, and try the operation again.

HSCF0012 HSCF0012

Explanation: Permanent flash side is active.

Problem determination: To switch to the temporary side, refer to Working with the temporary and permanent side of the service processor.

HSCF0013 HSCF0013

Explanation: There are no applicable levels for displaying cover letter information.

HSCF0014 HSCF0014

Explanation: At least one target has its flash p-side active. Contact a user with service mode authority to use the Flash Side Selection task to make the flash t-side active, and then start this task again.

Problem determination: To switch to the temporary side, refer to Working with the temporary and permanent side of the service processor.

HSCF0015 HSCF0015

Explanation: An internal code error occurred on the target. The task will be terminated

HSCF0016 HSCF0016

Explanation: The operation failed because the drive is in use or can not be accessed for some other reason.

HSCF0017 HSCF0017

Explanation: The DVD does not contain any applicable upgrade updates. Insert another DVD, and click continue.

HSCF0018 • HSCF0042

HSCF0018 HSCF0018

Explanation: At least one target does not have an applicable upgrade update. Start the task again without selecting the applicable target(s).

HSCF0019 HSCF0019

Explanation: Retrieving updates.

HSCF0020 HSCF0020

Explanation: Installing updates.

HSCF0021 HSCF0021

Explanation: Activating updates - Power Off.

HSCF0022 HSCF0022

Explanation: Activating updates - Restarting FSP.

HSCF0023 HSCF0023

Explanation: Activating updates - Power On.

HSCF0024 HSCF0024

Explanation: Activating updates - FSP.

HSCF0025 HSCF0025

Explanation: Activating updates - PHYP.

HSCF0026 HSCF0026

Explanation: Activating updates - PFW.

HSCF0027 HSCF0027

Explanation: Update complete.

HSCF0028 HSCF0028

Explanation: Removing updates.

HSCF0029 HSCF0029

Explanation: Saving accepted level.

HSCF0030 HSCF0030

Explanation: Saving accepted level.

HSCF0031 HSCF0031

Explanation: Unable to contact the IBM service web site.

HSCF0032 HSCF0032

Explanation: Unable to contact the IBM support system.

HSCF0033 HSCF0033

Explanation: Unable to contact the FTP site.

HSCF0034 HSCF0034

Explanation: Unable to log into the FTP site using the specified user ID and password.

HSCF0035 HSCF0035

Explanation: Unable to access the specified FTP site directory.

HSCF0036 HSCF0036

Explanation: The connection to the target was lost during a reboot of the FSP.

HSCF0037 HSCF0037

Explanation: Licensed Internal code was changed as requested, but a failure occurred returning the managed system to its original state.

HSCF0038 HSCF0038

Explanation: Retrieve of licensed internal code failed.

HSCF0039 HSCF0039

Explanation: FRUs updated during a phase of power ACDL.

HSCF0040 HSCF0040

Explanation: Power ACDL started.

HSCF0041 HSCF0041

Explanation: Licensed Internal Code update cannot be started because ACDL is pending.

HSCF0042 HSCF0042

Explanation: Licensed Internal Code update cannot be started because the system has N mode power.

Problem determination: The system has power to only one of the two AC power cords. In general, N mode power means the system is not operating in a redundant state (N+1 power means the system can survive the loss of that particular power component). If both line cords are not powered, only one Bulk Power Controller (BPC) will be powered. Both BPCs need to be powered to load LIC.

HSCF0043 HSCF0043

Explanation: The installation type for Managed System and Power LIC indicates to install and activate disruptively. I/O LIC cannot be updated when that installation type is selected.

Problem determination: Ensure that either the I/O LIC checkbox is not checked, or click the Back button and ensure that the Managed System and Power LIC checkbox is not checked. When the LIC update completes, you can restart the Change Internal Code wizard to install the other LIC updates.

HSCF0044 HSCF0044

Explanation: Select a single row in the table, and try the operation again.

HSCF0045 HSCF0045

Explanation: Firmware update was successful to all primary service processors for the targeted object. There was a failure attempting to update the backup service processor.

HSCF0046 HSCF0046

Explanation: Firmware update was successful to all primary service processors for the targeted object. There was a failure attempting to update I/O microcode.

HSCF0047 HSCF0047

Explanation: This message was used temporarily in a previous release only.

HSCF0048 HSCF0048

Explanation: Power code download failed.

HSCF0049 HSCF0049

Explanation: Failure downloading file from the IBM service web site.

HSCF0050 HSCF0050

Explanation: The repository does not contain any applicable upgrade updates.

HSCF0051 HSCF0051

Explanation: There is a new upgrade release available at the repository.

HSCF0052 HSCF0052

Explanation: Frame is locked by another process.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0053 HSCF0053

Explanation: Deferred fixes are present in the fix pack.

Problem determination: Deferred fixes will be activated after the next IPL of the system. An immediate IPL is not required, unless you want to activate one of the fixes now.

HSCF0055 HSCF0055

Explanation: Click to start the disruptive operation, otherwise click cancel.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0056 HSCF0056

Explanation: The level of Firmware being installed has not been tested with the active management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0057 HSCF0057

Explanation: Accept was not done for some components because the permanent flash side is active.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0058 HSCF0058

Explanation: The operation failed due to an internal code failure.

Problem determination: This error was reported to your service provider. Contact your next level of support for further assistance.

HSCF0059 HSCF0059

Explanation: Reject was not done for some components because the temporary flash side is active.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0060 • HSCF0078

HSCF0060 HSCF0060

Explanation: Synchronization of Redundant Service Processors completed successfully.

Problem determination: no action required

HSCF0061 HSCF0061

Explanation: Redundant Service Processor synchronization failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0063 HSCF0063

Explanation: The permanent flash side is active on some components.

Problem determination: The accept operation cannot be performed on these components. The accept operation will be performed only for components on which the temporary flash side is active. You can continue or quit.

HSCF0064 HSCF0064

Explanation: Waiting for Flexible Service Processor lock.

Problem determination: No action required

HSCF0065 HSCF0065

Explanation: Activating updates - Restarting Bulk Power Controller.

Problem determination: No action required

HSCF0066 HSCF0066

Explanation: Accepting updates.

Problem determination: No action required

HSCF0067 HSCF0067

Explanation: Writing to file.

Problem determination: No action required

HSCF0068 HSCF0068

Explanation: Surveillance command failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0069 HSCF0069

Explanation: No connection exists.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0072 HSCF0072

Explanation: The requested Licensed Internal Code operation cannot be started due to errors.

Problem determination: Correct the errors and retry the operation. If the error persists, contact your next level of support.

HSCF0073 HSCF0073

Explanation: The requested Licensed Internal Code operation cannot be started due errors.

Problem determination: Correct the errors and retry the operation. If the error persists, contact your next level of support.

HSCF0074 HSCF0074

Explanation: Licensed Internal Code update has detected errors.

Problem determination: An override is enabled which will allow the update to be attempted without correcting these errors. Contact your next level of support to disable the override.

HSCF0075 HSCF0075

Explanation: Primary Flexible Service Processor.

Problem determination: No action required

HSCF0076 HSCF0076

Explanation: Secondary Flexible Service Processor.

Problem determination: No action required

HSCF0077 HSCF0077

Explanation: Side A Bulk Power Controller.

Problem determination: No action required

HSCF0078 HSCF0078

Explanation: Side B Bulk Power Controller.

Problem determination: No action required

HSCF0082 HSCF0082

Explanation: Unable to determine managed frame ownership information.

Problem determination: Ensure that communication is possible to all managed frames and that all managed frames are in Standby/Standby state.

HSCF0084 HSCF0084

Explanation: Fault indicator is true.

Problem determination: No action required

HSCF0085 HSCF0085

Explanation: All Good indicator is false.

Problem determination: No action required

HSCF0086 HSCF0086

Explanation: Mailbox Present indicator is false.

Problem determination: No action required

HSCF0087 HSCF0087

Explanation: BPF Good indicator is false.

Problem determination: No action required

HSCF0088 HSCF0088

Explanation: Secondary Flexible Service Processor is not functional.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0089 HSCF0089

Explanation: Secondary service processor is unusable due to an error or because it has been manually deconfigured by a user.

Problem determination: If the secondary service processor cannot be manually reconfigured, or if this condition persists for longer than one hour, contact your hardware service representative.

HSCF0090 HSCF0090

Explanation: Managed frame state is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0091 HSCF0091

Explanation: Error checking Bulk Power Controller status.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0092 HSCF0092

Explanation: Unable to determine power subsystem readiness.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0093 HSCF0093

Explanation: Unable to determine managed system readiness.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0094 HSCF0094

Explanation: Completed All Updates.

Problem determination: No action required

HSCF0095 HSCF0095

Explanation: Some of the targets have one or more components that will be downleveled during the Licensed Internal Code update.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0096 HSCF0096

Explanation: The selected installation type indicates to install concurrently with deferred disruptive activate, but one or more selected targets do not permit that operation.

Problem determination: Either select a different installation type, or start the task again without selecting the target(s) that do not permit operation.

HSCF0097 HSCF0097

Explanation: The remote support system cannot be contacted because Outbound Connectivity is not enabled or not configured.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0098 • HSCF0117

HSCF0098 HSCF0098

Explanation: Writing update files.

Problem determination: No action required

HSCF0099 HSCF0099

Explanation: Finished writing update files.

Problem determination: No action required

HSCF0100 HSCF0100

Explanation: No update needed.

Problem determination: No action required

HSCF0101 HSCF0101

Explanation: No update needed.

Problem determination: No action required

HSCF0102 HSCF0102

Explanation: Completed Retrieve.

Problem determination: No action required

HSCF0103 HSCF0103

Explanation: Flexible Service Processor Restart completed successfully.

Problem determination: No action required

HSCF0104 HSCF0104

Explanation: Power code download started.

Problem determination: No action required

HSCF0105 HSCF0105

Explanation: Power code download completed.

Problem determination: No action required

HSCF0106 HSCF0106

Explanation: Deferred fix information is not available.

Problem determination: No action required

HSCF0107 HSCF0107

Explanation: All non-disruptive Licensed Internal Code update processing has completed.

Problem determination: The managed system will be powered off during the next phase. Quiesce any applications currently running on your operating systems.

HSCF0108 HSCF0108

Explanation: Waiting for confirmation.

Problem determination: No action required

HSCF0109 HSCF0109

Explanation: Licensed Internal Code operation canceled by user.

Problem determination: No action required

HSCF0111 HSCF0111

Explanation: Licensed Internal Code Readiness Check detected errors.

Problem determination: These errors must be corrected before updating Licensed Internal Code.

HSCF0112 HSCF0112

Explanation: Licensed Internal Code Readiness Check detected errors.

Problem determination: These errors must be corrected before updating Licensed Internal Code.

HSCF0113 HSCF0113

Explanation: Licensed Internal Code Readiness check found no errors.

Problem determination: No action required

HSCF0114 HSCF0114

Explanation: Activating updates.

Problem determination: No action required

HSCF0115 HSCF0115

Explanation: Bulk Power Controller Restart completed successfully.

Problem determination: No action required

HSCF0116 HSCF0116

Explanation: Updating accepted level.

Problem determination: No action required

HSCF0117 HSCF0117

Explanation: Preparing for install.

Problem determination: No action required

HSCF0118 HSCF0118

Explanation: Licensed Internal Code Update successful - Deferred Fixes are present in the fixpack.

Problem determination: No action required

HSCF0121 HSCF0121

Explanation: Attention: This action is disruptive.

Problem determination: However for the selected targets the firmware can be downgraded to the selected levels concurrently by performing the Remove and Activate Function.

HSCF0122 HSCF0122

Explanation: Licensed Internal Code update control is not set to management console.

Problem determination: No action required

HSCF0123 HSCF0123

Explanation: An exception occurred while querying to see if Licensed Internal Code update control is set to management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0124 HSCF0124

Explanation: An exception occurred while querying to see if concurrent updating is allowed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0125 HSCF0125

Explanation: Processing I/O updates.

Problem determination: No action required

HSCF0126 HSCF0126

Explanation: A Licensed Internal Code update operation is currently running.

Problem determination: No action required

HSCF0127 HSCF0127

Explanation: A managed system has not reached a stable state.

Problem determination: No action required

HSCF0128 HSCF0128

Explanation: A managed system is not ready to start Licensed Internal Code Update.

Problem determination: No action required

HSCF0129 HSCF0129

Explanation: The requested operation cannot be performed because a Licensed Internal Code update operation is currently running on one or more components.

Problem determination: No action required

HSCF0130 HSCF0130

Explanation: Secondary service processor has been manually deconfigured by a user.

Problem determination: No action required

HSCF0131 HSCF0131

Explanation: Failover in progress.

Problem determination: No action required

HSCF0132 HSCF0132

Explanation: Configuration mismatch detected.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0133 HSCF0133

Explanation: IPL or Power Off in progress.

Problem determination: No action required

HSCF0134 HSCF0134

Explanation: Code update in progress.

Problem determination: No action required

HSCF0135 HSCF0135

Explanation: System dump in progress.

Problem determination: No action required

HSCF0136 HSCF0136

Explanation: Generic failure on Flexible Service Processor.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0137 • HSCF0152

HSCF0137 HSCF0137

Explanation: Secondary service processor is in a state which does not support the operation.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCF0138 HSCF0138

Explanation: Internal communication path between primary and secondary service processors cannot be established.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCF0139 HSCF0139

Explanation: A concurrent maintenance operation is in progress.

Problem determination: No action required

HSCF0140 HSCF0140

Explanation: Secondary service processor detected system configuration mismatch.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0141 HSCF0141

Explanation: Unexpected error code.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0142 HSCF0142

Explanation: The Licensed Internal Code version is not compatible with the management console version.

Problem determination: The management console must be updated before Licensed Internal Code can be updated.

HSCF0143 HSCF0143

Explanation: Secondary service processor has been automatically deconfigured by the system due to an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0144 HSCF0144

Explanation: Activation completed.

Problem determination: No action required

HSCF0145 HSCF0145

Explanation: An error has occurred while displaying the license agreement.

Problem determination: The task will be terminated.

HSCF0146 HSCF0146

Explanation: Retrieving Licensed Internal Code files.

Problem determination: No action required

HSCF0147 HSCF0147

Explanation: Copying Licensed Internal Code to inactive side.

Problem determination: No action required

HSCF0148 HSCF0148

Explanation: Copy completed.

Problem determination: No action required

HSCF0149 HSCF0149

Explanation: Service Processor failover started.

Problem determination: No action required

HSCF0150 HSCF0150

Explanation: Service Processor failover completed.

Problem determination: No action required

HSCF0151 HSCF0151

Explanation: Service Processor failover failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0152 HSCF0152

Explanation: Service processor is in half-genesis condition. Licensed Internal Code update will cause loss of service processor redundancy.

Problem determination: The system must be powered off and a service processor failover must be initiated before updating Licensed Internal Code.

HSCF0153 HSCF0153

Explanation: The temporary flash side is active on some components.

Problem determination: The reject operation cannot be performed on these components. The reject operation will be performed only for components on which the permanent flash side is active.

HSCF0154 HSCF0154

Explanation: Cannot be updated.

Problem determination: Permanent flash side is active.

HSCF0155 HSCF0155

Explanation: Cannot be updated.

Problem determination: Temporary flash side is active.

HSCF0156 HSCF0156

Explanation: Service processor failover is required during the update process when redundancy is enabled, but cannot be performed due to error condition(s).

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0157 HSCF0157

Explanation: Service processor failover was initiated during the update process but did not complete successfully.

Problem determination: Error code has been reported to your service provider. Contact your next level of support for further assistance.

HSCF0158 HSCF0158

Explanation: The synchronize function was invoked to copy from the secondary service processor to the primary service processor with redundancy enabled.

Problem determination: This is not allowed.

HSCF0159 HSCF0159

Explanation: An error occurred while trying to manage the lock.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0160 HSCF0160

Explanation: The requested operation cannot be performed because another management or service task is already running.

Problem determination: The conflicting task was initiated from management console.

HSCF0161 HSCF0161

Explanation: The requested Licensed Internal Code is not compatible with the current management console level.

Problem determination: Update the management console and retry the operation. If the error persists, contact your next level of support.

HSCF0162 HSCF0162

Explanation: Licensed Internal Code level not compatible with management console level.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0163 HSCF0163

Explanation: Managed System Licensed Internal Code is not compatible with Power Subsystem Licensed Internal Code.

Problem determination: Select compatible Licensed Internal Code levels and retry the operation. If the error persists, contact your next level of support.

HSCF0164 HSCF0164

Explanation: New Managed System level is not compatible with new Power Subsystem level.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0165 HSCF0165

Explanation: New Managed System level is not compatible with current Power Subsystem level.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0166 HSCF0166

Explanation: Current Managed System level is not compatible with new Power Subsystem level.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0167 HSCF0167

Explanation: Power code download status information cannot be determined.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0168 HSCF0168

Explanation: The managed system is not ready to perform Licensed Internal Code update.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0169 HSCF0169

Explanation: Redundancy is enabled but a secondary service processor is not present.

Problem determination: This configuration is not supported.

HSCF0170 HSCF0170

Explanation: Service processor failover has been temporarily disabled by the service processor.

Problem determination: The service processor will automatically enable failover again when it is ready.

HSCF0171 HSCF0171

Explanation: The internal communication path between the secondary service processor and the POWER hypervisor cannot be established.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0172 HSCF0172

Explanation: The selected operation can disrupt the power supply to all managed systems in the managed frame. Any managed system which is not powered off will be powered off during the update.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0173 HSCF0173

Explanation: The selected operation can disrupt the power supply to all managed systems in the managed frame. Any managed system which is not powered off will be powered off during the update.

Problem determination: The --allowpoweroff option must be specified to allow the update to continue.

HSCF0174 HSCF0174

Explanation: All managed systems in the managed frame must be managed by the management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0175 HSCF0175

Explanation: Previous power code download did not complete successfully.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0176 HSCF0176

Explanation: Power code download status information cannot be determined.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0177 HSCF0177

Explanation: Operation completed successfully.

Problem determination: No action required

HSCF0178 HSCF0178

Explanation: Operation completed successfully. Deferred Fixes are present in the fixpack.

Problem determination: No action required

HSCF0179 HSCF0179

Explanation: Operation was partially successful.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0180 HSCF0180

Explanation: Operation failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0181 HSCF0181

Explanation: Waiting for operation to complete on another target.

Problem determination: No action required

HSCF0182 HSCF0182

Explanation: Shared frame will be updated by another target.

Problem determination: No action required

HSCF0183 HSCF0183

Explanation: An error occurred while trying to query frame cage data for Managed Frame.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0184 HSCF0184

Explanation: The compatibility of Managed System and Power Subsystem Licensed Internal Code cannot be determined for Managed Frame because the some Managed Systems are not managed by the management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0185 HSCF0185

Explanation: after reboot was performed

Problem determination: No action required

HSCF0186 HSCF0186

Explanation: after service processor failover was performed

Problem determination: No action required

HSCF0187 HSCF0187

Explanation: after disruptive power code download was performed

Problem determination: No action required

HSCF0188 HSCF0188

Explanation: due to an unexpected error

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0189 HSCF0189

Explanation: The management console could not establish a connection.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0191 HSCF0191

Explanation: An error occurred while trying to determine the status.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0192 HSCF0192

Explanation: Managed system state is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0193 HSCF0193

Explanation: Managed frame state is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0194 HSCF0194

Explanation: The same media device was selected as the source and destination of the retrieve operation.

Problem determination: Select a different device and try the operation again.

HSCF0195 HSCF0195

Explanation: No media was found in the device.

Problem determination: Please make sure that the media has been inserted in the device and try the operation again.

HSCF0196 HSCF0196

Explanation: The requested media device could not be found.

Problem determination: Please make sure that the device has been inserted correctly and try the operation again.

HSCF0197 HSCF0197

Explanation: The requested media device is already locked by another process.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0198 HSCF0198

Explanation: An error occurred while trying to use the requested media device.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0199 HSCF0199

Explanation: An error occurred while trying to copy a file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0200 HSCF0200

Explanation: An error occurred. The file does not exist.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0201 HSCF0201

Explanation: The retrieve of internal code changes from the remote support system has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0202 HSCF0202

Explanation: No internal code changes were found at this source.

Problem determination: You may be at the latest change level.

HSCF0203 HSCF0203

Explanation: The remote support system cannot be contacted because Outbound Connectivity is not supported.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0204 HSCF0204

Explanation: The selected LIC level will be used to update the components.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0205 HSCF0205

Explanation: The managed frame does not contain any managed systems.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0206 HSCF0206

Explanation: The following target(s) failed to set the next IPL side.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0207 HSCF0207

Explanation: Partition firmware activation started but was not complete on the following partitions:

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0208 HSCF0208

Explanation: Partition firmware activation was not started on the following partitions:

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0209 HSCF0209

Explanation: Partition firmware activation failed on the following partitions:

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0210 HSCF0210

Explanation: The activate-firmware request failed:

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0211 HSCF0211

Explanation: The partition is not DLPAR capable or no RMC connection exists.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0212 HSCF0212

Explanation: An error occurred when trying to invoke the activate-firmware request.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0213 HSCF0213

Explanation: Partition Firmware activation can be completed by stopping and restarting any partition which has failed or has not completed. PHYP and Partition Firmware activation for all partitions can be executed again by issuing the command: updlic -o v -m managed-system

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0214 HSCF0214

Explanation: Activating updates - PFW. partitions completed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0215 HSCF0215

Explanation: A timeout occurred during Partition Firmware activation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0216 HSCF0216

Explanation: The compatibility of Managed System and Power Subsystem Licensed Internal Code cannot be determined.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0217 HSCF0217

Explanation: All managed frames must be managed by the management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCF0218 HSCF0218

Explanation: A connection was found to a redundant FSP, but no state information could be determined.

Problem determination: Please verify the redundant FSP is configured and enabled.

HSCF0219 HSCF0219

Explanation: The selected target system is not compatible with the selected firmware release.

HSCF0220 HSCF0220

Explanation: Could not process the target level restriction file.

HSCF0221 HSCF0221

Explanation: Could not free the locks on the systems.

Problem determination: To attempt to manually free the locks on an FSP, issue the following command from the management console: rmsysconn -o remove --ip (IP address of the target FSP) This will remove the connection from this management console. To attempt to manually free the locks on a BPC, issue the following command from the management console: rmlock -e (MTMS)

HSCF0222 HSCF0222

Explanation: Managed systems are not found or not managed by the management console.

HSCF0071E HSCF0071E

Explanation: Communication error to Side A|B BPC on tttt-mmm*sssssss: No connection exists.

Problem determination: There is no connection data found for the Bulk Power Controller.

HSCF0079E HSCF0079E

Explanation: Managed system state state on ttt-mmmm sssssss is incorrect. Valid states are: Operating, Power Off, Error Terminated, Standby.

Problem determination: Correct the managed system operating state. Retry the Licensed Internal Code update. If the problem persists, contact your next level of support.

HSCF0080E HSCF0080E

Explanation: Side A|B BPC on tttt-mmm*sssssss has failed a redundancy test.

Problem determination: Correct any open issues in the Service Focal Point. Retry the Licensed Internal

HSCF0081E • HSCF0083E

Code update. If the problem persists, contact your next level of support.

HSCF0081E HSCF0081E

Explanation: ACDL is pending for Side A | B BPC on tttt-mmm*sssssss.

Problem determination: Correct any open issues in the Service Focal Point. Retry the Licensed Internal Code update. If the problem persists, contact your next level of support.

HSCF0083E HSCF0083E

Explanation: Side A | B BPC on tttt-mmm*sssssss has reported an error condition: reason.

Problem determination: Reason could be one of the following: Fault indicator is true All Good indicator is false Mailbox Present indicator is false BPF Good indicator is false Correct any open issues in the Service Focal Point. Retry the Licensed Internal Code update. If the problem persists, contact your next level of support.

(HSCI) Reference codes

HSCI0100 HSCI0100

Explanation: No managed systems were detected that are attached to this system console.

HSCI0101 HSCI0101

Explanation: No logical partitions have been defined for this managed system.

HSCI0102 HSCI0102

Explanation: A blank or invalid entry was entered in the partition password field.

Problem determination: Enter a valid password value.

HSCI0103 HSCI0103

Explanation: A blank or invalid entry was entered in the listening port field.

Problem determination: Enter a valid port value.

HSCI0104 HSCI0104

Explanation: A blank or invalid entry was entered in the IP address field.

Problem determination: Enter a valid IP address value.

HSCI0110 HSCI0110

Explanation: The Inventory Scout Services command completed successfully.

HSCI0111 HSCI0111

Explanation: The Inventory Scout Services command request failed

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0112 HSCI0112

Explanation: The removable media cannot be mounted. Ensure the media is inserted correctly in the drive and retry the operation.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the

operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0113 HSCI0113

Explanation: The media specified is write protected. Adjust the media and retry.

Problem determination: Remove write protection and try the operation again.

HSCI0114 HSCI0114

Explanation: The Inventory Scout Services request failed. Ensure the removable media is correctly inserted in the drive.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0115 HSCI0115

Explanation: An error occurred while copying the Inventory Scout Services data. Verify that a blank formatted diskette is inserted correctly in the drive and retry the operation.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0116 HSCI0116

Explanation: An error occurred while compressing the Inventory Scout Services data. Retry the operation.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0117 HSCI0117

Explanation: An error occurred while trying to unmount the media.

Problem determination: Verify that the removable

HSCI0118 • HSCI0122

media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0118 HSCI0118

Explanation: The Inventory Scout Services daemon was restarted successfully.

HSCI0119 HSCI0119

Explanation: The Inventory Scout Services daemon could not be restarted.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0120 HSCI0120

Explanation: The managed system name is malformed.

HSCI0121 HSCI0121

Explanation: The Inventory Scout Services request failed. An error occurred while copying data to removable media.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. Contact your next level of support or your service provider.

HSCI0122 HSCI0122

Explanation: The system partitions did not respond to query attempts.

Problem determination: Check that the management console host name and the host name of the partition are fully qualified domain names (not a short host name). If they are not, this must be corrected for remote security to work. Verify that the network routing is set up so the management console can use ping to reach the partition and vice versa. If one or both cannot be reached from the other, correct the routing. Ensure that /var is not full on the partition, which would prevent certain processes from running correctly. Verify that the following file sets have been installed correctly on the AIX logical partitions: rsct.core csm.client devices.chrp.base.ServiceRM Log in to one of the logical partitions and issue the following command: lssrc -s ctcas If the output shows ctcsd is inoperative, issue the command: ls -l on the

/var/ct/cfg/ directory. If the files ct_has.pkf and ct_has.qkf are zero-length, there was an (AIX) installation configuration problem. These zero-length files should be removed. Issue the command startsrc -s ctcas If the startsrc -s ctcas command does not work, the AIX lpp might not have been installed. If the output is still blank, shut down and restart the management console. After the shutdown and restart occurs, wait at least 10 minutes before trying again to ensure all the logical partitions have resynchronized their information with the management console. If the problem persists, contact your next level of support or your service provider.

(HSCL0xxx) Reference codes

HSCL0001 HSCL0001

Explanation: There is no more space for a new profile name.

Problem determination: Reuse profile names being used by other profiles or remove the profiles that are no longer needed.

HSCL0002 HSCL0002

Explanation: Too many I/O units are being used in profiles.

Problem determination: Remove the I/O units that no longer exist or are not needed.

HSCL0003 HSCL0003

Explanation: The profile data save area is full. Remove any profiles that are no longer needed.

Problem determination: Remove the profiles that are no longer needed.

HSCL0004 HSCL0004

Explanation: A profile with the specified name already exists in the partition in the profile data of the managed system. Provide another name for this profile.

Problem determination: Rename the profile to a name that is not already in use in this partition.

HSCL0005 HSCL0005

Explanation: Cannot find information regarding profile data of the managed system. Run a rebuild managed system operation.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0006 HSCL0006

Explanation: The managed system's profile data has been corrupted. You must either restore or reinitialize the profile data.

Problem determination: Restore the profile data. If the problem persists, contact your next level of support or your service provider.

HSCL0007 HSCL0007

Explanation: The profile data of the managed system

cannot be accessed or modified. Run a rebuild managed system operation.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0008 HSCL0008

Explanation: Could not construct or initialize profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0009 HSCL0009

Explanation: Could not construct or initialize the profile data from the backup file. Repeat the operation.

Problem determination: Repeat the operation. If the problem persists, see Recovering partition data on a managed system. If the problem persists, contact your next level of support or your service provider.

HSCL000A HSCL000A

Explanation: Could not build the profile for the managed system. Repeat the operation.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL000B HSCL000B

Explanation: Could not get the activated partition profile from the profile data. Perform a rebuild managed system operation.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL000C HSCL000C

Explanation: Could not get the activated system profile from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL000D HSCL000D

Explanation: Could not get all the system profiles

HSCL000E • HSCL001A

from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL000E HSCL000E

Explanation: Could not get the default system profile from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL000F HSCL000F

Explanation: Could not get the default system profile from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0010 HSCL0010

Explanation: Could not get the partition profile from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0011 HSCL0011

Explanation: Could not get the partition profiles for the partition from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0012 HSCL0012

Explanation: Could not get the system profile from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0013 HSCL0013

Explanation: Could not remove the partition profile from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0014 HSCL0014

Explanation: Could not remove the system profile from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0015 HSCL0015

Explanation: Could not save the partition profile to the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0016 HSCL0016

Explanation: Could not save the system profile to the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0017 HSCL0017

Explanation: Could not create the partition profile in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0018 HSCL0018

Explanation: Could not create the system profile in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0019 HSCL0019

Explanation: Could not set the activated partition profile in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL001A HSCL001A

Explanation: Could not set the activated system profile in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL001B HSCL001B

Explanation: Could not set the default partition profile in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL001C HSCL001C

Explanation: Could not set the default system profile in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL001D HSCL001D

Explanation: Could not clean up the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL001E HSCL001E

Explanation: Could not update the profile data cache. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL001F HSCL001F

Explanation: Could not check for duplicate partition name. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0020 HSCL0020

Explanation: Could not remove the partition profile from the system profile content in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0021 HSCL0021

Explanation: Could not add the partition profile to the system profile in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0022 HSCL0022

Explanation: Could not get the partition name from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0023 HSCL0023

Explanation: Could not get all the partition names from the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0024 HSCL0024

Explanation: Could not set the partition name in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0025 HSCL0025

Explanation: Could not build the profile data from the local file. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0026 HSCL0026

Explanation: Could not write the data to the managed system. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0027 HSCL0027

Explanation: Could not back up the profile data to a file. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0028 HSCL0028

Explanation: Could not read profile data from the managed system. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0029 HSCL0029

Explanation: Could not delete profiles at the partition with ID in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL002A HSCL002A

Explanation: Could not modify the system profiles containing the partition slot ID in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL002B HSCL002B

Explanation: Could not perform a priority restore on the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL002C HSCL002C

Explanation: Could not merge the profile information in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL002D HSCL002D

Explanation: Could not merge partition name data in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL002E HSCL002E

Explanation: Could not merge default and activated list data in the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL002F HSCL002F

Explanation: Could not merge I/O unit and profile information data in the profile data.

Problem determination: Execute a rebuild managed system operation.

HSCL0030 HSCL0030

Explanation: Could not initialize the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0031 HSCL0031

Explanation: The profile data has been cleared. Either restore or reinitialize the profile data save area.

Problem determination: Restore the profile data. For details, see Recovering partition data on a managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0032 HSCL0032

Explanation: Could not set the system profile's user-defined name to the profile data. Rebuild the managed system.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. If the problem persists, contact your next level of support or your service provider.

HSCL0034 HSCL0034

Explanation: The levels of managed system and profile data area are not matching. Upgrade the managed system version to the correct level.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. If the same error occurs, update the managed system to a correct version. If you are not sure what version to use, contact your next level of support or your service provider.

HSCL0035 HSCL0035

Explanation: Cannot restore profile data with two different versions of profile save data.

Problem determination: Perform the operation again. If the same error occurs, restore using another profile data file. For details, see Recovering partition data on a managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0036 HSCL0036

Explanation: Migrate profile data failed.

Problem determination: Perform the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0038 HSCL0038

Explanation: Creation of logical partition profiles failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0039 HSCL0039

Explanation: Deletion of logical partitions failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL003A HSCL003A

Explanation: Removal of system profiles failed at profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL003B HSCL003B

Explanation: Setting of partition information failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL003C HSCL003C

Explanation: Retrieval of all logical partition information failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL003D HSCL003D

Explanation: Retrieval of partition information failed in the profile data save area.

Problem determination: Rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0040 HSCL0040

Explanation: No more space for physical location code in the profile data save area.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0041 HSCL0041

Explanation: Migration of partition information failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. If the problem persists, contact your next level of support or your service provider.

HSCL0042 HSCL0042

Explanation: Migration of profile names failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. If the problem persists, contact your next level of support or your service provider.

HSCL0043 HSCL0043

Explanation: Migration of default profile list failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. If the problem persists, contact your next level of support or your service provider.

HSCL0044 HSCL0044

Explanation: Migration of activated profile list failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. If the problem persists, contact your next level of support or your service provider.

HSCL0045 HSCL0045

Explanation: Migration of physical location code information failed in profile data save area.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0046 HSCL0046

Explanation: Migration of I/O unit and profile information failed in the profile data save area.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. If the problem persists, contact your next level of support or your service provider.

HSCL0047 HSCL0047

Explanation: Migration of time stamps of profile data save area failed.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. If the problem persists, contact your next level of support or your service provider.

HSCL0048 HSCL0048

Explanation: Migration of checksums of the profile data save area failed.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information for details. If the problem persists, contact your next level of support or your service provider.

HSCL0049 HSCL0049

Explanation: Unable to get next available profile ID from the management console profile data.

HSCL004A HSCL004A

Explanation: Management console Save Area Set Fast Activation failed.

HSCL004B HSCL004B

Explanation: Management Console Save Area Get Fast Activation failed.

HSCL004C HSCL004C

Explanation: Unable to open the Management console Save Area file.

HSCL004D HSCL004D

Explanation: The management console could not retrieve information from the managed system.

HSCL004E HSCL004E

Explanation: Unable to set partition information in the profile data. Execute a rebuild managed system operation.

HSCL004F HSCL004F

Explanation: Management console Save Area Get System Credential Information failed.

HSCL0050 HSCL0050

Explanation: Management console Save Area Set System Credential Information failed.

HSCL0051 HSCL0051

Explanation: Cannot retrieve virtual Ethernet MAC address prefix.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0052 HSCL0052

Explanation: Cannot set virtual Ethernet MAC address prefix.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0053 HSCL0053

Explanation: Attempt to update profile information failed due to invalid resource lock type.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0054 HSCL0054

Explanation: Cannot set SharedDedicated processing mode in Save Area.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0055 HSCL0055

Explanation: Cannot set Electronic Error Reporting in Save Area.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0056 HSCL0056

Explanation: Given Electronic Error Reporting value is invalid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL01F5 HSCL01F5

Explanation: Unable to lock the Service Processor.

Problem determination: Perform one of the following steps: (1) Check serial cable connection; (2) Check if another Console is communicating with the Service Processor; (3) Perform the Release Lock task; (4) Perform Rebuild task to re-establish the connection.

HSCL01F7 HSCL01F7

Explanation: Unable to get the current time from the managed system.

Problem determination: Rebuild the managed system. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL01F8 HSCL01F8

Explanation: This property cannot be altered.

HSCL01FA HSCL01FA

Explanation: The managed system is already powered off.

Problem determination: The managed system was already powered off before your attempt to power it off. No action is required.

HSCL01FB HSCL01FB

Explanation: The number of parameters is incorrect. Specify a different value.

HSCL01FC HSCL01FC

Explanation: The parameter specified is not valid. Specify a different value.

HSCL01FD HSCL01FD

Explanation: Power on failed. Try again.

Problem determination: Retry starting the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL01FE HSCL01FE

Explanation: The managed system is already powered on.

HSCL01FF HSCL01FF

Explanation: Could not rebuild. Shut down and restart the management console.

Problem determination: Retry the task. If it fails again, shut down and restart the management console. Check the state of the managed system. Refer to

Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL0200 HSCL0200

Explanation: Unable to communicate with Service Processor.

Problem determination: Check Serial Cable connection.

HSCL0201 HSCL0201

Explanation: Service processor command failed: Invalid response.

Problem determination: Wait several minutes and try the task again.

HSCL0202 HSCL0202

Explanation: Service Processor Socket is corrupted.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0203 HSCL0203

Explanation: Command sent to service processor failed.

Problem determination: Try the task again. Check the state of the managed system. Refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. If the problem persists, contact your next level of support or your service provider.

HSCL0204 HSCL0204

Explanation: Command failed. Unknown error.

Problem determination: Shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL0205 HSCL0205

Explanation: The managed system is in the error state and is unable to continue with the task.

Problem determination: The recovery partition data task cannot be run until the managed system is no longer in error state. Record the error message. Check the state of the managed system. Refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state.

HSCL0206 HSCL0206

Explanation: Unable to power on the managed system. Unable to continue with the power on task.

Problem determination: Check the Operator panel value column for the managed system to verify that it is in the No power state and that the managed system is not in the Error state. If the managed system is in the error state, refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. Verify that no other task is being performed, and then retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0207 HSCL0207

Explanation: Failed to Power Off the Managed System. Unable to continue with the Recover Partition Data Task.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0208 HSCL0208

Explanation: Unable to power on the managed system. Unable to continue with the power on task.

Problem determination: Check the Operator panel value column for the managed system to verify that it is in the No power state and that the managed system is not in the Error state. If the managed system is in the error state, refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. Verify that no other task is being performed, and then retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0209 HSCL0209

Explanation: Remote virtual terminal sessions are not allowed. Check the remote virtual terminal settings.

Problem determination: Virtual terminal cannot open remotely at this time. If this feature is needed, use the Enable/Disable Remote Virtual Terminal task in the System Configuration menu to enable remote connections.

HSCL020A HSCL020A

Explanation: The power on system profile operation timed out. Activate the system profile manually after the managed system is powered on.

Problem determination: Activate the system profile manually after the managed system is powered on.

HSCL020D HSCL020D

Explanation: The command you issued contained incorrect data.

Problem determination: Contact your next level of support or your service provider.

HSCL0212 HSCL0212

Explanation: The managed system is not capable of Capacity on Demand (CoD) at the present time.

Problem determination: Ensure that the managed system is powered on. If it is powered on, check the managed system's properties window to verify that the system is not CoD capable. Contact your local representative for more information about this feature.

HSCL0213 HSCL0213

Explanation: The managed system does not support Capacity on Demand upgrades for processors.

Problem determination: Contact your local representative for more information about this feature.

HSCL0214 HSCL0214

Explanation: The managed system does not support Capacity on Demand upgrades for memory.

Problem determination: Contact your local representative for more information about this feature.

HSCL0215 HSCL0215

Explanation: There was an error trying to save processor order information to a diskette.

Problem determination: Verify that the diskette is writable, and retry the operation again. If the error persists, contact your next level of support or your service provider.

HSCL0219 HSCL0219

Explanation: The Properties File, HscPciClassCodeInfo, is not available.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL021A HSCL021A

Explanation: IOError : Failure during the Properties Initialization of the class code.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL021B HSCL021B

Explanation: Error in initialization of the class code property file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL021C HSCL021C

Explanation: Inconsistent partition type found during rebuild.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL021E HSCL021E

Explanation: No profile found for partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0222 HSCL0222

Explanation: The operation cannot be performed because the managed system is not logical partition capable.

Problem determination: If you believe that the managed system should be capable of logical partitioning, restart the management console and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0223 HSCL0223

Explanation: Firmware is not ready to accept the specified command. Try again later.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0224 HSCL0224

Explanation: There was an error dumping the partition configuration. Check the console event log.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0225 HSCL0225

Explanation: There was an error clearing the partition configuration. Check the console event log.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0226 HSCL0226

Explanation: The firmware power off policy returned from the service processor is not valid. Unable to determine whether the firmware should power off or stay running after last partition powers off.

Problem determination: Check that the inputs are correct. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0227 HSCL0227

Explanation: This operation is only allowed when the managed system is in the Standby state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0228 HSCL0228

Explanation: The managed system could not be found in the database. Rebuild the managed system, and try again.

Problem determination: Shut down and restart the management console. Rebuild the managed system. For details, see Updating managed system or frame information. If the problem persists, contact your next level of support or your service provider.

HSCL0229 HSCL0229

Explanation: Memory specified is not a multiple of the system memory region size. Modify the value to be a multiple of the memory region size and try again.

Problem determination: Modify the value of the memory specified to be a multiple of the memory region size and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL022A HSCL022A

Explanation: i5/OS partitions are not supported on the managed system.

Problem determination: The managed system is not capable of creating or managing i5/OS partitions. If you believe that the managed system should be i5/OS capable, restart the management console and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL022B HSCL022B

Explanation: Get the managed system state has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL022C HSCL022C

Explanation: The managed system is not in a valid state to perform the operation. Check the state of the managed system and retry the operation.

Problem determination: Try the task again. Refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. If the problem persists, contact your next level of support or your service provider.

HSCL022D HSCL022D

Explanation: Unable to perform a get or a set operation on the managed system's platform IPL parameters.

Problem determination: Try the task again. Perform the appropriate actions to put the managed system in the correct state. For details, see Correcting the managed system operating state. If the problem persists, contact your next level of support or your service provider.

HSCL022E HSCL022E

Explanation: Unable to restore the profile data when the managed system is not in the Operating or Standby state.

Problem determination: Verify that the managed system is in the Operating or Standby state, and retry the operation. If the managed system is not in the correct state, refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. If the problem persists, contact your next level of support or your service provider.

HSCL022F HSCL022F

Explanation: Unable to delete the profile data backup file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL022R HSCL022R

Explanation: Unable to delete the profile data backup file.

Problem determination: Try the task again. Rebuild the managed system and try the task again. For details, see Updating managed system or frame information. If the problem persists, contact your next level of support or your service provider.

HSCL0230 HSCL0230

Explanation: Unable to get managed system credential information.

Problem determination: Rebuild the managed system. Then try the task again. Restart the management console and then retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0231 HSCL0231

Explanation: Unable to set managed system credential information.

Problem determination: Rebuild the managed system. Then try the task again. Restart the management console and then retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0232 HSCL0232

Explanation: Rebuild managed system operation failed.

Problem determination: Try the operation again.

HSCL0233 HSCL0233

Explanation: Unable to change the service partition to the partition specified. Check your current setting(s) and ensure this change is allowed.

Problem determination: The service partition cannot be changed. Check current settings and verify that this change is allowed. Rebuild the managed system and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0234 HSCL0234

Explanation: Failed to transition out of standby state. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. Then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL0235 HSCL0235

Explanation: Cannot change service partition from one partition to another if either one of them is not in the Not Activated state.

Problem determination: Ensure that the current service partition is not activated. Ensure that the partition user who tried to assign the server authority is not activated. Rebuild the managed system. Then try the task again. If the problem persists, contact your

next level of support or your service provider.

HSCL0236 HSCL0236

Explanation: The name specified contains unprintable or invalid characters. Remove the invalid characters and try again.

Problem determination: Ensure that all the characters specified in the name are valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0237 HSCL0237

Explanation: This operation is not allowed when the managed system is in the current state.

Problem determination: After you have established a connection from the management console to the managed system and have entered a valid management console access password, try the operation again.

HSCL0238 HSCL0238

Explanation: This operation is only allowed when the managed system is in the Operating state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0239 HSCL0239

Explanation: This operation is not allowed when the managed system is in the current state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL023A HSCL023A

Explanation: This operation is allowed only when the managed system is powered off.

Problem determination: No recovery action.

HSCL023B HSCL023B

Explanation: This operation is allowed only after the managed system has been powered on at least once, and then powered off.

Problem determination: No recovery action.

HSCL0240 HSCL0240

Explanation: The password is locked and cannot be changed while it is locked.

Problem determination: The password has been locked. Contact your next level of support or your hardware service provider to unlock the password.

HSCL0241 HSCL0241

Explanation: The password is locked.

Problem determination: The password has been locked. Contact your next level of support or your hardware service provider to unlock the password.

HSCL0242 HSCL0242

Explanation: Failed to set i5/OS partition as the service partition for this managed system. Only an AIX or Linux logical partition can be designated as the service partition on IBM System p5 or IBM eServer p5 servers.

Problem determination: Choose an AIX or Linux logical partition as the service partition for your managed system.

HSCL0243 HSCL0243

Explanation: The Machine Code (Licensed Internal Code) on your managed system does not support viewing the Virtualization Engine systems technologies activation history log. In order to view the history log on your managed system, you need to update your managed system's Machine Code (Licensed Internal Code).

Problem determination: Contact your service provider to determine which level of management console Machine Code supports viewing the Virtualization Engine systems technologies activation history log. Update your managed system's Machine Code to that level or greater. For details, see Getting fixes and upgrades. Try the task again.

HSCL0244 HSCL0244

Explanation: Failed to restore the IPL source on the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0245 HSCL0245

Explanation: Failed to restore the partition workload group on the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0246 HSCL0246

Explanation: Failed to set the partition information in the profile data area on the partition.

Problem determination: Run the rebuild managed system operation or reboot the management console

HSCL0247 • HSCL025C

and try again. If the problem persists, contact your next level of support or your service provider.

HSCL0247 HSCL0247

Explanation: Failed to restore the partition MSP attribute on the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0248 HSCL0248

Explanation: Failed to restore the partition time reference attribute on the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0249 HSCL0249

Explanation: This operation is only allowed when the partition is in the Running state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0250 HSCL0250

Explanation: The managed system machine type, model, and serial number (MTMS) is empty.

HSCL0251 HSCL0251

Explanation: Service processor command failed. The connection to the hardware server is broken.

Problem determination: Ensure that the network connection is working. If the problem persists, contact your next level of support or your service provider.

HSCL0252 HSCL0252

Explanation: Service processor command failed. The connection to service processor is not available.

Problem determination: Ensure that the network connection is working. If the problem persists, contact your next level of support or your service provider.

HSCL0253 HSCL0253

Explanation: Service processor command failed. The managed system has been deleted.

Problem determination: Ensure that the network connection is working. If the problem persists, contact your next level of support or your service provider.

HSCL0254 HSCL0254

Explanation: Hardware server command failed. No response package.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0255 HSCL0255

Explanation: Hardware server command failed. The request ID has been deleted from the ID table.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0258 HSCL0258

Explanation: Issuing a service processor pass through failed. An expected exception was thrown.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0259 HSCL0259

Explanation: Service processor lock failed. The lock manager is not active.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL025A HSCL025A

Explanation: Service processor lock failed. Try again later.

Problem determination: Another management console might be performing this operation. Try again later. If the problem persists, contact your next level of support or your service provider.

HSCL025B HSCL025B

Explanation: Query service processor data failed.

HSCL025C HSCL025C

Explanation: Service processor command failed. Service processor authentication needs to be done first.

Problem determination: Ensure that the managed system is authenticated first. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL025D HSCL025D

Explanation: Service processor command failed. The Hypervisor is not ready to accept commands.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. If the problem persists, contact your next level of support or your service provider.

HSCL025E HSCL025E

Explanation: The lock table in the managed system is full. Try again.

Problem determination: Wait and then try the operation again.

HSCL025F HSCL025F

Explanation: There is a managed system lock.

Problem determination: Wait and then try the operation again.

HSCL0260 HSCL0260

Explanation: Unexpected error happened when trying to acquire a managed system lock.

Problem determination: Wait and then try the operation again.

HSCL0261 HSCL0261

Explanation: Unexpected error happened when trying to acquire a managed system lock.

Problem determination: Report the problem to your next level of support or your service provider.

HSCL0262 HSCL0262

Explanation: Supplement lock operation failed.

Problem determination: Check the input and permission and try the task again.

HSCL0263 HSCL0263

Explanation: The service processor does not support more than one management console connection. No service processor lock is needed.

Problem determination: Contact your next level of support or your service provider.

HSCL0264 HSCL0264

Explanation: The console command manager is not active.

Problem determination: Try the operation again. If the

problem persists, contact your next level of support or your service provider.

HSCL0265 HSCL0265

Explanation: No destination was specified for command. The command cannot be sent.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0266 HSCL0266

Explanation: The request to query data on the managed system failed.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0267 HSCL0267

Explanation: The connection to the service processor has been lost. A long-running task was stopped.

Problem determination: Verify the completion of the long-running task. If the task did not complete successfully, try the task again.

HSCL0268 HSCL0268

Explanation: An unexpected error occurred in a long-running task.

Problem determination: Verify the completion of the long-running task. If the task did not complete successfully, try the task again.

HSCL0269 HSCL0269

Explanation: Managed system cannot be found.

Problem determination: Verify the specified IP address. Specify a valid IP address and try the request again.

HSCL026A HSCL026A

Explanation: The specified managed system name is not valid with the specified IP address. The managed system cannot be removed.

Problem determination: Specify a valid managed system name and a valid IP address. Then try the request again.

HSCL026B HSCL026B

Explanation: Cannot find a managed system with the specified name.

Problem determination: Verify the specified system

HSCL026C • HSCL0278

name. Specify a valid managed system name and try the request again.

HSCL026C HSCL026C

Explanation: The request to add a new managed system failed.

Problem determination: Verify the specified IP address. Specify a valid IP address and try the request again.

HSCL026D HSCL026D

Explanation: Lock type specified is not valid for the managed system.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL026E HSCL026E

Explanation: The lock manager for managed system is not active.

Problem determination: Try the request again later. If the problem persists, contact your service provider.

HSCL026F HSCL026F

Explanation: Either the managed system name or the IP address is not specified in the request to remove the managed system.

Problem determination: Specify both the managed system name and the IP address. Then try the request again.

HSCL0270 HSCL0270

Explanation: The specified command destination cannot be found. The command cannot be sent.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0271 HSCL0271

Explanation: The connection state of the specified command destination is not valid. The command cannot be sent.

Problem determination: The connection to the managed system has been lost. Try the request again later.

HSCL0272 HSCL0272

Explanation: Service processor command failed. The service processor is in prestandby state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0273 HSCL0273

Explanation: A command that was targeted to the managed system has timed out.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0274 HSCL0274

Explanation: The managed system does not support the Power Saver feature. Check your firmware and platform capabilities.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0275 HSCL0275

Explanation: The user does not have the proper authority to perform this operation on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0276 HSCL0276

Explanation: The managed system is already processing a power saver change request.

Problem determination: Try the operation again later.

HSCL0277 HSCL0277

Explanation: Failed to set the power saver mode on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0278 HSCL0278

Explanation: The requested operation cannot be performed because another management or service task is already running.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0280 HSCL0280

Explanation: The service processor managed system state is not valid.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0281 HSCL0281

Explanation: The operation cannot be done because the managed system is not shared processor capable.

Problem determination: No recovery action is required.

HSCL0282 HSCL0282

Explanation: The virtual Ethernet adapter cannot be defined because the partition already defines a trunk adapter in its virtual I/O slot. Modify the profile accordingly and reactivate the partition.

Problem determination: Modify the profile accordingly and reactivate the partition.

HSCL0285 HSCL0285

Explanation: The managed system does not support SNI message passing.

Problem determination: No recovery action.

HSCL0286 HSCL0286

Explanation: The managed system firmware release level does not support service processor failover.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0287 HSCL0287

Explanation: Service processor failover is not enabled on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0288 HSCL0288

Explanation: The managed system is not ready for service processor failover.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0289 HSCL0289

Explanation: Service processor failover cannot be performed because the secondary service processor is unusable due to an error or because it has been manually deconfigured by a user.

Problem determination: If the secondary service processor cannot be manually reconfigured, or if this condition persists for longer than one hour, contact your hardware service representative.

HSCL028A HSCL028A

Explanation: Service processor failover cannot be performed because a secondary service processor is not installed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL028B HSCL028B

Explanation: Service processor failover cannot be performed because the code levels on the service processors do not match.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL028C HSCL028C

Explanation: Service processor failover cannot be performed because there is an error in the service processor configuration.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL028D HSCL028D

Explanation: Service processor failover cannot be performed because the managed system is either restarting or powering off.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL028E HSCL028E

Explanation: Service processor failover cannot be performed because Licensed Internal Code update is in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL028F HSCL028F

Explanation: Service processor failover cannot be performed because a system dump is in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0290 HSCL0290

Explanation: Service processor failover cannot be performed because service processor failover is already in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0291 HSCL0291

Explanation: The trunk adapter in Virtual I/O slot has the same trunk priority as the trunk adapter in another Virtual I/O slot.

Problem determination: Trunk adapters on the same Virtual LAN(s) must have different priorities. Please modify the profile or create a new profile accordingly, and retry activation.

HSCL0292 HSCL0292

Explanation: The trunk adapter in Virtual I/O slot has a different set of Virtual LAN IDs than the trunk adapter in Virtual I/O slot.

Problem determination: If more than one trunk adapter share Virtual LANs they must have a complete and exact overlap. Please modify the profile or create a new profile accordingly, and retry activation.

HSCL0293 HSCL0293

Explanation: The service process is in half genesis condition.

Problem determination: It needs to be powered off before trying to enable failover.

HSCL0294 HSCL0294

Explanation: Service processor failover cannot be performed because the secondary service processor is in a state which does not support failover.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCL0295 HSCL0295

Explanation: Service processor failover cannot be performed because the internal communication path between the primary and secondary service processors cannot be established.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCL0296 HSCL0296

Explanation: Service processor failover cannot be performed because the secondary service processor has been manually deconfigured by a user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0297 HSCL0297

Explanation: Service processor failover cannot be performed because a concurrent maintenance operation is in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0298 HSCL0298

Explanation: Service processor failover cannot be performed because the secondary service processor has detected a system configuration mismatch.

Problem determination: Contact your hardware service representative.

HSCL0299 HSCL0299

Explanation: Service processor failover cannot be performed because the secondary service processor has been automatically deconfigured by the system due to an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL029A HSCL029A

Explanation: This operation is not allowed because the managed system does not support partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL029B HSCL029B

Explanation: This operation is not allowed because the managed system does not support inactive partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL029C HSCL029C

Explanation: This operation is not allowed because the managed system does not support active partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL029D HSCL029D

Explanation: Adding new VSCSI adapter to Virtual IO Server failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL029E HSCL029E

Explanation: Service processor failover is not supported for this server model.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL029F HSCL029F

Explanation: Service processor failover can be enabled or disabled only when the managed system is in the Power Off state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02A0 HSCL02A0

Explanation: Service processor failover cannot be disabled until failover occurs again to cause the primary and secondary service processors to swap roles.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02A1 HSCL02A1

Explanation: Service processor failover cannot be enabled or disabled because the state of the secondary service processor does not match the state of the primary service processor.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCL02A2 HSCL02A2

Explanation: Service processor failover cannot be enabled because a secondary service processor is not installed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02A3 HSCL02A3

Explanation: Service processor failover cannot be enabled or disabled because the internal communication path between the primary and secondary service processors cannot be established.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCL02A4 HSCL02A4

Explanation: Service processor failover has been temporarily disabled by the service processor. The service processor will automatically enable failover again when it is ready.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02A5 HSCL02A5

Explanation: Service processor failover cannot be performed because the internal communication path between the secondary service processor and the POWER hypervisor cannot be established.

Problem determination: Contact your hardware service representative.

HSCL02A6 HSCL02A6

Explanation: The service processor failover request was ignored since a failover required for a concurrent maintenance operation has already occurred.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02A7 HSCL02A7

Explanation: Service processor failover cannot be performed for this concurrent maintenance operation because it has been requested out of order.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02A8 HSCL02A8

Explanation: A Licensed Internal Code update is not in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02A9 HSCL02A9

Explanation: The managed system does not support the address broadcast performance policy.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02AA HSCL02AA

Explanation: Service processor failover cannot be performed because the code levels on the primary and secondary service processors do not match.

Problem determination: If this failure persists after performing a code update, contact your hardware service representative.

HSCL02AB HSCL02AB

Explanation: The managed system does not support the specified partition start policy.

Problem determination: If this failure persists after performing a code update, contact your hardware service representative.

HSCL02AC HSCL02AC

Explanation: The managed system does not support partition power management.

Problem determination: If this failure persists after performing a code update, contact your hardware service representative.

HSCL02AD HSCL02AD

Explanation: This operation is not allowed because the managed system does not support selective memory mirroring.

Problem determination: If this failure persists after

performing a code update, contact your hardware service representative.

HSCL02AE HSCL02AE

Explanation: This operation is not allowed because selective memory mirroring is not enabled on the managed system.

Problem determination: If this failure persists after performing a code update, contact your hardware service representative.

HSCL02B0 HSCL02B0

Explanation: The attempt to update the repository for all partitions in the managed system failed.

Problem determination: If this failure persists, contact your hardware service representative.

HSCL02B1 HSCL02B1

Explanation: An error occurred.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCL02B3 HSCL02B3

Explanation: This operation is not allowed because the managed system does not support SPCN loops.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02B7 HSCL02B7

Explanation: A normal power off operation cannot be performed at this time because a concurrent maintenance operation is in progress.

Problem determination: You can either wait until the concurrent maintenance operation completes then issue the normal power off operation again, or you can issue a fast power off operation which the managed system will queue until the concurrent maintenance operation completes.

HSCL02B8 HSCL02B8

Explanation: This operation is not allowed because the managed system does not support partition suspend or resume operations.

Problem determination: You can either wait until the concurrent maintenance operation completes then issue the normal power off operation again, or you can issue a fast power off operation which the managed system will queue until the concurrent maintenance operation completes.

HSCL02C0 HSCL02C0

Explanation: The managed system does not support partition virtual switch partition access lists.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02C1 HSCL02C1

Explanation: The partition is already in the partition access list for virtual switch.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02C2 HSCL02C2

Explanation: The partition is not in the partition access list for virtual switch.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02C3 HSCL02C3

Explanation: The operation to modify the partition access list for the virtual switch has failed because partitions that are currently connected to the virtual switch cannot be removed from the partition access list.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL02C4 HSCL02C4

Explanation: The operation has failed because the virtual Ethernet adapter in slot is configured to connect to a virtual switch to which this partition is not authorized to connect.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL03E5 HSCL03E5

Explanation: The managed system does not support TurboCore mode.

Problem determination: You can either wait until the concurrent maintenance operation completes then issue the normal power off operation again, or you can issue a fast power off operation which the managed system will queue until the concurrent maintenance operation completes.

HSCL03E6 HSCL03E6

Explanation: TurboCore mode cannot be enabled on the managed system because the managed system does not have enough nodes.

Problem determination: You can either wait until the concurrent maintenance operation completes then issue the normal power off operation again, or you can issue a fast power off operation which the managed system will queue until the concurrent maintenance operation completes.

HSCL03E7 HSCL03E7

Explanation: TurboCore mode cannot be enabled on the managed system because not all of the installed processors support TurboCore mode.

Problem determination: You can either wait until the concurrent maintenance operation completes then issue the normal power off operation again, or you can issue a fast power off operation which the managed system will queue until the concurrent maintenance operation completes.

HSCL03E8 HSCL03E8

Explanation: The managed system must be in the Standby, Operating, or Power Off state to configure TurboCore mode.

Problem determination: You can either wait until the concurrent maintenance operation completes then issue the normal power off operation again, or you can issue a fast power off operation which the managed system will queue until the concurrent maintenance operation completes.

HSCL03E9 HSCL03E9

Explanation: The managed system does not support partition placement configuration.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL03EA HSCL03EA

Explanation: There is an insufficient number of processors. Check that there are enough processors available to activate the partition. If not, create a new profile or modify the existing profile with the available resources, and then activate the partition. If the partition must be activated with the specified number of processors, deactivate any active logical partitions using the resource, and then activate the partition.

Problem determination: Check the managed system properties window to ensure that enough processors are available to activate the partition. If there are not enough processors available, create a new profile or

modify the existing profile with the available resources. Then activate the partition. If the partition must be activated at any cost, deactivate any running partition that is using the resource and then activate the partition. If the problem persists, contact your service provider.

HSCL03EB HSCL03EB

Explanation: Unable to allocate the I/O slot for activation. This I/O slot is identified as a required adapter to activate this partition. Verify that the specified I/O is available to activate the partition. If it is not available, either create a new profile or modify the existing profile to identify the I/O adapter as a non-required resource, and then try to activate the partition again. If the partition must be activated with these resources, deactivate any running partition that is using the resource, and then try to activate this partition again.

Problem determination: Check the managed system properties window to ensure that enough I/O slots are available to activate the partition. If there are not enough I/O slots available, create a new profile or modify the existing profile with the available resources. Then activate the partition. If the partition must be activated at any cost, deactivate any running partition that is using the resource and then activate the partition. Note If you must activate the partition and you have tried unsuccessfully to recover using the above action, edit the profile for the partition you are activating and remove all slots that are associated with the identified slot's PHB. See the PCI Adapter Placement Reference, order number SA38-0538 for information on PHB slot associations. If the problem persists, contact your service provider.

HSCL03EC HSCL03EC

Explanation: There is not enough memory. Check that there is enough memory available to activate the partition. If not, create a new profile or modify the existing profile with the available resources, then activate the partition. If the partition must be activated with these resources, deactivate any running partition or partitions using the resource, then activate this partition.

Problem determination: Check the managed system properties window to ensure that enough memory is available to activate the partition. If there is not enough available memory, create a new profile or modify the existing profile with the available resources and then activate the partition. If the partition must be activated at any cost, deactivate any running partition using the resource, and activate the partition. If the problem persists, contact your service provider.

HSCL03ED HSCL03ED

Explanation: The I/O unit specified by this ID cannot be found and might have been deleted from the managed system. Modify the profile.

Problem determination: Modify the partition profile so that the unit that cannot be found is no longer part of the profile's resources.

HSCL03EE HSCL03EE

Explanation: The specified slot number cannot be found. Ensure the profile is not using I/O unit slots that do not exist in the managed system.

Problem determination: The adapter specified cannot be found. Modify partition profiles so that the slot that cannot be found is not part of any partition profile.

HSCL03EF HSCL03EF

Explanation: The number of system units, slots, and I/O required and desired information stored in the properties do not match. The profile might be corrupted. Perform the Restore Profile Data task.

Problem determination: The profile might be corrupted. Restore the profile data. For details, see Restoring profile data. If the problem persists, delete the profile and create a new profile.

HSCL03F0 HSCL03F0

Explanation: Could not allocate the I/O slot for activation in I/O drawer. Slot is currently being used by another partition. Perform one of the following three actions: 1) Remove this I/O slot from the profile, 2) Change the I/O slot from Required to Desired in the profile, or 3) Remove the I/O slot from the other partition.

Problem determination: Perform one of the following actions: Remove this I/O slot from the profile. Change the I/O slot from Required to Desired in the profile. Remove the I/O slot from the other partition.

HSCL03F1 HSCL03F1

Explanation: Unable to allocate one or more I/O slots.

Problem determination: Please complete one of the following actions: Remove this I/O slot from the profile, or change the I/O slot from required to desired in the profile, or reboot the managed system to restore the PCI slots in error to normal state.

HSCL03F2 HSCL03F2

Explanation: Unable to allocate the I/O slot for activation -I/O unit.

Problem determination: Please remove this I/O slot

from the profile or change the I/O slot from required to desired in the profile.

HSCL03F3 HSCL03F3

Explanation: Unable to allocate the I/O slot for activation -I/O unit, slot is system deconfigured.

Problem determination: Please remove this I/O slot from the profile or change the I/O slot from required to desired in the profile.

HSCL03F4 HSCL03F4

Explanation: Not enough processing resources to meet the allocation setting

Problem determination: Ensure there is enough processors to start the partition. Rebuild the managed system. For details, see Updating managed system or frame information. If the problem persists, contact your next level of support or your service provider.

HSCL03F5 HSCL03F5

Explanation: There is an insufficient amount of shared processing resources. Check that there is enough processing resources available to activate the partition. If not, create a new profile or modify the existing profile with the available resources, then activate the partition. If the partition must be activated with the specified amount of processing resources, deactivate any active partitions using the resource then activate this partition.

Problem determination: Ensure there is enough processors to start the partition. Rebuild the managed system. For details, see Updating managed system or frame information. If the problem persists, contact your next level of support or your service provider.

HSCL03F6 HSCL03F6

Explanation: The 5250 CPW needed by the partition exceeds the system limit.

Problem determination: Check the 5250 CPW. If the problem persists, contact your next level of support or your service provider.

HSCL03F7 HSCL03F7

Explanation: Insufficient amount of 5250 CPW for allocation.

Problem determination: Ensure there are enough 5250 CPW to start the partition. Rebuild managed system. If the problem persists, contact your next level of support or your service provider.

HSCL03F8 HSCL03F8

Explanation: The 5250 CPW set by user is below the partition minimum allowed.

Problem determination: Ensure the 5250 CPW setting is correct. If the problem persists, contact your next level of support or your service provider.

HSCL03F9 HSCL03F9

Explanation: Not enough memory resources to meet the allocation setting.

Problem determination: Ensure there is enough memory to start the partition. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL03FA HSCL03FA

Explanation: Unable to gather I/O information of the managed system.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL03FB HSCL03FB

Explanation: Unable to gather virtual I/O information of the managed system.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL03FC HSCL03FC

Explanation: The MAC address prefix specified was not valid. The MAC address prefix must be 6 characters long, and only contain hexadecimal values (0-9 and A-F).

Problem determination: Ensure the MAC address conforms with the rule specified. If the problem persists, contact your next level of support or your service provider.

HSCL03FD HSCL03FD

Explanation: The MAC address prefix cannot have the multicast bit set. The multicast bit is the 0x01 bit in the byte zero of the prefix.

Problem determination: Ensure the multicast bit is not on. If the problem persists, contact your next level of support or your service provider.

HSCL03FE HSCL03FE

Explanation: There was an error updating a virtual Ethernet adapter MAC address.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL03FF HSCL03FF

Explanation: Failed to extract system resources information. Ensure the managed system is powered on.

Problem determination: Retry the task. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0400 HSCL0400

Explanation: Failed to determine the minimum amount of memory required for the amount of maximum specified.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0401 HSCL0401

Explanation: Failed to determine the valid 5250 CPW range with the amount of processing given.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0402 HSCL0402

Explanation: Not enough system firmware memory is available to perform this task. The managed system needs additional memory.

Problem determination: You can free memory resources by removing memory through dynamic logical partitioning or by deleting partitions that are not being used.

HSCL0403 HSCL0403

Explanation: The number of processors available for IBM i partitions is not sufficient.

Problem determination: You can create a new profile or modify the existing profile to use the number of obtained processors, and then activate the partition. If the partition must be activated with the required number of processors, first shut down the active IBM i partitions that are using the required processors, and then activate this partition.

HSCL0404 HSCL0404

Explanation: The number of shared processing resources available for IBM i partitions is not sufficient.

Problem determination: You can create a new profile or modify the existing profile to use the number of obtained processors resources, and then activate the partition. If the partition must be activated with the required number of processing resources, first shut down the active IBM i partitions that are using the required processing resources, and then activate this partition.

HSCL0405 HSCL0405

Explanation: Huge page memory is not supported on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0406 HSCL0406

Explanation: The maximum memory setting exceeds the maximum system memory capacity. Please check the capacity and modify the maximum memory setting in the profile accordingly.

Problem determination: Check the capacity and modify the maximum memory setting in the profile accordingly.

HSCL0407 HSCL0407

Explanation: Not enough huge page memory regions resources to meet the allocation setting.

Problem determination: Ensure there is enough pages of huge page memory to start the partition. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0408 HSCL0408

Explanation: Not enough Barrier Synchronization Register (BSR) resources to meet the allocation setting.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0409 HSCL0409

Explanation: Barrier Synchronization Registers (BSR's) are not supported on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL040A HSCL040A

Explanation: The requested slot was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL040C HSCL040C

Explanation: The managed system does not support user modification of the processor limit for partitions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL040D HSCL040D

Explanation: The processor limit for partitions for the next system restart cannot be modified when TurboCore mode is enabled for the next system restart.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL040E HSCL040E

Explanation: The partition cannot be activated with this profile, which is a full system profile. It is not possible to have a full system partition on this managed system because all of the processors in the system cannot be allocated to a single partition because of the processor limit for this partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL040F HSCL040F

Explanation: A full system partition or profile cannot be created for this managed system. It is not possible to have a full system partition on this managed system because all of the processors in the system cannot be allocated to a single partition since the processor limit is hit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0410 HSCL0410

Explanation: You do not have full access to one or more partitions in the managed system. Only users with access to all of the partitions in the managed system are allowed to power off the system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0500 HSCL0500

Explanation: The operation violates the Workload Management Policy. It may be due to one of the following reasons:

Problem determination: Delete a partition which belongs to a cluster; Change a partition cluster id from one cluster to another cluster; Executing dynamic partition move operation between two partitions which belong to the same cluster.

HSCL0589 HSCL0589

Explanation: Could not delete partition. Refresh the interface and check whether the operation was performed. If not, try the operation again.

Problem determination: Refresh the interface and check whether the operation was performed. If not, rebuild the managed system, and try the task again. For details, see Updating managed system or frame information. If the operation still fails, contact your next level of support or your service provider.

HSCL058A HSCL058A

Explanation: Could not activate the logical partition. Refresh the interface and check whether the operation was performed. If not, try the operation again.

Problem determination: Perform a rebuild of the managed system. For details, see Updating managed system or frame information. Try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL058C HSCL058C

Explanation: User defined name cannot be blank or empty.

Problem determination: Set a non-blank user defined name for this partition. If the problem persists, contact your next level of support or your service provider.

HSCL058D HSCL058D

Explanation: The user defined name is too long.

Problem determination: The partition's user-defined name is too long. Shorten this partition's user-defined name, and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0591 HSCL0591

Explanation: Cannot activate logical partition when an affinity logical partition has already been activated since powering on.

Problem determination: If the problem persists,

HSCL0592 • HSCL05A3

contact your next level of support or your service provider.

HSCL0592 HSCL0592

Explanation: Cannot activate a 4-processor affinity logical partition when a logical partition or other type of affinity logical affinity partition has already been activated since powering on.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0593 HSCL0593

Explanation: Cannot activate an 8-processor affinity logical partition when a logical partition or other type of affinity logical partition has already been activated since powering on.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0594 HSCL0594

Explanation: Managed system is not capable of activating a 8-processor affinity logical partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0595 HSCL0595

Explanation: Managed system is not capable of activating a 4-processor affinity logical partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0596 HSCL0596

Explanation: Cannot activate a Full Machine Partition in a non-SMP capable managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL059A HSCL059A

Explanation: Cannot activate the logical partition. The profile's maximum memory amount exceeds the managed system's memory limit. Change the profile's maximum memory amount.

Problem determination: Change the profile's maximum memory amount, and retry the operation.

HSCL059B HSCL059B

Explanation: The group number is invalid.

Problem determination: Group numbers cannot contain any letters or characters other than the numbers 0 thru 9.

HSCL059C HSCL059C

Explanation: The Workload Management group number is invalid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL059D HSCL059D

Explanation: This panel function is not enabled at this time.

HSCL059E HSCL059E

Explanation: Failed to get supported panel functions from firmware.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL05A0 HSCL05A0

Explanation: User-defined name cannot be blank or empty.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL05A1 HSCL05A1

Explanation: The processor compatibility mode setting for the partition cannot be used.

Problem determination: Specify a processor compatibility mode that is supported by the managed system, and try the operation again.

HSCL05A2 HSCL05A2

Explanation: The processor compatibility mode setting for the partition cannot be used.

Problem determination: The processor compatibility mode can be set to only "default" for IBM i partitions.

HSCL05A3 HSCL05A3

Explanation: The remote restart capable partition cannot be activated because the managed system does not support partition remote restart operations.

Problem determination: Retry the operation. If the

problem persists, contact your next level of support or your service provider.

HSCL05A4 HSCL05A4

Explanation: The remote restart capable partition cannot be activated. To activate the partition with this profile, assign a reserved storage device with a minimum size to the partition, then try the operation again.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL05A5 HSCL05A5

Explanation: The remote restart capable partition cannot be activated because VIOS partition, which has reserved storage device for the partition, is not running.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL05A6 HSCL05A6

Explanation: The remote restart capable partition cannot be activated.

Problem determination: Run the rebuild managed system task and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL05A7 HSCL05A7

Explanation: The remote restart capable partition cannot be activated because the partition is not in a valid remote restart state.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL05A9 HSCL05A9

Explanation: The remote restart capable partition cannot be activated.

Problem determination: Assign a reserved storage device to the partition and try again. If the problem persists, contact your next level of support or your service provider.

HSCL05AB HSCL05AB

Explanation: The remote restart capable partition cannot be set to automatically start with the managed system.

Problem determination: Retry the operation. If the

problem persists, contact your next level of support or your service provider.

HSCL05DB HSCL05DB

Explanation: The partition does not have Virtual IO Client capability.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL05DC HSCL05DC

Explanation: The partition does not have Virtual IO Server capability.

Problem determination: Choose the correct partition and retry the command.

HSCL05DD HSCL05DD

Explanation: Could not get logical partition state. Repeat the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL05DE HSCL05DE

Explanation: A logical partition in the managed system already uses the specified name. Provide another name for this logical partition.

Problem determination: Rename the logical partition to a name that is not yet used by other logical partitions in the same managed system. Refer to the logical partition help text for details.

HSCL05DF HSCL05DF

Explanation: The logical partition is not in a state under which this operation can be performed. Check the state of the logical partition.

Problem determination: Verify that the operation is allowable under this logical partition state. Refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state.

HSCL05E0 HSCL05E0

Explanation: The logical partition is in an undefined state. Rebuild the managed system.

Problem determination: Rebuild the managed system. Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL05E1 HSCL05E1

Explanation: There are no more unallocated logical partitions available. Delete unused or unwanted logical partitions for this managed system and retry the operation. Logical partitions in the ready state are currently not in use.

Problem determination: Delete unused or unwanted logical partitions. Logical partitions in the ready state are currently not in use. Refer to the logical partition help text for details.

HSCL05E2 HSCL05E2

Explanation: Partition is in an unrecognized state.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL05E3 HSCL05E3

Explanation: Partition is in an unrecognized state.

Problem determination: Rebuild the managed system. For details, see Updating managed system or frame information. Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL05E4 HSCL05E4

Explanation: Unable to delete a full system partition. You do not have the necessary permission to delete a full system partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL05E5 HSCL05E5

Explanation: Unable to create partition when the managed system is not in the Operating or Standby state.

Problem determination: Verify that the managed system is in the Operating or Standby state. If it is not in the Operating or Standby state refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. If the problem persists, contact your next level of support or your service provider.

HSCL05E6 HSCL05E6

Explanation: Logical partition delete failed. Cannot delete a partition when its state is not in the Not Activated state. Perform a shut down operation then delete the partition.

Problem determination: Verify the partition is in Not Activated state. Perform a Rebuild Managed System operation. For details, see Updating managed system or frame information. Then try the task again.

HSCL05E7 HSCL05E7

Explanation: The profile you tried to activate does not belong to the logical partition you specified. Select the correct partition profile.

Problem determination: Verify that you selected the correct logical partition profile to activate.

HSCL05E8 HSCL05E8

Explanation: Partition delete failed.

Problem determination: Cannot delete a partition when the managed system is in current state.

HSCL05E9 HSCL05E9

Explanation: Could not activate the logical partition. Ensure that the partition is not already activated and that the managed system is in the Operating or Standby state.

Problem determination: Verify that the logical partition is not already activated, and the state and power-on condition of the managed system are correct, and try the operation again. If necessary, refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. If the problem persists, contact your next level of support or your service provider.

HSCL05EA HSCL05EA

Explanation: Cannot activate the partition when the partition is in current state. Ensure the partition is in the Not Activated state.

Problem determination: Verify that the logical partition is not in the running, booting, or open firmware state. If necessary, refer to Correcting the managed system operating state and perform the appropriate procedure to put the managed system in the correct state. If it still fails, contact your next level of support or your service provider.

HSCL05EB HSCL05EB

Explanation: Could not create the partition. Make sure that all requirements are met for creating a logical partition.

Problem determination: To verify that all the requirements for creating a logical partition are met, refer to Partitioning the server. If all requirements are met, do a rebuild of the managed system. For details, see Updating managed system or frame information.

Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL05EC HSCL05EC

Explanation: Could not delete logical partition. Ensure that all requirements are met for deleting a logical partition.

Problem determination: Verify that all the requirements for deleting a logical partition are met. Perform a rebuild of the managed system. For details, see Updating managed system or frame information. Retry the task. If it still fails, contact your next level of support or your service provider.

HSCL05ED HSCL05ED

Explanation: Could not set the properties for logical partition. Try again

Problem determination: Repeat the operation. If the operation still fails, contact your next level of support or your service provider.

HSCL05EE HSCL05EE

Explanation: Could not get the managed system's service provider. processor log entry. Try again

Problem determination: Repeat the operation. If the operation still fails, contact your next level of support or your service provider.

HSCL05EF HSCL05EF

Explanation: This new logical partition does not have a user-defined name. Specify a name for the logical partition.

Problem determination: Set the user-defined name for this logical partition. For details, see Viewing information about the managed system. If it still fails, contact your next level of support or your service provider.

HSCL05F0 HSCL05F0

Explanation: Cannot create the partition for the managed system.

Problem determination: Make sure the managed system is powered on with Partition Standby.

HSCL05F1 HSCL05F1

Explanation: Could not delete partition.

Problem determination: Make sure that the managed system was powered on with Partition Standby.

HSCL05F3 HSCL05F3

Explanation: Could not display the OS reset dialog for logical partition. Try again.

Problem determination: Refresh the interface and check whether the operation was performed. If not, rebuild the managed system. Retry the task. If the operation still fails, contact your next level of support or your service provider.

HSCL05F4 HSCL05F4

Explanation: Could not display the logical partition activate dialog for logical partition. Try again.

Problem determination: Log off and then log in to the management console and try the operation again. If this does not correct the problem, contact your next level of support or your service provider.

HSCL05F5 HSCL05F5

Explanation: Could not display the create logical partition dialog for the managed system. Try again.

Problem determination: Log off and then log in to the management console and try the operation again. If this does not correct the problem, contact your next level of support or your service provider.

HSCL05F6 HSCL05F6

Explanation: Could not create the partition on the managed system.

Problem determination: Refresh the interface and check whether the operation was performed. If not, try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL05F7 HSCL05F7

Explanation: Could not open the virtual terminal for logical partition.

Problem determination: Refresh the interface and check whether the operation was performed. If not, rebuild the managed system, and try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL05F8 HSCL05F8

Explanation: Could not perform the OS reset on logical partition.

Problem determination: Refresh the interface and check whether the operation was performed. If not, rebuild the managed system, and try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL05F9 HSCL05F9

Explanation: Could not delete logical partition. Refresh the interface and check whether the operation was performed. If not, try the operation again.

Problem determination: Verify that the logical partition displays on the graphical user interface. Delete the logical partition again, and check the graphical user interface to see if it is updated appropriately. Log off and log back in to the management console. Contact your next level of support or your service provider.

HSCL0601 HSCL0601

Explanation: Cannot create partition with bootable definition state setting.

Problem determination: Rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0602 HSCL0602

Explanation: Partition with the same ID is already defined in the managed system.

Problem determination: Check the entry and try again. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0604 HSCL0604

Explanation: Could not read the dump.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0605 HSCL0605

Explanation: The initialize dump request failed because the managed system is already in the process of creating a dump of the specified type.

Problem determination: The keylock position of the managed system needs to be set to manual mode.

HSCL0606 HSCL0606

Explanation: Managed system is not in the Operating state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0607 HSCL0607

Explanation: Dump partition does not exist.

Problem determination: Ensure that the dump partition has been mounted. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0608 HSCL0608

Explanation: Could not mount the dump partition.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0609 HSCL0609

Explanation: Could not move the dumps to new location.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0610 HSCL0610

Explanation: Could not get the maximum number of dumps.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0611 HSCL0611

Explanation: Could not mount the dump partition.

Problem determination: Ensure that the dump partition has been mounted and has an access to it. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0612 HSCL0612

Explanation: Could not process dump header.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0613 HSCL0613

Explanation: Could not query the dump.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0614 HSCL0614

Explanation: Could not set as a Master management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0615 HSCL0615

Explanation: Could not get the Master management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0616 HSCL0616

Explanation: Cannot use the 5250 CPW setting. Check whether the setting is valid.

Problem determination: Ensure the 5250 CPW setting is correct. If the problem persists, contact your next level of support or your service provider.

HSCL0617 HSCL0617

Explanation: Cannot use the memory resource setting.

Problem determination: Check whether the setting is valid or not.

HSCL0618 HSCL0618

Explanation: The minimum memory value is invalid for the maximum memory value specified.

Problem determination: Correct the minimum memory setting of the partition profile and try the operation again.

HSCL0619 HSCL0619

Explanation: Cannot use the I/O setting for allocation. Check whether the setting is valid.

Problem determination: Check the I/O setting is valid. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL061A HSCL061A

Explanation: Cannot use the virtual I/O setting for allocation. Check whether the setting is valid.

Problem determination: Check that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL061B HSCL061B

Explanation: Operation failed to set partition activation policies.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL061C HSCL061C

Explanation: Operation failed to allocate memory for the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL061D HSCL061D

Explanation: Operation failed to allocate virtual I/O for the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL061E HSCL061E

Explanation: Operation failed to allocate 5250 CPW for the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL061F HSCL061F

Explanation: Operation failed to allocate processing resource for the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0620 HSCL0620

Explanation: Operation failed to allocate I/O slots for the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0621 HSCL0621

Explanation: The dedicated processor settings in the partition profile are not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0622 • HSCL062E

HSCL0622 HSCL0622

Explanation: The shared processor settings in the partition profile are not valid.

Problem determination: Check the processors settings. If the problem persists, contact your next level of support or your service provider.

HSCL0623 HSCL0623

Explanation: Partition cluster ID cannot be modified when the partition is not in the Not Activated state.

Problem determination: Ensure the partition is in Not Activated state. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0624 HSCL0624

Explanation: Unable to launch Update Password Dialog. Try again.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0625 HSCL0625

Explanation: Cannot activate partition when the managed system state is not in the Operating or Standby state.

Problem determination: Ensure the partition is in Operating or Standby state. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0626 HSCL0626

Explanation: Cannot find the partition profile to activate the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0627 HSCL0627

Explanation: The virtual I/O specified for tagged I/O is not valid.

Problem determination: Check that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0628 HSCL0628

Explanation: Resource specified as load source must be required.

Problem determination: Resource specified as load source must be required. Retry the task. If the problem

persists, contact your next level of support or your service provider.

HSCL0629 HSCL0629

Explanation: Must specify resource for load source setting.

Problem determination: Resource specified as load source must be required. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL062A HSCL062A

Explanation: Cluster ID specified is greater than maximum allowable value.

Problem determination: Ensure the setting is valid. Retry the operation.

HSCL062B HSCL062B

Explanation: Cannot change maximum virtual I/O Slots value when partition is not in the Not Activated state.

Problem determination: Ensure the setting is valid. Retry the operation.

HSCL062C HSCL062C

Explanation: The partition cannot be deleted.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL062D HSCL062D

Explanation: The partition is currently in a state of Running, Initializing or Open Firmware, and cannot be deleted.

Problem determination: A partition cannot be deleted when it is in Running, Initializing, or Open Firmware state. Deactivate the partition and retry the operation. If you believe that the partition is already stopped, rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL062E HSCL062E

Explanation: Unable to shut down the partition using operation system command.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL062F HSCL062F

Explanation: You must select one profile to activate the partition with or select Cancel.

Problem determination: Only one partition profile can be used to activate a partition. Either retry the operation, selecting a profile to activate the partition with, or select Cancel. If the problem persists, contact your next level of support or your service provider.

HSCL0630 HSCL0630

Explanation: Could not display the partition activate advance dialog for partition. Try the operation again.

Problem determination: Refresh the graphical user interface and retry the operation. Log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0631 HSCL0631

Explanation: Could not display the partition reboot dialog. Try the operation again.

Problem determination: Refresh the graphical user interface and retry the operation. Log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0632 HSCL0632

Explanation: Could not perform the reboot partition operations. Refresh the interface and check whether the operation was performed. If not, try the operation again.

Problem determination: Refresh the interface and check whether the operation was performed. If not, rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0633 HSCL0633

Explanation: Could not display the partition shut down dialog. Try the operation again.

Problem determination: Refresh the graphical user interface and retry the operation. Log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0634 HSCL0634

Explanation: Could not perform the shut down partition operations. Refresh the interface and check whether the operation was performed. If not, try the operation again.

Problem determination: Refresh the interface and check whether the operation was performed. If not, rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL0635 HSCL0635

Explanation: Could not display the change default profile dialog. Try the operation again.

Problem determination: Refresh the graphical user interface and retry the operation. Log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL0636 HSCL0636

Explanation: Unable to modify processing information of the partition. The information could be out of sync. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0637 HSCL0637

Explanation: Unable to modify processing information of the partition. The information could be out of sync. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0638 HSCL0638

Explanation: Unable to modify 5250 CPW information of the partition. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0639 HSCL0639

Explanation: Unable to modify OptiConnect setting of the partition. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL063A HSCL063A

Explanation: Unable to extract partition's virtual I/O information.

Problem determination: Rebuild the managed system.

HSCL063B • HSCL0647

Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL063B HSCL063B

Explanation: Failed to set I/O adapter for the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL063C HSCL063C

Explanation: Failed to set tagged I/Os for the partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL063D HSCL063D

Explanation: Failed to change the partition's processor type.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL063E HSCL063E

Explanation: Failed to change the partition's processor settings.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL063F HSCL063F

Explanation: Cannot assign a storage device under I/O processor to AIX/Linux partition.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0640 HSCL0640

Explanation: OptiConnect Pool IDs may only be set on i5/OS partitions.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0641 HSCL0641

Explanation: Cannot activate a profile using full system resources while other partitions are powered on.

Problem determination: Ensure there are no partitions running. Rebuild the managed system. Retry the task.

If the problem persists, contact your next level of support or your service provider.

HSCL0642 HSCL0642

Explanation: Partition ID specified is over max number of partition supported by the system. Check the entry and try again.

Problem determination: Ensure the partition ID specified does not exceed the maximum number of logical partitions supported. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL0643 HSCL0643

Explanation: Virtual I/O server command for partition failed.

Problem determination: The I/O server command for the partition failed. The reason or cause is included in the error message. Check the command and retry. If the error persists, contact your next level of support or your service provider.

HSCL0644 HSCL0644

Explanation: The number of processing units must be less than or equal to the number of virtual processors.

Problem determination: In the partition profile properties, make sure the number of processing units is less than or equal to the number of virtual processors.

HSCL0645 HSCL0645

Explanation: The ratio of processing units to virtual processors must be equal to or greater than the value specified in the partition profile properties.

Problem determination: In the partition profile properties, make sure the ratio of processing units to virtual processors is equal to or greater than the value that is specified.

HSCL0646 HSCL0646

Explanation: Processor pool ID specified is over maximum processor pools system allowed.

Problem determination: Make sure the processor pool ID specified is not over the maximum processor pools system allowed.

HSCL0647 HSCL0647

Explanation: The workload group setting for the partition could not be changed. Try the operation again. If the problem persists, contact your technical support provider.

Problem determination: Retry the operation. If the

problem persists, contact your next level of support or your service provider.

HSCL0648 HSCL0648

Explanation: The setting for power controlling partitions could not be changed. Try the operation again. If the problem persists, contact your technical support provider.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0649 HSCL0649

Explanation: The opticonnect settings for the partition could not be changed. Try the operation again. If the problem persists, contact your technical support provider.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL064A HSCL064A

Explanation: Cannot use the SMA setting for allocation. Check whether the setting is valid.

HSCL064B HSCL064B

Explanation: Cannot use the HCA setting for allocation. Check whether the setting is valid.

Problem determination: Ensure that this HCA adapter is not allocated to another Active partition and retry the operation.

HSCL064C HSCL064C

Explanation: Could not assign GUID of the HCA adapter to the partition.

Problem determination: Please verify if the HCA configuration is valid, (if the assigned GUID index is -1, the adapter could have been replaced with a new set of GUIDs, the assigned index needs to be updated to a valid number in the GUID range), execute a rebuild managed system operation, and retry the operation. If the error persists contact your support representative.

HSCL064D HSCL064D

Explanation: Could not unassign the GUID of the HCA adapter.

Problem determination: Execute a rebuild managed system operation and retry the operation. If the error persists contact your service support representative.

HSCL064E HSCL064E

Explanation: The GUID of the HCA adapter is being used by another partition.

Problem determination: Please select a different GUID and retry the operation.

HSCL064F HSCL064F

Explanation: The operation failed because the HCA adapter ID is out of capability resources.

Problem determination: Please remove the HCA assignment for this partition or free up HCA resources by deactivating some partition(s) that are using the same HCA adapter then retry the operation.

HSCL0650 HSCL0650

Explanation: An i5/OS partition or profile is not allowed to use all the resources in a IBM System p5 or IBM eServer p5 server.

HSCL0651 HSCL0651

Explanation: The maximum number of processors specified exceeds the i5/OS processor capacity limit of processors for the managed system. Reduce the number and try again.

Problem determination: Reduce the number specified for the maximum number of processors to a number that is less than or equal to the i5/OS processor capacity limit for your managed system. Try the task again.

HSCL0652 HSCL0652

Explanation: The maximum number of processing units specified exceeds the i5/OS processor capacity limit of processing units for the managed system. Reduce the number and try again.

Problem determination: Reduce the number specified for the maximum number of virtual processors to a number that is less than or equal to the i5/OS processor capacity limit for your managed system. Try the task again.

HSCL0653 HSCL0653

Explanation: The maximum number of virtual processors specified exceeds the i5/OS processor capacity limit of processors for the managed system. Reduce the number and try again.

Problem determination: Reduce the number specified for the maximum number of processing units to a number that is less than or equal to the i5/OS processor capacity limit for your managed system. Try the task again.

HSCL0654 HSCL0654

Explanation: The HCA device has a hardware error. You cannot activate the profile containing a GUID from this device. Clear the adapter configuration from the profile and try again or contact your service provider.

Problem determination: If the device is needed for the partition, contact your next level of support or service provider.

HSCL0655 HSCL0655

Explanation: The profile contains a GUID for an HCA device not managed by the management console. Clear the adapter configuration from the profile and try again.

Problem determination: If the device should be managed from the HMC, or if the device is needed for the partition, contact your next level of support or service provider.

HSCL0656 HSCL0656

Explanation: The HEA has a hardware error.

Problem determination: You cannot activate a profile containing an LHEA from this device. Clear the adapter configuration from the profile and try again, or contact your hardware service representative.

HSCL0657 HSCL0657

Explanation: Logical port belonging to port group of the HEA is being used by the running partition.

Problem determination: Please select a different logical port and try the operation again.

HSCL0658 HSCL0658

Explanation: Required number of entities are not available.

Problem determination: Change the LHEA Capability for HEA or change the custom value and try activation operation again.

HSCL0659 HSCL0659

Explanation: Failed to unassign logical port from the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL065A HSCL065A

Explanation: Could not assign the Logical Ports for HEA to partition.

Problem determination: Please try to activate it again

HSCL065B HSCL065B

Explanation: You may not specify LHEAs in this logical partition profile as the managed system does not support this.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL065C HSCL065C

Explanation: HEA was not found to exist in this managed system. Therefore an LHEA can not be specified in a partition profile for this HEA.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL065D HSCL065D

Explanation: A logical port with specified DRC Index was not found in HEA. Therefore an LHEA can not be specified in a partition profile using this logical port.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL065E HSCL065E

Explanation: The partition profile specifies capabilities for an LHEA using an HEA, but no logical ports from this HEA were specified for the LHEA.

Problem determination: Please check the profile.

HSCL065F HSCL065F

Explanation: HEA was not found in the managed system.

Problem determination: Verify this value and retry the operation.

HSCL066A HSCL066A

Explanation: Error In HEA Activation. Couldn't query Repository Error

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL066B HSCL066B

Explanation: The managed system does not support Host Ethernet Adapters (HEA).

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL066C HSCL066C

Explanation: A port group was not found in HEA.

Problem determination: Please check the HEA configuration and change the profile definition accordingly.

HSCL066D HSCL066D

Explanation: A physical port was not found in a port group in HEA.

Problem determination: Please check the HEA configuration and change the profile definition accordingly.

HSCL066E HSCL066E

Explanation: The logical port with specified DRC Index was not found in port group in HEA. Therefore an LHEA can not be specified in a partition profile for this HEA.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL066F HSCL066F

Explanation: The logical port belongs to a HEA which is non-functional. You cannot configure logical ports of a non-functional HEA.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0670 HSCL0670

Explanation: The HEA with specified DRC Index is not functional. You can not set any physical port configuration for this HEA.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0671 HSCL0671

Explanation: The dump file cannot be read because the dump directory on the management console does not have sufficient available space.

Problem determination: Delete old dump files and

start the dump process again.

HSCL0672 HSCL0672

Explanation: An error occurred while executing the script to check for free space in the dump directory on the management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0673 HSCL0673

Explanation: Promiscuous Id/Name is not a valid partition ID/Name.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0674 HSCL0674

Explanation: Physical Port belonging to port group cannot be configured for specified speed.

Problem determination: For Physical Port of type 10G , allowed speed values are 10Gbps and AUTO. For Physical Port of type 1G , allowed speed values are AUTO, 10Mbps, 100Mbps, 1000Mbps.

HSCL0675 HSCL0675

Explanation: Physical Port belonging to port group cannot be configured for Half Duplex.

Problem determination: For Half Duplex speed should be either 10 Mbps or 100 Mbps

HSCL0676 HSCL0676

Explanation: Physical port belonging to port group cannot be configured for Jumbo packet size.

Problem determination: For Jumbo packet size, speed be either 1Gbps or 10 Gbps.

HSCL0679 HSCL0679

Explanation: Cannot change the pending MCS value for port group because some logical ports in the port group are assigned to running partitions.

Problem determination: After a managed system reboot they will become inactive if this operation is allowed.

HSCL067A HSCL067A

Explanation: Some Logical Ports belonging to Port Group are unavailable now due to change in MCS Value.

Problem determination: If the problem persists,

HSCL067B • HSCL0689

contact your next level of support or your service provider.

HSCL067B HSCL067B

Explanation: Logical Port belonging to port Group of HEA cannot be activated due to Pending MCS Value.

Problem determination: Either change the Pending MCS value or change the profile and try it again.

HSCL067C HSCL067C

Explanation: Logical HEA assigned to partition failed to be deleted.

Problem determination: Please retry the partition activation.

HSCL067D HSCL067D

Explanation: Wrong Speed Duplex combination for Physical Port belonging to Port Group, as either both speed and duplex should be AUTO or both should not be AUTO.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL067E HSCL067E

Explanation: Cannot Create Logical HEA for partition.

Problem determination: Please retry the partition activation.

HSCL067F HSCL067F

Explanation: Invalid Pending MCS Value. The Pending MCS Value for Port Group is not a Valid MCS Value.

Problem determination: Check the Value and Try it again with Valid MCS Value.

HSCL0680 HSCL0680

Explanation: Cannot Have more than One Logical Port Per Physical Port.

Problem determination: Change the Profile and Try it again.

HSCL0682 HSCL0682

Explanation: Cannot Activate With Logical Ports Belonging to HEA Adapter, as the HEA Adapter State is Non Functional

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0683 HSCL0683

Explanation: Logical Port belonging to port Group of HEA Cannot be activated due to Current MCS Value.

Problem determination: Either change the Current MCS Value or Change the Profile and try it again.

HSCL0684 HSCL0684

Explanation: Memory Region Value defined in the LHEA Capability for HEA Adapter is not valid.

Problem determination: Correct the Memory Region Value and try it again.

HSCL0685 HSCL0685

Explanation: partition Id is not a valid partition ID.

Problem determination: Check the partition ID and try it again.

HSCL0686 HSCL0686

Explanation: Cannot Set Logical HEA to specified partition ID because of Insufficient System Firmware Memory.

Problem determination: Reduce the maximum Memory in the Profile and try it again.

HSCL0687 HSCL0687

Explanation: The LHEA definition in this partition profile for HEA does not match the hardware present in the server.

Problem determination: Please remove the logical port(s) specified for this LHEA, and respecify logical ports from the present hardware.

HSCL0688 HSCL0688

Explanation: HEA dynamic partitioning recovery Failed. Some operations might have succeeded despite the failures.

Problem determination: Please try lshwres command to verify it.

HSCL0689 HSCL0689

Explanation: Logical Partition can not be designated as the promiscuous partition.

Problem determination: To allow this designation to be accepted, you must ensure no other partitions have logical ports on this physical port. If so, you must reactivate them without the logical ports to clear their usage of the physical port.

HSCL068A HSCL068A

Explanation: Logical port can not be assigned to partition because this partition is not the promiscuous partition for the physical port.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL068B HSCL068B

Explanation: The partition cannot be activated because HEA is missing.

Problem determination: Remove the HEA from the profile, then try the operation again.

HSCL068C HSCL068C

Explanation: Port group specified of the HEA is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL068D HSCL068D

Explanation: Physical port specified belonging to port group of the HEA is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0750 HSCL0750

Explanation: There is an insufficient amount of system memory available to activate this partition.

Problem determination: If you want to activate this partition with this HCA, you must reduce the amount of memory required for this partition, or you must free sufficient system memory. Some of your options are: 1. Decrease the memory settings in the profile you are trying to activate. 2. Remove memory from any shutdown dedicated memory partitions. 3. Remove memory from any running dedicated memory partition.

HSCL07C0 HSCL07C0

Explanation: The virtual SCSI server adapter cannot be created because the partition does not have virtual I/O server capability. Only i5/OS partitions in IBM System i5, eServer i5, or virtual I/O server partitions have virtual I/O server capability.

HSCL07C1 HSCL07C1

Explanation: The virtual serial client adapter cannot be created because the partition does not have virtual I/O server capability.

HSCL07C2 HSCL07C2

Explanation: Managed system was in checkstop state and unable to send the dump. A post-checkstop IPL was initiated. Please retry the operation.

Problem determination: Perform the operation again after the system was re-IPLed. If the problem persists, contact your next level of support or your service provider.

HSCL07C3 HSCL07C3

Explanation: Failed to save the IPL source in the partition information data area on the partition

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07C4 HSCL07C4

Explanation: Failed to save the partition workload group in the partition information data area on the partition

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07C5 HSCL07C5

Explanation: This operation cannot be performed because the management console is not connected to the service processor. Check the connection and try the operation again.

Problem determination: Ensure that the management console is connected to the service processor. If the problem persists, contact your next level of support or your service provider.

HSCL07C6 HSCL07C6

Explanation: Cannot use the huge page memory regions resource setting. Check whether the setting is valid or not.

Problem determination: Ensure the page setting is correct. If the problem persists, contact your next level of support or your service provider.

HSCL07C7 HSCL07C7

Explanation: There is not enough huge page memory regions. Check that there is enough huge page memory regions available to activate the partition. If not, create a new profile or modify the existing profile with the available resources, then activate the partition. If the partition must be activated with these resources, deactivate any running partition(s) using the resource then activate this partition.

Problem determination: Check the managed system properties window to ensure that enough pages of huge page memory is available to activate the partition. If there is not enough available pages of huge page memory, create a new profile or modify the existing profile with the available resources and then activate the partition. If the partition must be activated at any cost, deactivate any running partition using the resource, and activate the partition. If the problem persists, contact your next level of support or your service provider.

HSCL07C8 HSCL07C8

Explanation: Operation failed to allocate huge page memory regions for the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07C9 HSCL07C9

Explanation: There is not enough Barrier Synchronization Register (BSR) arrays.

Problem determination: Check that there is enough BSR arrays available to activate the partition. If not, create a new profile or modify the existing profile with the available resources, then activate the partition. If the partition must be activated with these resources, deactivate any running partition(s) using the resource then activate this partition.

HSCL07CA HSCL07CA

Explanation: Cannot use the Barrier Synchronization Register (BSR) arrays resource setting.

Problem determination: Check whether the setting is valid or not.

HSCL07CB HSCL07CB

Explanation: Operation failed to allocate Barrier Synchronization Register (BSR) arrays for the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07CC HSCL07CC

Explanation: Failed to save the partition MSP attribute in the partition information data area on the partition

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07CD HSCL07CD

Explanation: Failed to save the partition time reference attribute in the partition information data area on the partition

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07CE HSCL07CE

Explanation: Dump not allowed; dump initiation deactivated.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07CF HSCL07CF

Explanation: Dump offload is not allowed; dump offload is already in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07D0 HSCL07D0

Explanation: This partition is not bootable therefore a profile cannot be generated according to the partition's current configuration.

Problem determination: A "Save profile" cannot be done when the partition is not bootable. The resource of this partition might have been taken by another partition. Try to activate the partition with an appropriate profile.

HSCL07D1 HSCL07D1

Explanation: This logical partition profile is currently active in its logical partition and cannot be modified or deleted. To make the profile inactive, bring the partition to the Not Activated state, then repeat the operation.

Problem determination: Partition profiles that are active in a logical partition cannot be deleted. Perform an operating system reset on the partition to bring it to the Not Activated state, at which time the profile will no longer be active. For details, see Resetting the operating system on a partition. If it still fails, contact your next level of support or your service provider.

HSCL07D2 HSCL07D2

Explanation: This logical partition profile is the logical partition's default profile and cannot be deleted. If you still want to delete it, change the default profile for this logical partition or, if necessary, create another logical partition profile to be the default profile.

Problem determination: All logical partitions must have at least one partition profile, which is designated as the default profile because it is the profile implicitly used when the logical partition is activated with no profile specified. If you still want to delete it, change the default profile for this logical partition (create another logical partition profile if necessary). If it still fails, contact your next level of support or your service provider.

HSCL07D3 HSCL07D3

Explanation: The logical partition profile could not be found in the management console save area. The management console is either out of sync with the console save area, or has been corrupted. Rebuild this logical partition profile's managed system.

Problem determination: Ensure that the inputs are correct. Restore the profile data. If the problem persists, contact your next level of support or your service provider.

HSCL07D4 HSCL07D4

Explanation: The specified profile named already exists for this logical partition. Choose a different name for the new system profile.

Problem determination: All partition profiles for a logical partition must have unique names. Choose a different name for the new profile. If the problem persists, contact your next level of support or your service provider.

HSCL07D5 HSCL07D5

Explanation: Creation of partition profiles for the full system partition is not allowed.

Problem determination: You must use one of the predefined partition profiles for the full system partition.

HSCL07D6 HSCL07D6

Explanation: You cannot delete full system partition profiles.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07D7 HSCL07D7

Explanation: You cannot modify the full system partition profile's properties.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07D8 HSCL07D8

Explanation: Deleting default profile associations within the current context is not allowed.

HSCL07D9 HSCL07D9

Explanation: Setting a default profile association is only allowed during create.

HSCL07DA HSCL07DA

Explanation: The partition profile could not be found in the management console save area. The management console is either out of sync with the save area or the save area has been corrupted.

Problem determination: Rebuild this partition profile's managed system.

HSCL07DB HSCL07DB

Explanation: An attempt to create a profile failed.

Problem determination: Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL07DC HSCL07DC

Explanation: An attempt to modify a profile failed.

Problem determination: Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL07DD HSCL07DD

Explanation: The processing resources settings in the partition profile are not valid. Check profile processing resource setting.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07DE HSCL07DE

Explanation: The partition profile's 5250 CPW setting is not valid. Check profile processing resource setting.

Problem determination: Check the 5250 CPW. If the problem persists, contact your next level of support or your service provider.

HSCL07DF HSCL07DF

Explanation: Virtual slot 0 and 1 are set to default as virtual serial adapters when a partition is created. No modification can be made regarding these 2 slots.

HSCL07E0 HSCL07E0

Explanation: The partition profile could not be found in the database. Perform a rebuild managed system operation, and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL07E1 HSCL07E1

Explanation: An error occurred while changing the default profile for the partition. Retry the operation.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL07E2 HSCL07E2

Explanation: Required processor information is not specified in the partition profile. Make sure values are provided in the partition profile for minimum processing units, desired processing units, maximum processing units, processing mode, and sharing mode.

Problem determination: Ensure that the setting is valid. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL07E3 HSCL07E3

Explanation: Failed to delete the partition profile from partition.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL07E5 HSCL07E5

Explanation: The critical I/O setting is incorrect. Check the setting and try again.

Problem determination: Ensure the tagged I/O setting is correct. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL07E6 HSCL07E6

Explanation: At least one of the type 1 reserved memory settings is not specified.

Problem determination: Specify a value for minimum

memory, desired memory, and maximum memory in the type 1 reserved memory settings

HSCL07E7 HSCL07E7

Explanation: At least one of the type 2 reserved memory settings is not specified.

Problem determination: Specify a value for minimum memory, desired memory, and maximum memory in the type 2 reserved memory settings.

HSCL07E8 HSCL07E8

Explanation: SNI device IDs may not be specified in this profile because the managed system does not support SNI message passing.

Problem determination: No recovery action is needed.

HSCL07E9 HSCL07E9

Explanation: SNI device IDs may not be specified in this profile because the partition is not AIX or Linux.

Problem determination: No recovery action is needed.

HSCL07EA HSCL07EA

Explanation: SNI device IDs may not be specified in this profile because no SNI adapters are installed in the managed system.

HSCL07EB HSCL07EB

Explanation: The partition specified is over the maximum number of partitions supported on the system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07EC HSCL07EC

Explanation: The specified profile named already exists for this logical partition. Choose a different name for the new system profile or use the force option to overwrite the existing profile.

Problem determination: All partition profiles for a logical partition must have unique names. Choose a different name for the new profile or use the force option to overwrite the existing profile. If the problem persists, contact your next level of support or your service provider.

HSCL07ED HSCL07ED

Explanation: The specified profile named is a full system profile and cannot be overwritten. Choose a different name for the new full system profile.

Problem determination: All full system profiles must have unique names. If the problem persists, contact your next level of support or your service provider.

HSCL07EE HSCL07EE

Explanation: The HPT ration specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07EF HSCL07EF

Explanation: The partition type specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL07F0 HSCL07F0

Explanation: The affinity group ID specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0814 HSCL0814

Explanation: The managed system does not support this operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0815 HSCL0815

Explanation: An internal error occurred.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCL0817 HSCL0817

Explanation: The managed system cannot perform this operation at this time.

Problem determination: This condition is temporary. Try the operation again later.

HSCL0819 HSCL0819

Explanation: A system dump cannot be performed because system dumps have been disabled for this managed system.

Problem determination: System dumps can be enabled using the Advanced System Management interface, or the management console (POWER6 servers only).

HSCL081A HSCL081A

Explanation: This request was incorrectly sent to the wrong service processor.

Problem determination: This could be because a service processor failover was in progress at the time the request was sent. Try the operation again. If this error persists, contact your service representative.

HSCL081B HSCL081B

Explanation: A system dump already exists on the managed system.

Problem determination: Offload the existing system dump, then initiate the system dump again.

HSCL081C HSCL081C

Explanation: A service processor or power subsystem dump already exists.

Problem determination: Offload the existing dump, then initiate the dump again.

HSCL081D HSCL081D

Explanation: A system dump is already in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL081E HSCL081E

Explanation: An unknown error occurred.

Problem determination: Try the operation again. If this error persists, contact your hardware service representative.

HSCL081F HSCL081F

Explanation: The dump cannot be initiated due to an unknown error.

Problem determination: Update your management console software, and try the operation again.

HSCL0823 HSCL0823

Explanation: A service processor or power subsystem dump cannot be performed because those types of dumps have been disabled for this managed system.

Problem determination: Service processor and power subsystem dumps can be enabled using the Advanced System Management interface.

HSCL0825 HSCL0825

Explanation: The managed system does not support node service processors.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0826 HSCL0826

Explanation: A dump of this service processor cannot be performed at this time because the dump storage area on this service processor is full.

Problem determination: Offload the service processor dumps, then initiate a dump of this service processor again.

HSCL0827 HSCL0827

Explanation: A service processor dump cannot be performed because service processor dumps have been disabled for this managed system.

Problem determination: Service processor dumps can be enabled using the Advanced System Management interface.

HSCL0828 HSCL0828

Explanation: The service processor dump cannot be initiated because the service processor has been manually deconfigured by a user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0829 HSCL0829

Explanation: A node service processor is not installed at specified location.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL082A HSCL082A

Explanation: The service processor dump cannot be initiated because the service processor has been automatically deconfigured by the system due to an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL082B HSCL082B

Explanation: The node service processor dump cannot be initiated because the internal communication path between the primary service processor and the node service processor has not been established.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCL082C HSCL082C

Explanation: The node service processor location code is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL082D HSCL082D

Explanation: A dump of this service processor is already in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL082F HSCL082F

Explanation: This command is not supported for a POWER5 server.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0831 HSCL0831

Explanation: The service processor command failed due to an unknown error.

Problem determination: Update your management console software, and try the operation again.

HSCL09C6 HSCL09C6

Explanation: Could not find the system profile in memory. It might be corrupted. Restore the profile data.

Problem determination: The system profile might be corrupted. Restore the profile data. If the problem persists, delete and re-create a new system profile. If the problem persists, contact your next level of support or your service provider.

HSCL09C7 HSCL09C7

Explanation: The specified system profile name already exists for this managed system. Choose a different name for the new system profile.

Problem determination: Every system profile created

for an individual managed system must have a unique name. Choose a different name for the new system profile. If it still fails, contact your next level of support or your service provider.

HSCL09C8 HSCL09C8

Explanation: Could not open the Copy System Profile dialog. Try again.

Problem determination: Log off the HMC, and log back in. Try the task again. If it still fails, contact your next level of support or your service provider.

HSCL09C9 HSCL09C9

Explanation: Could not copy the system profile. Try again.

Problem determination: Log off the HMC, and log back in. Try the task again. If it still fails, contact your next level of support or your service provider.

HSCL09CA HSCL09CA

Explanation: Could not delete the system profile. Try the task again.

Problem determination: Log off the HMC, and log back in. Try the task again. If it still fails, contact your next level of support or your service provider.

HSCL09CB HSCL09CB

Explanation: Cannot activate a system profile when there are partitions not in the Not Activated state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL09CC HSCL09CC

Explanation: Cannot activate a Full System partition profile when the managed system is powered on with Partition Standby.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL09CD HSCL09CD

Explanation: Cannot activate user-defined partition profiles when the managed system is powered on with Full System Partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL09CE HSCL09CE

Explanation: Partition profiles included in a System Profile must all be of the same type.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL09CF HSCL09CF

Explanation: Validation of system profile failed. Retry the operation.

Problem determination: Retry the operation. If it still fails, contact your next level of support or your service provider.

HSCL09D0 HSCL09D0

Explanation: Cannot validate system profile if the managed system is not in Operating or Standby state.

Problem determination: Ensure that the managed system is in the Operating or Standby state and then retry the operation. If it still fails, contact your next level of support or your service provider.

HSCL09D1 HSCL09D1

Explanation: Cannot validate system when the managed system is powered-on with the Full System Partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL09D2 HSCL09D2

Explanation: The partition or partitions failed to activate.

Problem determination: A logical partition that is part of the system profile failed to activate. Ensure that you have enough available resources to activate the desired partition profile. If so, rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09D3 HSCL09D3

Explanation: An unknown error occurred during system profile activation. Retry the operation.

Problem determination: Rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09D4 HSCL09D4

Explanation: Update of the system profile failed.

Problem determination: Please retry the operation.

HSCL09D5 HSCL09D5

Explanation: An unknown error occurred during system profile creation. Retry the operation.

Problem determination: Rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09D6 HSCL09D6

Explanation: An unknown error occurred during deletion of the system profile. Retry the operation.

Problem determination: Rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09D7 HSCL09D7

Explanation: The system profile that you have chosen to validate could not be found.

Problem determination: The system profile might be corrupted. Restore the profile data. If the problem persists, delete and re-create a new system profile. If the problem persists, contact your next level of support or your service provider.

HSCL09D8 HSCL09D8

Explanation: The System profile was not found in the managed system.

Problem determination: A profile that is part of the system profile cannot be found in the managed system. Rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09D9 HSCL09D9

Explanation: System profile contains multiple profiles belonging to the same partition. Take one of the profiles out of the system profile list and try again.

Problem determination: There is more than one profile in the system profile that belongs to the same partition. Ensure that each partition has at most one profile in the system profile, and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09DA HSCL09DA

Explanation: A profile is listed more than once in the system profile. Take one of the profiles out of the system profile list and try again.

Problem determination: A profile is listed more than once in the system profile. Ensure that all partition profiles are only listed once in the system profile, and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09DB HSCL09DB

Explanation: Partition could not be activated because it is already active.

Problem determination: This error occurs when a logical partition listed in the system profile is already activated. If the logical partition is not activated, rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09DC HSCL09DC

Explanation: If a full system partition profile is part of a system profile, there can be no other partition profiles listed in that system profile.

Problem determination: If a full system partition profile is part of a system profile, there can be no other partition profiles listed in that system profile. Either take all other profiles except the full system partition profile out of the system profile, or remove the full system partition profile from the system profile. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09DD HSCL09DD

Explanation: The partition profile ID does not correspond to a valid profile. Retry the command.

Problem determination: Rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL09DE HSCL09DE

Explanation: The system profile cannot be created because no user-defined name was given. Ensure to enter a user-defined name, and try the operation again.

Problem determination: No user-defined system profile name was given during system profile creation. Retry the creation operation again, this time making sure to enter a user-defined name. If the problem persists, contact your next level of support or your service provider.

HSCL09DF HSCL09DF

Explanation: The system profile cannot be created because there are no partition profiles currently included in the system profile. Specify partition profiles for the system profile or click "Cancel" .

Problem determination: Partition profiles for the system profile must be specified during system profile creation. Retry the system profile creation operation, making sure to add at least one partition profile to the system profile. If the problem persists, contact your next level of support or your service provider.

HSCL09E0 HSCL09E0

Explanation: The profile belongs to a partition that currently has a profile already included in the system profile. Select a profile from a different partition or first remove the conflicting partition's profile from the system profile, then add the desired profile again.

HSCL09E1 HSCL09E1

Explanation: There is currently a system profile with the specified name created for this system. Enter a unique name.

Problem determination: If there is not a system profile with the specified name displayed in the console, refresh the console and try the command again. If it fails again, rebuild the managed system. Restart the management console and then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL09E2 HSCL09E2

Explanation: Validation results for system profile.

Problem determination: This message is for informational purposes only regarding the outcome of system profile validation. No recovery action should be taken.

HSCL09E3 HSCL09E3

Explanation: Activation results for system profile.

Problem determination: This message is for informational purposes only regarding the outcome of system profile validation. No recovery action should be taken.

HSCL09E4 HSCL09E4

Explanation: The specified System profile action could not be completed because shared memory partition profiles are not supported in system profiles.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL09E5 HSCL09E5

Explanation: The specified System profile could not be activated because it contains a shared memory profile.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL09E6 HSCL09E6

Explanation: Profiles for the partitions cannot be included in the system profile because those partitions are remote restart capable.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0BB9 HSCL0BB9

Explanation: Polling of LED failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0BBA HSCL0BBA

Explanation: There was an error while invoking CIM method.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0BBB HSCL0BBB

Explanation: Can not get LED.

Problem determination: Rebuild the managed system. Retry the operation. Restart the management console and then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL0DB0 HSCL0DB0

Explanation: A Soft Operating System Reset can be issued for the managed system when it is in the Operating state only if it was powered on in Full System Partition mode.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0DB1 HSCL0DB1

Explanation: An Operating System Reset can be issued for a Logical Partition only if the partition is in the Running state.

Problem determination: If the problem persists,

HSCL0DB2 • HSCL0FA7

contact your next level of support or your service provider.

HSCL0DB2 HSCL0DB2

Explanation: An operating system reset can be issued for a logical partition only if the partition is in the running or starting state.

Problem determination: Rebuild the managed system. Try the task again.

HSCL0DB3 HSCL0DB3

Explanation: An Operating System Shutdown can be issued for the managed system when it is in the Operating state only if it was powered on in Full System Partition mode.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0DB4 HSCL0DB4

Explanation: An Operating System shut down cannot be performed because the operating system image running does not support remote execution of this task from the management console.

Problem determination: Ensure the network connection between partition and management console is working. Rebuild the managed system. Try the task again.

HSCL0DB5 HSCL0DB5

Explanation: An Operating System Shut down can be issued for a logical partition only if the partition is in the Running state.

Problem determination: A partition must be in the Running state in order for an operating system shutdown operation to be performed. Ensure that the partition's state is Running, and try the task again. If your partition is in a state other than Running, but you are sure that the partition is in fact running, rebuild the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0DB7 HSCL0DB7

Explanation: Fail to shut down partition through operation system command.

Problem determination: Ensure that the network between the management console and the partition is working. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL0FA1 HSCL0FA1

Explanation: The managed system's service processor could not open a virtual terminal session.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0FA2 HSCL0FA2

Explanation: All available virtual terminal sessions have been opened and are in use.

Problem determination: To force a new open session, perform a Close Terminal Session operation which frees up the session.

HSCL0FA3 HSCL0FA3

Explanation: Unable to close the virtual terminal session.

Problem determination: Issue a Close Virtual Terminal Connection operation.

HSCL0FA4 HSCL0FA4

Explanation: There is no virtual terminal session with specified session number open.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL0FA5 HSCL0FA5

Explanation: The Virtual Terminal cannot be opened to managed system because there's an active device on the S1 serial port.

Problem determination: Please ensure the device is inactive before retrying the operation. The device is considered inactive when the DCD (Data Carrier Detect) is not asserted.

HSCL0FA6 HSCL0FA6

Explanation: Connection has closed.

Problem determination: Connection was closed by you or another user. Close the window and open another terminal session.

HSCL0FA7 HSCL0FA7

Explanation: The open failed. The session may already be open on another management console. The server may not be ready to accept connections.

Problem determination: Try the Close Terminal Connection task then retry to open the session again. Closing the session will terminate the session of other users. If the problem persists, contact your next level of

support or your service provider.

HSCL0FA8 HSCL0FA8

Explanation: Error in communication path to the partition.

Problem determination: The managed system is not accepting connections. Check the network connection to the server. Wait for few minutes and retry the connection. If the connection still fails, restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL0FA9 HSCL0FA9

Explanation: Internal error encountered.

Problem determination: Wait for few minutes and retry the connection. Shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL0FAA HSCL0FAA

Explanation: Lost connection to the Managed System. Attempting to reconnect.

Problem determination: A network problem has been encountered, or the service processor has gone offline. The session is attempting to reconnect to the server. If the server state is in No Connection or Error state, then the connection attempt will fail.

HSCL0FAB HSCL0FAB

Explanation: A terminal session is already open for this partition. Only one open session is allowed for a partition.

Problem determination: Another user is using the virtual terminal for this partition. Use the Close Terminal Connection task to disconnect the other session. Closing the session will terminate the session of the other user.

HSCL0FAC HSCL0FAC

Explanation: A terminal session is already open for this partition. Only one open session is allowed for a partition. Exiting.

Problem determination: Another user is using the virtual terminal for this partition. Use the Close Terminal Connection task to disconnect the other session. Closing the session will terminate the session of the other user.

HSCL0FAD HSCL0FAD

Explanation: The connection to the server is not available. Exiting.

Problem determination: A network problem has been encountered, or the service processor has gone offline. Wait for few minutes and retry the connection. Ensure the network connection between the management console and the managed system is good. Shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL0FAE HSCL0FAE

Explanation: The connection to the server is not available.

Problem determination: A network problem has been encountered, or the service processor has gone offline. Wait for few minutes and retry the connection. Ensure the network connection between the management console and the managed system is good. Shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL0FAF HSCL0FAF

Explanation: Received invalid connection information. Operation cancelled.

Problem determination: Close the terminal window and open another window. If the problem persists, contact your next level of support or your service provider.

HSCL0FB0 HSCL0FB0

Explanation: Received invalid connection information. Operation cancelled. Exiting.

Problem determination: Close the terminal window and open another window. If the problem persists, contact your next level of support or your service provider.

HSCL0233C HSCL0233C

Explanation: The password entered contains an invalid character.

Problem determination: Passwords cannot contain the following character(s): double-quote, single-quote, and back-slash. Please retry command.

(HSCL1xxx) Reference codes

HSCL1195 HSCL1195

Explanation: Unable to back up the profile data to the backup file. Try again.

Problem determination: Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1196 HSCL1196

Explanation: You do not have read access permission on the backup file. Refresh the interface and check whether the operation was completed. If not, try the operation again.

Problem determination: Try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL1197 HSCL1197

Explanation: Unable to read the profile data's backup file. Refresh the interface and check whether the operation was completed. If not, try the operation again.

Problem determination: Try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL1198 HSCL1198

Explanation: Cannot find backup file for profile data. Select a valid, existing backup file.

Problem determination: Try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL1199 HSCL1199

Explanation: A full restore is not permitted when there are logical partitions not in Not Activatded state. A full restore can only be issued when the managed system was powered on and all partitions are in the Not Activated state.

Problem determination: Verify the managed system was powered-on to run in Partition Standby. Try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL119A HSCL119A

Explanation: There was an I/O error while backing up the profile data. Try again.

Problem determination: Try the task again. Shut down and restart the HMC, and then try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL119B HSCL119B

Explanation: The restore profile data operation failed. Try again.

Problem determination: Try the task again. Shut down and restart the HMC, and then try the task again. If the operation still fails, contact your next level of support or your service provider.

HSCL119C HSCL119C

Explanation: Cannot initialize profile data when the managed system was not in the Standby or Operating state, or when there is any partition not in the Not Activated state.

Problem determination: Verify that the managed system is in the Standby or Operating state, and that no logical partitions are running. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL119D HSCL119D

Explanation: Cannot restore the profile data if the managed system is not int the Standby or Ready state.

Problem determination: Verify that the managed system is in the Standby or Ready state, and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL119E HSCL119E

Explanation: Cannot initialize the profile data if the managed system is not in the Standby or Ready state.

Problem determination: Verify that the managed system is in the Standby or Ready state, and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL119F HSCL119F

Explanation: The backup file used to restore the profile data is not valid. Its file size is not correct. Select a valid backup file.

Problem determination: The backup file selected is not valid. The file might be corrupted. Try the task again. Select another backup file and try the task again. If the problem persists, contact your next level of

HSCL11A0 • HSCL11AC

support or your service provider.

HSCL11A0 HSCL11A0

Explanation: Cannot restore the profile data if the managed system is not in the correct state. The managed system must be in the Operating or Standby state.

Problem determination: Verify that the managed system is in Operating or Standby state. Try the task again.

HSCL11A1 HSCL11A1

Explanation: Cannot initialize the profile data if the managed system is not in the correct state. The managed system must be in the Operating or Standby state.

Problem determination: Verify that the managed system is in Operating or Standby state. Try the task again.

HSCL11A2 HSCL11A2

Explanation: Could not display the backup dialog for the managed system. Try the operation again.

Problem determination: Try the task again. Log off the HMC, and then log back in. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL11A3 HSCL11A3

Explanation: Could not back up the profile data for the managed system.

Problem determination: Refresh the graphical user interface. Try the task again. Shut down and restart the HMC, and then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL11A4 HSCL11A4

Explanation: Cannot back up profile data to the default backup file.

Problem determination: Cannot back up the profile data to the default backup file. Choose a different backup file name. If the problem persists, contact your next level of support or your service provider.

HSCL11A5 HSCL11A5

Explanation: Could not display the remove backup dialog for the managed system. Try again.

Problem determination: Try the task again. Log off the HMC, and log back in. Try the task again. Contact your next level of support or your service provider.

HSCL11A6 HSCL11A6

Explanation: Could not remove the backup file from the managed system.

Problem determination: Refresh the graphical user interface. Try the task again. Shut down and restart the HMC, and then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL11A7 HSCL11A7

Explanation: No backup file has been selected for the operation. Select a backup file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11A9 HSCL11A9

Explanation: Could not initialize the profile data task on the managed system. Refresh the interface and check whether the operation was performed. If not, try the operation again.

Problem determination: Refresh the graphical user interface. Ensure the operation has been performed and displays on the graphical user interface. If not, repeat the operation. If the problem persists, contact your next level of support or your service provider.

HSCL11AA HSCL11AA

Explanation: Could not restore the profile data task on the managed system. Refresh the interface and check whether the operation was performed. If not, try the operation again.

Problem determination: Refresh the graphical user interface. Try the task again. Rebuild the managed system. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL11AB HSCL11AB

Explanation: Could not display the recover partition data dialog for the managed system.

Problem determination: Try the task again. Log off the HMC, and then log back in. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL11AC HSCL11AC

Explanation: Could not perform the recover logical partition data task on the managed system.

Problem determination: Refresh the graphical user interface. Try the task again. Rebuild the managed

system. If the problem persists, contact your next level of support or your service provider.

HSCL11AD HSCL11AD

Explanation: Could not display the Rebuild Computer System dialog for managed system.

Problem determination: Refresh the graphical user interface and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL11B0 HSCL11B0

Explanation: The pool ID specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11B1 HSCL11B1

Explanation: An I/O entitled memory amount cannot be specified when automatic I/O entitled memory management is specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11B2 HSCL11B2

Explanation: The amount of I/O entitled memory for the partition must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11B3 HSCL11B3

Explanation: Shared memory partitions can only use shared processors.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11B4 HSCL11B4

Explanation: The processor mode must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11C0 HSCL11C0

Explanation: The Virtual I/O Server partition cannot be deleted because it is assigned to the reserved storage device pool or the shared memory pool.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCL11C2 HSCL11C2

Explanation: A shared memory partition cannot have any physical I/O adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11C3 HSCL11C3

Explanation: The amount of I/O entitled memory cannot exceed the size of the shared memory pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11C4 HSCL11C4

Explanation: The amount of I/O entitled memory must be greater than zero and it cannot exceed the desired amount of logical memory for the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11C5 HSCL11C5

Explanation: The memory mode is not valid because the managed system does not support Active Memory Sharing.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11C6 HSCL11C6

Explanation: A shared memory pool is not configured.

Problem determination: Configure the shared memory pool, then try the operation again.

HSCL11C7 HSCL11C7

Explanation: A shared memory partition cannot have huge page memory.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11C9 HSCL11C9

Explanation: A shared memory partition cannot have Barrier Synchronization Register arrays.

Problem determination: If the problem persists,

HSCL11CA • HSCL1207

contact your next level of support or your service provider.

HSCL11CA HSCL11CA

Explanation: A shared memory partition cannot use Host Ethernet Adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11CB HSCL11CB

Explanation: A shared memory partition cannot have any Host Channel Adapter resources assigned to it.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11CC HSCL11CC

Explanation: A Virtual I/O Server partition cannot use shared memory.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL11CD HSCL11CD

Explanation: The Virtual I/O Server partition cannot be shut down because it is being used to provide paging services for shared memory partitions.

Problem determination: Shut down the shared memory partitions first, then shut down the Virtual I/O Server partition.

HSCL11CE HSCL11CE

Explanation: A shared memory partition cannot have reserved memory.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1200 HSCL1200

Explanation: The managed system does not allow customized MAC addresses to be specified from the management console.

HSCL1201 HSCL1201

Explanation: The managed system does not support Quality of Service virtual Ethernet priority levels.

HSCL1202 HSCL1202

Explanation: The MAC address is not valid because the multicast bit is on. The multicast bit is 0x010000000000.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1203 HSCL1203

Explanation: The MAC address is not valid because the locally administered address bit is off. The locally administered address bit is 0x020000000000.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1204 HSCL1204

Explanation: The list of allowed MAC addresses for the virtual Ethernet adapter in the slot contains the duplicate MAC addresses.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1205 HSCL1205

Explanation: The list of allowed MAC addresses for the logical port on the HEA adapter in the slot contains the duplicate MAC addresses.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1206 HSCL1206

Explanation: The number of MAC addresses in the list of allowed MAC addresses for the virtual Ethernet adapter has exceeded the maximum MAC addresses.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1207 HSCL1207

Explanation: The number of MAC addresses in the list of allowed MAC addresses for the logical port on the HEA adapter has exceeded the maximum MAC addresses.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1208 HSCL1208

Explanation: The Quality of Service priority level specified for the virtual Ethernet adapter is not valid. Valid values are "none", or 0 to 7, inclusive.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1209 HSCL1209

Explanation: A MAC address for the virtual Ethernet adapter in the slot cannot be specified because the managed system does not allow customized MAC addresses to be specified from the management console.

HSCL120A HSCL120A

Explanation: Allowed OS MAC addresses for the virtual Ethernet adapter in the slot cannot be specified because the managed system does not allow customized MAC addresses to be specified from the management console.

HSCL120B HSCL120B

Explanation: A Quality of Service priority level cannot be specified for the virtual Ethernet adapter in the slot because the managed system does not allow Quality of Service priority levels.

HSCL120C HSCL120C

Explanation: Allowed OS MAC addresses for logical port on the HEA adapter cannot be specified because the managed system does not allow customized MAC addresses to be specified from the management console.

HSCL1213 HSCL1213

Explanation: A virtual Ethernet adapter with the same MAC address already exists.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1214 HSCL1214

Explanation: The MAC address prefix must have the locally administered bit set. The locally administered bit is the 0x02 bit in byte zero of the prefix.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1220 HSCL1220

Explanation: The managed system does not support changing the properties of a virtual Ethernet adapter that is assigned to a running partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1221 HSCL1221

Explanation: Modification of virtual I/O resources failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1230 HSCL1230

Explanation: Adapter is already in dedicated mode or it is not assigned to an IO slot.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1231 HSCL1231

Explanation: Adapter is in SRIOV mode.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1233 HSCL1233

Explanation: The command failed because the adapter is in use by partitions.

Problem determination: Remove the adapter's resources from the specified partitions and try the operation again.

HSCL1234 HSCL1234

Explanation: The adapter cannot support additional logical ports.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1235 HSCL1235

Explanation: The adapter is not in a running state.

Problem determination: If the adapter is initializing, try again when the adapter is running.

HSCL1236 • HSCL1245

HSCL1236 HSCL1236

Explanation: Adapter is not in SRIOV mode.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1237 HSCL1237

Explanation: Adapter is not SRIOV capable.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1238 HSCL1238

Explanation: The managed system does not support SRIOV.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1239 HSCL1239

Explanation: The number of logical ports in use exceeds the specified value..

Problem determination: Try the operation again with a larger number.

HSCL123A HSCL123A

Explanation: The operation cannot be completed because the management console does not support SRIOV operations.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL123D HSCL123D

Explanation: The profile contains SRIOV configuration information that is not valid.

Problem determination: This may have resulted from a failure to remove all SRIOV adapter usage before changing the adapter mode.

HSCL123E HSCL123E

Explanation: The SRIOV logical port defined for the virtual slot is incorrect because the capacity that was specified is not valid.

Problem determination: Valid values are 1 - 100.

HSCL123F HSCL123F

Explanation: The group ID specified is not valid.

Problem determination: The group ID must be a number from 1 to 1023.

HSCL1240 HSCL1240

Explanation: One of the SRIOV mappings that was specified has a missing or invalid value.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1241 HSCL1241

Explanation: The SRIOV logical port defined for the virtual slot is incorrect because the priority level that was specified is not valid.

Problem determination: Valid values are 0 - 7.

HSCL1242 HSCL1242

Explanation: The SRIOV logical port defined for this slot is incorrect because the tuning buffer ID that was specified is not valid.

Problem determination: Valid values are 0 - 254 and none.

HSCL1243 HSCL1243

Explanation: The tuning parameters that were specified are not valid.

Problem determination: The tuning parameters must be 2 to 8000 characters long, and only contain hexadecimal values (0-9 and A-F).

HSCL1244 HSCL1244

Explanation: The list of allowed MAC addresses for the SRIOV logical port in this slot contains duplicate MAC addresses.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1245 HSCL1245

Explanation: Logical port is not assigned to partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1246 HSCL1246

Explanation: The specified physical port already has the maximum number of logical ports that can be assigned..

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1247 HSCL1247

Explanation: The specified physical port already has the maximum number of promiscuous logical ports that can be assigned.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1248 HSCL1248

Explanation: The specified number of logical ports for the physical port exceeds the maximum of logical ports that are allowed for the specified physical port.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1249 HSCL1249

Explanation: Physical port cannot be found on the SRIOV adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL124A HSCL124A

Explanation: The specified number of logical ports allowed per physical port is greater than the maximum number of logical ports for the entire adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL124B HSCL124B

Explanation: The value specified for the port speed was rejected by the adapter.

Problem determination: Try the operation again with a different port speed.

HSCL124C HSCL124C

Explanation: The specified maximum number of logical ports allowed per physical port conflicts with the current number of logical ports in use by one of the physical ports.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL124D HSCL124D

Explanation: The management console cannot configure the SRIOV logical ports.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL124E HSCL124E

Explanation: Group ID has already been assigned to another SRIOV adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL124F HSCL124F

Explanation: The user does not have the appropriate authority to change the `promiscuous_mode` or the `diagnostic_mode` attributes.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1250 HSCL1250

Explanation: The specified port was not recognized.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1251 HSCL1251

Explanation: The SRIOV logical port defined for the virtual slot is incorrect because it has duplicate VLAN IDs.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1252 HSCL1252

Explanation: The SRIOV logical port defined for virtual slot is incorrect because the number of VLAN IDs exceeds the maximum allowed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1253 HSCL1253

Explanation: The SRIOV logical port defined for virtual slot is incorrect because the VLAN ID exceeds the maximum allowed value.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1254 HSCL1254

Explanation: The number of MAC addresses in the list of allowed MAC addresses for the SRIOV logical port in slot had exceeded the maximum of MAX addresses.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1255 HSCL1255

Explanation: The operation failed because you specified an invalid physical port ID.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1259 HSCL1259

Explanation: An internal error occurred.

Problem determination: Try the operation again. If the error persists, contact your service representative.

HSCL125A HSCL125A

Explanation: The set SRIOV physical port operation failed because you specified an invalid MTU.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL125B HSCL125B

Explanation: The set SRIOV physical port operation failed because you specified an invalid speed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL125C HSCL125C

Explanation: The set SRIOV physical port operation failed because you specified an invalid loopback.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL125D HSCL125D

Explanation: The set SRIOV physical port operation failed because you enabled receive flow control which is not supported by the adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL125E HSCL125E

Explanation: The set SRIOV physical port operation failed because you enabled transmit flow control which is not supported by the adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL125F HSCL125F

Explanation: The operation failed because you specified multiple adapter IDs. When paired with a physical port ID, only one adapter ID is allowed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1260 HSCL1260

Explanation: The SRIOV adapter ID is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1261 HSCL1261

Explanation: The SRIOV adapter is not in a valid state to be configured.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1262 HSCL1262

Explanation: The VLAN list for logical port is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1263 HSCL1263

Explanation: The MAC address filter is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1264 HSCL1264

Explanation: The maximum number of SRIOV logical ports supported by partition has been exceeded.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1265 HSCL1265

Explanation: The number of physical ports specified are invalid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1266 HSCL1266

Explanation: Unable to set adapter information for SRIOV adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1267 HSCL1267

Explanation: Unable to get tuning parameter data from managed system..

Problem determination: If the problem persists, contact your service representative.

HSCL1268 HSCL1268

Explanation: Unable to set tuning parameter data in the managed system with tuning paramter.

Problem determination: If the problem persists, contact your support representative.

HSCL1269 HSCL1269

Explanation: Physical port on SRIOV adapter is not an Ethernet port.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL126A HSCL126A

Explanation: Cannot add logical port because the VF limit of SRIOV adapter exceeds the configured limit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL126B HSCL126B

Explanation: A logical port from SRIOV adapter cannot be added because the adapter does not have any unconfigured logical ports.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL126C HSCL126C

Explanation: The logical port cannot be added because with personality-A of logical port, the total personality setting of physical port is more than 100.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL126D HSCL126D

Explanation: One of the logical ports on physical port on SRIOV adapter is already configured in diagnostic mode. Another logical port on the same physical port cannot be configured in diagnostics mode.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL126E HSCL126E

Explanation: One of the logical ports on the physical port is already configured in diagnostic mode.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL126F HSCL126F

Explanation: Logical port cannot be added to the partition as promiscuous mode since the number of promiscuous logical port supported by the phy is exceeding from it is supported, .

Problem determination: Try to delete the few of the logical port which are assigned to the partition as promiscuous mode.

HSCL1270 HSCL1270

Explanation: Partition is not assigned with any of the SRIOV logical port.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1271 HSCL1271

Explanation: With the addition of specified vlans will exceed the limit of logical port limit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1272 HSCL1272

Explanation: The number of MAC addresses specified in the list for SRIOV logical port has exceeded the maximum of supported MAC addresses.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1273 HSCL1273

Explanation: An error occurred while removing logical port and an error occurred during recovery as well.

Problem determination: Please run the rsthwres command to perform recovery.

HSCL1274 HSCL1274

Explanation: Virtual slot is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1275 HSCL1275

Explanation: Virtual slot for logical port is already in use by another virtual adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1276 HSCL1276

Explanation: Cannot add logical port because all slots are in use by other virtual adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1277 HSCL1277

Explanation: An error occurred while adding logical port and an error occurred during recovery as well.

Problem determination: Please run the rsthwres command to perform recovery.

HSCL1278 HSCL1278

Explanation: Sum of proposed logical port limit from each physical port is greater than supported logical port limit for SRIOV.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1279 HSCL1279

Explanation: Logical port assigned to physical port is greater than the new proposed configure-logical port limit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL127A HSCL127A

Explanation: For the physical port new proposed logical port limit is greater than physical port supported logical port limit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL127C HSCL127C

Explanation: SRIOV adapter does not support QoS, therefore personalityA should not be specified for logical port.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL127D HSCL127D

Explanation: Logical port cannot be added to the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL127E HSCL127E

Explanation: Logical port is assigned to partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL138A HSCL138A

Explanation: Unable to a get the socket connection to the CSP.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCL138B HSCL138B

Explanation: Unable to create an event listener for the managed system's service processor.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL138C HSCL138C

Explanation: Unable to find the Machine Type Mode Serial number of this HSC.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL138D HSCL138D

Explanation: Could not release the management framework socket.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL138F HSCL138F

Explanation: Could not get the management console host name. Check the network settings within the system configuration.

Problem determination: Check the network setting under system configuration, and then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1391 HSCL1391

Explanation: The management framework socket is not registered.

Problem determination: Make sure to not attempt any operations while the delete, rebuild, or restore profile data tasks are being performed. Execute the Rebuild managed systemtask.

HSCL1392 HSCL1392

Explanation: The management framework socket is either deleted or changed.

Problem determination: Do not execute any operations while the delete, rebuild, or restore profile data tasks are being performed. Execute the Rebuild managed system task.

HSCL1393 HSCL1393

Explanation: Could not load the list of IBM PC product names.

Problem determination: Shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1394 HSCL1394

Explanation: There was an I/O error while reading from memory.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1395 HSCL1395

Explanation: Could not launch the Confirmation dialog. Try again.

Problem determination: Refresh the graphical user interface. Try the task again. Log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL1396 HSCL1396

Explanation: Unable to initialize the HMC-CSP Version compatibility table.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1397 HSCL1397

Explanation: Could not determine the version of the firmware that is loaded on the service processor.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL1398 HSCL1398

Explanation: Could not determine what version of service processor firmware is compatible with this version of the management console.

Problem determination: Check the version of your managed system and the management console version first with Administration staff. Then determine the compatibility from the document, if they do match.

HSCL1399 HSCL1399

Explanation: The managed system does not have Virtual IO Server capability.

Problem determination: There is no recovery action necessary.

HSCL1400 HSCL1400

Explanation: The firmware operation failed.

Problem determination: Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1402 HSCL1402

Explanation: The operation failed.

HSCL1403 HSCL1403

Explanation: Could not display the dialog. Try the operation again.

Problem determination: Refresh the graphical user interface. Retry the operation. If it still fails, log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL1450 HSCL1450

Explanation: There is an insufficient number of unallocated processors to perform the operation.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1451 HSCL1451

Explanation: Attempted to allocate a number of processors below the minimum processor setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1452 HSCL1452

Explanation: Attempted to allocate a number of processors above the maximum processor setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1453 HSCL1453

Explanation: There is an insufficient amount of unallocated processing units to perform the operation.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1454 HSCL1454

Explanation: Attempted to allocate an amount of processing units below the minimum processing unit setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1455 HSCL1455

Explanation: Attempted to allocate an amount of processing units above the maximum processing setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1456 HSCL1456

Explanation: The processor setting exceeds the maximum system configuration.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1457 HSCL1457

Explanation: There is an insufficient amount of unallocated memory to perform the operation.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1458 HSCL1458

Explanation: Attempted to allocate an amount of memory below the minimum memory setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1459 HSCL1459

Explanation: Attempted to allocate an amount of memory above the maximum memory setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL145A HSCL145A

Explanation: The minimum memory amount is below the required amount of memory with the maximum specified.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL145B HSCL145B

Explanation: There is an insufficient amount of unallocated 5250 CPW to perform the operation.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL145C HSCL145C

Explanation: Attempted to allocate an amount of 5250 CPW below the minimum setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL145D HSCL145D

Explanation: Attempted to allocate an amount of 5250 CPW above the maximum setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL145E HSCL145E

Explanation: Attempted to allocate processing units greater than the maximum capacity allowed with the specified virtual processor setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL145F HSCL145F

Explanation: The ratio of assigned processing units to assigned virtual processors for the partition is less than the minimum ratio supported by the managed system.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1460 HSCL1460

Explanation: Attempted to set maximum processing units greater than the maximum capacity allowed with the specified virtual processor setting.

Problem determination: Ensure that the setting is

valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1461 HSCL1461

Explanation: The ratio of minimum processing units to minimum virtual processors for the partition is less than the minimum ratio supported by the managed system.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1462 HSCL1462

Explanation: Attempted to set minimum processing units greater than the maximum capacity allowed with the specified virtual processor setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1463 HSCL1463

Explanation: The ratio of maximum processing units to maximum virtual processors for the partition is less than the minimum ratio supported by the managed system.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1464 HSCL1464

Explanation: The partition is not currently configured for shared processing.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1465 HSCL1465

Explanation: The partition is not currently configured for dedicated processing.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1466 HSCL1466

Explanation: The partition specified is not valid. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1467 HSCL1467

Explanation: The partition specified is not valid. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1468 HSCL1468

Explanation: The I/O pool ID specified is not valid.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1469 HSCL1469

Explanation: The shared processor pool ID specified is not valid.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL146A HSCL146A

Explanation: The I/O adapter is not valid.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL146B HSCL146B

Explanation: The partition name specified has already been used by another partition. Specify a different name.

HSCL146C HSCL146C

Explanation: The partition name specified is not acceptable. Check the name and try again.

HSCL146D HSCL146D

Explanation: The partition is currently in a state where this configuration change is not allowed. Rebuild the managed system and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL146E HSCL146E

Explanation: The number of power controlling partitions for this partition is not valid. Check the setting and try again.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact

your next level of support or your service provider.

HSCL146F HSCL146F

Explanation: Changing from shared to dedicated processing is not allowed with the current processing setting.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1472 HSCL1472

Explanation: The SNI adapter specified is not valid. Check the entry and try again.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1473 HSCL1473

Explanation: Cannot perform atomic operation. Atomic operations are not enabled.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1474 HSCL1474

Explanation: The processing weight specified is not valid. Check the entry and try again.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1475 HSCL1475

Explanation: Unable to switch out or into manufacturing default configuration at this point.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1477 HSCL1477

Explanation: Unable to perform atomic operation(s) at this point since one is already in progress.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1478 HSCL1478

Explanation: The virtual I/O adapter type specified is not valid. Check the entry and try again.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact

your next level of support or your service provider.

HSCL1479 HSCL1479

Explanation: The atomic operation failed.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL147A HSCL147A

Explanation: The RIO bus number is not valid. Check the entry and try again.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL147B HSCL147B

Explanation: The hardware page table ratio specified is not valid. Check the entry and try again.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL147C HSCL147C

Explanation: The I/O adapter cannot be assigned to the pool specified.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL147D HSCL147D

Explanation: Cannot change the processing setting to uncapped.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL147E HSCL147E

Explanation: The OptiConnect pool specified is not acceptable by the managed system. Check the entry and try again.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL147F HSCL147F

Explanation: The HSL OptiConnect pool specified is not acceptable by the managed system. Check the entry and try again.

Problem determination: Retry the task. If the problem

persists, contact your next level of support or your service provider.

HSCL1481 HSCL1481

Explanation: Cannot perform this operation because the partition belongs to a workload management group joined by other partitions.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL150B HSCL150B

Explanation: Cannot change the I/O pools of the partition since the partition is still using an I/O adapter participating in one of the pool IDs.

HSCL150C HSCL150C

Explanation: Cannot use the I/O adapter since the partition is not part of the pool this adapter belongs to.

HSCL150D HSCL150D

Explanation: Cannot use the I/O adapter because it is not available.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL150E HSCL150E

Explanation: Cannot use the I/O adapter since it is configured under an I/O unit marked as switchable.

HSCL150F HSCL150F

Explanation: Cannot vary off the I/O adapter because it is still in use by the partition.

HSCL1510 HSCL1510

Explanation: This I/O adapter is marked as multi-hub reserving for shark partition.

HSCL1511 HSCL1511

Explanation: Cannot use the I/O adapter because it is either used by another partition or an allocation is already in progress.

HSCL1512 HSCL1512

Explanation: Cannot vary off the I/O adapter because the partition is not ready to release the adapter

HSCL1513 HSCL1513

Explanation: Cannot change the OptiConnect setting since the communication with the partition is still active.

HSCL1514 HSCL1514

Explanation: The virtual LAN ID is not valid or it conflicts with one of the additional virtual LAN IDs.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1515 HSCL1515

Explanation: Cannot use a virtual slot number greater or equal to the maximum number of virtual slots allowed with this partition.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1516 HSCL1516

Explanation: Cannot specify additional virtual LAN IDs since this virtual Ethernet adapter is not IEEE compatible.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1517 HSCL1517

Explanation: The virtual slot number specified to query or set virtual slot information is not valid.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1518 HSCL1518

Explanation: The virtual slot state specified is not valid.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1519 HSCL1519

Explanation: The maximum number of virtual slots specified is not valid.

HSCL151A HSCL151A

Explanation: A trunk adapter already exists on one or more of the same VLANs as the truck adapter being added, and the configuration of the two adapters is not compatible. Please verify that the truck priorities of the two adapters are different, and that the two adapters participate on all of the same VLANs.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL151B HSCL151B

Explanation: Unable to delete the partition when there is a virtual terminal connection opened.

Problem determination: Close the terminal session for the partition you want to delete. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL151C HSCL151C

Explanation: Server adapter setting of the virtual slot is not valid.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL151D HSCL151D

Explanation: The virtual adapter cannot be set up for management console connection.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL151E HSCL151E

Explanation: Cannot have multicast MAC address for the virtual Ethernet trunk adapter.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1523 HSCL1523

Explanation: Shared pool ID specified is not valid.

Problem determination: Ensure that the setting is valid. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL152A HSCL152A

Explanation: Cannot change the managed system from the manufacturing default configuration because a partition is running with a device that does not support extended error handling (EEH).

HSCL152D HSCL152D

Explanation: The managed system is not ready for the management console to extract partition and resource information.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1537 HSCL1537

Explanation: The partition is not responsive for dynamic resource configuration changes.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1538 HSCL1538

Explanation: There is an insufficient amount of memory for maintaining system firmware.

HSCL1539 HSCL1539

Explanation: Memory configuration for the partition cannot be satisfied due to system memory usage limitation.

HSCL1540 HSCL1540

Explanation: The pool ID is not valid.

HSCL1541 HSCL1541

Explanation: The pool ID is still in use.

HSCL1542 HSCL1542

Explanation: The Virtual I/O Server partition is assigned to the reserved storage device pool or the shared memory pool.

HSCL1543 HSCL1543

Explanation: The new shared memory pool size exceeds the maximum shared memory pool size.

HSCL1544 HSCL1544

Explanation: The new shared memory pool size is less than the total amount of allocated I/O entitled memory.

HSCL1545 HSCL1545

Explanation: The new maximum shared memory pool size is greater than the maximum amount of memory supported on the managed system.

HSCL1546 HSCL1546

Explanation: A Virtual I/O Server partition for the pool must be specified.

HSCL1547 HSCL1547

Explanation: A Virtual I/O Server partition is being used in the reserved storage device pool or the shared memory pool.

HSCL1549 HSCL1549

Explanation: A Virtual I/O Server partition is already assigned to the pool.

HSCL154A HSCL154A

Explanation: A primary Virtual I/O Server partition to provide paging services for the shared memory partition must be specified.

HSCL154B HSCL154B

Explanation: A secondary Virtual I/O Server partition to provide paging services for the shared memory partition must be specified.

HSCL154C HSCL154C

Explanation: A shared memory partition cannot have reserved memory.

HSCL154D HSCL154D

Explanation: A shared memory partition cannot have huge page memory.

HSCL1550 HSCL1550

Explanation: Firmware command failed.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1551 HSCL1551

Explanation: The firmware command failed.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1552 HSCL1552

Explanation: The firmware operation failed with extended error.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1553 HSCL1553

Explanation: This operation cannot be performed because there is an insufficient number of unallocated processors for the i5/OS partitions.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL1554 HSCL1554

Explanation: This operation cannot be performed because there is an insufficient number of unallocated processing units for the IBM i partitions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1555 HSCL1555

Explanation: The virtual I/O adapter configuration is not valid. If the remote partition and the remote partition virtual slot number are configured, make sure they are not the same number as the partition number and slot number of the virtual I/O adapter.

HSCL1556 HSCL1556

Explanation: The virtual I/O adapter cannot be configured as a server adapter. The configuration is not allowed under the partition specified. The partition must be an i5/OS partition in an IBM System i5, eServer i5 system, or a virtual I/O server partition.

HSCL1557 HSCL1557

Explanation: The partition ID specified for this operation does not exist.

Problem determination: Rebuild the managed system and repeat the operation.

HSCL1558 HSCL1558

Explanation: The operation is unavailable in the current partition state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1559 HSCL1559

Explanation: The operation is not allowed when the managed system is in the process of powering off.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1560 HSCL1560

Explanation: The current level of management console code does not support the requested operation.

Problem determination: It is recommended that this management console be upgraded to the same level as the managed system or higher.

HSCL1561 HSCL1561

Explanation: The resource is not powered off and is still in use by the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1562 HSCL1562

Explanation: Unable to clear VPD data for the I/O slot.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1563 HSCL1563

Explanation: The I/O slot is not empty.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1564 HSCL1564

Explanation: The virtual switch operation failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1565 HSCL1565

Explanation: There is no reserved storage device attached to the partition or the attached reserved storage device is not accessible. Correct the reserved storage device configuration and try the operation again.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL157D HSCL157D

Explanation: The virtual I/O adapter cannot be configured as a server adapter. The configuration is not allowed under the partition specified. The partition must be an i5/OS partition in an IBM System i5, eServer i5 system, or a virtual I/O server partition.

HSCL157E HSCL157E

Explanation: Unable to edit. Check user permissions, then log in as the proper user and try editing again.

Problem determination: Check your user role's permissions. If your user role does not permit the desired action, log out and log back in as the correct user, and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL157F HSCL157F

Explanation: Cannot find an instance of the object specified. Either there is no instance and it must be created or a path to the object was incorrect.

Problem determination: Ensure that the inputs are correct. Rebuild the managed system. Then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1580 HSCL1580

Explanation: Improper number of arguments passed in. Check the parameters of the invoked method.

Problem determination: Verify that the command is being called correctly, and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1581 HSCL1581

Explanation: The method name passed in the invoke method does not match the name of the method you are trying to invoke. Check the method name and the required parameters.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1582 HSCL1582

Explanation: The wrong path is being used for the object manager. Check the code for build CIMObjectPath and its contents.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1583 HSCL1583

Explanation: The wrong object manager method is being invoked.

Problem determination: Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1584 HSCL1584

Explanation: You do not have the proper authorization or permission to perform this task. Log in as the proper user and try again.

Problem determination: Log in with appropriate permissions to perform the task. If the problem persists, contact your next level of support or your service provider.

HSCL1585 HSCL1585

Explanation: There was an unknown error while querying the object manager database.

Problem determination: Try the task again. Shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1586 HSCL1586

Explanation: Cannot find an instance with object manager.

Problem determination: Check the input. Rebuild the managed system. Then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1587 HSCL1587

Explanation: The method is not accessible. The method may not be declared with public access.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1588 HSCL1588

Explanation: An exception was encountered while calling the method.

Problem determination: Retry the operation. If the problem persists, rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL159B HSCL159B

Explanation: The group number is invalid. Group numbers cannot contain any letters or characters other than the numbers 0 through 9.

Problem determination: Enter the new group number again without alphabetic characters.

HSCL159C HSCL159C

Explanation: The Workload Management group number is not valid.

Problem determination: Enter a number inside the valid range for workload management group numbers.

HSCL15E7 HSCL15E7

Explanation: The profile you tried to activate does not belong to the partition you specified. Select the correct partition profile.

Problem determination: Verify that you selected the correct logical partition profile to activate. If the operation still fails, contact your next level of support or your service provider.

HSCL1771 HSCL1771

Explanation: Could not create console information and set it with the managed system. Perform the rebuild managed system operation.

Problem determination: Rebuild the managed system.

HSCL1772 HSCL1772

Explanation: Could not set management console information. Perform the rebuild managed system operation.

Problem determination: Rebuild the managed system.

HSCL1773 HSCL1773

Explanation: Invocation of the management console information method failed. Perform the rebuild managed system operation.

Problem determination: Rebuild the managed system.

HSCL1774 HSCL1774

Explanation: Unable to get the defined slot number for management console information slots. Perform the rebuild managed system operation.

Problem determination: Rebuild the managed system.

HSCL1776 HSCL1776

Explanation: Could not get the management console information. Perform the rebuild managed system operation.

Problem determination: Rebuild the managed system.

HSCL1777 HSCL1777

Explanation: Failed to construct the management console information string. Perform the rebuild managed system operation.

Problem determination: Rebuild the managed system.

HSCL1778 HSCL1778

Explanation: Could not create the management console instance in the object manager. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1779 HSCL1779

Explanation: Could not create the management console motherboard instance in the object manager. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL177A HSCL177A

Explanation: Could not create the management console chassis instance in the object manager. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL177B HSCL177B

Explanation: Could not create the management console network setting instance in the object manager. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL177C HSCL177C

Explanation: Could not create the management console partition management instance in the object manager. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL177D HSCL177D

Explanation: Could not create the management console operating system instance in the object manager. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL177E HSCL177E

Explanation: Could not create the management console memory instance in the object manager. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL177F HSCL177F

Explanation: Could not delete the management console instance.

Problem determination: Rebuild the managed system. Shut down and restart the management console and then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1780 HSCL1780

Explanation: Could not delete management console and its related instances.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1781 HSCL1781

Explanation: Could not obtain management console's VPD information. Restart the management console.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1782 HSCL1782

Explanation: Could not delete the management console Motherboard instance and its associations.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1783 HSCL1783

Explanation: Could not delete the management console chassis instance and its associations.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1784 HSCL1784

Explanation: Could not delete the management console network setting instance and its associations.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1785 HSCL1785

Explanation: Could not delete the management console partition management instance and its associations.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1786 HSCL1786

Explanation: Could not delete the management console operating systems instance and its associations.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1787 HSCL1787

Explanation: Could not delete the management console memory instance and its associations.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL1965 HSCL1965

Explanation: Unable to determine the management console server's host name. Check the management console network settings under System Configuration and verify that they are correct.

Problem determination: Check the management console Network Settings under System Configuration

HSCL1966 • HSCL1974

to verify that the settings are correct and that you have a valid host name for the management console. Contact your system or network administrator for network settings help.

HSCL1966 HSCL1966

Explanation: You must select one profile for powering on the Full System Partition (SMP) or select Cancel.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1967 HSCL1967

Explanation: You must select one system profile to power on with or select Cancel.

Problem determination: Select a system profile from the window or select Cancel to close the window.

HSCL1968 HSCL1968

Explanation: You must select a power on option or select Cancel.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1969 HSCL1969

Explanation: Could not retrieve information from the GUI server. Check your network configuration and connection.

Problem determination: Check the management console network settings under System Configuration and verify that the settings are correct. If the problem persists, contact your next level of support or your service provider.

HSCL196A HSCL196A

Explanation: Choose a new default profile from the list or select Cancel.

Problem determination: Choose only one new default profile. Either choose a new default profile, or select Cancel. If the problem persists, contact your next level of support or your service provider.

HSCL196B HSCL196B

Explanation: The object is not found in the data area. Refresh the interface.

Problem determination: Perform the refresh task. If the problem persists, contact your next level of support or your service provider.

HSCL196C HSCL196C

Explanation: Problem obtaining object information. Refresh the interface.

Problem determination: Perform the refresh task. If the same error occurs, perform the rebuild managed system operation. If the problem persists, contact your next level of support or your service provider.

HSCL196E HSCL196E

Explanation: Could not display the Operating System Shut down dialog. Try the operation again.

Problem determination: Refresh the graphical user interface. Retry the operation. If it still fails, log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL1970 HSCL1970

Explanation: Parent name space not set.

Problem determination: Rebuild the managed system. Restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1971 HSCL1971

Explanation: There was an error retrieving necessary information from the Hardware Management Console. Refresh the console and try the operation again.

Problem determination: Rebuild the managed system. Restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1972 HSCL1972

Explanation: Unable to power on system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1973 HSCL1973

Explanation: Unable to power off system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1974 HSCL1974

Explanation: Unable to remove machine.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1975 HSCL1975

Explanation: The management console Access Password has been set from another management console or ASM screen before this Update Password task completed. You must cancel out of the Update Password - Authentication Pending dialog and reselect this managed object to proceed.

Problem determination: Rebuild the managed system. If the managed system state remains in Pending Authentication, restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1976 HSCL1976

Explanation: The ASM General Password has been set from another management console or ASM screen before this Update Password task completed. You must cancel out of the Update Password - Authentication Pending dialog and reselect this managed object to proceed.

Problem determination: Rebuild the managed system. Restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1977 HSCL1977

Explanation: The ASM Administrator Password has been set from another management console or ASM screen before this Update Password task completed. You must cancel out of the Update Password - Authentication Pending dialog and reselect this managed object to proceed.

Problem determination: Rebuild the managed system. Restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1978 HSCL1978

Explanation: An error occurred while attempting to update the management console Access Password. Try to update the password again by either entering it again here or by cancelling out of this dialog and reselecting this managed system and its Update Managed System Password task.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL1979 HSCL1979

Explanation: An error occurred while attempting to update the ASM General Password. Try to update the password again by either entering it again here or by cancelling out of this dialog and reselecting this

managed system and its Update Managed System Password task.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL197A HSCL197A

Explanation: An error occurred while attempting to update the ASM Administrator Password. Try to update the password again by either entering it again here or by cancelling out of this dialog and reselecting this managed system and its Update Managed System Password task.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL197B HSCL197B

Explanation: Failed to backup the profile data to file.

Problem determination: Refresh the graphical user interface. Retry the task. Restart the HMC, then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL197C HSCL197C

Explanation: Failed to remove backup file from Managed System.

Problem determination: Refresh the graphical user interface. Retry the task. Restart the HMC, then try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL197D HSCL197D

Explanation: Failed to initialize profile data at Managed System.

Problem determination: Refresh the graphical user interface. Ensure that the operation was performed and that it displays on the graphical user interface. If not, repeat the operation. If the problem persists, contact your next level of support or your service provider.

HSCL197E HSCL197E

Explanation: Failed to restore Managed System from backup file.

Problem determination: Refresh the graphical user interface. Retry the task. Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL197F HSCL197F

Explanation: Frame operation failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1980 HSCL1980

Explanation: Failed to copy profile.

Problem determination: Try the task again. Rebuild the managed system. Retry the operation. If the problem still persists, contact your next level of support or your service provider.

HSCL1981 HSCL1981

Explanation: Failed to delete selected system profile(s).

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1982 HSCL1982

Explanation: Profile Property Display failed.

Problem determination: Refresh the graphical user interface. Retry the task. Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL1983 HSCL1983

Explanation: An error occurred trying to validate the system profile.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1984 HSCL1984

Explanation: Failed to open terminal on partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1985 HSCL1985

Explanation: Error(s) occurred during the operating system shut down of partition.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL1986 HSCL1986

Explanation: There was an unknown error while changing the default profile.

Problem determination: Try the task again. Rebuild the managed system. Retry the operation. If the problem still persists, contact your next level of support or your service provider.

HSCL1987 HSCL1987

Explanation: Failed to delete managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1988 HSCL1988

Explanation: Failed to power off.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL1989 HSCL1989

Explanation: Failed to power on.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL198A HSCL198A

Explanation: No objects were found in the database. Possible problems and solutions are: The database is currently being populated. The object(s) should appear automatically when the database is fully populated, or you can retry later by clicking on Reload. There is a problem with the connection between the Console and the Managed System. Ensure the network is correctly configured between the Console and the Managed System.

Problem determination: Ensure the network is correctly configured. Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL198B HSCL198B

Explanation: Failed to delete the selected profile(s).

Problem determination: Try the task again. Rebuild the managed system. Retry the operation. If the problem still persists, contact your next level of support or your service provider.

HSCL198C HSCL198C

Explanation: Failed to refresh the GUI for the deletion of the profile.

Problem determination: Refresh the graphical user interface. Verify that the profile is deleted. If the problem still persists, contact your next level of support or your service provider.

HSCL198D HSCL198D

Explanation: The New management console Access Password and Verify management console Access Password do not match. Enter matching passwords to proceed.

Problem determination: Enter matching passwords.

HSCL198E HSCL198E

Explanation: The New ASM General Password and Verify ASM General Password do not match. Enter matching passwords to proceed.

Problem determination: Enter matching passwords.

HSCL198F HSCL198F

Explanation: The New ASM Administrator Password and Verify ASM Administrator Password do not match. Enter matching passwords to proceed.

Problem determination: Enter matching passwords.

HSCL1990 HSCL1990

Explanation: You have entered an incorrect password. Either the current management console Access password specified is incorrect, or the management console Access password has been changed already at another management console and the New management console Access password you specified here is wrong. Correct the password(s), then select OK once again from this dialog to retry the operation.

Problem determination: Enter the correct management console Access password.

HSCL1991 HSCL1991

Explanation: The management console Access Password you specified is incorrect. Enter the correct management console Access Password to login.

Problem determination: Enter the correct management console Access password.

HSCL1992 HSCL1992

Explanation: The management console Access Password specified is invalid. Enter the new password again to proceed.

Problem determination: Re-enter a password that conforms to the password rules.

HSCL1993 HSCL1993

Explanation: The ASM General Password specified is invalid. Enter the new password again to proceed.

Problem determination: Re-enter a password that conforms to the password rules.

HSCL1994 HSCL1994

Explanation: The ASM Administrator Password specified is invalid. Enter the new password again to proceed.

Problem determination: Re-enter a password that conforms to the password rules.

HSCL1995 HSCL1995

Explanation: Your attempt to update the password(s) has failed, because a successful attempt to update these passwords has taken place elsewhere during the time that has elapsed since this management console last connected to the managed system. A reconnection to the managed system has been initiated to reset the password status, and the managed system state will be updated to reflect the true authentication state once this has completed. Note that none of the passwords stored on the managed system are what you attempted to set them to in this dialog.

Problem determination: Rebuild the managed system. If the managed system state remains in Pending Authentication, restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1996 HSCL1996

Explanation: Your attempt to update the password(s) has succeeded. However, your attempt to update the password(s) has failed because an update on this (these) password(s) has already happened successfully elsewhere during the time that has elapsed since this management console last connected to the managed system. A reconnection to the managed system has been initiated to reset the password status, and the managed system state will be updated to reflect the true authentication state once this has completed. Note that for the failure cases, the password(s) stored on the managed system are not what you attempted to set them to in this dialog.

Problem determination: Rebuild the managed system.

HSCL1997 • HSCL199E

If the managed system state remains in Pending Authentication, restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1997 HSCL1997

Explanation: Your attempt to update the password(s) has failed, because a successful attempt to update these passwords has taken place elsewhere during the time that has elapsed since this management console last connected to the managed system. A subsequent attempt to reconnect to the managed system and reset the authentication state has also failed. 'Exit the Update Password - Pending Authentication dialog and retry the connection reset operation by selecting the 'Reset or Remove Connection' managed system task. If the problem persists, contact support.

Problem determination: Rebuild the managed system. If the managed system state remains in Pending Authentication, restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1998 HSCL1998

Explanation: Your attempt to update the password(s) has passed. However, your attempt to update the password(s) has failed, because an update on this (these) passwords has already happened successfully elsewhere during the time that has elapsed since this management console last connected to the managed system. A subsequent attempt to reconnect to the managed system and reset the authentication state has also failed. Exit the Update Password - Pending Authentication dialog and retry the connection reset operation by selecting the 'Reset or Remove Connection' managed system task. If the problem persists, contact support.

Problem determination: Rebuild the managed system. If the managed system state remains in Pending Authentication, restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL1999 HSCL1999

Explanation: Your attempt to update the password(s) has failed, because a successful attempt to update these passwords has taken place elsewhere during the time that has elapsed since this management console last connected to the managed system. A reconnection to the managed system will be initiated to reset the password status once you exit this dialog, and the managed system state will be updated to reflect the true authentication state once this has completed. 'Note that none of the passwords stored on the managed system are what you attempted to set them to in this dialog.

Problem determination: Rebuild the managed system. If the managed system state remains in Pending Authentication, restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL199A HSCL199A

Explanation: Your attempt to update the password or passwords has succeeded. However, your attempt to update the password or passwords has failed, because an update has already happened successfully elsewhere during the time that has elapsed since this management console last connected to the managed system. A reconnection to the managed system will be initiated to reset the password status once you exit this dialog, and the managed system state will be updated to reflect the true authentication state once this has completed. Note that for the failure cases, the password or passwords stored on the managed system are not what you attempted to set them to in this dialog.

Problem determination: Rebuild the managed system. If the managed system state remains in Pending Authentication, restart the management console and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL199B HSCL199B

Explanation: The management console Access Password specified is invalid. Re-enter a password of the correct length in this field to proceed.

Problem determination: Re-enter a password that conforms to the password rules.

HSCL199C HSCL199C

Explanation: The ASM General Password specified is invalid. Re-enter a password of the correct length in this field to proceed.

Problem determination: Re-enter a password that conforms to the password rules.

HSCL199D HSCL199D

Explanation: The ASM Administrator Password specified is invalid. Re-enter a password of the correct length in this field to proceed.

Problem determination: Re-enter a password that conforms to the password rules.

HSCL199E HSCL199E

Explanation: An error occurred while trying to open the 5250 console.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL199F HSCL199F

Explanation: An error occurred while trying to open the 5250 console.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL19A0 HSCL19A0

Explanation: An error occurred while trying to open the 5250 console. The operation timed out.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL19A1 HSCL19A1

Explanation: An error occurred while trying to open the 5250 console. Try the operation again. If the problem persists, contact your service provider.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL19A2 HSCL19A2

Explanation: Failed to save profile.

Problem determination: The Save profile command has failed. This operation cannot be done when the partition is either not bootable or has not been booted for the first time. You might try to activate the partition with an appropriate profile, or rebuild the managed system. Rebuild the managed system.

(HSCL2xxx) Reference codes

HSCL233C HSCL233C

Explanation: Sorry, passwords do not match.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL233D HSCL233D

Explanation: Setting user password failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL233E HSCL233E

Explanation: User does not exist or is not an management console user.

Problem determination: Please retry the command.

HSCL233F HSCL233F

Explanation: The operation is invalid for root or hscroot user.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2340 HSCL2340

Explanation: Bad password: it is too simplistic/systematic.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2341 HSCL2341

Explanation: The operation is invalid for hscpe user.

HSCL2400 HSCL2400

Explanation: The command failed during a HCA related operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2401 HSCL2401

Explanation: The specified HCA data is not valid because it has been assigned to the profile already.

Problem determination: Please select another adapter or remove the current assignment of the adapter and retry the operation.

HSCL2402 HSCL2402

Explanation: The specified HCA data is not valid for the operation.

Problem determination: Either the adapter ID or GUID does not exist, the resource capability is not valid, or the data is not in the format 'Adapter ID/GUID/Capabilities'. Please correct and retry the operation.

HSCL2403 HSCL2403

Explanation: IBM i partitions do not support HCA adapter in this release.

Problem determination: Please remove the HCA adapter and retry the operation.

HSCL2404 HSCL2404

Explanation: The GUID index out of valid range.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2405 HSCL2405

Explanation: The specified value is outside of the valid range for the maximum logical partitions per HCA.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2406 HSCL2406

Explanation: The maximum logical partitions per HCA setting is not supported on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2410 HSCL2410

Explanation: Currently, there isn't enough huge page memory to activate partition.

Problem determination: Activation of the system profile may fail.

HSCL2411 HSCL2411

Explanation: The system profile needs a minimum of regions to activate all profiles, and currently, there are not enough regions of free huge page memory in the system.

Problem determination: Activation of this system profile may fail.

HSCL2412 HSCL2412

Explanation: There is a huge page memory resource conflict within the system profile.

Problem determination: The system profile needs a minimum of regions to activate all profiles.

HSCL2413 HSCL2413

Explanation: Currently, there is probably not enough huge page memory to activate all profiles in this system profile.

Problem determination: The system profile needs a minimum of regions to activate all profiles. Activation of this system profile may fail; however, due to the complex nature of huge page memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of huge page memory resource conflicts, make your last profile's minimum amount of huge page memory as low as you can.

HSCL2414 HSCL2414

Explanation: There is probably a huge page memory resource conflict within the system profile.

Problem determination: The system profile needs a minimum of regions to activate all profiles. Activation of this system profile may fail; however, due to the complex nature of huge page memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of huge page memory resource conflicts, make your last profile's minimum amount of huge page memory as low as you can.

HSCL2415 HSCL2415

Explanation: There should be no huge page memory resource conflict within the system profile. The system profile needs a minimum of regions of huge page memory to activate all profiles. However, due to the complex nature of huge page memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of huge page memory resource conflicts, make your last profile's minimum amount of huge page memory as low as you can.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2416 HSCL2416

Explanation: There should be no memory resource conflict within the system profile.

Problem determination: The system profile needs a minimum of memory to activate all profiles. However, due to the complex nature of memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of memory resource conflicts, make your last profile's minimum amount of memory as low as you can.

HSCL2417 HSCL2417

Explanation: There should be no huge page memory resource conflict within the system profile.

Problem determination: The system profile needs a minimum of regions of huge page memory to activate all profiles. However, due to the complex nature of huge page memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of huge page memory resource conflicts, make your last profile's minimum amount of huge page memory as low as you can.

HSCL2418 HSCL2418

Explanation: There should be no huge page memory resource conflict with huge page memory resources currently used by the system.

Problem determination: The system profile needs a minimum of regions of huge page memory to activate all profiles. However, due to the complex nature of huge page memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of huge page memory resource conflicts, make your last profile's minimum amount of huge page memory as low as you can.

HSCL2419 HSCL2419

Explanation: There should be no huge page memory resource conflict with huge page memory resources currently used by the system.

Problem determination: The system profile needs a minimum of regions of huge page memory to activate all profiles. However, due to the complex nature of huge page memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of huge page memory resource conflicts, make your last profile's minimum amount of huge page memory as low as you can.

HSCL241A HSCL241A

Explanation: There should be no huge page memory resource conflict with huge page memory resources currently used by the system.

Problem determination: The system profile needs a minimum of regions of huge page memory to activate all profiles. However, due to the complex nature of huge page memory allocation and fragmentation issues, this is just an estimate. To reduce the likelihood of huge page memory resource conflicts, make your last profile's minimum amount of huge page memory as low as you can.

HSCL241B HSCL241B

Explanation: The managed system does not support overriding the huge page memory pool configuration.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL241C HSCL241C

Explanation: The operation to configure the huge page memory pool failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL251D HSCL251D

Explanation: There was an unknown internal management console error.

Problem determination: Repeat the operation. If it still fails, restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL251E HSCL251E

Explanation: Failed to set the 'enable remote virtual terminal' option.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL251F HSCL251F

Explanation: An error was encountered. Retry the operation.

Problem determination: Ensure the network connection between the management console and the partition is working. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL2520 HSCL2520

Explanation: The command entered is not supported.

Problem determination: Retry the task. If the problem

persists, contact your next level of support or your service provider.

HSCL2521 HSCL2521

Explanation: There was a failure in the management console repository.

Problem determination: Restart the HMC, and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2522 HSCL2522

Explanation: The firmware command failed.

Problem determination: Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL2523 HSCL2523

Explanation: A critical property stored in the repository is not set.

Problem determination: Rebuild the managed system, and try the task again. Restart the HMC, and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2524 HSCL2524

Explanation: Invalid subscription ID

Problem determination: Log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL2525 HSCL2525

Explanation: Authentication failed.

Problem determination: Log off and then log back in to the management console and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL2526 HSCL2526

Explanation: Errors occurred during the operation.

HSCL2527 HSCL2527

Explanation: The Service Reference Code requested does not exist in firmware.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2725 HSCL2725

Explanation: The partition and default profile information got corrupted. Unable to create a Apartition configuration.

Problem determination: Please try to set up the configuration again.

HSCL2727 HSCL2727

Explanation: The operation failed.

Problem determination: It is possible that another user is in the process of creating or updating affinity logical partitions. If this is not the case, please restore profile data and retry the operation.

HSCL2728 HSCL2728

Explanation: Your partition names are not all unique.

Problem determination: No partitions have been created. Please try again, and make sure that all partition names are different from each other and those of already created partitions.

HSCL272A HSCL272A

Explanation: An error occurred in partition creation. Default profiles and the system profile may have to be created manually.

Problem determination: First, rebuild the managed system, and then create items if needed.

HSCL272B HSCL272B

Explanation: An error occurred in default profile creation. Default profiles and the system profile will have to be created manually.

Problem determination: First rebuild the managed system, and then create the needed items.

HSCL272C HSCL272C

Explanation: An error occurred in default profile creation. Default profiles and the system profile will have to be created manually.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL272D HSCL272D

Explanation: An error occurred in default profile creation. The system profile will have to be created manually.

Problem determination: First rebuild the managed system, and then create the missing system profile, if desired.

HSCL272E HSCL272E

Explanation: An unknown error occurred during creation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL272F HSCL272F

Explanation: An error occurred in partition creation. Affinity partitions have been created, but default profiles and the system profile may have to be created manually.

Problem determination: First, recover partition data, and then create items if needed.

HSCL2730 HSCL2730

Explanation: Unable to get the resources of the partition since it is not an affinity logical partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2731 HSCL2731

Explanation: The addition of affinity logical partitions exceeds the maximum limit.

Problem determination: Delete other partitions and retry the task.

HSCL2732 HSCL2732

Explanation: Reserved partition slots where found.

Problem determination: It is possible that another user is in the process of setting up or updating physical partitions.

HSCL2733 HSCL2733

Explanation: There are physical partitions in the Running state.

Problem determination: Please stop all the physical partitions before updating an Apartition configuration.

HSCL2734 HSCL2734

Explanation: Cannot create only one affinity logical partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2735 HSCL2735

Explanation: Cannot delete only one affinity logical partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2736 HSCL2736

Explanation: The update operation cannot be performed since there are no affinity logical partitions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2737 HSCL2737

Explanation: The operation failed since the update parameter is invalid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2738 HSCL2738

Explanation: The operation failed since the cluster size parameter is invalid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2739 HSCL2739

Explanation: The update operation failed since the hardware resources have not changed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL273B HSCL273B

Explanation: The managed system cannot handle the creation of partitions with the specified cluster size.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL273D HSCL273D

Explanation: Deletion of affinity logical partitions failed.

Problem determination: Recover partition data and retry the operation.

HSCL273E HSCL273E

Explanation: Deletion of partition failed.

Problem determination: The partition cannot be deleted when it is not in the Not Activated state. Stop the partition and retry the task.

HSCL2901 HSCL2901

Explanation: This logical partition is not capable of adding, removing, or moving processors dynamically.

Problem determination: Ensure your logical partitions are capable of performing dynamic logical partition operations.

HSCL2902 HSCL2902

Explanation: The destination logical partition is not capable of adding, removing, or moving processors dynamically.

Problem determination: Ensure your logical partitions are capable of performing dynamic logical partition operations.

HSCL2903 HSCL2903

Explanation: Your processor request goes below the profile's required processor limit. You can remove or move some processors. Retry the operation.

Problem determination: Retry the operation, entering a smaller number of processors.

HSCL2904 HSCL2904

Explanation: Your processor request exceeds the profile's maximum processor limit. You can add or move some processors. Retry the operation.

Problem determination: Retry the operation, entering a smaller number of processors.

HSCL2905 HSCL2905

Explanation: This logical partition is not capable of adding, removing, or moving memory dynamically.

Problem determination: Ensure your logical partitions are capable of performing dynamic logical partition operations.

HSCL2906 HSCL2906

Explanation: The destination logical partition is not capable of adding, removing, or moving memory dynamically.

Problem determination: Ensure your logical partitions are capable of performing dynamic logical partition operations.

HSCL2907 HSCL2907

Explanation: Your memory request exceeds the profile's maximum memory limit.

Problem determination: Retry the task and request a smaller memory amount. Reset the logical partition, reactivate the logical partition, and then retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2908 HSCL2908

Explanation: Your memory request goes below the profile's minimum memory limit.

Problem determination: Retry the task and request a smaller memory amount. Reset the logical partition, reactivate the logical partition, and then retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2909 HSCL2909

Explanation: Your memory request exceeds the total available memory of the managed system.

Problem determination: Retry the task and request a smaller memory amount. Reset the logical partition, reactivate the logical partition, and then retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL290B HSCL290B

Explanation: This logical partition is not capable of adding, removing, or moving I/O slots dynamically.

Problem determination: Ensure your logical partitions are capable of performing dynamic logical partition operations.

HSCL290C HSCL290C

Explanation: The destination logical partition is not capable of adding, removing, or moving I/O slots dynamically.

Problem determination: Ensure your logical partitions are capable of performing dynamic logical partition operations.

HSCL290D HSCL290D

Explanation: Since the managed system is not capable of dynamic logical partitioning, you cannot unassign resources.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL290E HSCL290E

Explanation: Since the managed system is not capable of dynamic logical partitioning, you cannot correct requested memory values.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL290F HSCL290F

Explanation: The partition cannot be activated because there are not enough free processors to satisfy the partition's requirements. However, there are stopped processors available which are still assigned to running partitions that you may unassign.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2910 HSCL2910

Explanation: The partition cannot be activated because there are not enough free adapters to satisfy the partition's requirements. However, there are stopped adapters available which are still assigned to running partitions that you may unassign.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2911 HSCL2911

Explanation: The partition cannot be activated because there is not enough available system memory to satisfy the profile's required amount. However, there is some memory available which was requested by running partitions but is not being used that you may unassign.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2912 HSCL2912

Explanation: The managed system is powered off. You must power on the managed system to perform a dynamic logical partitioning operation.

Problem determination: Ensure the managed system is powered on. Rebuild managed system. If the problem persists, contact your next level of support or your service provider.

HSCL2913 HSCL2913

Explanation: Unknown operation type!

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCL2914 HSCL2914

Explanation: The quantity to be added exceeds the available resources.

Problem determination: Ensure that memory is available in the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2916 HSCL2916

Explanation: The partition could not be found in the database. Perform a rebuild managed system operation, and try again.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL2917 HSCL2917

Explanation: The selected logical partition is not enabled for dynamic logical partitioning operations.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2925 HSCL2925

Explanation: An unknown error occurred during the add Virtual adapter operation. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2926 HSCL2926

Explanation: An unknown error occurred during the remove Virtual adapter operation. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2927 HSCL2927

Explanation: Dynamic move processing resources failed.

Problem determination: Retry the task. Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL2928 HSCL2928

Explanation: Dynamic add of I/O resources failed.

Problem determination: Ensure you have the resources available to perform the operation. Retry the operation. If operation still fails, rebuild the managed system and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL2929 HSCL2929

Explanation: Dynamic remove of I/O resources failed.

Problem determination: Ensure you have the resources available to perform the operation. Retry the operation. If operation still fails, rebuild the managed system and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL2930 HSCL2930

Explanation: Dynamic logical partition MOVE I/O resources failed.

Problem determination: Ensure you have the resources available to perform the operation. Retry the operation. If operation still fails, rebuild the managed system and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL2931 HSCL2931

Explanation: Dynamic add memory resources failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2932 HSCL2932

Explanation: Dynamic remove memory resources failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2933 HSCL2933

Explanation: Dynamic move memory resources failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2934 HSCL2934

Explanation: The operating system drmgr command failed. Consult the appropriate operating system log files for further information and retry the operation if desired.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2935 HSCL2935

Explanation: The operation for resource did not finish completely in the timeout value specified. Increase the timeout value if needed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2936 HSCL2936

Explanation: The operation for resource failed.

Problem determination: Ensure the network connection between the management console and the logical partition is working. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2937 HSCL2937

Explanation: The operation has completed, but not all were successful. The partition standard output/error is not available.

HSCL2939 HSCL2939

Explanation: The operation has completed, but not all were successful.

HSCL293A HSCL293A

Explanation: The operation has completed, but not all were successful.

HSCL293B HSCL293B

Explanation: The return code is {0}. The partition return code is {1}.

HSCL293C HSCL293C

Explanation: The partition does not support dynamic logical partitioning operations.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL293D HSCL293D

Explanation: Partition is not in the correct state to perform dynamic logical partitioning operations.

Problem determination: Dynamic logical partitioning operations can only be performed on running partitions. Verify that the partition is in the Running state, and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL293E HSCL293E

Explanation: Cannot get logical partition states or definitions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL293F HSCL293F

Explanation: Cannot retrieve processor information.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2940 HSCL2940

Explanation: An unknown dynamic logical partitioning error has occurred. Try the operation again.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2941 HSCL2941

Explanation: There are no processors available for dynamic logical partitioning on this partition.

Problem determination: Ensure that there are available processors in the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2942 HSCL2942

Explanation: There is no memory available for dynamic logical partitioning on this partition.

Problem determination: Ensure that there are available processors in the managed system. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2943 HSCL2943

Explanation: There are no I/O slots available for dynamic logical partitioning on this partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2944 HSCL2944

Explanation: The I/O slot cannot be found. Ensure that the correct slot ID and unit ID were entered.

Problem determination: Ensure the inputs are correct. Rebuild managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL2945 HSCL2945

Explanation: The shut down operation on the logical partition failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2947 HSCL2947

Explanation: An error occurred while trying to restore stopped processors.

HSCL2948 HSCL2948

Explanation: An error occurred while trying to correct the requested memory value. There were partitions that were corrected.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2949 HSCL2949

Explanation: An error occurred while trying to restore stopped I/O devices.

HSCL294A HSCL294A

Explanation: The I/O slot cannot be found or it is required. Ensure that the valid slot ID and unit ID were entered.

Problem determination: Ensure the inputs are correct. Ensure the adapter is not marked as required. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL294C HSCL294C

Explanation: Dynamic add of Virtual I/O resources failed.

Problem determination: Correct the error and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL294D HSCL294D

Explanation: Dynamic remove of Virtual I/O resources failed.

Problem determination: Correct the error and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL294E HSCL294E

Explanation: Dynamic add processing resources failed.

Problem determination: Retry the operation. If operation still fails, perform a Rebuild Managed System operation, and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL294F HSCL294F

Explanation: Dynamic remove processing resources failed.

Problem determination: Retry the operation. If operation still fails, perform a Rebuild Managed System operation, and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL2950 HSCL2950

Explanation: Dynamic partitioning operation on the PCI Host Bridge failed.

Problem determination: Ensure you have the resources available to perform the operation. Retry the operation. If operation still fails, perform a Rebuild Managed System operation, and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL2952 HSCL2952

Explanation: The dynamic logical partitioning requested could not be completed due to an unknown error(s) in the local system. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL2953 HSCL2953

Explanation: Dynamic add of processing resources failed. Trial CoD processors are still in use after the Trial CoD activation period has expired.

Problem determination: Immediately make this capacity available to be reclaimed by the system by removing the processors from partitions, or enter a CUoD processor activation code to permanently activate this capacity.

HSCL2954 HSCL2954

Explanation: Dynamic move of processing resources failed. Trial CoD processors are still in use after the Trial CoD activation period has expired.

Problem determination: Immediately make this capacity available to be reclaimed by the system by removing the processors from partitions, or enter a CUoD processor activation code to permanently activate this capacity.

HSCL2955 HSCL2955

Explanation: Dynamic add of memory resources failed. Trial CoD memory is still in use after the Trial CoD activation period has expired.

Problem determination: Immediately make this capacity available to be reclaimed by the system by removing the memory from partitions, or enter a CUoD memory activation code to permanently activate this capacity.

HSCL2956 HSCL2956

Explanation: Dynamic move of memory resources failed. Trial CoD memory is still in use after the Trial CoD activation period has expired.

Problem determination: Immediately make this capacity available to be reclaimed by the system by removing the memory from partitions, or enter a CUoD memory activation code to permanently activate this capacity.

HSCL2957 HSCL2957

Explanation: There is currently no RMC connection between the management console and the RPA partition. This could be because the partition is inactive, a firewall, or an improper network setup causing RMC not to recognize the partition. Please check the system network setup.

Problem determination: Ensure that the network connection is working between management console and the partition. If the problem persists, contact your next level of support or your service provider.

HSCL2958 HSCL2958

Explanation: A Workload manager, such as eWLM, seems to be running on the selected partition.

Problem determination: It is highly recommended that you shutdown the manager prior to proceeding. If you choose to continue, you should synchronize the current state of the system with that which the workload manager has set. If you choose to continue, you may receive unexpected results.

HSCL2959 HSCL2959

Explanation: You are attempting to change resources dynamically on an AIX, Linux, or virtual I/O server logical partition, and the management console cannot connect with the Resource Monitoring and Control (RMC) daemon on the operating system of that logical partition. RMC requires an active LAN connection to the management console for its resource configuration and management functions.

Problem determination: Possible causes are as follows: The LAN is not configured to connect the management console and the operating system of the logical partition directly together. (You might choose to configure your LAN in this way for security purposes.) The connection between the management console and the operating system of the logical partition is broken. The RMC daemon is not running on the operating system of the logical partition. If you want to connect the RMC daemon and the management console, cancel this operation, ensure the connection is available and operational, and retry the procedure. Otherwise, shutdown the partition and then retry the procedure.

HSCL295A HSCL295A

Explanation: An error occurred while trying to correct the pending memory resource.

Problem determination: Please retry the operation.

HSCL2960 HSCL2960

Explanation: An error occurred while trying to correct the pending processor resource.

Problem determination: Please retry the operation.

HSCL2961 HSCL2961

Explanation: An error occurred while trying to unassign the io slot. There were partitions that were corrected.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2962 HSCL2962

Explanation: An error occurred while trying to re-sync the io slot resource.

Problem determination: Please retry the operation.

HSCL2963 HSCL2963

Explanation: An error occurred while trying to correct the pending memory value. There were partitions that were corrected.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2964 HSCL2964

Explanation: An error occurred while trying to correct the pending processor value. There were partitions that were corrected.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2965 HSCL2965

Explanation: Dynamic add of processing resources failed. The requested number of processors to be added exceeds the number of processors that are currently available for i5/OS partitions.

Problem determination: If there are processors currently available for i5/OS partitions, reduce the requested number of processors to be added to be less than or equal to that number. Alternatively, shut down other i5/OS partitions or use Dynamic Logical Partitioning to remove processing resources from other i5/OS partitions to release enough processors. Note that the number of i5/OS processors in use by an uncapped i5/OS partition is equivalent to the number of virtual processors in use by that partition. Therefore, in order to release i5/OS processors from an uncapped i5/OS partition, you must release virtual processors from that partition. Releasing one virtual processor from an uncapped i5/OS partition will release one physical i5/OS processor. Try the task again.

HSCL2966 HSCL2966

Explanation: Dynamic add of processing resources failed. The requested number of processing units to be added exceeds the number of processing units that are currently available for i5/OS capped partitions.

Problem determination: If there are processing units currently available for i5/OS capped partitions, reduce the requested number of processing units to be added to be less than or equal to that number. Alternatively, shut down other i5/OS partitions or use Dynamic Logical Partitioning to remove processing resources

from other i5/OS partitions to release enough processing units. Note that the number of i5/OS processing units in use by an uncapped i5/OS partition is equivalent to the number of virtual processors in use by that partition. Therefore, in order to release i5/OS processing units from an uncapped i5/OS partition, you must virtual processors from that partition. Releasing one virtual processor from an uncapped i5/OS partition will release one physical i5/OS processing unit. Try the task again.

HSCL2967 HSCL2967

Explanation: Dynamic add of processing resources failed. The requested number of virtual processors to be added exceeds the number of virtual processors that are currently available for i5/OS uncapped partitions.

Problem determination: If there are virtual processors currently available for i5/OS uncapped partitions, reduce the requested number of virtual processors to be added to be less than or equal to that number. Alternatively, shut down other i5/OS partitions or use Dynamic Logical Partitioning to remove processing resources from other i5/OS partitions to release enough virtual processors. To add one virtual processor to an uncapped i5/OS partition, one physical i5/OS processor must be available. Try the task again.

HSCL2968 HSCL2968

Explanation: Dynamic move of processing resources failed. The requested number of processors cannot be moved to the i5/OS partition because doing so would cause the i5/OS processor capacity limit for processors for this managed system to be exceeded.

Problem determination: If possible, reduce the requested number of processors to be moved to the i5/OS partition, and try the task again. Alternatively, move processing resources from other i5/OS partitions to this partition. Alternatively, shut down other i5/OS partitions to release i5/OS processors. Note that the number of i5/OS processors in use by an uncapped i5/OS partition is equivalent to the number of virtual processors in use by that partition. Therefore, shutting down an uncapped i5/OS partition will release one physical i5/OS processor for each virtual processor assigned to that partition.

HSCL2969 HSCL2969

Explanation: Dynamic move of processing resources failed. The requested number of processing units cannot be moved to the i5/OS partition because doing so would cause the i5/OS processor capacity limit for processing units for this managed system to be exceeded.

Problem determination: If possible, reduce the requested number of processing units to be moved to the i5/OS partition, and try the task again.

HSCL296A • HSCL2975

Alternatively, move processing resources from other i5/OS partitions to this partition. Alternatively, shut down other i5/OS partitions to release i5/OS processing units. NOTE The number of i5/OS processing units in use by an uncapped i5/OS partition is equivalent to the number of virtual processors in use by that partition. Therefore, shutting down an uncapped i5/OS partition will release one physical i5/OS processor.

HSCL296A HSCL296A

Explanation: Dynamic move of processing resources failed. The requested number of virtual processors cannot be moved to the i5/OS partition because doing so would cause the i5/OS processor capacity limit for processors for this managed system to be exceeded.

Problem determination: If possible, reduce the requested number of virtual processors to be moved to the i5/OS partition, and try the task again. Alternatively, move processing resources from other i5/OS partitions to this partition. Alternatively, shut down other i5/OS partitions to release i5/OS virtual processors. To move one virtual processor to an uncapped i5/OS partition, one physical i5/OS processor must be available.

HSCL296B HSCL296B

Explanation: The i5/OS partition cannot be changed to an uncapped partition because too many virtual processors are assigned to the partition. Reduce the number of virtual processors assigned to the partition and try again.

Problem determination: Make sure that the maximum number of virtual processors defined for the partition is less than or equal to the i5/OS processor capacity limit for your managed system. If it is not, then reduce the maximum number of virtual processors defined in the partition's profile, and then reactivate the partition. Try the task again. Use Dynamic Logical Partitioning to remove virtual processors from the partition until the total number of processing resources in use by all i5/OS partitions, including the number of virtual processors assigned to this partition, does not exceed the i5/OS processor capacity limit for your managed system. Note that the number of i5/OS processors in use by an uncapped i5/OS partition is equivalent to the number of virtual processors in use by that partition. Alternatively, shut down other i5/OS partitions or use Dynamic Logical Partitioning to remove processing resources from other i5/OS partitions to release enough virtual processors for this partition. Try the task again.

HSCL296D HSCL296D

Explanation: The number of commands to be run in partition batch mode for this operation will exceed the maximum number of batch mode commands the system firmware supports.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL2970 HSCL2970

Explanation: The IOServer command has failed.

Problem determination: Retry the command. If the problem persists, contact your next level of support or your service provider.

HSCL2971 HSCL2971

Explanation: The IOServer command fails because the partition is unknown to RMC/partitionCmdRM. This could be because of a firewall or an improper network setup causing RMC not to recognize the partition. Check the system network setup.

Problem determination: This could be caused by a firewall or an incorrect network setup causing Resources Monitoring Control (RMC) not to recognize the partition. Check the system network setup.

HSCL2972 HSCL2972

Explanation: There is no active session between the management console and the partition.

Problem determination: There could be a short interruption in the network causing Resources Monitoring Control (RMC) to not recognize the partition. Retry the operation later or restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL2973 HSCL2973

Explanation: The IOServer command contained illegal characters such as ; or > .

Problem determination: Illegal characters are in the IOServer command. Check the IOServer command to make sure it does not include illegal characters, and try the task again.

HSCL2974 HSCL2974

Explanation: The active profile includes all resources. You are not allowed to add, remove, or move resources from this configuration

Problem determination: No recovery action.

HSCL2975 HSCL2975

Explanation: The IOClient command has failed.

Problem determination: No recovery action.

HSCL2976 HSCL2976

Explanation: The IOClient command fails because the partition is unknown to RMC/partitionCmdRM. This could be because the partition is inactive, or because a firewall or an improper network setup causing RMC not to recognize the partition. Please check the system network setup.

Problem determination: Check the system network setup.

HSCL2977 HSCL2977

Explanation: The IOClient command contains illegal characters such as ; or > .

Problem determination: No recovery action.

HSCL2978 HSCL2978

Explanation: The partition is not in the Running state. First activate the partition and try the operation again.

Problem determination: Activate the partition and try the operation again.

HSCL2979 HSCL2979

Explanation: There was an error retrieving the Virtual IO connection status for the managed system. Execute a rebuild managed system operation. If the error persists contact your service representative.

Problem determination: Perform a rebuild of the managed system. Try the task again. If the operation still fails, contact support.

HSCL297A HSCL297A

Explanation: There are some mismatches between pending and current values.

Problem determination: Run the rsthwres command to re-sync values.

HSCL297B HSCL297B

Explanation: The dynamic logical partitioning requested could not be completed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL297C HSCL297C

Explanation: The new total number of processing units for this partition exceeds this partition's maximum processing units limit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL297D HSCL297D

Explanation: The new total number of processing units for this partition is below this partition's minimum processing units limit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL297E HSCL297E

Explanation: There was an internal management console error.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCL297F HSCL297F

Explanation: The request to add the I/O adapter has timed out on the managed system.

Problem determination: Please check the I/O adapter in the partition for reasons the operation timed out before trying the operation again with an increased timeout value.

HSCL2980 HSCL2980

Explanation: The request to remove the I/O adapter has timed out on the managed system.

Problem determination: Please check the I/O adapter in the partition for reasons the operation timed out before trying the operation again with an increased timeout value.

HSCL2981 HSCL2981

Explanation: The request to move the I/O adapter has timed out on the managed system.

Problem determination: Please check the I/O adapter in the partition for reasons the operation timed out before trying the operation again with an increased timeout value.

HSCL2990 HSCL2990

Explanation: An error occurred when changing the value of the Active Memory Expansion factor.

Problem determination: Try the operation again.

HSCL299A HSCL299A

Explanation: SSlot is already assigned to partition.

Problem determination: Try the operation again.

HSCL299B

HSCL299B HSCL299B

Explanation: SLot is not assigned to partition.

Problem determination: Try the operation again.

(HSCL3xxx) Reference codes

HSCL3001 HSCL3001

Explanation: LED operations are not supported with this CSP version.

Problem determination: For LED operations, please upgrade to CSP version 3.0 or greater.

HSCL3002 HSCL3002

Explanation: The LED operation failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3004 HSCL3004

Explanation: The indicator state is invalid for location.

Problem determination: Check the indicator state and try again.

HSCL3005 HSCL3005

Explanation: Cannot currently perform LED operation.

Problem determination: There is another LED operation in progress. Wait and retry the operation.

HSCL3006 HSCL3006

Explanation: The LED operation failed. Refer to the management console Operations Guide for more details.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3007 HSCL3007

Explanation: Cannot currently perform LED operation.

Problem determination: There is another LED operation in progress. Wait and retry the operation.

HSCL3008 HSCL3008

Explanation: Errors occurred during the LED operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3009 HSCL3009

Explanation: The request type for the LED operation is not valid.

Problem determination: Refer to the management console Operations Guide for more details.

HSCL3051 HSCL3051

Explanation: An error occurred during frame initialization.

Problem determination: Not all I/O may have been powered on. Please retry the operation.

HSCL3052 HSCL3052

Explanation: An error occurred during frame initialization.

Problem determination: Not all managed systems could be powered on. Please retry the operation.

HSCL3053 HSCL3053

Explanation: An unknown error occurred during frame initialization.

Problem determination: Please retry the operation.

HSCL3054 HSCL3054

Explanation: An error occurred during frame initialization.

Problem determination: Please retry the operation.

HSCL3055 HSCL3055

Explanation: An error occurred while deactivating CSPs.

Problem determination: Please retry the operation.

HSCL3056 HSCL3056

Explanation: An error occurred during the pinhole reset.

Problem determination: Please retry the operation.

HSCL3057 HSCL3057

Explanation: An error occurred while deactivating I/O units.

Problem determination: Please retry the operation.

HSCL3058 • HSCL3072

HSCL3058 HSCL3058

Explanation: Frame information retrieval failed.

Problem determination: Please retry the operation.

HSCL3059 HSCL3059

Explanation: The refresh operation failed.

Problem determination: Please retry the operation.

HSCL305A HSCL305A

Explanation: The wrong number of cages was received.

Problem determination: The I/O cages must be specified in pairs. Please retry the operation.

HSCL305B HSCL305B

Explanation: The list of I/O units to deactivate was not sent correctly.

Problem determination: Please send the cage numbers of the I/O units in pairs.

HSCL305C HSCL305C

Explanation: The connection to the hardware server failed.

Problem determination: Please retry the operation.

HSCL305D HSCL305D

Explanation: An error occurred while setting the frame number.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL305E HSCL305E

Explanation: Unable to set the frame number.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL305F HSCL305F

Explanation: Either the connection to the bulk power assembly was lost, or there is no bulk power assembly.

Problem determination: Please retry the operation or contact your service representative.

HSCL3060 HSCL3060

Explanation: The managed frames failed to initialize. If the error persists, contact your software service representative.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3061 HSCL3061

Explanation: An error occurred while deactivating the High Performance Switch(s).

Problem determination: Please retry the operation.

HSCL3062 HSCL3062

Explanation: The frame number cannot be set because the system's Emergency Power Off(EPO) Switch is not in the OFF state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3063 HSCL3063

Explanation: The frame number cannot be set because the system is in an invalid state to perform this operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3070 HSCL3070

Explanation: The Frame lock action failed. Try the operation again.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3071 HSCL3071

Explanation: The Frame Guided Maintenance operation failed. Try the operation again.

Problem determination: Try the operation again. If the problem persists, contact your hardware representative.

HSCL3072 HSCL3072

Explanation: The Frame FRU deactivation operation failed. Try the operation again.

Problem determination: Try the operation again. If the problem persists, contact your hardware representative.

HSCL3073 HSCL3073

Explanation: The Frame FRU activation operation failed. Try the operation again.

Problem determination: Try the operation again. If the problem persists, contact your hardware representative.

HSCL3074 HSCL3074

Explanation: The frame host information was not saved. Ensure the management console has enough disk space and the correct file permission and try the operation again.

Problem determination: Ensure that the /opt/hsc/data directory contains enough disk space so that the management console can save the frame host information when needed.

HSCL3075 HSCL3075

Explanation: The frame host information that was found is not valid. Check the host information you provided and try the operation again.

Problem determination: Check the frame host information that was entered into the application program to ensure the host name, password, and frame bulk power controller (BPC) internal identification are valid.

HSCL3076 HSCL3076

Explanation: An error has occurred while attempting the bulk power assembly connection operation. Retry the operation. If the problem persists, contact your service representative.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3077 HSCL3077

Explanation: This operation is not allowed in the frame's current state. In order for this operation to be performed, at least one bulk power assembly (BPA) must be in the Standby state.

Problem determination: Make sure that at least one bulk power assembly is in the Standby state, and try the operation again. If the problem persists, contact your hardware representative.

HSCL3078 HSCL3078

Explanation: The request to power on the drawer or planar for the frame failed. Try the request again.

Problem determination: Try the request again. If the problem persists, contact your service provider.

HSCL3079 HSCL3079

Explanation: The request to add a drawer to the frame failed. Try the request again.

Problem determination: Try the request again. If the problem persists, contact your service provider.

HSCL307A HSCL307A

Explanation: This operation cannot be performed because the management console is not connected to side of the bulk power assembly (BPA). Check the connection and try the operation again.

Problem determination: Check the connection. Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL3080 HSCL3080

Explanation: The request to remove a planar from the frame failed. Try the request again.

Problem determination: Try the request again. If the problem persists, contact your next level of support or your service provider.

HSCL3081 HSCL3081

Explanation: The request to remove a drawer from the frame failed. Try the request again.

Problem determination: Try the request again. If the problem persists, contact your next level of support or your service provider.

HSCL3082 HSCL3082

Explanation: The request to send the frame IP information to the managed system has failed.

Problem determination: Try the request again. If the problem persists, contact your next level of support or your service provider.

HSCL3083 HSCL3083

Explanation: This operation is not allowed when the cage is powered on. Before this operation can be performed, all the cages must be powered off.

HSCL3084 HSCL3084

Explanation: This operation is not allowed when the BPA is in any of the following states: Incomplete, No Connection, or Not Available. After you have established a connection from the management console to the BPA, and have entered a valid management console access password, try the operation again.

HSCL3086 • HSCL3301

HSCL3086 HSCL3086

Explanation: The BPA service lock is currently held by another management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3087 HSCL3087

Explanation: There are different versions of this BPA command.

Problem determination: Please use the appropriate version according to your BPA hardware level.

HSCL3088 HSCL3088

Explanation: The request to get the managed frame environmental information failed.

Problem determination: Try the operation again.

HSCL3089 HSCL3089

Explanation: The request to get the environmental information for the systems in the managed frame failed.

Problem determination: Try the operation again.

HSCL3090 HSCL3090

Explanation: The request to set the frame number failed.

Problem determination: Try the operation again.

HSCL3091 HSCL3091

Explanation: The request to power on the frame cage failed.

Problem determination: Try the operation again.

HSCL3092 HSCL3092

Explanation: The request to power off the frame cage failed.

Problem determination: Try the operation again.

HSCL3093 HSCL3093

Explanation: The request to power off the unowned cages failed.

Problem determination: Try the operation again.

HSCL3200 HSCL3200

Explanation: Unknown lock error.

Problem determination: Contact your next level of support or your service provider.

HSCL3201 HSCL3201

Explanation: Lock type not valid.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL3202 HSCL3202

Explanation: Failed to acquire lock because of timeout.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL3203 HSCL3203

Explanation: Nested lock type requested not valid.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL3204 HSCL3204

Explanation: Lock not held.

Problem determination: Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL3205 HSCL3205

Explanation: The managed system is busy, try the operation again later.

Problem determination: The managed system is busy doing another action. Wait and then retry the action.

HSCL3300 HSCL3300

Explanation: Partition cannot be activated with SNI adapter because this adapter is already being used by another partition.

Problem determination: Please remove this SNI adapter from your profile configuration, and retry the operation.

HSCL3301 HSCL3301

Explanation: Partition cannot be activated with SNI adapter because the adapter has already been assigned to its maximum number of logical partitions.

Problem determination: Please remove this SNI

adapter from your profile configuration, and retry the operation.

HSCL3302 HSCL3302

Explanation: Partition cannot be activated with SNI adapter because not enough windows are available on adapter.

Problem determination: Please remove this SNI adapter from your profile configuration, and retry the operation.

HSCL3303 HSCL3303

Explanation: The partition cannot be activated because an SNI adapter pair was bad.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3304 HSCL3304

Explanation: Adapters should be sent down in pairs.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3305 HSCL3305

Explanation: The partition cannot be activated because the SNI adapter pair are not installed or have been removed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3351 HSCL3351

Explanation: The code update process is not allowed by the management console. Check the code update status to verify the code update owner.

Problem determination: Check the code update status to verify the code update owner. Retry the operation if management console is the code update owner. If the problem persists, contact your next level of support or your service provider.

HSCL3352 HSCL3352

Explanation: Code update is already in progress by another management console or by the firmware. Verify that no other code update is in progress and retry the operation.

Problem determination: Verify that no other code update operation is in progress and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3353 HSCL3353

Explanation: Code update is not allowed to the specified side. Check the current flash side.

Problem determination: Rebuild the managed operation. Check the power-on side from the managed system property panel and ensure you are not performing code update to the power-on side and then retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3354 HSCL3354

Explanation: Code update is already in progress from this management console. Ensure that no code update operation is in progress on the management console before retrying the operation.

Problem determination: Ensure that no code update operation is in progress on the management console before retrying the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3355 HSCL3355

Explanation: The code update operation failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3356 HSCL3356

Explanation: The code update is not in progress by this management console. The start code update task should have been performed prior to code update complete by this management console.

Problem determination: Ensure that the start code update task has been performed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3357 HSCL3357

Explanation: The operation failed since another commit or long running code update is in progress.

Problem determination: Ensure that no other code update operation is in progress. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3358 HSCL3358

Explanation: The delete LID operation is not allowed when a write LID is in progress.

Problem determination: Ensure that no other code update operation is in progress. Retry the operation. If

HSCL3359 • HSCL3372

the problem persists, contact your next level of support or your service provider.

HSCL3359 HSCL3359

Explanation: The code update operation failed since an invalid LID ID was specified.

Problem determination: Check the LID file ID and retry the operation with a valid LID file ID. If the problem persists, contact your next level of support or your service provider.

HSCL3360 HSCL3360

Explanation: Error accessing the flash.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3361 HSCL3361

Explanation: An unknown error occurred during code update operation. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3362 HSCL3362

Explanation: An unknown error occurred during reboot service processor. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3363 HSCL3363

Explanation: The size of the LID number array is not the same as the Filename array. Ensure every LID number has a corresponding filename.

Problem determination: Ensure every LID number has a corresponding filename and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3364 HSCL3364

Explanation: The read LID operation failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3365 HSCL3365

Explanation: Error: The file(s) already exist(s).

Problem determination: Ensure the files to read in the LID files do not exist and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3366 HSCL3366

Explanation: File(s) got an exception while reading the lid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3367 HSCL3367

Explanation: The input parameter arrays should all be of the same length. Check the lengths and retry the operation.

Problem determination: Ensure the lengths of the input parameters are the same and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3368 HSCL3368

Explanation: The Max write block size for the start code update did not get set. Retry the operation.

Problem determination: Retry the operation for the LID files that failed. If the problem persists, contact your next level of support or your service provider.

HSCL3370 HSCL3370

Explanation: The deletion of the LID(s) failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3371 HSCL3371

Explanation: The write LID operation failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3372 HSCL3372

Explanation: The LID filenames are not files.

Problem determination: Ensure the LID files exist and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3373 HSCL3373

Explanation: The LID files are empty.

Problem determination: Ensure that the LID files are valid and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3374 HSCL3374

Explanation: The LID files do not exist.

Problem determination: Ensure the LID files exist and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3375 HSCL3375

Explanation: File(s) got an exception while writing the LID to the service processor.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3376 HSCL3376

Explanation: Invalid value returned from the service processor to indicate whether service partition firmware code LID updates are enabled or disabled.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3377 HSCL3377

Explanation: The start code update operation failed since an invalid component to update was specified. Retry the operation with the a valid firmware component to update.

Problem determination: Retry the operation with a valid firmware component to update. If the problem persists, contact your next level of support or your service provider.

HSCL3378 HSCL3378

Explanation: The start code update operation failed since the managed system is not in the valid state. Check the state of the managed system and retry the operation.

Problem determination: Check the state of the managed system and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3379 HSCL3379

Explanation: There is a permanent error in flash, retry the operation and if the problem persists contact support.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3380 HSCL3380

Explanation: The Code Update operation failed since the managed system is not in the Power Off, Operating, or Standby state. Check the managed system's state and retry the operation.

Problem determination: Check the state of the managed system and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3381 HSCL3381

Explanation: The Complete Code Update operation failed since an invalid completion type was specified. Retry the operation with a valid completion type.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3382 HSCL3382

Explanation: The Code Update is not in progress. The start code update operation needs to be performed before the Complete Code Update operation.

Problem determination: Ensure the start code update operation is performed first. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3383 HSCL3383

Explanation: One or more LIDs are invalid in the primary LID list.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3384 HSCL3384

Explanation: For the partial read the specified length was not read since the end of file flag was reached.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3385 HSCL3385

Explanation: Error: The file(s) specified an invalid data for the Special LID Designator or the code update side.

Problem determination: Retry the operation with valid special LID designator or the code update side. If the problem persists, contact your next level of support or your service provider.

HSCL3386 HSCL3386

Explanation: The read partial/special LID operation failed, since writing to the file on the management console got an error. Check the log for the error and retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3387 HSCL3387

Explanation: An unknown error occurred during the open of firmware files. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3388 HSCL3388

Explanation: The fileid-subid specified an invalid open type.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3389 HSCL3389

Explanation: The fileid-subid specified an invalid Force Flag.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3390 HSCL3390

Explanation: Error: The files got an exception while trying to open the firmware file.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3391 HSCL3391

Explanation: The open firmware file operation failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3392 HSCL3392

Explanation: An unknown error occurred during the write operation of firmware files. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3393 HSCL3393

Explanation: An unknown error occurred during the close of firmware files. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3394 HSCL3394

Explanation: An unknown error occurred during the get firmware status update operation. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3395 HSCL3395

Explanation: An unknown error occurred during the start firmware update operation. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3396 HSCL3396

Explanation: Failed to delete the partition since it is the service partition.

Problem determination: Ensure the partition is not the service partition. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL3397 HSCL3397

Explanation: The secondary service processor is not available for the managed system.

Problem determination: Check the FSP configuration and make sure that the service processor is installed and available for failover. If the problem persists,

contact your next level of support or your service provider.

HSCL3398 HSCL3398

Explanation: The code update service processor lock is already taken. Check that no other code update operation is running and retry the operation.

Problem determination: Check that no other code update operation is in progress and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3399 HSCL3399

Explanation: The code update service processor lock is not taken. Ensure the lock is taken before trying to release the code update service processor lock.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3400 HSCL3400

Explanation: The service processor target that was specified is not valid. Verify the service processor target name and try the request again.

Problem determination: Rebuild the managed frame. Try the task again. If the problem persists, contact your service provider.

HSCL3401 HSCL3401

Explanation: The get power domain operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3402 HSCL3402

Explanation: The get power domain power state operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3403 HSCL3403

Explanation: The set service lock operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3404 HSCL3404

Explanation: The reset service lock operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3405 HSCL3405

Explanation: The FRU level activate operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3406 HSCL3406

Explanation: The FRU level deactivate operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3407 HSCL3407

Explanation: The vary off power domain platform operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3408 HSCL3408

Explanation: The vary off power domain platform operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3409 HSCL3409

Explanation: The vary on power domain platform operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3410 HSCL3410

Explanation: The vary off power domain partition operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3411 HSCL3411

Explanation: The vary off power domain partition operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3412 HSCL3412

Explanation: The vary on power domain partition operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3413 HSCL3413

Explanation: No Partitions are defined for the managed system. Check the user interface to see if partitions are defined and then retry the operation.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL3414 HSCL3414

Explanation: The start I/O concurrent maintenance operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3415 HSCL3415

Explanation: The I/O concurrent maintenance operation failed. Retry the operation.

Problem determination: The I/O concurrent maintenance command failed. Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3416 HSCL3416

Explanation: The get configuration ID operation failed. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3417 HSCL3417

Explanation: The set configuration ID operation failed. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3418 HSCL3418

Explanation: The get IO unit configuration ID and MTMS operation failed. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3419 HSCL3419

Explanation: The set IO unit MTMS operation failed. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3420 HSCL3420

Explanation: The set IO unit configuration ID operation failed. Retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3421 HSCL3421

Explanation: This operation is not allowed in the managed system's current state. Check the state of the managed system and retry the operation.

Problem determination: Check the state of the managed system and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3422 HSCL3422

Explanation: This operation cannot be completed because a conflicting concurrent maintenance operation is already in progress. Ensure that the other operation has completed and then retry the operation.

Problem determination: Retry the operation. If the

problem persists, contact your next level of support or your service provider.

HSCL3423 HSCL3423

Explanation: Invalid data was specified for this operation. Check the data and retry the operation.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3424 HSCL3424

Explanation: The I/O concurrent maintenance operation failed.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3425 HSCL3425

Explanation: The activate service processor operation failed.

Problem determination: Please retry the operation.

HSCL3426 HSCL3426

Explanation: The deactivate service processor operation failed.

Problem determination: Please retry the operation.

HSCL3427 HSCL3427

Explanation: The cleanup service processor operation failed.

Problem determination: Please retry the operation.

HSCL3428 HSCL3428

Explanation: The clear I/O slot operation failed.

Problem determination: Verify that the requested I/O slot is valid, and try the operation again. If this error persists, contact your service representative.

HSCL3429 HSCL3429

Explanation: The managed system does not support clearing I/O slots.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL342A HSCL342A

Explanation: The clear I/O bus operation failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCL3431 HSCL3431

Explanation: The command display service effect failed. Please retry the operation again.

HSCL3432 HSCL3432

Explanation: The system level deactivation failed. Please retry the operation.

HSCL3433 HSCL3433

Explanation: The system level deactivation failed. Please retry the operation.

HSCL3437 HSCL3437

Explanation: The managed system does not have Concurrent Maintenance capability. Please upgrade the firmware and retry the operation.

Problem determination: Upgrade the firmware that supports Platform Hardware Concurrent Maintenance and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3438 HSCL3438

Explanation: The managed system does not have PHYP Concurrent Maintenance capability. Please upgrade the firmware and retry the operation.

Problem determination: Upgrade the firmware that supports Platform Hardware Concurrent Maintenance and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3439 HSCL3439

Explanation: Query FSP CM Service Lock failed. Please retry the operation.

Problem determination: Please retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL3440 HSCL3440

Explanation: The Get Node Controller Configuration command failed.

Problem determination: Try the operation again.

HSCL3441 • HSCL350F

HSCL3441 HSCL3441

Explanation: The location code of the unit to be varied off cannot be null.

Problem determination: Try the operation again.

HSCL3442 HSCL3442

Explanation: Cannot begin the service procedure for the given service type.

Problem determination: Try the operation again.

HSCL3443 HSCL3443

Explanation: The platform does not support Concurrent Maintenance.

Problem determination: Please upgrade the firmware and try the operation again.

HSCL3445 HSCL3445

Explanation: The managed system does not support reserved I/O slots.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3500 HSCL3500

Explanation: The function completed successfully.

HSCL3501 HSCL3501

Explanation: The operation failed because of a non-trivial reason.

Problem determination: Restart the management console and retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL3503 HSCL3503

Explanation: Input error: The specified value is out of range or undefined.

Problem determination: Contact your next level of support or your service provider.

HSCL3504 HSCL3504

Explanation: An invalid input file or an error has occurred during an operation on the specified file.

Problem determination: Restart the system. If the problem persists, contact your next level of support or your service provider.

HSCL3505 HSCL3505

Explanation: An error occurred while contacting the access control system. Retry the operation.

Problem determination: Restart the system. If the problem persists, contact your next level of support or your service provider.

HSCL350A HSCL350A

Explanation: Invalid input parameter(s).

Problem determination: Check the input and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL350B HSCL350B

Explanation: The user does not have the appropriate authority.

Problem determination: Try the task again. Restart the system. If the problem persists, contact your next level of support or your service provider.

HSCL350C HSCL350C

Explanation: Input error: An invalid operation has been specified.

Problem determination: Check the input and try the task again. Restart the system. If the problem persists, contact your next level of support or your service provider.

HSCL350D HSCL350D

Explanation: Input error: An invalid user ID has been specified.

Problem determination: Check the input and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL350E HSCL350E

Explanation: Input error: An invalid task has been specified.

Problem determination: Check the input and try the task again. Restart the system. If the problem persists, contact your next level of support or your service provider.

HSCL350F HSCL350F

Explanation: Input error: The input resource is not valid or conflicts with the role in the operation.

Problem determination: Check the input and try the task again. Restart the system. If the problem persists, contact your next level of support or your service provider.

HSCL3510 HSCL3510

Explanation: Input error: An invalid role or parent role has been specified.

Problem determination: Check the input and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL3511 HSCL3511

Explanation: Input error: An invalid subsystem has been specified.

Problem determination: Check the input and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL3512 HSCL3512

Explanation: Input error: An invalid option has been specified.

Problem determination: Check the input and try the task again. If the problem persists, contact your next level of support or your service provider.

HSCL3513 HSCL3513

Explanation: Input error: An invalid managed resource role name has been specified.

Problem determination: Check the input and try the task again. Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL3514 HSCL3514

Explanation: The role specified already exists.

Problem determination: A duplicate role name has been specified in the operation. Select a different name.

HSCL3532 HSCL3532

Explanation: An unknown error, such as an exception, has occurred during the operation.

Problem determination: Try the task again. Restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCL3533 HSCL3533

Explanation: Invalid operation. The input role is a system predefined role.

Problem determination: The operation is not allowed.

HSCL3534 HSCL3534

Explanation: An invalid assignment has been specified. The resource type of the assignment is invalid or conflicts with the user's role.

Problem determination: The resource type specified in the assignment is not valid or conflicts with the user role. Give the user a different assignment or role and retry the operation.

HSCL3563 HSCL3563

Explanation: The function specified is not available in the current release.

HSCL3601 HSCL3601

Explanation: Shared processor pool is not configured.

Problem determination: Configure the shared processor pool and retry the operation.

HSCL3604 HSCL3604

Explanation: Cannot proceed with the configuration of the shared processor pool.

Problem determination: Run the rebuild managed system operation, and try again.

HSCL3605 HSCL3605

Explanation: The shared processor pool ID specified is invalid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3606 HSCL3606

Explanation: A shared processor pool name or ID must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3607 HSCL3607

Explanation: Shared processor pool was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3609 HSCL3609

Explanation: Reserved processing units cannot be set for the default shared processor pool.

Problem determination: If the problem persists,

HSCL360A • HSCL3621

contact your next level of support or your service provider.

HSCL360A HSCL360A

Explanation: The maximum processing units of the default shared processor pool cannot be set.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL360B HSCL360B

Explanation: A shared processor pool already exists.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL360C HSCL360C

Explanation: The maximum processing units of a shared processor pool cannot exceed the set limit.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL360D HSCL360D

Explanation: The reserved processing units cannot equal or exceed the maximum processing units of the shared processor pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL360E HSCL360E

Explanation: The configuration of the shared processor pool cannot be changed as requested.

Problem determination: The sum of the processing units assigned to the partitions in the shared processor pool plus the reserved processing units in the shared processor pool cannot exceed the maximum processing units of the shared processor pool.

HSCL360F HSCL360F

Explanation: No shared processor pools exist in the management console's internal database.

Problem determination: Run the rebuild managed system operation, and try again.

HSCL3610 HSCL3610

Explanation: You cannot configure this many shared processor pools at a time.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3611 HSCL3611

Explanation: Shared processor pool ID specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3614 HSCL3614

Explanation: The shared processor pool cannot be unconfigured since at least one partition is using the shared processor pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3615 HSCL3615

Explanation: This operation is only allowed when the managed system is in the Standby or Operating state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3616 HSCL3616

Explanation: The partition is not associated with any shared processor pool.

Problem determination: Ensure that the partition has been activated at least once and is using a shared processor pool.

HSCL3620 HSCL3620

Explanation: There are a number of reserved processing units in the shared processor pools of the managed system.

Problem determination: If this partition must be activated, set the reserved processing units in all of the shared processor pools to zero.

HSCL3621 HSCL3621

Explanation: The managed system does not support multiple shared processor pools.

Problem determination: Set the shared processor pool ID to zero in the partition profile and try the operation again.

HSCL3622 HSCL3622

Explanation: This partition requires a number of processing units that exceeds the processing units available in shared processor pool.

Problem determination: Activating this partition will cause the maximum processing units of shared processor pool to be exceeded. If you want to activate this partition in this shared processor pool, perform one or more of the following actions, then activate this partition again. 1. Create a new profile or modify the existing profile to reduce the minimum processing units for this partition. 2. Shut down active partitions that are using this shared processor pool. 3. Reduce the number of reserved processing units in this shared processor pool.

HSCL3623 HSCL3623

Explanation: The partition cannot be activated because all shared processor partitions in the same workload group also have to be in the same shared processor pool.

Problem determination: If you want to activate the partition in workload group, modify the partition profile or create a new profile for the partition and set the shared processor pool ID. Then activate the partition again.

HSCL3624 HSCL3624

Explanation: The partition's workload group cannot be changed because this partition is using shared processor pool, and all of the shared processor partitions in workload group are using the same shared processor pool.

Problem determination: All of the shared processor partitions that belong to the same workload group must use the same shared processor pool.

HSCL3625 HSCL3625

Explanation: The partition add operation cannot be performed.

Problem determination: Adding the specified amount of processing units to the partition in shared processor pool will exceed the maximum processing units of the shared processor pool.

HSCL3626 HSCL3626

Explanation: The partition move operation cannot be performed.

Problem determination: Moving the specified amount of processing units to the partition in shared processor pool will exceed the maximum processing units of the shared processor pool.

HSCL3627 HSCL3627

Explanation: Pool ID specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3628 HSCL3628

Explanation: The name of the default shared processor pool cannot be changed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3629 HSCL3629

Explanation: The maximum processing units of the shared processor pool must be a whole number.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL362A HSCL362A

Explanation: The specified shared processor pool was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL362B HSCL362B

Explanation: The partition cannot be moved to the specified shared processor pool.

Problem determination: The number of processing units assigned to the partition will cause the shared processor pool to exceed its maximum processing units.

HSCL362C HSCL362C

Explanation: The partition cannot be moved to another shared processor pool since it belongs to the same workload group as at least one other partition.

Problem determination: All of the shared processor partitions that belong to the same workload group must use the same shared processor pool.

HSCL362D HSCL362D

Explanation: The partition cannot be migrated or remotely restarted because the processing resources it requires exceeds the available processing resources in the destination managed system's shared processor pool.

Problem determination: If possible, free up processing

HSCL362E • HSCL364B

resources from that shared processor pool, and try the operation again.

HSCL362E HSCL362E

Explanation: The migrating partition is using dedicated processors.

Problem determination: The specified shared processor pool will be ignored during the migration operation.

HSCL3640 HSCL3640

Explanation: The managed system does not support virtual switch configuration from the management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3641 HSCL3641

Explanation: The Virtual switch name specified already exists.

Problem determination: Choose a different name.

HSCL3642 HSCL3642

Explanation: The Virtual switch specified was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3643 HSCL3643

Explanation: The maximum number of virtual switches have already been created for this managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3644 HSCL3644

Explanation: The Virtual LAN specified was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3645 HSCL3645

Explanation: The Virtual switch specified cannot be removed because it is being used by an active partition.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCL3646 HSCL3646

Explanation: The Virtual LAN specified cannot be removed because it is being used by an active partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3647 HSCL3647

Explanation: One or more inactive partitions have virtual Ethernet adapters that are configured to use the virtual switch.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3648 HSCL3648

Explanation: One or more inactive partitions have virtual ethernet adapters that are configured to use the virtual LAN.

Problem determination: Specify the --force option to remove the virtual LAN.

HSCL3649 HSCL3649

Explanation: The partition cannot be migrated because the partition is using the virtual switch which does not exist on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL364A HSCL364A

Explanation: The default virtual switch cannot be removed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL364B HSCL364B

Explanation: One or more partition profiles have virtual ethernet adapters that are configured to use the virtual switch.

Problem determination: To remove the virtual switch, you must first remove all references to the virtual switch from your partition profiles.

HSCL364E HSCL364E

Explanation: The specified virtual switch name is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL364F HSCL364F

Explanation: Virtual I/O Server partition does not support partition virtual switch functions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3650 HSCL3650

Explanation: The default virtual switch names do not match on the source and destination managed systems.

Problem determination: All of the virtual Ethernet adapters using the source managed system's default virtual switch will be assigned to the destination managed system's default virtual switch, and those virtual Ethernet adapters may not function properly after the migration.

HSCL3651 HSCL3651

Explanation: The virtual switch is used by a source partition's virtual Ethernet adapter.

Problem determination: There is no virtual switch on the destination managed system with this name. Therefore, the management console will create a new virtual switch on the destination managed system during the migration process.

HSCL3652 HSCL3652

Explanation: The destination managed system does not support non-default virtual switches.

Problem determination: A virtual Ethernet adapter using a non-default virtual switch may not function properly after the migration.

HSCL3653 HSCL3653

Explanation: The Secure Shell (SSH) communication configuration between the source and destination management consoles has not been set up properly for the user.

Problem determination: Run the mkauthkeys command to set up the SSH communication authentication keys.

HSCL3654 HSCL3654

Explanation: The host key may have just been changed.

Problem determination: Add correct host key `/.ssh/known_hosts` to get rid of this message. The host key for the remote server has changed and you have requested strict checking. Please run the mkauthkeys command again to set up the SSH communication authentication keys.

HSCL3655 HSCL3655

Explanation: The Secure Shell (SSH) communication to the destination management console has failed.

Problem determination: Check if the specified remote management console IP address or host name is valid.

HSCL3656 HSCL3656

Explanation: There is an insufficient amount of memory available on the destination managed system for the configuration of the partition.

Problem determination: Please perform one or both of the following actions: 1. Remove memory from any shutdown dedicated memory partitions on the destination managed system. 2. Remove memory from any running dedicated memory partitions on the destination managed system.

HSCL3657 HSCL3657

Explanation: The device selected for this partition cannot be activated on Virtual I/O Server partition.

Problem determination: Remove this device from the reserved storage device pool or shared memory pool, then try migrating this partition again.

HSCL3658 HSCL3658

Explanation: The Partition specified is not in the correct definition state to perform release all resource operations.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3659 HSCL3659

Explanation: The partition migration has been stopped because orchestrator detected an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL365A HSCL365A

Explanation: The partition migration has been stopped because source MSP detected an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL365B HSCL365B

Explanation: The partition migration has been stopped because partition firmware detected an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL365C HSCL365C

Explanation: The partition migration has been stopped because platform firmware detected an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL365D HSCL365D

Explanation: The partition migration has been stopped because target MSP detected an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL365E HSCL365E

Explanation: The partition migration has been stopped because migrating partition detected an error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL365F HSCL365F

Explanation: The partition cannot be migrated because the maximum processor setting exceeds the maximum system capacity on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3660 HSCL3660

Explanation: The partition cannot be migrated because the maximum virtual processor setting exceeds the maximum system capacity of virtual processors on the destination managed system.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCL3661 HSCL3661

Explanation: The partition will not be activated successfully on the destination managed system with the generated migration profile because the maximum processor setting exceeds the maximum system capacity of processors on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3662 HSCL3662

Explanation: The partition will not be activated successfully on the destination managed system with the generated migration profile because the maximum virtual processor setting exceeds the maximum system capacity of virtual processors on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3663 HSCL3663

Explanation: The partition cannot be migrated because the current processor usage exceeds the limit of processors for a partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3664 HSCL3664

Explanation: The partition cannot be migrated because the current virtual processor usage exceeds the limit of virtual processors for a partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3665 HSCL3665

Explanation: In the generated migration profile, the desired processor setting exceeds the limit of processors for a partition on the destination managed system.

Problem determination: When activated with this profile on the destination managed system, the partition cannot obtain more processors than this limit.

HSCL3666 HSCL3666

Explanation: In the generated migration profile, the desired virtual processor setting exceeds the limit of virtual processors for a partition on the destination managed system.

Problem determination: When activated with this profile on the destination managed system, the partition cannot obtain more virtual processors than this limit.

HSCL3667 HSCL3667

Explanation: The partition will not be activated successfully on the destination managed system with the generated migration profile because the minimum processor setting exceeds the limit of processors for a partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3668 HSCL3668

Explanation: The partition will not be activated successfully on the destination managed system with the generated migration profile because the minimum virtual processor setting exceeds the limit of virtual processors for a partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3669 HSCL3669

Explanation: The operation to set the inactive partition profile migration policy failed on the managed system.

Problem determination: Check the state of the managed system and try the operation again.

HSCL366A HSCL366A

Explanation: The partition migration operation failed because the source management console cannot validate that the OS level of the migrating partition supports moving from POWER6 processors to POWER7 processors.

Problem determination: To migrate the partition to a managed system with POWER7 processors, you must upgrade the source management console to V7R7.1, or later.

HSCL366B HSCL366B

Explanation: The processor class of the source managed system is different from the processor class of the destination managed system, therefore the partition cannot be migrated because its OS level does not support moving between processor classes.

Problem determination: Please upgrade the OS level of the partition, and try the operation again.

HSCL366C HSCL366C

Explanation: The managed system does not support virtual server network phase 2 configuration.

HSCL366E HSCL366E

Explanation: There is currently no RMC connection between the management console and the partitions associated with virtual switch. This could be because the partition is not in the Running state, or a firewall or an improper network setup is causing RMC not to recognize the partition.

Problem determination: Check the system network setup.

HSCL3670 HSCL3670

Explanation: There was an error accessing the management console persistent storage area.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL3680 HSCL3680

Explanation: Partition cannot be activated due to insufficient resources in its current configuration.

Problem determination: Please activate the partition with a profile.

HSCL3681 HSCL3681

Explanation: Partition cannot be activated since it is not in the Not Activated state.

HSCL3682 HSCL3682

Explanation: Partition cannot be activated due to an unknown error.

HSCL3683 HSCL3683

Explanation: Activation from current configuration task failed.

(HSCL4xxx) Reference codes

HSCL4000 HSCL4000

Explanation: The VIOS partition ID specified is either not valid or the VIOS is not responding.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4001 HSCL4001

Explanation: The VIOS storage pool name specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4002 HSCL4002

Explanation: The VIOS storage pool type specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4003 HSCL4003

Explanation: One or more of the physical device names are not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4004 HSCL4004

Explanation: The VIOS storage pool size specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4005 HSCL4005

Explanation: The VIOS storage pool backing file name specified is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4006 HSCL4006

Explanation: The VIOS storage pool creation operation failed for some unknown reason.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4007 HSCL4007

Explanation: The backing device is not in the specified storage pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4008 HSCL4008

Explanation: There was a VIOS RMC communication error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4009 HSCL4009

Explanation: There was a VIOS RMC communication error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL400A HSCL400A

Explanation: There was a problem running the VIOS command.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL400B HSCL400B

Explanation: The specified virtual disk name is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL400C HSCL400C

Explanation: A VIOS command syntax error has occurred.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL400D HSCL400D

Explanation: The execution of the VIOS command was incomplete.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL400E HSCL400E

Explanation: The VIOS reports insufficient memory to complete the command.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL400F HSCL400F

Explanation: The specified name is already in use.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4010 HSCL4010

Explanation: The specified virtual device was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4011 HSCL4011

Explanation: The file backing device name cannot exceed 38 characters in length.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4012 HSCL4012

Explanation: The physical disk is currently backing a storage pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4013 HSCL4013

Explanation: The physical disk is currently attached to a running partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4014 HSCL4014

Explanation: At least one VIOS with an active RMC connection is required for this task.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4015 HSCL4015

Explanation: The default storage pool cannot be removed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4016 HSCL4016

Explanation: There was an unknown VIOS error.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4017 HSCL4017

Explanation: There was an error running the command.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL4018 HSCL4018

Explanation: There was a command syntax error.

Problem determination: Usually this is an indicator of an incompatible VIOS version. Select OK to continue.

HSCL4019 HSCL4019

Explanation: There are no compatible adapters on the VIOS.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL401C HSCL401C

Explanation: The destination Server Virtual SCSI Device was not found by the Virtual I/O Server.

Problem determination: Run the command 'cfgdev' on the Virtual I/O Server and try the operation again.

HSCL401D HSCL401D

Explanation: An error occurred when verifying the backing device for vSwitch and VLAN on VIOS.

Problem determination: If the problem persists, contact your next level of support or your service provider.

(HSCL7xxx) Reference codes

HSCL7001 HSCL7001

Explanation: The partition profile was not found.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL7002 HSCL7002

Explanation: The partition was not found.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL7003 HSCL7003

Explanation: The partition was not found.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL7005 HSCL7005

Explanation: The partition was not found.

Problem determination: Rebuild the managed system. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL7007 HSCL7007

Explanation: The connection information in the database may be corrupted.

Problem determination: Retry the operation. If this error persists, Shut down and restart the management console to rebuild the database. Try the task again.

HSCL7009 HSCL7009

Explanation: This operation is only allowed when the partition is in the Not Activated, Suspended, or Running state.

(HSCL8xxx) Reference codes

HSCL8001 HSCL8001

Explanation: The frame entered was not found.

Problem determination: Please check your entry and retry the command.

HSCL8002 HSCL8002

Explanation: The managed system entered was not found. Check your entry and retry the command.

Problem determination: Ensure the inputs are correct. Retry the task. If the problem persists, contact your next level of support or your service provider.

HSCL8003 HSCL8003

Explanation: The partition entered was not found.

Problem determination: Please check your entry and retry the command.

HSCL8004 HSCL8004

Explanation: An error occurred while trying to perform the command.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL8005 HSCL8005

Explanation: The object could not be deleted because it was not found in the search order. Retry the command.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL8006 HSCL8006

Explanation: An error occurred while trying to perform the command.

Problem determination: A profile with the file name specified already exists. Please change the file name and retry the command.

HSCL8007 HSCL8007

Explanation: An error occurred while unpacking the corrective service file.

Problem determination: The file may be corrupted or the management console may have run out of disk

space. Please retry the command.

HSCL8008 HSCL8008

Explanation: An error occurred while trying to run corrective services. Check your entry and retry the command.

Problem determination: This is an unexpected error. Contact your next level of support or your service provider.

HSCL8009 HSCL8009

Explanation: An error occurred while attempting to remotely connect to the server. Retry the command.

Problem determination: An unexpected error occurred while trying to change the Web Server settings. Retry the command. If the problem persists, contact your next level of support or your service provider.

HSCL800A HSCL800A

Explanation: An error occurred while attempting to change web server settings. Retry the command.

Problem determination: An unexpected error occurred while trying to change the Web Server settings. Retry the command. If the problem persists, contact your next level of support or your service provider.

HSCL800B HSCL800B

Explanation: An error occurred while attempting to change user interface server settings. Retry the command.

Problem determination: An unexpected error occurred while trying to change the Web-based System Manager settings. Retry the command. If the problem persists, contact your next level of support or your service provider.

HSCL800C HSCL800C

Explanation: An error occurred while attempting to change syslogd settings. Retry the command.

Problem determination: An unexpected error occurred while trying to change the syslog settings. Retry the command. If the problem persists, contact your next level of support or your service provider.

HSCL800D HSCL800D

Explanation: Cannot specify both IP address and hostname.

Problem determination: A syntax error occurred. Retry the command with only one of the options (IP address or host name) specified.

HSCL800E HSCL800E

Explanation: An I/O exception occurred reading the file. Check the file and try again.

Problem determination: Check the file. Retry the command. If the problem persists, contact your next level of support or your service provider.

HSCL800F HSCL800F

Explanation: The partition profile was not found. Check your entry and retry the command.

Problem determination: Check the profile name entered to ensure that it is correct and retry the command. Rebuild the managed system and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL8010 HSCL8010

Explanation: The system profile was not found. Check your entry and retry the command.

Problem determination: Ensure that the system profile entered was correct, and retry the command. If this does not work, the system profile might be corrupted. Restore the profile data. If problem persists, delete and re-create a new system profile. If the problem persists, contact your next level of support or your service provider.

HSCL8011 HSCL8011

Explanation: The partition was not found. Check your entry and retry the command.

Problem determination: Ensure the correct partition ID was entered and retry the command. Rebuild the managed system and retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL8012 HSCL8012

Explanation: The partition was not found. Check your entry and retry the command.

Problem determination: Ensure you specified a valid partition. Retry the command. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL8013 HSCL8013

Explanation: The partition specified for the attribute was not found. Correct the configuration data and retry the command.

Problem determination: Ensure you specified a valid partition. Retry the command. Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCL8014 HSCL8014

Explanation: Error reading password.

Problem determination: Please retry the command.

HSCL8015 HSCL8015

Explanation: Licensed Internal Code cannot be updated.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL8016 HSCL8016

Explanation: An unknown error occurred while trying to perform this command. Retry the command. If the error persists, contact support.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL8017 HSCL8017

Explanation: This command is not allowed when the management console is in Cluster-Ready Hardware Server mode.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL8018 HSCL8018

Explanation: The managed system was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL8019 HSCL8019

Explanation: There is an insufficient amount of memory available in the shared memory pool to activate this partition.

Problem determination: If you want to activate this partition, you must increase the amount of memory available in the shared memory pool, or you must reduce the amount of I/O entitled memory required for

this partition. Some of your options are: 1. Increase the size of the shared memory pool. 2. Remove I/O entitled memory from any of the shutdown shared memory partitions. 3. Remove I/O entitled memory from any running shared memory partition. 4. If the profile you are trying to activate is configured to use automatic I/O entitled memory management, remove one or more virtual SCSI, virtual Ethernet, or virtual fibre channel adapters from the profile. 5. If the profile you are trying to activate is configured to use custom I/O entitled memory, reduce the amount of I/O entitled memory specified in the profile.

HSCL801A HSCL801A

Explanation: There is an insufficient amount of system memory available to activate this partition with the maximum memory setting specified in the profile.

Problem determination: If you want to activate this partition, you must decrease the maximum memory setting in the profile, or you must free sufficient system memory. Some of your options to free system memory are: 1. Remove memory from any of the shutdown dedicated memory partitions. 2. Remove memory from any running dedicated memory partition.

HSCL801B HSCL801B

Explanation: I/O entitled memory must be removed from partitions in the shared memory pool before the size of the shared memory pool can be decreased by the requested amount.

Problem determination: You can remove I/O entitled memory from any running shared memory partition, or remove I/O entitled memory from any of the shutdown shared memory partitions.

HSCL801C HSCL801C

Explanation: There is an insufficient amount of system memory available to increase the size of the shared memory pool by the requested amount.

Problem determination: If you want to increase the size of the shared memory pool by the requested amount, you must free sufficient system memory first. Some of your options to free system memory are: 1. Remove memory from any of the shutdown dedicated memory partitions. 2. Remove memory from any running dedicated memory partition.

HSCL801D HSCL801D

Explanation: The partition has an insufficient amount of I/O entitled memory to support this virtual adapter, and there is an insufficient amount of memory available in the shared memory pool that can be added to this partition to increase the amount of I/O entitled memory for this partition to the required amount.

Problem determination: An additional amount of I/O

entitled memory is required for this partition. If you want to add this virtual adapter to this partition, perform one or more of the following actions first. 1. Increase the size of the shared memory pool. 2. Remove I/O entitled memory from any of the shutdown shared memory partitions. 3. Remove I/O entitled memory from any running shared memory partition.

HSCL801E HSCL801E

Explanation: There is an insufficient amount of memory available in the shared memory pool to add the requested amount of I/O entitled memory to this partition.

Problem determination: If you want to add the requested amount of I/O entitled memory to this partition, perform one or more of the following actions first. 1. Increase the size of the shared memory pool. 2. Remove I/O entitled memory from any of the shutdown shared memory partitions. 3. Remove I/O entitled memory from any running shared memory partition.

HSCL801F HSCL801F

Explanation: There is an insufficient amount of memory available in the shared memory pool to add the required amount of I/O entitled memory to this partition to reset automatic I/O entitled memory management for this partition.

Problem determination: If you want to reset automatic I/O entitled memory management for this partition, perform one or more of the following actions first. 1. Increase the size of the shared memory pool. 2. Remove I/O entitled memory from any of the shutdown shared memory partitions. 3. Remove I/O entitled memory from any running shared memory partition.

HSCL8020 HSCL8020

Explanation: There is an insufficient amount of system memory available to create a shared memory pool of the requested size.

Problem determination: If you want to create the shared memory pool with that size, you must free sufficient system memory first. Some of your options to free system memory are: 1. Remove memory from any of the shutdown dedicated memory partitions. 2. Remove memory from any running dedicated memory partition.

HSCL8021 HSCL8021

Explanation: Partition profile was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL8022 • HSCL8026

HSCL8022 HSCL8022

Explanation: This command is only supported for POWER6 servers.

HSCL8023 HSCL8023

Explanation: The specified source profile was not found.

HSCL8024 HSCL8024

Explanation: The managed system does not support the setting of power-on speed attributes from the management console.

HSCL8025 HSCL8025

Explanation: The partition has an insufficient amount of I/O entitled memory to support this SR-IOV logical port, and there is an insufficient amount of memory available in the shared memory pool that can be added to this partition to increase the amount of I/O entitled memory for this partition to the required amount. Additional MB of I/O entitled memory is required for this partition.

Problem determination: If you want to add this SR-IOV logical port to this partition, perform one or more of the following actions first. 1. Increase the size of the shared memory pool. 2. Remove I/O entitled memory from any of the following shutdown or suspended shared memory partition. 3. Remove I/O entitled memory from any running shared memory partition.

HSCL8026 HSCL8026

Explanation: The system with IP address or host name is already managed by this management console.

(HSCL9xxx) Reference codes

HSCL9000 HSCL9000

Explanation: This operation is not allowed because Capacity on Demand is not supported on the managed system.

HSCL9001 HSCL9001

Explanation: The operation has failed on the managed system.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL9002 HSCL9002

Explanation: The operation has failed on the managed system.

Problem determination: Contact your hardware service representative.

HSCL9003 HSCL9003

Explanation: The operation has failed on the managed system. Retry the operation. If the failure persists, contact your hardware service representative.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL9004 HSCL9004

Explanation: The information could not be retrieved from the managed system.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL9005 HSCL9005

Explanation: The information could not be retrieved from the managed system. contact your next level of support or your service provider.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL9006 HSCL9006

Explanation: The information could not be retrieved from the managed system. Retry the operation. If the problem persists, contact IBM[®] support.

Problem determination: Retry the operation. If the problem persists, contact your next level of support or your service provider.

HSCL9007 HSCL9007

Explanation: This operation is not allowed because Capacity on Demand for processors is not supported on the managed system

HSCL9008 HSCL9008

Explanation: This operation is not allowed because Capacity on Demand for memory is not supported on the managed system.

HSCL9009 HSCL9009

Explanation: This operation is not allowed because Capacity Upgrade on Demand for processors is not supported on the managed system.

HSCL900A HSCL900A

Explanation: This operation is not allowed because Capacity Upgrade on Demand for memory is not supported on the managed system.

HSCL900B HSCL900B

Explanation: This operation is not allowed because On/Off Capacity on Demand for processors is not supported on the managed system.

HSCL900C HSCL900C

Explanation: This operation is not allowed because On/Off Capacity on Demand for memory is not supported on the managed system.

HSCL900D HSCL900D

Explanation: This operation is not allowed because Reserve Capacity on Demand is not supported on the managed system.

HSCL900E HSCL900E

Explanation: This operation is not allowed because Trial Capacity on Demand for processors is not supported on the managed system.

HSCL900F HSCL900F

Explanation: This operation is not allowed because

HSCL9010 • HSCL9019

Trial Capacity on Demand for memory is not supported on the managed system.

HSCL9010 HSCL9010

Explanation: This operation is only allowed when the managed system is in the Standby or Operating state.

Problem determination: Ensure that the managed system is in the Operating or Standby state, and then try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCL9011 HSCL9011

Explanation: This operation is not allowed because unreturned On/Off CoD processors are currently in use on the managed system. Remove the On/Off CoD processors from partitions to make them available to be reclaimed by the system, then try the operation again.

Problem determination: Currently there are unreturned On/Off CoD processors in use on the managed system. Before this operation is allowed they must be made available to be reclaimed by the system. Check the number of unreturned On/Off CoD processors, and then remove processors from partitions, if necessary, until the number of available processors is equal to or greater than the number of On/Off CoD processors that were unreturned. To remove them, either use dynamic partitioning to remove the On/Off CoD processors from a running partition, or shut down and then delete the partition to release the processors. Retry the operation.

HSCL9012 HSCL9012

Explanation: This operation is not allowed because unreturned On/Off CoD memory is currently in use on the managed system. Remove the On/Off CoD memory from partitions to make it available to be reclaimed by the system, then try the operation again.

Problem determination: Remove the On/Off CoD memory from partitions to make it available to be reclaimed by the system, then try the operation again.

HSCL9013 HSCL9013

Explanation: This operation is not allowed because unreturned Trial CoD processors are currently in use on the managed system. Immediately remove the Trial CoD processors from partitions to make them available to be reclaimed by the system, or enter a CUoD processor activation code to permanently activate this capacity.

Problem determination: Immediately remove the Trial CoD processors from partitions to make them available to be reclaimed by the system, or enter a CUoD processor activation code to permanently activate this capacity.

HSCL9014 HSCL9014

Explanation: This operation is not allowed because unreturned Trial CoD memory is currently in use on the managed system. Immediately remove the Trial memory from partitions to make it available to be reclaimed by the system, or enter a CUoD memory activation code to permanently activate this capacity.

Problem determination: Immediately remove the Trial memory from partitions to make it available to be reclaimed by the system, or enter a CUoD memory activation code to permanently activate this capacity.

HSCL9015 HSCL9015

Explanation: The managed system cannot currently process this operation. This condition is temporary. Retry the operation.

Problem determination: The managed system is busy, but the condition is temporary. Retry the operation after a period of time. If the condition persists, contact your next level of support or your service provider.

HSCL9016 HSCL9016

Explanation: You did not enter the CoD code correctly. Try again.

Problem determination: The CoD code was entered incorrectly. Try the operation again by carefully re-entering the code exactly as it was given to you.

HSCL9017 HSCL9017

Explanation: The sequence number of the CoD code indicates that this code has been used before. Obtain a new CoD code and try again.

Problem determination: The CoD code that was entered has been used before and cannot be used more than once. Check to make sure you are entering a new CoD code and try again.

HSCL9018 HSCL9018

Explanation: The CoD feature for which the CoD code was generated is not supported on the managed system.

Problem determination: The CoD feature for which this CoD code was generated is not supported on the managed system. Verify that the CoD code you are trying to enter was generated for the managed system on which you are trying to enter it.

HSCL9019 HSCL9019

Explanation: The CoD code has been rejected by the managed system because too many invalid CoD codes have been entered. The managed system must be rebooted before another CoD code will be accepted.

Problem determination: Restart the management console. Try the task again with a valid CoD code.

HSCL901A HSCL901A

Explanation: Not enough inactive processors are available to accept this CoD code because On/Off CoD processors are currently activated. Remove some On/Off CoD processors from partitions, if necessary, to make them available to be reclaimed by the system. Then deactivate those On/Off CoD processors to reduce the number of activated On/Off CoD processors, and enter the CUoD processor activation code again.

Problem determination: Currently, there are not enough inactive processors available to accept this CoD code for CUoD processors, because On/Off processors are currently activated. Check the number of available processors, and then remove processors from logical partitions, if necessary, until the number of available processors is equal to or greater than the number of On/Off processors that have been activated. To do this, either use dynamic partitioning to remove the On/Off CoD processors from a running partition, or shut down and then delete the partition to release the processors. If the problem persists, contact your next level of support or your service provider.

HSCL901B HSCL901B

Explanation: Not enough inactive memory is available to accept this CoD code because On/Off CoD memory is currently activated. Remove some On/Off CoD memory from partitions, if necessary, to make it available to be reclaimed by the system. Then deactivate that On/Off CoD memory to reduce the amount of activated On/Off CoD memory, and enter the CUoD memory activation code again.

Problem determination: There is not enough inactive memory currently available to accept this CUoD memory activation code, because On/Off CoD memory is currently activated. Check the amount of available system memory, and then remove memory from partitions, if necessary, until the amount of available system memory is equal to or greater than the amount of On/Off CoD memory that has been activated. (Use dynamic partitioning to remove memory from one or more running partitions, or delete one or more shut down partitions to release memory.) Deactivate the On/Off CoD memory. Retry the operation.

HSCL901C HSCL901C

Explanation: There are not enough inactive processors available to accept this CoD code because Trial CoD processors are currently activated. Either wait until the current Trial CoD activation period expires, or stop the current trial. Then enter the CUoD processor activation code again.

Problem determination: Wait until the current Trial CoD activation period expires, or stop the current trial. Retry the operation.

HSCL901D HSCL901D

Explanation: There is not enough inactive memory available to accept this CoD code because Trial CoD memory is currently activated. Either wait until the current Trial CoD activation period expires, or stop the current trial. Then enter the CUoD memory activation code again.

Problem determination: Wait until the current Trial CoD activation period expires, or stop the current trial. Retry the operation.

HSCL901E HSCL901E

Explanation: Not enough inactive processors are available to accept this CoD code because On/Off CoD processors and Trial CoD processors are currently activated. Remove some On/Off CoD processors or Trial CoD processors from partitions, if necessary, to make them available to be reclaimed by the system. Then deactivate those On/Off CoD and/or Trial CoD processors to reduce the number of activated CoD processors, and enter the CUoD processor activation code again.

HSCL901F HSCL901F

Explanation: Not enough inactive memory is available to accept this CoD code because On/Off CoD memory and Trial CoD memory are currently activated. Remove some On/Off CoD memory or Trial CoD memory from partitions, if necessary, to make it available to be reclaimed by the system. Then deactivate that On/Off CoD and/or Trial CoD memory to reduce the amount of activated CoD memory, and enter the CUoD memory activation code again.

HSCL9020 HSCL9020

Explanation: The CoD code cannot be accepted because Trial CoD processors are already activated on the managed system.

Problem determination: A Trial processor code cannot be accepted when Trial CoD processors are already activated.

HSCL9021 HSCL9021

Explanation: The CoD code cannot be accepted because Trial CoD memory is already activated on the managed system.

Problem determination: A Trial memory code cannot be accepted when Trial CoD memory is already activated. Wait until the current Trial CoD activation

HSCL9022 • HSCL9028

period expires, or stop the current Trial. Retry the operation.

HSCL9022 HSCL9022

Explanation: Not enough inactive processors are available to accept this CoD code because On/Off CoD processors are currently activated. Remove some On/Off CoD processors from partitions, if necessary, to make them available to be reclaimed by the system. Then deactivate those On/Off CoD processors to reduce the number of activated On/Off CoD processors, and enter the Trial processor code again.

Problem determination: There are not enough inactive processors currently available to accept this Trial processor code, because On/Off CoD processors are currently activated. Check the number of available system processors, and then remove processors from partitions, if necessary, until the number of available system processors is equal to or greater than the number of On/Off CoD processors that have been activated. (Use dynamic partitioning to remove processors from one or more running partitions, or delete one or more shut down partitions to release the processors.) Deactivate the On/Off CoD processors. Retry the operation.

HSCL9023 HSCL9023

Explanation: There is not enough inactive memory available to accept this CoD code because On/Off CoD memory is currently activated. If necessary, remove memory from partitions until the amount of On/Off CoD memory that is activated has been made available to be reclaimed by the system. Then deactivate the On/Off CoD memory, and reenter the Trial memory code.

Problem determination: There is not enough inactive memory currently available to accept this Trial memory code, because On/Off CoD memory is currently activated. Check the amount of available system memory, and then remove memory from partitions, if necessary, until the amount of available system memory is equal to or greater than the amount of On/Off CoD memory that has been activated. (Use dynamic partitioning to remove memory from one or more running partitions, or delete one or more shut down partitions to release the memory.) Deactivate the On/Off CoD memory. Retry the operation.

HSCL9024 HSCL9024

Explanation: There is not enough inactive memory available to accept this CoD code because On/Off CoD memory is currently activated. If necessary, remove memory from partitions until the amount of On/Off CoD memory that is activated has been made available to be reclaimed by the system. Then deactivate the On/Off CoD memory, and reenter the Trial memory code.

Problem determination: The CoD code to terminate On/Off CoD cannot be accepted, because On/Off resources are currently activated. Check the amount of available resources, and then remove resources from partitions, if necessary, until the amount of available resources is equal to or greater than the amount of resources that have been activated for CoD. Do this by either using dynamic partitioning to remove the On/Off resources from a running partition, or shut down and delete the partition to release the resources. Retry the operation.

HSCL9025 HSCL9025

Explanation: The CoD code cannot be accepted because there are insufficient resources available on the managed system.

Problem determination: If there are temporary CoD resources activated on your system, deactivate them. Retry the operation.

HSCL9026 HSCL9026

Explanation: The number of On/Off CoD processors requested exceeds the number of inactive processors that are currently available on the managed system. Reduce the number of processors requested and try again..

Problem determination: Reduce the number of processors requested. Retry the operation.

HSCL9027 HSCL9027

Explanation: The amount of On/Off CoD memory requested exceeds the amount of inactive memory that is currently available on the managed system. Reduce the amount of memory requested and try again.

Problem determination: Reduce the amount of memory requested so that the amount requested is less than or equal to the amount of inactive memory available for On/Off CoD. Retry the operation.

HSCL9028 HSCL9028

Explanation: Not enough On/Off CoD processor days remain to accept the On/Off CoD processor activation request. Either reduce the number of processors and/or days requested or obtain and enter a new On/Off processor enablement code.

Problem determination: Reduce the number of processors or days requested so that the number of processor days requested (the number of processors multiplied by the number of days) is less than or equal to the number of processor days available for new On/Off CoD requests. Alternatively, obtain and enter a new On/Off processor enablement code.

HSCL9029 HSCL9029

Explanation: Not enough On/Off CoD memory days remain to accept the On/Off CoD memory activation request. Either reduce the amount of memory and/or number of days requested or obtain and enter a new On/Off memory enablement code.

Problem determination: Reduce the amount of memory or number of days requested so that the number of memory days requested (the GBs of memory multiplied by the number of days) is less than or equal to the number of memory days available for new On/Off CoD requests. Alternatively, obtain and enter a new On/Off memory enablement code.

HSCL902A HSCL902A

Explanation: There are insufficient resources available to accept the On/Off CoD activation request.

Problem determination: The number of processors multiplied by the number of days cannot exceed the number of processor days remaining in the current On/Off CoD processor enablement period. Reduce either the number of processors or the number of days by amounts such that the product of these two values is less than or equal to the number of processor days remaining in the current On/Off CoD processor enablement period. Alternatively, you might obtain another On/Off CoD processor enablement code to extend your On/Off CoD processor enablement period.

HSCL902B HSCL902B

Explanation: The On/Off CoD processor activation request cannot be accepted because On/Off CoD processors are currently activated. The Current On/Off CoD processors must be deactivated before a new On/Off CoD processor activation request can be accepted.

Problem determination: On/Off CoD processors are already activated. Deactivate current On/Off CoD processors. Retry the operation.

HSCL902C HSCL902C

Explanation: The On/Off CoD memory activation request cannot be accepted because On/Off CoD memory is currently activated. The current On/Off CoD memory must be deactivated before a new On/Off CoD memory activation request can be accepted.

Problem determination: On/Off CoD memory is already activated. Deactivate the current On/Off CoD memory. Retry the operation.

HSCL902D HSCL902D

Explanation: The On/Off CoD processor activation request cannot be accepted because Trial CoD processors are currently activated. Either wait until the current Trial CoD activation period expires, or stop the current trial. Then retry the On/Off CoD processor activation request.

Problem determination: Wait until the current Trial CoD activation period expires, or stop the current trial. Retry the operation.

HSCL902E HSCL902E

Explanation: The On/Off CoD memory activation request cannot be accepted because Trial CoD memory is currently activated. Either wait until the current Trial CoD activation period expires, or stop the current trial. Then retry the On/Off CoD memory activation request.

Problem determination: Wait until the current Trial CoD activation period expires, or stop the current trial. Retry the operation.

HSCL902F HSCL902F

Explanation: The number of processors to activate is not valid.

Problem determination: Enter a valid number of processors. Retry the operation.

HSCL9030 HSCL9030

Explanation: The amount of memory to activate is not valid.

Problem determination: Enter a valid amount of memory. Retry the operation.

HSCL9031 HSCL9031

Explanation: On/Off CoD processors are not currently enabled on the managed system. An On/Off processor enablement code must be obtained and entered before On/Off CoD processors can be activated.

Problem determination: On/Off CoD processors are not currently enabled on the system. Obtain an On/Off CoD processor enablement code, and then try again to activate the processors after the enablement code has been entered.

HSCL9032 HSCL9032

Explanation: On/Off CoD for memory is not currently enabled on the managed system. An On/Off memory enablement code must be obtained and entered before On/Off CoD memory can be activated.

Problem determination: An On/Off memory enablement code must be obtained and entered before

HSCL9033 • HSCL903B

On/Off CoD memory can be activated. Obtain and enter an On/Off memory enablement code. Retry the operation.

HSCL9033 HSCL9033

Explanation: The On/Off CoD processor deactivation request cannot be accepted because there are no On/Off CoD processors that are currently activated on the managed system.

Problem determination: An attempt was made to deactivate processors that have not been activated; therefore, there is no recovery action.

HSCL9034 HSCL9034

Explanation: The On/Off CoD memory deactivation request cannot be accepted because there is no On/Off CoD memory that is currently activated on the managed system.

HSCL9035 HSCL9035

Explanation: The On/Off CoD processors cannot be deactivated because they cannot be reclaimed by the managed system. Remove processors from partitions to make them available to be reclaimed by the system, then try again.

Problem determination: An attempt was made to deactivate On/Off CoD processors when there are not enough available processors for the system to reclaim. Deallocate the processors by checking the number of available processors and removing processors from partitions, if necessary, until the number available is equal to or greater than the number of processors that have been activated for On/Off CoD. Either use dynamic partitioning to remove the On/Off processors from a running partition, or shut down and delete the partition to release the processors. Retry the operation.

HSCL9036 HSCL9036

Explanation: The On/Off CoD memory cannot be deactivated because it cannot be reclaimed by the managed system. Remove memory from partitions to make it available to be reclaimed by the system, then try again.

Problem determination: An attempt was made to deactivate On/Off CoD memory when there is not enough available memory for the system to reclaim. Check the amount of available system memory, and then remove memory from partitions, if necessary, until the amount of available system memory is equal to or greater than the amount of On/Off CoD memory that is activated. (Use dynamic partitioning to remove memory from one or more running partitions, or delete one or more shut down partitions to release the memory.) Retry the operation.

HSCL9037 HSCL9037

Explanation: This request cannot be accepted because a CoD processor trial is not currently running on the managed system.

HSCL9038 HSCL9038

Explanation: This request cannot be accepted because a CoD memory trial is not currently running on the managed system.

HSCL9039 HSCL9039

Explanation: This request cannot be accepted because the activated Trial CoD processors cannot be reclaimed by the managed system. Remove processors from partitions to make them available to be reclaimed by the system, then try again.

Problem determination: An attempt was made to stop a CoD processor trial when there are not enough available processors for the system to reclaim. Check the number of available system processors, and then remove processors from partitions, if necessary, until the number of available system processors is equal to or greater than the number of Trial CoD processors that are activated. (Use dynamic partitioning to remove processors from one or more running partitions, or delete one or more shut down partitions to release the processors.) Retry the operation.

HSCL903A HSCL903A

Explanation: This request cannot be accepted because the activated Trial CoD memory cannot be reclaimed by the managed system. Remove memory from partitions to make it available to be reclaimed by the system, then try again.

Problem determination: An attempt was made to stop a CoD memory trial when there is not enough available memory for the system to reclaim. Check the amount of available system memory, and then remove memory from partitions, if necessary, until the amount of available system memory is equal to or greater than the amount of Trial CoD memory that is activated. (Use dynamic partitioning to remove memory from one or more running partitions, or delete one or more shut down partitions to release the memory.) Retry the operation.

HSCL903B HSCL903B

Explanation: An error occurred while trying to save the information to a diskette. Verify that the diskette is writeable and try the operation again. If the problem persists, contact your service representative.

Problem determination: Verify that the diskette is writeable and try the operation again. If the problem persists, contact your service representative.

HSCL903C HSCL903C

Explanation: An error occurred while trying to send the information to the remote system.

Problem determination: Verify the network connection to the remote system and that the user has access to the remote system and the directory where the file will be copied. If the problem persists, contact your software support representative.

HSCL903D HSCL903D

Explanation: The Reserve CoD processor activation request cannot be accepted because On/Off CoD processors are currently activated. Either wait until the On/Off CoD processor request expires, or cancel the current On/Off processor activation request. Then try the Reserve CoD processor activation request again.

Problem determination: Either wait until the On/Off CoD processor request expires, or cancel the current On/Off processor activation request. Then retry the Reserve CoD processor activation request.

HSCL903E HSCL903E

Explanation: The On/Off CoD processor activation request cannot be accepted because Reserve CoD processors are currently activated. The Reserve CoD processors must be deactivated before an On/Off CoD processor activation request can be accepted.

Problem determination: The Reserve CoD processors must be deactivated before an On/Off CoD processor activation request can be accepted.

HSCL903F HSCL903F

Explanation: The Reserve CoD processor activation request cannot be accepted because Trial CoD processors are currently activated. Either wait until the Trial CoD activation period expires, or stop the current trial. Then try the Reserve CoD processor activation request again.

Problem determination: Either wait until the Trial CoD activation period expires, or stop the current trial. Then retry the Reserve CoD processor activation request.

HSCL9040 HSCL9040

Explanation: The number of CoD processors requested exceeds the number of inactive processors that are currently available on the managed system. Reduce the number of processors and try again.

Problem determination: Reduce the number of processors and try the operation again.

HSCL9041 HSCL9041

Explanation: Not enough processor days remain to accept the Reserve CoD processor activation request. Either reduce the number of processors requested or obtain and enter an additional Reserve capacity prepaid code.

Problem determination: Either reduce the number of processors requested, or obtain and enter an additional Reserve CoD processor enablement code.

HSCL9042 HSCL9042

Explanation: Reserve CoD for processors is not currently enabled on the managed system. A Reserve capacity prepaid code must be obtained and entered before Reserve CoD processors can be activated.

Problem determination: A Reserve processor enablement code must be obtained and entered before Reserve CoD processors can be activated. Enter a Reserve processor enablement code, and then try the operation again.

HSCL9043 HSCL9043

Explanation: The Reserve CoD deactivation request cannot be accepted because there are no Reserve CoD processors currently activated on the managed system.

Problem determination: Reserve CoD processors need to be activated before a deactivation request can be accepted.

HSCL9044 HSCL9044

Explanation: There are not enough inactive processors available to accept this CoD code because Reserve CoD processors are currently activated. Reserve CoD processors must be deactivated before this CoD code can be accepted.

Problem determination: To make the processors available to be reclaimed by the system, deactivate Reserve CoD processors. Then re-enter the CUoD processor activation code.

HSCL9045 HSCL9045

Explanation: There are not enough inactive processors available to accept this CoD code because Reserve CoD processors are currently activated. Reserve CoD processors must be deactivated before this CoD code can be accepted.

Problem determination: To make the processors available to be reclaimed by the system, deactivate the Reserve CoD processors. Then re-enter the Trial CoD processor activation code.

HSCL9046 HSCL9046

Explanation: The On/Off processor enablement code cannot be accepted because Reserve CoD processors are currently activated. The Reserve CoD processors must be deactivated before an On/Off CoD processor enablement code can be accepted.

Problem determination: The Reserve CoD processors must be deactivated before an On/Off CoD processor enablement code can be accepted. Deactivate the Reserve CoD processors, and try the operation again.

HSCL9047 HSCL9047

Explanation: The Reserve capacity prepaid code cannot be accepted because On/Off CoD processors are currently activated. The On/Off CoD processors must be deactivated before a Reserve capacity prepaid code can be accepted.

Problem determination: The On/Off CoD processors must be deactivated before a Reserve CoD processor enablement code can be accepted. Deactivate the On/Off CoD processors, and try the operation again.

HSCL9048 HSCL9048

Explanation: This operation is not allowed because unreturned CoD processors are currently in use on the managed system.

Problem determination: Check the number of unreturned On/Off CoD or Trial CoD processors that are currently in use. Remove that number of processors from partitions. (Use dynamic partitioning to remove processors from one or more running partitions, or delete one or more shut down partitions to release the processors.) Retry the operation.

HSCL9049 HSCL9049

Explanation: This operation is not allowed because unreturned CoD memory is currently in use on the managed system.

Problem determination: Check the amount of unreturned On/Off CoD or Trial CoD memory that is currently in use. Remove that amount of memory from partitions. (Use dynamic partitioning to remove memory from one or more running partitions, or delete one or more shut down partitions to release the memory.) Retry the operation.

HSCL904A HSCL904A

Explanation: The activation code you entered has been rejected because it is not a Capacity on Demand code.

Problem determination: An attempt was made to enter an activation code that is not a Capacity on Demand code. The code might be a Virtualization Engine systems technologies activation code. If you

intended to enter a Virtualization Engine systems technologies code, then select Manage On Demand Activations > Virtualization Engine Technologies > Enter Activation Code and try again. If you intended to enter a Capacity on Demand activation code, then obtain a Capacity on Demand activation code for this system and try again.

HSCL904B HSCL904B

Explanation: This operation is not allowed because Mobile Capacity on Demand for processors is not supported on the managed system.

Problem determination: No recovery action.

HSCL904C HSCL904C

Explanation: This operation is not allowed because Mobile Capacity on Demand for memory is not supported on the managed system.

Problem determination: No recovery action.

HSCL904D HSCL904D

Explanation: The Capacity on Demand code type specified is not supported by the managed system.

Problem determination: No recovery action.

HSCL904E HSCL904E

Explanation: The CoD code cannot be accepted because the number of processors to be removed exceeds the number of permanent processors that can be removed on the managed system.

Problem determination: If possible, obtain and enter a new Mobile CoD processor remove code for removal of fewer processors.

HSCL904F HSCL904F

Explanation: The CoD code cannot be accepted because the amount of memory to be removed exceeds the amount of permanent memory that can be removed on the managed system.

Problem determination: If possible, obtain and enter a new Mobile CoD memory remove code for removal of less memory.

HSCL9050 HSCL9050

Explanation: The CoD code cannot be accepted because the number of processors to be removed exceeds the number of processors that are currently available on the managed system.

Problem determination: Either remove processors from logical partitions to make them available to be removed, or if possible, obtain and enter a new Mobile

CoD processor remove code for removal of fewer processors.

HSCL9051 HSCL9051

Explanation: The CoD code cannot be accepted because the amount of memory to be removed exceeds the amount of memory that is currently available on the managed system.

Problem determination: Either remove memory from logical partitions to make it available to be removed, or if possible, obtain and enter a new Mobile CoD memory code for removal of less memory.

HSCL9052 HSCL9052

Explanation: The additional number of On/Off CoD processors requested exceeds the number of inactive processors that are currently available on the managed system. Reduce the number of processors requested and try again.

Problem determination: Reduce the number of processors requested and try again.

HSCL9053 HSCL9053

Explanation: The additional amount of On/Off CoD memory requested exceeds the amount of inactive memory that is currently available on the managed system. Reduce the amount of memory requested and try again.

Problem determination: Reduce the amount of memory requested and try again.

HSCL9054 HSCL9054

Explanation: The request to reduce the number of On/Off CoD processors cannot be accepted. The On/Off CoD processors to be deactivated cannot be deactivated because they cannot be reclaimed by the managed system. Remove processors from partitions to make them available to be reclaimed, then try again.

Problem determination: Remove processors from partitions to make them available to be reclaimed, then try again.

HSCL9055 HSCL9055

Explanation: The number of days specified is not valid.

Problem determination: No recovery action.

HSCL9056 HSCL9056

Explanation: The number of days specified is not valid.

Problem determination: No recovery action.

HSCL9057 HSCL9057

Explanation: The index field of the CoD code is not valid.

Problem determination: Obtain a new CoD code and try again.

HSCL9058 HSCL9058

Explanation: The On/Off processor enablement code was not accepted because Utility CoD processors are currently activated.

Problem determination: All Utility CoD processors must be removed from the shared processor pool before an On/Off processor enablement code can be accepted.

HSCL9059 HSCL9059

Explanation: The Utility CoD enablement code was not accepted because On/Off CoD processors are currently activated.

Problem determination: All On/Off CoD processors must be deactivated before a Utility CoD enablement code can be accepted.

HSCL905A HSCL905A

Explanation: The Utility CoD enablement code was not accepted because the number of unreported processor minutes has equaled or exceeded the Utility CoD reporting threshold for 30 or more consecutive days.

Problem determination: Report your Utility CoD processor minutes at the CoD website and enter the resulting Utility CoD reporting code on the management console. Then enter the Utility CoD enablement code again.

HSCL905B HSCL905B

Explanation: The Utility CoD enablement code was not accepted because the Utility CoD reporting limit has been reached.

Problem determination: Report your Utility CoD processor minutes at the CoD website and enter the resulting Utility CoD reporting code on the management console. Then enter the Utility CoD enablement code again.

HSCL905C HSCL905C

Explanation: The Utility CoD reporting code was not accepted because there is a Utility CoD reporting code that was previously generated for this managed system but never entered.

Problem determination: Utility CoD reporting codes

HSCL905D • HSCL9067

must be entered on the management console in the order in which they were generated.

HSCL905D HSCL905D

Explanation: The Utility CoD termination code was not accepted because there are unreported Utility CoD processor minutes.

Problem determination: Report your Utility CoD processor minutes at the CoD website and enter the resulting Utility CoD reporting code on the management console. Then enter the Utility CoD termination code again.

HSCL905E HSCL905E

Explanation: The CUoD processor activation code was not accepted because there are not enough inactive processors available for permanent activation since Utility CoD processors are currently activated.

Problem determination: Remove Utility CoD processors from the shared processor pool to make enough processors available for permanent activation, then enter the CUoD processor activation code again.

HSCL905F HSCL905F

Explanation: The Utility CoD termination code was not accepted because Utility CoD processors are currently activated.

Problem determination: All Utility CoD processors must be removed from the shared processor pool before a Utility CoD termination code can be accepted.

HSCL9060 HSCL9060

Explanation: The Trial processor code was not accepted because there are not enough inactive processors available for trial activation since Utility CoD processors are currently activated.

Problem determination: Utility CoD processors must be removed from the shared processor pool to make enough processors available for trial activation before the Trial processor code can be accepted.

HSCL9061 HSCL9061

Explanation: This operation is not allowed because Utility Capacity on Demand is not supported on the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL9062 HSCL9062

Explanation: There are no Utility CoD processors currently in the shared processor pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL9063 HSCL9063

Explanation: Utility CoD processors cannot be requested because Utility CoD is not enabled.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL9064 HSCL9064

Explanation: Utility CoD processors cannot be requested because Trial CoD processors are activated.

Problem determination: To request Utility CoD processors, you must either wait until the current Trial CoD activation period expires or stop the current trial.

HSCL9065 HSCL9065

Explanation: The number of Utility CoD processors requested is not a multiple of the Utility CoD processor increment.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL9066 HSCL9066

Explanation: The number of Utility CoD processors requested exceeds the number of inactive processors that are currently available.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL9067 HSCL9067

Explanation: Utility CoD processors cannot be requested because the Utility CoD reporting limit has been reached.

Problem determination: Report your Utility CoD processor minutes and request a new Utility CoD enablement code at the CoD website. Enter the Utility CoD reporting code first and then enter the Utility CoD enablement code on the management console. Then you can request more Utility CoD processors.

HSCL9068 HSCL9068

Explanation: Utility CoD processors cannot be requested because the managed system does not support micro-partitioning.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL9069 HSCL9069

Explanation: Utility CoD processors cannot be requested because On/Off CoD processors are activated. All On/Off CoD processors must be deactivated before Utility CoD processors can be requested.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL906A HSCL906A

Explanation: Utility CoD processors cannot be requested because the number of unreported processor minutes has equaled or exceeded the Utility CoD reporting threshold for 30 or more consecutive days.

Problem determination: Report your Utility CoD processor minutes and request a new Utility CoD enablement code at the CoD website. Enter the Utility CoD reporting code first and then enter the Utility CoD enablement code on the management console.

HSCL906B HSCL906B

Explanation: Utility CoD processors cannot be requested because your Utility CoD processor minute usage limit has been reached.

Problem determination: To request Utility CoD processors, reset or disable your Utility CoD processor minute usage limit.

HSCL906C HSCL906C

Explanation: Utility CoD processors cannot be requested because the managed system is in the manufacturing default configuration.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL906D HSCL906D

Explanation: The On/Off CoD processor activation request was not accepted because Utility CoD processors are currently activated.

Problem determination: All Utility CoD processors must be removed from the shared processor pool

before an On/Off CoD processor activation request can be accepted.

HSCL9077 HSCL9077

Explanation: This operation is only allowed when there are Utility CoD processors in the shared processor pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL907B HSCL907B

Explanation: Not enough inactive processors are available to accept this CoD code.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCL907C HSCL907C

Explanation: An On/Off CoD request for 0 days cannot be started at this time since there are no hours remaining from a previous On/Off CoD request.

Problem determination: Specify a non-zero number of days and try again.

HSCL907D HSCL907D

Explanation: You have exceeded the maximum number of attempts to enter a valid CoD code.

Problem determination: You must power off the managed system then power it back on before another CoD code will be accepted. Alternatively, if your managed system is a POWER6 or later server, you can contact your CoD administrator. Your CoD administrator can provide you with a CoD code which you can enter without restarting your managed system.

HSCL907E HSCL907E

Explanation: You have exceeded the maximum number of attempts to enter a valid CoD code. You cannot enter another CoD code of the same CoD type for at least one hour.

Problem determination: Verify the code and try again later, or contact your CoD administrator.

HSCL907F HSCL907F

Explanation: The number of On/Off CoD processors requested must equal or exceed the number of unreturned On/Off CoD processors that currently exist on the managed system.

Problem determination: Increase the number of processors requested and try again.

HSCL9080

HSCL9080 HSCL9080

Explanation: The amount of On/Off CoD memory requested must equal or exceed the number of unreturned On/Off CoD memory that currently exist on the managed system.

Problem determination: Increase the amount of memory requested and try again.

(HSCLAxxx) Reference codes

HSCLA000 HSCLA000

Explanation: This operation is not allowed because activation of CoD advanced functions are not supported on the managed system.

Problem determination:

HSCLA001 HSCLA001

Explanation: The Show Code Information operation failed. Try the operation again.

Problem determination: Try the operation again. If the problem persists, contact your software representative.

HSCLA002 HSCLA002

Explanation: The Enter Activation Code operation failed. Try the operation again.

Problem determination: Try the operation again. If the problem persists, contact your software representative.

HSCLA003 HSCLA003

Explanation: You did not enter the activation code correctly. Try again.

Problem determination: Enter the activation code again, ensuring that it is correct. If you are certain that you entered the correct activation code, contact your Virtualization Engine systems technologies administrator.

HSCLA004 HSCLA004

Explanation: The sequence number of the activation code indicates that this code has been used before. Obtain a new activation code and try again.

Problem determination: Obtain a new activation code and try the operation again. If the problem persists, contact your Virtualization Engine systems technologies administrator.

HSCLA005 HSCLA005

Explanation: The capability for which the activation code was generated is not supported on the managed system.

Problem determination: The activation code that was entered is for a capability that is not supported on the managed system. Obtain a new activation code and try the operation again. If the problem persists, contact your Virtualization Engine systems technologies administrator.

HSCLA006 HSCLA006

Explanation: The operation failed on the managed system. Try the operation again. If the failure persists, contact your hardware service representative.

Problem determination: Try the operation again. If the failure persists, contact your next level of support or your hardware service provider.

HSCLA007 HSCLA007

Explanation: You have exceeded the maximum number of attempts to enter a valid advanced function activation code.

Problem determination: You must power off the managed system then power it back on before another advanced function activation code will be accepted.

HSCLA008 HSCLA008

Explanation: The activation code entered is a CoD activation code instead of a Virtualization Engine Technologies activation code. Try again.

Problem determination: Make sure to obtain a Virtualization Engine Technologies activation code for this system. Try the operation again. If the problem persists, contact your Virtualization Engine systems technologies administrator.

HSCLA009 HSCLA009

Explanation: The activation code that you entered is not valid for your managed system.

Problem determination: Contact your Capacity on Demand administrator.

HSCLA00A HSCLA00A

Explanation: The activation code is the wrong length.

Problem determination: Make sure that your activation code is correct, and is exactly 34 characters in length. Try the operation again. If the problem persists, contact your Virtualization Engine systems technologies administrator.

HSCLA00B HSCLA00B

Explanation: Unknown code information format. Try the operation again.

Problem determination: Try the operation again. You might need to upgrade to a newer management console.

HSCLA00C • HSCLA206

level to fix this problem. If the problem persists, contact your service provider.

HSCLA00C HSCLA00C

Explanation: An Active Memory Expansion trial activation code was entered.

Problem determination: The code was rejected by the managed system because Active Memory Expansion is already permanently enabled.

HSCLA00D HSCLA00D

Explanation: You have exceeded the maximum number of attempts to enter a valid advanced function activation code. You cannot enter another advanced function activation code for at least one hour.

Problem determination: Verify the code and try again later, or contact your CoD administrator.

HSCLA00E HSCLA00E

Explanation: A Live Partition Mobility trial code was entered. The code was rejected because Live Partition Mobility is already permanently enabled.

Problem determination: Verify the code and try again later, or contact your CoD administrator.

HSCLA00F HSCLA00F

Explanation: A Live partition Mobility trial code was entered. The code was rejected because PowerVM Standard Edition is not enabled. Obtain and enter a PowerVM Standard Edition code, then enter the Live Partition Mobility trial code again.

Problem determination: Verify the code and try again later, or contact your CoD administrator.

HSCLA101 HSCLA101

Explanation: The bulk power assembly that was specified is not valid. Verify the bulk power assembly target name and try the request again.

Problem determination: Rebuild the managed frame. Try the task again. If the problem persists, contact your service provider.

HSCLA110 HSCLA110

Explanation: The managed system does not support service processor failover.

Problem determination: No recovery action.

HSCLA200 HSCLA200

Explanation: An unknown error occurred during the partition migration.

Problem determination: Try the operation again. If the failure persists, contact your hardware service representative.

HSCLA201 HSCLA201

Explanation: An error occurred during the logging of the partition migration.

Problem determination: Try the operation again. If the failure persists, contact your hardware service representative.

HSCLA202 HSCLA202

Explanation: An error occurred during the rollback check of the partition migration.

Problem determination: Try the operation again. If the failure persists, contact your hardware service representative.

HSCLA203 HSCLA203

Explanation: A failure occurred when trying to get a partition migration lock required for the operation being requested.

Problem determination: This may be due to a partition migration taking place at the time of the lock request, or it may be caused by other circumstances that are preventing the lock from being acquired. Please try the operation again later.

HSCLA204 HSCLA204

Explanation: The partition cannot be migrated at this time because managed system has already reached its maximum number of concurrent active partition migration, suspend, and resume operations.

Problem determination: Try the operation again later.

HSCLA205 HSCLA205

Explanation: The partition cannot be migrated at this time because managed system has already reached its maximum number of concurrent inactive partition migrations.

Problem determination: Try the operation again later.

HSCLA206 HSCLA206

Explanation: The current migration state of the partition does not support the migration operation just requested.

Problem determination: Migrations can be started

only on partitions that are currently not migrating and can be stopped only if it is not too late in the migration process to safely stop.

HSCLA207 HSCLA207

Explanation: The current migration state of this partition does not support a request to stop the migration.

Problem determination: A migration stop operation can be started only on partitions in a migration state of Migration Starting.

HSCLA208 HSCLA208

Explanation: The current migration state of this partition does not support a recovery operation because it is not a lost-connection migration state.

Problem determination: Use the force option to recover a partition that is not in a lost-connection migration state.

HSCLA209 HSCLA209

Explanation: The partition was not found.

Problem determination: Please check your entry and try the command again.

HSCLA20A HSCLA20A

Explanation: The partition was not found.

Problem determination: Please check your entry and try the command again.

HSCLA20B HSCLA20B

Explanation: The current partition state does not support a migration.

Problem determination: In order to be migrated, the partition must be in the Running or Not Activated state.

HSCLA20C HSCLA20C

Explanation: The partition migration operation was started but did not complete successfully.

Problem determination: Recovery procedures were performed successfully to both the source and destination managed systems.

HSCLA20D HSCLA20D

Explanation: The partition migration operation was started but did not complete successfully.

Problem determination: Recovery procedures were started and did not complete successfully. Try the migration recovery operation again.

HSCLA20E HSCLA20E

Explanation: The partition migration operation was started but did not complete successfully.

Problem determination: Perform the partition migration recovery operation.

HSCLA20F HSCLA20F

Explanation: The partition cannot be migrated because it is designated as the service partition for the source managed system.

Problem determination: Change the service partition property for the source managed system while the partition is powered off, and then try the operation again.

HSCLA210 HSCLA210

Explanation: The selected partition is using physical I/O.

Problem determination: The management console will migrate the partition without the physical I/O, which means that you may not be able to boot the partition once it has been migrated.

HSCLA211 HSCLA211

Explanation: The partition cannot be migrated because it is using Barrier Synchronization Register (BSR).

Problem determination: To migrate the partition, reset any BSR allocation in the partition profile and activate the partition again to apply the new profile. Then try the migration operation again.

HSCLA212 HSCLA212

Explanation: The partition cannot be migrated because it has been enabled to use the VMX facility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA213 HSCLA213

Explanation: The partition cannot be migrated because it is using huge page memory.

Problem determination: To migrate this partition, reset any huge page memory allocation in the partition profile and activate the partition again to apply the new profile. Then try the migration operation again.

HSCLA214 HSCLA214

Explanation: The partition cannot be migrated because it belongs to a workload group.

Problem determination: To migrate this partition, change the workload group partition property to none, then try the operation again.

HSCLA215 HSCLA215

Explanation: The partition cannot be migrated because its virtual I/O client adapters cannot be hosted by the existing virtual I/O server partitions on the destination managed system.

Problem determination: To migrate this partition, set up the necessary virtual I/O server hosts on the destination managed system, then try the operation again.

HSCLA216 HSCLA216

Explanation: The partition cannot be migrated because it is using an FSP serial port.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA217 HSCLA217

Explanation: The partition cannot be migrated because it is enabled as a redundant error path reporting partition.

Problem determination: To migrate this partition, change the redundant error path reporting property in the partition profile and activate the partition again to apply the new profile. Then try the migration operation again.

HSCLA218 HSCLA218

Explanation: The partition cannot be migrated because the partition firmware level it is currently running does not support partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA219 HSCLA219

Explanation: The partition cannot be migrated because one of the specified mover service partitions (MSPs) is not valid.

Problem determination: Select a new MSP pair, and then try the operation again.

HSCLA21A HSCLA21A

Explanation: The partition cannot be migrated because its effective firmware mode is not supported by the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA21B HSCLA21B

Explanation: The partition cannot be migrated because its effective processor mode is not supported by the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA21C HSCLA21C

Explanation: The partition cannot be migrated because the memory region size on the destination managed system is not the same as the memory region size on the source managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA21F HSCLA21F

Explanation: The partition cannot be migrated because the memory region size on the destination managed system is not the same as the memory region size on the source managed system.

Problem determination: The memory region size can be changed by using the Logical Memory Block Size option in the Advanced System Management Interface (ASMI), which will require that the managed system be shut down and restarted to take effect.

HSCLA220 HSCLA220

Explanation: The requested partition processor compatibility mode is not valid for the managed system.

Problem determination: Choose a processor compatibility mode that is supported by viewing the properties for the managed system, and then try the operation again.

HSCLA221 HSCLA221

Explanation: The requested partition firmware compatibility mode is not valid for the managed system.

Problem determination: Choose a firmware compatibility mode that is supported by viewing the

properties for the managed system, and then try the operation again.

HSCLA222 HSCLA222

Explanation: The requested partition Virtual I/O Server (VIOS) compatibility mode is not valid for the managed system.

Problem determination: Choose a VIOS compatibility mode that is supported by viewing the properties for the managed system, and then try the operation again.

HSCLA223 HSCLA223

Explanation: Only one Virtual Asynchronous Services Interface (VASI) device may be assigned to a Virtual I/O Server (VIOS) partition.

Problem determination: The request to set a virtual slot as a VASI adapter on the specified VIOS partition cannot be accepted because a VASI adapter has already been assigned to the partition.

HSCLA224 HSCLA224

Explanation: The partition cannot be migrated because it has been designated to use a processor compatibility level that is not supported by the destination managed system.

Problem determination: Use the management console to configure a level that is compatible with the destination managed system.

HSCLA225 HSCLA225

Explanation: The partition cannot be migrated because it has been designated to use a firmware compatibility level that is not supported by the destination managed system.

Problem determination: Use the management console to configure a level that is compatible with the destination managed system.

HSCLA226 HSCLA226

Explanation: The partition cannot be migrated because it has been designated to use a virtual I/O server (VIOS) compatibility level that is not supported by the destination managed system.

Problem determination: Use the management console to configure a level that is compatible with the destination managed system.

HSCLA227 HSCLA227

Explanation: The source managed system's firmware level is not compatible with the destination's. The partition cannot be migrated at this time.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA228 HSCLA228

Explanation: The requested operation cannot be performed because the managed system is not in the Standby or Operating state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA229 HSCLA229

Explanation: The partition cannot be migrated because the partition is already in use on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA22A HSCLA22A

Explanation: The partition cannot be migrated with the specified virtual I/O client adapter to virtual I/O server partition mappings.

Problem determination: Issue the migration command to list the possible and suggested mappings, and try the migration operation again using mappings from this list. Alternatively, allow the management console to make its selections automatically by not providing the mappings as input when starting the migration.

HSCLA22B HSCLA22B

Explanation: The partition cannot be migrated with the specified mover service partition (MSP) pair.

Problem determination: Issue the migration command to list the possible and suggested MSP pairs, and try the migration operation again using an MSP pair from this list. Alternatively, allow the management console to make its selections automatically by not providing an MSP pair as input when starting the migration.

HSCLA22C HSCLA22C

Explanation: The managed system could not be found.

Problem determination: Please check your entry and try the command again.

HSCLA22D HSCLA22D

Explanation: Communication cannot be established between the selected source and destination mover service partitions (MSPs).

HSCLA22E • HSCLA238

Problem determination: Verify the network IP address connections between the selected MSP pair or select a new MSP pair by issuing the command to list all possible and suggested MSP pairs. Then try the operation again.

HSCLA22E HSCLA22E

Explanation: The partition cannot be migrated because it has failed the request to prepare for migration.

Problem determination: Try the operation again later.

HSCLA22F HSCLA22F

Explanation: The command issued to the mover service partition to end the partition migration and close communications to the source and destination managed systems has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA230 HSCLA230

Explanation: The mover service partition on the source managed system has rejected the request to stop the migration.

Problem determination: Verify that the migration state of the partition is Migration Starting, and try the operation again.

HSCLA231 HSCLA231

Explanation: The destination mover service partition (MSP) was not found in the list of valid MSPs on the destination managed system.

Problem determination: Issue the migration command to list the possible and suggested MSP pairs, and try the migration operation again using an MSP pair from this list. Alternatively, allow the management console to make its selections automatically by not providing an MSP pair as input when starting the migration.

HSCLA232 HSCLA232

Explanation: A problem has been detected with the name of the adapter in the selected virtual asynchronous services interface (VASI) slot on the destination mover service partition (MSP).

Problem determination: Please verify the correct setup of the destination MSP and its VASI, and try the operation again.

HSCLA233 HSCLA233

Explanation: A problem has been detected with the network setup on the destination mover service partition (MSP).

Problem determination: Verify the network setup on the destination MSP to ensure that it has at least one IP address that can communicate with an IP address on the source MSP. Then try the operation again.

HSCLA234 HSCLA234

Explanation: The source mover service partition (MSP) was not found in the list of valid MSPs on the source managed system.

Problem determination: Issue the migration command to list the possible and suggested MSP pairs, and try the migration operation again using an MSP pair from this list. Alternatively, allow the management console to make its selections automatically by not providing an MSP pair as input when starting the migration.

HSCLA235 HSCLA235

Explanation: A problem has been detected with the name of the adapter in the selected virtual asynchronous services interface (VASI) slot on the source mover service partition (MSP).

Problem determination: Please verify the correct setup of the source MSP and its VASI, and try the operation again.

HSCLA236 HSCLA236

Explanation: A problem has been detected with the network setup on the source mover service partition (MSP).

Problem determination: Verify the network setup on the source MSP to ensure that it has at least one IP address that can communicate with an IP address on the destination MSP. Then try the operation again.

HSCLA237 HSCLA237

Explanation: The partition cannot be migrated because the request to suspend the partition has failed.

Problem determination: Try the operation again later.

HSCLA238 HSCLA238

Explanation: The recovery operation has failed because the migration state combination of the source and destination partitions is not valid.

Problem determination: Try the operation again later.

HSCLA239 HSCLA239

Explanation: The recovery operation has failed because the migration is still in progress.

Problem determination: Try the operation again later.

HSCLA23A HSCLA23A

Explanation: The recovery operation has failed because the destination partition could not be found.

Problem determination: Issue the migration recovery command again using the force option.

HSCLA23B HSCLA23B

Explanation: The recovery operation has failed because the managed system could not be found.

Problem determination: Issue the migration recovery command again using the force option.

HSCLA23C HSCLA23C

Explanation: The recovery operation failed because the virtual I/O server (VIOS) partition is powered off.

Problem determination: If possible, power on the VIOS partition and try the operation again. Otherwise, issue the migration recovery command again using the force option.

HSCLA23D HSCLA23D

Explanation: The recovery operation failed because either the network connection between the management console and the virtual I/O server partition is not available or because the VIOS partition is not capable of supporting this operation.

Problem determination: Verify the correct network and setup of the VIOS partition and try the operation again, or issue the operation recovery command using the force option.

HSCLA23E HSCLA23E

Explanation: The command to query for completion of adapter deconfigurations on the source virtual I/O server partition has failed. The migration recovery operation cannot complete.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA23F HSCLA23F

Explanation: The command to query for completion of adapter deconfigurations on the destination virtual I/O server partition has failed. The recovery operation cannot complete.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA240 HSCLA240

Explanation: The recovery operation failed because the mover service partition is invalid.

Problem determination: Issue the migration recovery command again using the force option.

HSCLA241 HSCLA241

Explanation: The recovery operation failed because the mover service partition was not found.

Problem determination: Issue the migration recovery command again using the force option.

HSCLA242 HSCLA242

Explanation: The recovery operation failed because the mover service partition (MSP) is not in the Running state.

Problem determination: If possible, power on the MSP and try the operation again. Otherwise, issue the migration recovery command again using the force option.

HSCLA243 HSCLA243

Explanation: The recovery operation failed because communications between the management console and the partitions belonging to the managed system cannot be established.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA244 HSCLA244

Explanation: The operation failed while attempting to remove virtual I/O slot from virtual I/O server partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA245 HSCLA245

Explanation: The command to query for completion of adapter deconfigurations on the virtual I/O server partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA246 HSCLA246

Explanation: The management console cannot communicate with partition.

Problem determination: Either the network connection is not available or the partition does not have a level of software that is capable of supporting this operation. Verify the correct network and setup of the partition, and try the operation again.

HSCLA247 HSCLA247

Explanation: The request to virtual I/O server (VIOS) partition to exchange the management console and VIOS interaction capabilities has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA248 HSCLA248

Explanation: The host adapter for virtual adapter on the Virtual I/O Server (VIOS) partition allows for any remote partition to connect, not just the migrating partition. For this reason, when you migrate the partition off of this managed system, the hosting virtual adapter will remain with the VIOS and you may not be able to migrate the partition back.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA249 HSCLA249

Explanation: The partition migration operation will not be completed because a command has been issued to terminate it.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA24A HSCLA24A

Explanation: The source managed system has rejected the request to transition the partition to the Migration Starting migration state.

Problem determination: Verify your migration setup, and then try the operation again. If the failure persists, contact your hardware service representative.

HSCLA24B HSCLA24B

Explanation: The destination managed system has rejected the request to transition the partition to the Migration Starting migration state.

Problem determination: Verify your migration setup, and then try the operation again. If the failure persists,

contact your hardware service representative.

HSCLA24C HSCLA24C

Explanation: The transfer of partition data from the source managed system to the destination managed system has failed.

Problem determination: Please try the operation again later. If the failure persists, contact your hardware service representative.

HSCLA24D HSCLA24D

Explanation: The mapping of the migrating partition's virtual SCSI adapter to the virtual I/O server (VIOS) partition on the destination managed system is not currently valid.

Problem determination: Please issue the command to list the possible and suggested client adapter to destination VIOS partition mappings, and try the operation again using a new mapping from this list. Alternatively, allow the management console to make its selection automatically by not specifying a mapping when starting the migration.

HSCLA24E HSCLA24E

Explanation: The migrating partition's virtual SCSI adapter cannot be hosted by the existing virtual I/O server (VIOS) partitions on the destination managed system.

Problem determination: To migrate the partition, set up the necessary VIOS hosts on the destination managed system, then try the operation again.

HSCLA24F HSCLA24F

Explanation: The management console is not able to suggest a virtual I/O server (VIOS) partition on the destination managed system to host the migrating partition's virtual SCSI client adapter.

Problem determination: To migrate the partition, verify the correct setup of the destination managed system's VIOS partitions, and try the operation again.

HSCLA250 HSCLA250

Explanation: An error has occurred with the mapping of the specified virtual SCSI client adapter because it cannot be found.

Problem determination: Please issue the command to list the possible and suggested virtual adapter mappings, and try the operation again using valid client adapters from this list. Alternatively, allow the management console to make its selection automatically by not specifying any mappings when starting the migration.

HSCLA251 HSCLA251

Explanation: The management console is not able to suggest a virtual I/O server (VIOS) partition on the destination managed system to host the migrating partition's virtual ethernet client adapter configured to use vlan.

Problem determination: To migrate the partition, verify the correct setup of the destination managed system's VIOS partitions, and try the operation again.

HSCLA252 HSCLA252

Explanation: An error has occurred with the specified vlan mapping.

Problem determination: Please issue the command to list the possible and suggested vlan mappings, and try the operation again using a valid mapping from this list. Alternatively, allow the management console to make its selection automatically by not specifying a mapping when starting the migration.

HSCLA253 HSCLA253

Explanation: The mapping of the migrating partition's virtual ethernet adapter configured to use vlan to the virtual I/O server (VIOS) partition on the destination managed system is not currently valid.

Problem determination: Please issue the command to list the possible and suggested vlan mappings, and try the operation again using a valid mapping from this list. Alternatively, allow the management console to make its selection automatically by not specifying a mapping when starting the migration.

HSCLA254 HSCLA254

Explanation: There is no virtual asynchronous services interface (VASI) device defined on the mover service partition (MSP).

Problem determination: Either define a VASI device on the MSP or choose another MSP pair from the list of possible pairs, and try the operation again.

HSCLA255 HSCLA255

Explanation: The management console cannot find a mover service partition (MSP) on the destination managed system that can communicate with the selected source managed system MSP.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA256 HSCLA256

Explanation: An active partition migration cannot be performed because partition is no longer in the Running state.

Problem determination: If the partition is in the Not Activated state and if you wish to perform an inactive partition migration, just issue the command again. Otherwise, activate the partition and try the operation again.

HSCLA257 HSCLA257

Explanation: The migrating partition has returned a failure response to the management console's request to perform a check for migration readiness.

Problem determination: The migrating partition is not ready for migration at this time. Try the operation again later.

HSCLA258 HSCLA258

Explanation: An inactive partition migration cannot be performed because partition is no longer in the Not Activated state.

Problem determination: If the partition is now in the Running state and if you wish to perform an active partition migration, just issue the command again. Otherwise, power off the partition to perform an inactive migration and try the operation again.

HSCLA259 HSCLA259

Explanation: The selected partition is not a valid partition type for migration.

Problem determination: Only AIX or Linux partitions can be migrated.

HSCLA25A HSCLA25A

Explanation: The partition cannot be migrated because it is missing its active profile.

Problem determination: Either the active profile has been removed or the partition has never been activated. Activate the partition to establish an active profile. Then power it off and try the operation again.

HSCLA25B HSCLA25B

Explanation: The partition cannot be migrated because it is using a physical IO slot.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA25C HSCLA25C

Explanation: The partition cannot be migrated because it is using an SNI adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA25D HSCLA25D

Explanation: The partition cannot be migrated because it is using an HCA adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA25E HSCLA25E

Explanation: The partition cannot be migrated because it is using an OptiConnect adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA25F HSCLA25F

Explanation: The partition cannot be migrated because it is using a virtual OptiConnect adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA260 HSCLA260

Explanation: The partition cannot be migrated because it is using an SMCA adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA261 HSCLA261

Explanation: The partition cannot be migrated because it belongs to a failover pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA262 HSCLA262

Explanation: The partition cannot be migrated because it belongs to an IO group.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA263 HSCLA263

Explanation: The partition cannot be migrated because it is using a non-default virtual serial I/O adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA264 HSCLA264

Explanation: This powered-off partition cannot be migrated because it is marked as not-bootable and the profile that was used for its activation prior to it being powered off is a full system profile.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA265 HSCLA265

Explanation: The partition cannot be migrated because the attempt to create the new migration profile for the partition on the destination managed system has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA266 HSCLA266

Explanation: The partition cannot be migrated because a partition with the same ID is already defined on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA267 HSCLA267

Explanation: The partition cannot be migrated because the destination managed system has already reached its maximum number of logical partitions.

Problem determination: Delete other partitions on the destination managed system and try the operation again.

HSCLA268 HSCLA268

Explanation: The partition cannot be migrated because the attempt to create its initial shell on the destination managed system failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA269 HSCLA269

Explanation: The attempt to remove the partition from the managed system has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA26A HSCLA26A

Explanation: The request to the managed system to migrate partition has failed because the unique migration identifier specified with the request is not valid.

Problem determination: Try the operation again, and if the problem persists, contact your hardware service representative.

HSCLA26C HSCLA26C

Explanation: The request to the managed system to migrate partition has failed because the managed system has already reached its maximum number of concurrent active partition migrations.

Problem determination: Wait for one or more of the other active migrations to complete, and then try the operation again.

HSCLA26D HSCLA26D

Explanation: The request to the managed system to migrate partition has failed because the managed system has already reached its maximum number of concurrent inactive partition migrations.

Problem determination: Wait for one or more of the other inactive migrations to complete, and then try the operation again.

HSCLA26E HSCLA26E

Explanation: The request to the managed system to transition partition to the migration state of Migration Starting has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA26F HSCLA26F

Explanation: The attempt to update the migration state for partition in the management console's internal database has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA270 HSCLA270

Explanation: The attempt to inform the managed system that the migration has finished and to transition partition back to a Not Migrating state has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA271 HSCLA271

Explanation: The attempt to inform the managed system of the completion status for the migration of partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA272 HSCLA272

Explanation: The attempt to get the migration data for partition from the managed system has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA273 HSCLA273

Explanation: The attempt to get the migration state of partition from the managed system has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA274 HSCLA274

Explanation: The management console was not able to obtain all the necessary information from its internal database about the migrating partition's virtual client adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA275 HSCLA275

Explanation: The management console was not able to locate the source Virtual I/O Server partition's hosting server adapter for the client virtual adapter in its internal database.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA276 HSCLA276

Explanation: The management console was not able to locate the source Virtual I/O Server partition for the client virtual adapter in its internal database.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA277 HSCLA277

Explanation: The management console was not able to obtain all the necessary information from its internal database about the source Virtual I/O Server partitions' virtual server adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA278 HSCLA278

Explanation: The attempt to obtain the list of the migrating partition's virtual ethernet client adapters from the management console's internal database has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA279 HSCLA279

Explanation: The management console was not able to obtain all the necessary information from its internal database about the migrating partition's virtual ethernet client adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA27A HSCLA27A

Explanation: The management console was not able to locate the source virtual I/O server partition's hosting server adapter for vlan in its internal database.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA27B HSCLA27B

Explanation: The partition cannot be migrated because the processor and/or memory resources it requires exceeds the available resources on the destination managed system.

Problem determination: If possible, free up resources from running partitions on the destination managed system, and try the operation again.

HSCLA27C HSCLA27C

Explanation: The operation to get the physical device location for adapter on the virtual I/O server partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA27D HSCLA27D

Explanation: The operation to lock the physical device location for source adapter on the virtual I/O server partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA27E HSCLA27E

Explanation: The operation to lock the physical device location for target adapter on the virtual I/O server partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA27F HSCLA27F

Explanation: The operation to establish the physical device location for adapter on the virtual IO server partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA280 HSCLA280

Explanation: The operation to unconfigure and undefine virtual adapter on the source virtual I/O server partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA281 HSCLA281

Explanation: The operation to query virtual I/O server partition for completion has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA282 HSCLA282

Explanation: The operation to check partition for migration readiness has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA283 HSCLA283

Explanation: The operation to prepare partition for migration failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA284 HSCLA284

Explanation: The request issued to the source mover service partition to start the migration has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA285 HSCLA285

Explanation: The request issued to the destination mover service partition to start the migration has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA286 HSCLA286

Explanation: The request issued to end the migration session between the management console and the mover service partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA287 HSCLA287

Explanation: The request issued to the source mover service partition to stop the migration has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA288 HSCLA288

Explanation: The request issued to the source mover service partition to make the migrating partition suspendable has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA289 HSCLA289

Explanation: The request issued to mover service partition to get the migration statistics has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA28A HSCLA28A

Explanation: The request issued to mover service partition to test its communications capability with the partner mover service partition has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA28B HSCLA28B

Explanation: The virtual I/O server partition does not provide support for partition migration commands.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA28C HSCLA28C

Explanation: The mover service partition does not provide support for partition migration commands.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA28D HSCLA28D

Explanation: The VIOS partition has not been defined to be a mover service partition (MSP).

Problem determination: If the intent is to use this VIOS partition as an MSP, set the MSP attribute for this partition, and try the operation again.

HSCLA28E HSCLA28E

Explanation: Virtual I/O server (VIOS) partition is not in the Running state.

Problem determination: The VIOS partition must be in the Running state in order for the migration to proceed.

HSCLA28F HSCLA28F

Explanation: The operation to lock the physical device location for source adapter has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA290 HSCLA290

Explanation: There are no I/O slots available on virtual I/O server partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA291 HSCLA291

Explanation: The selected partition may have an open virtual terminal session.

Problem determination: The management console will force termination of the partition's open virtual terminal session when the migration has completed.

HSCLA292 HSCLA292

Explanation: The selected partition's power controlling partitions list is not empty.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA293 HSCLA293

Explanation: The selected partition is using huge page memory.

Problem determination: The profile-specified amount of huge page memory may not be available on the destination managed system, in which case the partition may boot with only a portion or none of the huge page memory after the inactive migration.

HSCLA294 HSCLA294

Explanation: The selected partition is using Barrier Synchronization Register (BSR) arrays.

Problem determination: The profile-specified number of BSR resources may not be available on the destination managed system, in which case the partition will boot without BSR after the inactive migration.

HSCLA295 HSCLA295

Explanation: As part of the migration process, the management console will create a new migration profile containing the partition's current state.

Problem determination: The default is to use the current profile, which will replace the existing definition of this profile. While this works for most scenarios, other options are possible. You may specify a different existing profile, which would be replaced with the current partition definition, or you may specify a new profile to save the current partition state.

HSCLA296 HSCLA296

Explanation: The Dynamic Logical Partitioning Resource Manager (DRM) capability bits for partition are null.

Problem determination: The management console requires the DRM capability bits in order to determine if partition mobility functions are supported on the partition.

HSCLA297 HSCLA297

Explanation: Mover service partition (MSP) does not support partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA298 HSCLA298

Explanation: Virtual I/O Server partition does not support partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA299 HSCLA299

Explanation: The OS level on the migrating partition does not support partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA29A HSCLA29A

Explanation: The RMC command issued to partition failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA29B HSCLA29B

Explanation: Virtual I/O server (VIOS) partition is not in the Running state.

Problem determination: Activate the VIOS partition, and try the operation again.

HSCLA29C HSCLA29C

Explanation: The stop migration request is not valid because the management console is not currently controlling a migration of the specified partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA29D HSCLA29D

Explanation: The request to stop the migration of the partition cannot be accepted because the migration has progressed beyond the point where it can be safely stopped.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA29E HSCLA29E

Explanation: The request to get the migration data from the service partition for the partition has failed, because the migration state for the partition indicates that it is not currently migrating.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA29F HSCLA29F

Explanation: The migration data stored by the service processor for partition is empty.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A0 HSCLA2A0

Explanation: The migration data for the migrating partition does not contain a partition ID for the partition on the other side managed system.

Problem determination: This normally means that the shell partition has not yet been created on the destination managed system.

HSCLA2A1 HSCLA2A1

Explanation: The management console cannot find the Managed System Object Manager for partition from the given managed system serial number.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A2 HSCLA2A2

Explanation: The management console cannot find the Partition Object Manager for partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A3 HSCLA2A3

Explanation: The migration recovery operation cannot be performed for partition because the management console cannot find the unique migration identifier for the migration.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A4 HSCLA2A4

Explanation: The migration recovery operation cannot be performed for the partition, because the migration data stored by the service processor for the migration is either empty or not available.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A5 HSCLA2A5

Explanation: The partition migration has finished, and the management console is performing a migration cleanup for partition on the source managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A6 HSCLA2A6

Explanation: The partition migration has stopped, and the management console is performing a migration cleanup for the shell partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A7 HSCLA2A7

Explanation: Only the hypervisor migration state for partition can be cleaned up with the migration recovery operation, because the management console was not able to determine the unique migration identifier for the migration.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2A8 HSCLA2A8

Explanation: The management console is skipping the cleanup of the virtual SCSI adapters on the destination managed system's virtual I/O server partition because it is not activated.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA2A9 HSCLA2A9

Explanation: The management console cannot recover the virtual SCSI slots on the destination managed system's virtual I/O server partition because it is not activated.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2AA HSCLA2AA

Explanation: The management console is skipping the virtual SCSI adapter cleanup on the source managed system's virtual I/O server partition, because it is not activated.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2AB HSCLA2AB

Explanation: The management console cannot recover the virtual SCSI slots on the source managed system's virtual I/O server partition, because it is not activated.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2AC HSCLA2AC

Explanation: The requested operation cannot be performed because the managed system is not in the Operating state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2AD HSCLA2AD

Explanation: The migrating partition's compatibility data checking on the destination managed system has failed.

Problem determination: Verify that the partition has been correctly set up for migration to the selected destination managed system, and try the operation again.

HSCLA2AE HSCLA2AE

Explanation: The migrating partition's minimum required processing units value exceeds the number of configurable processors on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2AF HSCLA2AF

Explanation: The migrating partition's maximum required processing units value exceeds the maximum processor capacity of the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2B0 HSCLA2B0

Explanation: The migrating partition's minimum required memory value exceeds the amount of configurable memory on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2B1 HSCLA2B1

Explanation: The migrating partition's maximum required memory value exceeds the maximum memory capacity of the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2B2 HSCLA2B2

Explanation: The migration operation failed because the specified partition ID is no longer valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2B3 HSCLA2B3

Explanation: The migrating partition's virtual ethernet adapter configured to use vlan cannot be hosted by the existing virtual I/O server (VIOS) partitions on the destination managed system.

Problem determination: To migrate the partition, verify the correct setup of the destination managed system's VIOS partitions, then try the operation again.

HSCLA2B4 HSCLA2B4

Explanation: The partition cannot be migrated, because its MAC address base value is the same as the MAC address base value for partition on the destination managed system.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA2B5 HSCLA2B5

Explanation: The management console was not able to obtain the necessary virtual ethernet adapter information from its internal database for the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2B6 HSCLA2B6

Explanation: A virtual asynchronous services interface (VASI) or IP address selection has been specified without an accompanying mover service partition (MSP) selection.

Problem determination: Please include an MSP selection if specifying a VASI or IP address, or allow the management console to make the VASI, IP address, and MSP choices, by not specifying any selections when issuing the command to migrate.

HSCLA2B7 HSCLA2B7

Explanation: The management console was unable to find a valid mover service partition (MSP) on managed system.

Problem determination: MSPs must exist on both the source and destination managed systems, and they must be able to communicate with each other to be considered capable of performing an active partition migration. Verify your migration setup with correctly configured and communicating MSPs on both source and destination managed systems, and try the operation again.

HSCLA2B8 HSCLA2B8

Explanation: The selected mover service partition on the managed system does not provide support for partition migration commands.

Problem determination: Verify that the partition is running at a software level that supports partition migration, and try the operation again.

HSCLA2B9 HSCLA2B9

Explanation: The selected mover service partition (MSP) on the managed system has not been defined to be an MSP.

Problem determination: Set the MSP attribute for the partition, and try the operation again.

HSCLA2BA HSCLA2BA

Explanation: The selected mover service partition (MSP) on the managed system is not in the list of valid MSP-configured virtual I/O server partitions.

Problem determination: Verify the correct MSP configuration of the partition and try the operation again.

HSCLA2BB HSCLA2BB

Explanation: The selected mover service partition (MSP) on the managed system has not been defined to be an MSP and does not provide support for partition mobility commands.

Problem determination: Set the MSP attribute for the partition and verify that it is running at a software level that supports partition mobility, then try the operation again.

HSCLA2BC HSCLA2BC

Explanation: The selected mover service partition (MSP) cannot be used. It may have reached its maximum concurrent partition migration limit, or it can communicate with its partner MSP either because its given virtual asynchronous services interface (VASI) device is no longer valid or because its designated IP address cannot communicate with the designated IP address on its partner MSP.

Problem determination: Verify the network setup of the MSP to ensure that a valid VASI device has been specified and that it has at least one IP address that can communicate with an IP address on its partner MSP. Then try the operation again.

HSCLA2BD HSCLA2BD

Explanation: The management console was not able to find a valid virtual I/O server (VIOS) partition on the managed system.

Problem determination: Verify the correct migration setup of the managed system, including the configuration of one or more VIOS partitions, and try the operation again.

HSCLA2BE HSCLA2BE

Explanation: A migration is already in progress for partition.

Problem determination: Migration cannot be performed on a partition that is already migrating.

HSCLA2BF HSCLA2BF

Explanation: For the client virtual SCSI or virtual fibre channel adapter on the migrating partition, the associated virtual I/O server partition's virtual slot only allows the client partition's virtual slot to connect in.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2C0 HSCLA2C0

Explanation: The operation to establish the physical device location for adapter on the virtual I/O server (VIOS) partition has failed.

Problem determination: There exists a conflict with available virtual SCSI adapters on that VIOS.

HSCLA2C1 HSCLA2C1

Explanation: There is a conflict with the available virtual SCSI adapters on virtual I/O server partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2C2 HSCLA2C2

Explanation: The migration recovery cannot proceed because the service processor indicates that the given partition is not in the middle of a migration, and the saved migration transaction recovery file for this partition does not exist on this management console.

Problem determination: Perform one or more of the following steps: (1) Check the partition name to ensure that the correct partition name has been provided; (2) Restart the service processor; (3) Locate the management console that was used to perform the migration, which should have the saved migration transaction recovery file for this partition. Then try the migration recovery operation again.

HSCLA2C3 HSCLA2C3

Explanation: The migration recovery cannot proceed because the migration-related data that is saved in the service processor for the given partition is empty, and the saved migration transaction recovery file for this partition does not exist on this management console.

Problem determination: Locate the management console that was used to perform the migration, which should have the saved migration transaction recovery file for this partition. Then try the migration recovery operation again.

HSCLA2C4 HSCLA2C4

Explanation: The migration recovery cannot proceed because the saved migration transaction recovery file does not exist on this management console.

Problem determination: If possible, issue the migration recovery from the management console that was used to perform the migration, which should have the saved migration transaction recovery file for this partition. Otherwise, use the force option to force the recovery to proceed on this management console.

HSCLA2C5 HSCLA2C5

Explanation: The migration recovery cannot proceed because the management console cannot find the information for the partner managed system.

Problem determination: Use the force option to recover only one side of the migration.

HSCLA2C6 HSCLA2C6

Explanation: The migration recovery operation can recover only one side of the migration because it cannot get the information about the partner managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2C7 HSCLA2C7

Explanation: The management console cannot determine the MTMS of the partner managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2C8 HSCLA2C8

Explanation: The management console cannot determine the partition name of the migrating partition on the partner managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2C9 HSCLA2C9

Explanation: The management console is unable to open or write to the partition migration transaction recovery file.

Problem determination: Without a migration transaction file, the management console may be limited in its ability to fully recover a migration if it fails to complete successfully.

HSCLA2CA HSCLA2CA

Explanation: The management console is unable to open or read from the partition migration transaction recovery file.

Problem determination: Without access to the migration transaction file, the management console may be limited in its ability to perform a complete recovery of the partition migration.

HSCLA2CB HSCLA2CB

Explanation: The migration has been stopped by the management console administrator.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2CC HSCLA2CC

Explanation: The management console is unable to locate the migration transaction recovery file for the given unique migration identifier, the given source partition, and the given destination partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2CD HSCLA2CD

Explanation: The management console is unable to delete the migration transaction recovery file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2CE HSCLA2CE

Explanation: The management console is unable to locate or recreate the partition's migration transaction recovery file.

Problem determination: Without the migration transaction recovery file, the management console may be limited in its ability to perform a complete recovery of the partition's migration. If possible, issue the migration recovery from the management console that was used to perform the migration, which should have the saved migration transaction recovery file. Otherwise, use the force option to force the recovery to proceed without it on this management console.

HSCLA2CF HSCLA2CF

Explanation: The partition migration has been stopped unexpectedly.

Problem determination: Perform a migration recovery for this partition, if necessary.

HSCLA2D0 HSCLA2D0

Explanation: The migration has been stopped because the management console has lost connection to the source service processor.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2D1 HSCLA2D1

Explanation: The partition migration cannot proceed because the specified source and destination managed systems are the same.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2D2 HSCLA2D2

Explanation: The partition changes are not allowed because the partition is currently in a state of migration.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2D3 HSCLA2D3

Explanation: The managed system has rejected the migration operation due to an invalid partition ID.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2D4 HSCLA2D4

Explanation: This operation cannot be performed at this time because the managed system has reached its maximum number of concurrent active partition migration, suspend, and resume operations.

Problem determination: Try the operation again later.

HSCLA2D5 HSCLA2D5

Explanation: The partition cannot be migrated at this time because the managed system has reached its maximum number of concurrent inactive migrations.

Problem determination: Try the operation again later.

HSCLA2D6 HSCLA2D6

Explanation: The request to start migrating the partition has been rejected by the managed system because the unique migration identifier specified with the request is not valid.

Problem determination: Try the operation again, and

if the problem persists, contact your hardware service representative.

HSCLA2D7 HSCLA2D7

Explanation: The request to start migrating the partition has been rejected by the managed system due to the request for an invalid migration type.

Problem determination: Try the operation again, and if the problem persists, contact your hardware service representative.

HSCLA2D8 HSCLA2D8

Explanation: The managed system is currently using emergency power and therefore cannot accept the request to start migrating the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2D9 HSCLA2D9

Explanation: The managed system has returned a bad partition state error for the requested migration operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2DA HSCLA2DA

Explanation: The managed system has rejected the request to start a migration because the partition is using physical I/O.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2DB HSCLA2DB

Explanation: The managed system has rejected the request to migrate the partition because the configuration of the partition's virtual I/O adapters will not support a migration of the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2DC HSCLA2DC

Explanation: The managed system has rejected the migration request because the partition firmware level does not support partition mobility.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2DD HSCLA2DD

Explanation: Migration to the specified managed system cannot be performed on the partition because the source and destination managed systems' firmware levels are not compatible.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2DE HSCLA2DE

Explanation: The migration has been rejected by the destination managed system because the partition is using hardware features that are not supported by the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2DF HSCLA2DF

Explanation: The partition is running at a firmware compatibility level that is not supported by the destination managed system.

Problem determination: Use the management console to configure a level that is supported by the destination managed system.

HSCLA2E0 HSCLA2E0

Explanation: The partition is running at a processor compatibility level that is not supported by the destination managed system.

Problem determination: Use the management console to configure a level that is supported by the destination managed system.

HSCLA2E1 HSCLA2E1

Explanation: The request to set the final migration state for the partition has been rejected by the managed system because the specified final migration state is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2E2 HSCLA2E2

Explanation: The request to set the final migration state and end the migration cannot be accepted by the managed system because the mover service partition's VASI device is still open.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2E3 HSCLA2E3

Explanation: The operation has been rejected by the managed system because partition changes are still taking place.

Problem determination: Please wait five minutes, then try the recovery operation again.

HSCLA2E4 HSCLA2E4

Explanation: The partition cannot be migrated because the transfer of partition data has failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2E5 HSCLA2E5

Explanation: The partition migration data transfer has been rejected by the managed system because the migration type is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2E6 HSCLA2E6

Explanation: The managed system does not have any migration data stored for this partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2E7 HSCLA2E7

Explanation: The partition cannot be migrated because it is using a Host Ethernet Adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2E8 HSCLA2E8

Explanation: A partition migration was started but did not complete successfully. Recovery procedures were started but did not complete successfully.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2E9 HSCLA2E9

Explanation: The migrating partition belongs to a system profile. After the migration, it will be deleted from that system profile.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA2EA HSCLA2EA

Explanation: Too many partition mobility VASI adapters have been specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2EB HSCLA2EB

Explanation: The virtual adapter ID is reserved for virtual IO servers on systems with POWER6 processors. It cannot be used for user defined virtual adapters. The adapter ID must be greater than 10.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2EC HSCLA2EC

Explanation: The VASI adapter id is not valid. Only values between 2 and 10, inclusive, are valid.

HSCLA2ED HSCLA2ED

Explanation: The maximum number of virtual slots is not valid.

Problem determination: The number must be greater than 10 for a Virtual I/O Server partition on systems with POWER6 processors.

HSCLA2EE HSCLA2EE

Explanation: The maximum number of virtual slots is invalid.

Problem determination: It must be greater than 1.

HSCLA2EF HSCLA2EF

Explanation: The specified destination partition ID is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2F0 HSCLA2F0

Explanation: The partition cannot be migrated because it has a virtual Ethernet trunk adapter.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2F1 HSCLA2F1

Explanation: There are no partition IDs available on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2F2 HSCLA2F2

Explanation: The partition cannot be migrated because it has a virtual fibre channel adapter, and the destination managed system does not support virtual fibre channel adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2F3 HSCLA2F3

Explanation: The partition cannot be migrated because it is using a non-default virtual Ethernet switch, and the destination managed system does not support non-default virtual Ethernet switches.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2F4 HSCLA2F4

Explanation: Destination Virtual I/O Server (VIOS) partitions cannot be identified to host all of the migrating partition's virtual adapters.

Problem determination: Verify the correct setup of the destination managed system's VIOS partitions, and check the availability of slots in those partitions.

HSCLA2F5 HSCLA2F5

Explanation: The partition cannot be migrated because it is a shared memory partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2F7 HSCLA2F7

Explanation: The SSH authentication key is already set for the user on the management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2F8 HSCLA2F8

Explanation: The command failed.

Problem determination: Verify that the specified user ID and password are valid.

HSCLA2F9 HSCLA2F9

Explanation: The command failed.

Problem determination: Verify that the specified IP address or host name is valid.

HSCLA2FA HSCLA2FA

Explanation: The shared memory pool that is used by the migrating partition is not supported by the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2FB HSCLA2FB

Explanation: The specified virtual SCSI or virtual fibre channel adapter is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2FC HSCLA2FC

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA2FD HSCLA2FD

Explanation: The reserved storage device pool or shared memory pool on the destination managed system does not have an available device that is large enough for the migrating partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2FE HSCLA2FE

Explanation: The migrating partition uses shared memory, however no shared memory pool exists on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA2FF HSCLA2FF

Explanation: An internal management console error has occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA300 HSCLA300

Explanation: The Virtual I/O Server partition assigned to the shared memory pool to provide paging services is not in the Running state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA301 HSCLA301

Explanation: There is no RMC connection between the management console and the Virtual I/O Server partition assigned to the shared memory pool to provide paging services.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA302 HSCLA302

Explanation: The shared memory pool on the destination managed system has no Virtual I/O Server partition assigned to provide paging services.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA303 HSCLA303

Explanation: The destination shared memory pool does not provide the redundant paging services support required by the mobile partition. To migrate this partition, the destination shared memory pool must be configured with redundant paging VIOS partitions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA304 HSCLA304

Explanation: A suitable shared memory pool for the mobile partition was not found on the destination managed system.

Problem determination: In order to support the mobile partition, the destination managed system must have a shared memory pool that can accommodate the partition's entitled and maximum memory values, as well as its redundant paging requirements. If the destination managed system has a shared memory

pool, inability to support the mobile shared memory partition can be due to lack of sufficient memory in the pool, or lack of a paging space device in the pool that meets the mobile partition's redundancy and size requirements.

HSCLA305 HSCLA305

Explanation: An internal management console error occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA306 HSCLA306

Explanation: There is an insufficient amount of memory available in the shared memory pool on the destination managed system to migrate this partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA307 HSCLA307

Explanation: The command failed.

Problem determination: Verify that SSH is enabled on the remote management console.

HSCLA308 HSCLA308

Explanation: An internal management console error occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA309 HSCLA309

Explanation: An internal management console error occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA30A HSCLA30A

Explanation: An internal management console error occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA30B HSCLA30B

Explanation: An internal management console error occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA30C HSCLA30C

Explanation: An internal management console error occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA30D HSCLA30D

Explanation: The selected primary paging VIOS partition is not assigned to the shared memory pool on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA30E HSCLA30E

Explanation: There is not a device available in the reserved storage device pool or shared memory pool on the destination managed system that can be used by the mobile partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA30F HSCLA30F

Explanation: The selected reserved storage device cannot be found on the selected primary VIOS partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA310 HSCLA310

Explanation: A reserved storage device was selected for both the primary and secondary paging VIOS partitions. A reserved storage device can be selected for only the primary VIOS partition unless the mobile partition is configured to use redundant VIOS partitions on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA311 HSCLA311

Explanation: The selected reserved storage devices for the primary and secondary VIOS partitions on the destination managed system are not valid. You must specify the same device if selecting devices for both the primary and secondary VIOS partitions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA312 HSCLA312

Explanation: The selected reserved storage device is not in the list of devices that are hosted by the primary VIOS partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA313 HSCLA313

Explanation: The shared memory pool ID specified cannot be found on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA314 HSCLA314

Explanation: The maximum number of shared memory partitions that can be hosted by the paging VIOS partition on the destination managed system are running. If you want to migrate this partition, you must shut down one of the shared memory partitions first.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA315 HSCLA315

Explanation: The number of shared memory partitions currently using VIOS partition for paging cannot be determined.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA316 HSCLA316

Explanation: The number of shared memory partitions supported by the VIOS partitions used for paging on managed system cannot be determined.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA317 HSCLA317

Explanation: A partition migration cannot be stopped from the destination management console. A migration has to be stopped from the source management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA318 HSCLA318

Explanation: The migration command issued to the destination management console failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA319 HSCLA319

Explanation: The migrating partition's virtual fibre channel client adapter cannot be hosted by the existing Virtual I/O Server (VIOS) partitions on the destination managed system.

Problem determination: To migrate the partition, set up the necessary VIOS host on the destination managed system, then try the operation again.

HSCLA31A HSCLA31A

Explanation: The management console is not able to suggest a Virtual I/O Server (VIOS) partition on the destination managed system to host the migrating partition's virtual fibre channel client adapter.

Problem determination: To migrate the partition, verify the correct setup of the destination managed system's VIOS partitions, and try the operation again.

HSCLA31B HSCLA31B

Explanation: The mapping of the migrating partition's virtual fibre channel adapter to the Virtual I/O Server (VIOS) partition on the destination managed system is not currently valid.

Problem determination: Please issue the command to list the possible and suggested client adapter to destination VIOS partition mappings, and try the operation again using a new mapping from this list. Alternatively, allow the management console to make the selection automatically by not specifying a mapping when starting the migration.

HSCLA31C HSCLA31C

Explanation: The specified virtual fibre channel client adapter cannot be found.

Problem determination: Please issue the command to list the possible and suggested virtual adapter mappings, and try the operation again using valid client adapters from this list. Alternatively, allow the management console to make the selection automatically by not specifying any mappings when starting the migration.

HSCLA31D HSCLA31D

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA31E HSCLA31E

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA31F HSCLA31F

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA320 HSCLA320

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA321 HSCLA321

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA322 HSCLA322

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA323 HSCLA323

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA324 HSCLA324

Explanation: The request to the managed system to migrate partition has failed because the unique migration identifier specified with the request is already in use on the remote system.

Problem determination: Try the operation again. If

this error persists, contact your service representative.

HSCLA325 HSCLA325

Explanation: The managed system was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA326 HSCLA326

Explanation: The partition was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA327 HSCLA327

Explanation: The recovery operation failed.

Problem determination: If possible, perform the recovery operation from the management console that was used to perform the migration. Otherwise, perform the recovery operation again from this management console using the force option.

HSCLA328 HSCLA328

Explanation: The destination managed system was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA329 HSCLA329

Explanation: The source managed system was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA32A HSCLA32A

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA32B HSCLA32B

Explanation: An internal error occurred.

Problem determination: Try the migration operation again. If this error persists, contact your service representative.

HSCLA32C HSCLA32C

Explanation: Unable to determine remote user name due to a failure to retrieve the user context.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA32D HSCLA32D

Explanation: The recovery operation failed because the management console does not have enough information about the destination side, You can try issuing the migration recovery command again using the force option.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA32E HSCLA32E

Explanation: The management console cannot recover the destination system. You can try issuing the migration recovery command again using the force option.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA32F HSCLA32F

Explanation: The specified partition ID is no longer valid. The next valid available partition ID will be used.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA330 HSCLA330

Explanation: The virtual Ethernet trunk adapter cannot be created because the partition already has a trunk adapter in its virtual I/O slot that has the same trunk priority as the new trunk adapter you are creating.

Problem determination: Please modify the trunk priority of your new virtual Ethernet trunk adapter accordingly and reactivate the partition.

HSCLA331 HSCLA331

Explanation: The virtual Ethernet adapter cannot be created because the partition already has a trunk adapter in its virtual I/O slot. The new virtual Ethernet adapter has a matching trunk priority, incorrect VLAN ID, and mismatched Port VLAN IDs.

Problem determination: Please modify the profile

accordingly and reactivate the partition.

HSCLA332 HSCLA332

Explanation: The virtual Ethernet adapter cannot be created because the partition already has a trunk adapter in its virtual I/O slot with a VLAN ID that is different than the already defined virtual ethernet adapter.

Problem determination: Please modify the profile accordingly and reactivate the partition.

HSCLA333 HSCLA333

Explanation: The virtual Ethernet adapter cannot be created because the partition already has a trunk adapter in its virtual I/O slot that has a different number of Port VLAN IDs than the new virtual Ethernet adapter that will be created.

Problem determination: Please modify the profile accordingly and reactivate the partition.

HSCLA334 HSCLA334

Explanation: The virtual Ethernet adapter cannot be created because the partition already has a trunk adapter in its virtual I/O slot that has a mismatched set of Port VLAN IDs than the new virtual ethernet adapter that will be created.

Problem determination: Please modify the profile accordingly and reactivate the partition.

HSCLA335 HSCLA335

Explanation: The management console for the destination managed system does not support one or more capabilities required to perform this operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA336 HSCLA336

Explanation: The management console for the source managed system does not support one or more capabilities required by the management console managing the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA337 HSCLA337

Explanation: The operation involving the remote management console has failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA338 HSCLA338

Explanation: The destination managed system does not support Active Memory Sharing.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA339 HSCLA339

Explanation: The selected primary paging VIOS partition is not assigned to the shared memory pool on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA33A HSCLA33A

Explanation: The current primary paging VIOS setting for the migrating partition cannot be maintained on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA33B HSCLA33B

Explanation: The selected primary paging VIOS partition ID does not specify a valid partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA33C HSCLA33C

Explanation: The selected paging VIOS partition ID do not specify the same partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA33D HSCLA33D

Explanation: The selected primary paging VIOS partition does not specify a valid partition on the destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA33E HSCLA33E

Explanation: Invalid power and run state combination.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA33F HSCLA33F

Explanation: Active memory sharing attributes that were specified for the migrating partition will not be used, because this partition is not a shared memory partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA340 HSCLA340

Explanation: The management console may not be able to replicate the source multipath I/O configuration for the migrating partition's virtual I/O adapters on the destination.

Problem determination: This means one or both of the following: (1) Client adapters that are assigned to different source VIOS hosts may be assigned to a single VIOS host on the destination; (2) Client adapters that are assigned to a single source VIOS host may be assigned to different VIOS hosts on the destination. You can review the complete list of HMC-chosen mappings by issuing the command to list the virtual I/O mappings for the migrating partition.

HSCLA341 HSCLA341

Explanation: The specified virtual I/O server partition ID is not valid on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA342 HSCLA342

Explanation: The specified virtual I/O server partition is not valid on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA343 HSCLA343

Explanation: The specified virtual I/O server partition ID do not specify the same partition on destination managed system.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA344 HSCLA344

Explanation: The specified mover service partition ID is not valid on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA345 HSCLA345

Explanation: The specified mover service partition is not valid on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA346 HSCLA346

Explanation: The partition cannot be migrated with the selected mover service partitions pair, because the mover service partition ID do not specify the same partition on managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA347 HSCLA347

Explanation: The specified primary paging VIOS partition ID is not valid on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA348 HSCLA348

Explanation: The specified primary paging VIOS partition is not valid on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA349 HSCLA349

Explanation: The partition cannot be migrated with the selected primary paging VIOS partition ID and name, because the paging VIOS partition ID do not specify the same partition on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA34A HSCLA34A

Explanation: The specified shared processor pool ID is not valid on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA34B HSCLA34B

Explanation: The specified shared processor pool is not valid on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA34C HSCLA34C

Explanation: The partition cannot be migrated with the selected shared processor pool ID and name, because the shared processor pool ID do not specify the same pool on destination managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA34D HSCLA34D

Explanation: The specified migrating partition ID is not valid on source managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA34E HSCLA34E

Explanation: The specified migrating partition is not valid on source managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA34F HSCLA34F

Explanation: The specified migrating partition ID do not specify the same partition on source managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA350 HSCLA350

Explanation: The migration operation cannot be done because the destination managed system does not support multiple partition migration validation.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA351 HSCLA351

Explanation: The destination management console does not support partition mobility operations issued from another management console

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA352 HSCLA352

Explanation: The management console is unable to find a trunk adapter for VLAN.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA353 HSCLA353

Explanation: Using the destination Virtual I/O Server (VIOS) partition to host client adapter will cause a Virtual Target Device (VTD) name conflict. The destination VIOS partition will change the VTD name to avoid conflict. If you do not want the VTD name to be modified, you must specify a different VIOS partition to host client adapter on the destination managed system when you migrate the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA354 HSCLA354

Explanation: The request to stop the migration of this partition cannot be accepted, possibly because the migration has progressed beyond the point where it can safely be stopped. Alternatively, the stop migration request may have failed because you have attempted to stop the migration from an management console that does not control the migration. If so, then you should try the stop operation again on the management console from which the migration was started.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA355 HSCLA355

Explanation: The RMC command issued to partition failed.

Problem determination: This means that destination VIOS partition cannot be used to provide a bridge to the external virtual local area network (VLAN), which is needed by a virtual Ethernet adapter on the migrating partition.

HSCLA356 HSCLA356

Explanation: The RMC command issued to partition failed.

Problem determination: This means that destination VIOS partition cannot host the virtual adapter on the migrating partition.

HSCLA357 HSCLA357

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error code: 0x40000025.

HSCLA358 HSCLA358

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error code: 0x40000026

HSCLA359 HSCLA359

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x40000027.

HSCLA35A HSCLA35A

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x40000028.

HSCLA35B HSCLA35B

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x40000029.

HSCLA35C HSCLA35C

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x4000002A.

HSCLA35D HSCLA35D

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x4000002B.

HSCLA35E HSCLA35E

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x4000002C.

HSCLA35F HSCLA35F

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x4000002D.

HSCLA360 HSCLA360

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x4000002E.

HSCLA361 HSCLA361

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x4000002F.

HSCLA362 HSCLA362

Explanation: The OS level of the partition does not support suspend or resume operations.

HSCLA363 HSCLA363

Explanation: The management console cannot communicate suspend commands to partition. Either a network connection to the partition is not available or the OS level of the partition does not support suspend or resume operations.

HSCLA364 HSCLA364

Explanation: The partition has returned an error to the management console's request to perform a check for suspend readiness. This partition is not ready to be suspended at this time.

Problem determination: Try the operation again later.

HSCLA365 HSCLA365

Explanation: The partition migration has failed because the partition is not in the same state it was in when the migration was started.

Problem determination: Try the migration operation again.

HSCLA366 HSCLA366

Explanation: The reserved storage device assigned to the partition cannot be accessed from the destination management system.

HSCLA367 HSCLA367

Explanation: The migrating partition is using a manually assigned reserved storage device that cannot be accessed from the destination managed system. An automatically selected device will be used if possible.

HSCLA368 HSCLA368

Explanation: The destination managed system does not support the custom MAC address setting configured on the migrating partition.

Problem determination: To migrate the partition, the virtual Ethernet adapter must be configured to allow all OS defined MAC addresses.

HSCLA369 HSCLA369

Explanation: Since the destination managed system is a POWER6 server, the partition cannot be migrated because the MAC address assigned to the virtual Ethernet adapter in the slot of the migrating partition will change once the partition is shutdown and activated again on the destination managed system.

Problem determination: To perform a partition migration from a POWER7 server to a POWER6 server, you must make sure that the partition is running with MAC addresses by the management console for its virtual Ethernet adapters and that there are no virtual Ethernet adapters in slots greater than 255 on the migrating partition.

HSCLA36A HSCLA36A

Explanation: The partition cannot be migrated because the MAC address assigned to the virtual Ethernet adapter of the migrating partition will change once the partition is shut down and activated again on the destination managed system.

Problem determination: To perform a partition migration, you must make sure that the partition is running with MAC addresses assigned by the management console for its virtual Ethernet adapters and that there are no virtual Ethernet adapters placed in slots greater than 255 on the migrating partition.

HSCLA36B HSCLA36B

Explanation: The partition cannot be migrated because the MAC address assigned to the virtual Ethernet adapter of the migrating partition will change once the partition is shut down and activated again on the destination managed system.

Problem determination: To perform a partition migration, you must make sure that there are no virtual Ethernet adapters in slots greater than 255 on the migrating partition.

HSCLA36C HSCLA36C

Explanation: The partition cannot be migrated because the MAC address assigned to the virtual Ethernet adapter of the migrating partition is the same as the MAC address assigned to the virtual Ethernet adapter of the partition on the destination managed system.

HSCLA36D HSCLA36D

Explanation: The partition cannot be migrated because the destination management console cannot validate the MAC address of one of its virtual Ethernet adapters.

Problem determination: If the partition has a virtual Ethernet adapter in a slot greater than 255, you must either upgrade the source management console to V7R7.2 or later, or make sure there is no virtual Ethernet adapter in a slot greater than 255. Then try the operation again.

HSCLA36E HSCLA36E

Explanation: The maximum number of partitions that can be configured to be remote restart capable has already been reached on the managed system. The maximum number of remote restart capable partitions supported by this managed system.

HSCLA36F HSCLA36F

Explanation: The maximum number of partitions that can be configured to be suspend capable has already been reached on the managed system.

HSCLA370 HSCLA370

Explanation: The managed system does not support network management over SNMP from the management console.

HSCLA371 HSCLA371

Explanation: Network management over SNMP is already enabled for managed system.

HSCLA372 HSCLA372

Explanation: Network management over SNMP is already enabled on the management console.

HSCLA373 HSCLA373

Explanation: Network management over SNMP is not enabled on the management console.

HSCLA374 HSCLA374

Explanation: Network management over SNMP is not enabled on managed system.

HSCLA375 HSCLA375

Explanation: None of the managed systems connected by this management console support network management over SNMP from the management console.

HSCLA376 HSCLA376

Explanation: The maximum number of managed systems that can be configured for network management over SNMP has already been reached on the management console.

HSCLA377 HSCLA377

Explanation: The destination managed system firmware has failed the compatibility data checking performed on the migrating partition with the following error: 0x40000043.

HSCLA380 HSCLA380

Explanation: The management console for the destination managed system does not support one or more capabilities desired by the management console managing the source managed system.

HSCLA381 HSCLA381

Explanation: The destination managed system does not support partition power management. The power management setting of the partition will be lost after migration.

HSCLA382 HSCLA382

Explanation: The destination managed system does not support Quality of Service virtual Ethernet priority levels. The Quality of Service priority settings of the virtual Ethernet adapters of the partition will be lost after migration.

HSCLA383 HSCLA383

Explanation: The destination managed system does not support selective memory mirroring or does not have selective memory mirroring enabled.

HSCLA384 HSCLA384

Explanation: The destination managed system does not support SRIOV adapters.

HSCLA385 HSCLA385

Explanation: The source SRIOV Ethernet virtual adapter with virtual slot ID cannot be found on the source managed system.

HSCLA386 HSCLA386

Explanation: The destination SRIOV physical port selected for the source SRIOV Ethernet virtual adapter with virtual slot ID does not have any free logical ports.

HSCLA387 HSCLA387

Explanation: The destination SRIOV logical port selected for the source SRIOV Ethernet virtual adapter with virtual slot ID is already in use.

HSCLA388 HSCLA388

Explanation: The destination SRIOV physical port selected for the source SRIOV Ethernet virtual adapter with virtual slot ID does not support the configuration of the source SRIOV Ethernet virtual adapter.

HSCLA389 HSCLA389

Explanation: The destination SRIOV physical port selected for the source SRIOV Ethernet virtual adapter with virtual slot ID does not have any free logical ports.

HSCLA38A HSCLA38A

Explanation: The destination SRIOV physical port selected for the SRIOV Ethernet virtual adapter with virtual slot ID cannot be found on the target managed system.

HSCLA38B HSCLA38B

Explanation: The destination SRIOV physical port selected for SRIOV Ethernet virtual adapter with virtual slot ID does not have enough free logical ports.

HSCLA38C HSCLA38C

Explanation: The destination SRIOV physical port selected for the source SRIOV Ethernet virtual adapter with virtual slot ID does not have enough capacity.

HSCLA38D HSCLA38D

Explanation: An unknown error occurred when performing automatic SRIOV Ethernet virtual adapter mapping.

HSCLA38E HSCLA38E

Explanation: There is no SRIOV physical port on the target managed system that has available logical ports.

HSCLA38F HSCLA38F

Explanation: The management console cannot find a destination SRIOV Ethernet virtual adapter for the SRIOV Ethernet virtual adapter with virtual slot ID.

HSCLA390 HSCLA390

Explanation: There are not enough unconfigured SRIOV logical ports on the target managed system to support the migration.

HSCLA391 HSCLA391

Explanation: The failed partition operation cannot be cleaned up.

Problem determination: Try the recovery operation later.

HSCLA392 HSCLA392

Explanation: The request issued to clean up the session between the management console and the Virtual I/O Server partition has failed.

HSCLA393 HSCLA393

Explanation: Cannot migrate partition because it has a diagnostic SRIOV Ethernet virtual adapter configured.

Problem determination: Remove the diagnostic SRIOV Ethernet virtual adapter or change its mode to non-diagnostic.

HSCLA394 HSCLA394

Explanation: Cannot migrate partition because it has a promiscuous SRIOV Ethernet virtual adapter configured.

Problem determination: Remove the promiscuous SRIOV Ethernet virtual adapter or change its mode to non-diagnostic.

HSCLA395 HSCLA395

Explanation: Cannot migrate partition because it has non-functional SRIOV virtual adapter in virtual slots.

Problem determination: Remove those virtual adapters and try again.

HSCLA396 HSCLA396

Explanation: No source vsi VIOS found for vlan.

HSCLA397 HSCLA397

Explanation: The destination managed system does not support VSI profiles for virtual Ethernet (VETH) adapters. If the VSI profiles override has been specified, the VETH adapter VSI profiles for partition will be lost after the migration.

HSCLA398 HSCLA398

Explanation: The RMC command issued to partition failed. This means that the Virtual Station Interface (VSI) profile used by adapter Cannot be configured on the destination virtual I/O server partition. The search was performed for the following device description.

HSCLA399 HSCLA399

Explanation: The destination virtual I/O server partition is no longer a valid choice for configuring the Virtual Station Interface (VSI) profile belonging to the adapter in slot of the migrating partition.

Problem determination: Please try the operation again.

HSCLA39A HSCLA39A

Explanation: The operation to configure the Virtual Station Interface (VSI) profile for adapter on the virtual IO server partition has failed.

HSCLA400 HSCLA400

Explanation: Hardware Discovery slots not specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA401 HSCLA401

Explanation: Hardware Discovery operations are not supported on this managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA402 HSCLA402

Explanation: Hardware Discovery operation failed due to file open failure.

Problem determination: If the problem persists,

HSCLA403 • HSCLA416

contact your next level of support or your service provider.

HSCLA403 HSCLA403

Explanation: Hardware Discovery operation failed due to file construction failure.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA404 HSCLA404

Explanation: Hardware Discovery terminated due to conflict with scheduled operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA405 HSCLA405

Explanation: Hardware Discovery operation failed due to file read failure.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA406 HSCLA406

Explanation: Hardware Discovery operation failed due to file write failure.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA407 HSCLA407

Explanation: Hardware Discovery operations are not supported on this managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA408 HSCLA408

Explanation: Hardware Discovery operations failed because the partition is not bootable.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA409 HSCLA409

Explanation: Hardware Discovery operations failed because the partition is not in the Not Activated state.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA40C HSCLA40C

Explanation: Hardware discovery operations failed because a console terminal connection to the partition could not be opened.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA410 HSCLA410

Explanation: The pool is not configured.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA411 HSCLA411

Explanation: The pool does not exist.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA413 HSCLA413

Explanation: The managed system does not support Active Memory Sharing.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA414 HSCLA414

Explanation: Partition is not a Virtual I/O Server partition that supports Active Memory Sharing or partition suspend and resume operations.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA415 HSCLA415

Explanation: The Virtual I/O Server partition could not be set to provide paging services for the pool.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA416 HSCLA416

Explanation: The pool operation failed because the management console was unable to remove stale device data from the Virtual I/O Server partition.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA417 HSCLA417

Explanation: The pool operation failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA418 HSCLA418

Explanation: The migrating partition is using a reserved storage device. However, there are no reserved storage devices available on the destination managed system because it does not have a reserved storage device pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA419 HSCLA419

Explanation: The shared memory pool size must be a multiple of the memory region size for the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA41A HSCLA41A

Explanation: There is an insufficient amount of memory available on the managed system to set the shared memory pool to the requested size.

Problem determination: If you want to set the shared memory pool to the requested size, you must free sufficient system memory first.

HSCLA41B HSCLA41B

Explanation: The partition was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA41E HSCLA41E

Explanation: The device cannot be removed from the pool because it is being used by partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA41F HSCLA41F

Explanation: System firmware did not return the correct version of partition information. Run the rebuild managed system operation.

Problem determination: If this error persists, contact your service representative.

HSCLA420 HSCLA420

Explanation: The specified Virtual I/O Server partition is already assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA421 HSCLA421

Explanation: The size of the shared memory pool cannot be decreased by the requested amount because the requested amount exceeds the amount of memory that is available in the shared memory pool.

Problem determination: If you want to decrease the size of the shared memory pool by the requested amount and there are running shared memory partitions, you must remove sufficient I/O entitled memory from those partitions first.

HSCLA422 HSCLA422

Explanation: The maximum size of the shared memory pool cannot be less than the size of the shared memory pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA423 HSCLA423

Explanation: The request issued to the Virtual I/O Server partition that is assigned to the pool has failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA424 HSCLA424

Explanation: The device was not found on Virtual I/O Server partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA425 HSCLA425

Explanation: The new shared memory pool size is less than the minimum shared memory pool size allowed for the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA426 HSCLA426

Explanation: The new maximum shared memory pool size is less than the minimum shared memory pool size allowed for the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA427 HSCLA427

Explanation: The shared memory pool size cannot exceed the maximum shared memory pool size.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA428 HSCLA428

Explanation: The maximum shared memory pool size must be a multiple of the memory region size for the managed system.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA429 HSCLA429

Explanation: The size of the shared memory pool must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA430 HSCLA430

Explanation: The shared memory pool cannot be deleted because there are partitions configured to use this pool.

Problem determination: If you want to delete this pool, you must delete all of the shared memory partitions or reactivate them in dedicated memory mode.

HSCLA431 HSCLA431

Explanation: The pool cannot be created because it already exists.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA432 HSCLA432

Explanation: An internal management console error occurred.

Problem determination: If this error persists, contact your service representative.

HSCLA433 HSCLA433

Explanation: An internal error occurred.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA434 HSCLA434

Explanation: A Virtual I/O Server partition for the pool must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA435 HSCLA435

Explanation: There is not a device available in the reserved storage device pool or shared memory pool that can be the paging space for partition.

Problem determination: This partition requires a device with a larger size. Add a paging space device of at least the size needed to the shared memory pool, and try the operation again. If you want to use a smaller device, then modify the partition's profile to reduce the maximum memory setting for the partition so that it is less than or equal to the size of the available device that you want to use, then try the operation again.

HSCLA436 HSCLA436

Explanation: There is an insufficient amount of memory available in the shared memory pool to activate this partition.

Problem determination: An additional amount of memory is needed. If you want to activate this partition, you must increase the amount of memory available in the shared memory pool, or you must reduce the amount of I/O entitled memory required for this partition. Some of your options are: 1. Increase the size of the shared memory pool. 2. Remove I/O entitled memory from any running shared memory partition. 3. If the profile you are trying to activate is configured to use automatic I/O entitled memory management, remove one or more virtual SCSI, virtual Ethernet, or virtual fibre channel adapters from the profile. 4. If the profile you are trying to activate is configured to use custom I/O entitled memory, reduce the amount of I/O entitled memory specified in the profile.

HSCLA438 HSCLA438

Explanation: There is an error in the management console's internal database.

Problem determination: Run the rebuild managed system operation, and try again.

HSCLA439 HSCLA439

Explanation: There is no RMC connection between the management console and the Virtual I/O Server (VIOS) partition that will provide paging services for this shared memory partition.

Problem determination: This could be because the VIOS partition is not in the Running state. Check the VIOS partition state, and also check the network setup.

HSCLA43A HSCLA43A

Explanation: The device selected for this partition cannot be activated on Virtual I/O Server partition.

Problem determination: Remove this device from the reserved storage device pool or shared memory pool, and try activating this partition again.

HSCLA43B HSCLA43B

Explanation: I/O entitled memory could not be added to the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA43C HSCLA43C

Explanation: I/O entitled memory could not be removed from the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA43D HSCLA43D

Explanation: The memory weight for partition could not be modified.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA43E HSCLA43E

Explanation: The amount of I/O entitled memory for partition could not be modified because the current and pending amounts of I/O entitled memory for the partition are not the same, and the management console was unable to set them to be the same.

Problem determination: Run the rebuild managed system operation, and try again.

HSCLA43F HSCLA43F

Explanation: The memory weight value specified is not valid.

Problem determination: The value must be between 0 and 255, inclusive.

HSCLA440 HSCLA440

Explanation: The requested amount of I/O entitled memory cannot be added to this partition because it would cause the amount of I/O entitled memory to exceed the amount of logical memory for this partition.

Problem determination: If you want to add more, then add more logical memory to your partition also.

HSCLA441 HSCLA441

Explanation: You cannot remove more I/O entitled memory than your partition currently has assigned.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA442 HSCLA442

Explanation: The file is corrupted.

Problem determination: Contact your service representative.

HSCLA443 HSCLA443

Explanation: The file cannot be read.

Problem determination: Contact your service representative.

HSCLA444 HSCLA444

Explanation: This operation is only allowed for a shared memory partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA445 HSCLA445

Explanation: This operation is only allowed when the partition is in the Not Activated state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA447 HSCLA447

Explanation: Since this partition is in a workload group, the requested amount of memory cannot be removed because it will cause the amount of memory assigned to this partition to be less than this partition's minimum memory setting.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA448 HSCLA448

Explanation: The amount of memory to be removed must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA449 HSCLA449

Explanation: A partition must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA44A HSCLA44A

Explanation: You cannot remove more memory than your partition currently has assigned.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA44B HSCLA44B

Explanation: The requested amount of memory cannot be removed because it will cause the amount of memory assigned to this partition to be greater than 0 but less than the required minimum amount for this partition based on this partition's maximum memory setting. However, you can remove all of the memory assigned to this partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA44C HSCLA44C

Explanation: The RMC connection between the management console and the Virtual I/O Server partition that is assigned to the pool has been interrupted.

Problem determination: This could be because the partition is no longer in the Running state, or the partition is hung. Check the state of the partition.

HSCLA44D HSCLA44D

Explanation: The request issued to the Virtual I/O Server partition that is assigned to the pool has failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA44E HSCLA44E

Explanation: The requested amount of logical memory cannot be removed from this partition because it would cause the amount of logical memory to be less than the amount of I/O entitled memory for this partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA44F HSCLA44F

Explanation: The request issued to the partition to query its I/O entitled memory statistics has failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA450 HSCLA450

Explanation: The request issued to the partition to reset its I/O entitled memory statistics has failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA451 HSCLA451

Explanation: The partition's I/O entitled memory management mode could not be modified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA452 HSCLA452

Explanation: The memory weight for partition could not be modified.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA453 HSCLA453

Explanation: The Virtual I/O Server (VIOS) partition currently assigned to the shared memory pool cannot be changed because it is being used to provide paging services for running shared memory partitions.

Problem determination: If you want to change the VIOS partition currently assigned to the shared memory pool, you must shut down all of the running shared memory partitions first.

HSCLA454 HSCLA454

Explanation: The partition is not in the Running state.

Problem determination: This operation is only allowed when the partition is running.

HSCLA455 HSCLA455

Explanation: The device on Virtual I/O Server partition is in an unknown state and cannot be removed from the pool.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA457 HSCLA457

Explanation: Partition cannot be activated because its profile is missing a necessary virtual I/O adapter.

Problem determination: Shared memory partitions are required to have at least one virtual I/O adapter of any type other than virtual serial.

HSCLA458 HSCLA458

Explanation: Partition cannot be activated because the maximum number of shared memory partitions supported on this managed system are running.

Problem determination: If you want to activate this partition, you must shut down a shared memory partition first.

HSCLA459 HSCLA459

Explanation: Dynamic memory move operations are not supported for partitions that use shared memory.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA45A HSCLA45A

Explanation: Stale device data cannot be removed from the Virtual I/O Server partition because the partition is currently assigned to the reserved storage device or the shared memory pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA45B HSCLA45B

Explanation: The amount of I/O entitled memory assigned to partition could not be modified.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA45C HSCLA45C

Explanation: Some, but not all, of the requested amount of I/O entitled memory was added to, or removed from, the partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA45D HSCLA45D

Explanation: There is an insufficient amount of system memory available to activate this partition with the maximum memory setting specified in the profile.

Problem determination: Additional memory is needed. If you want to activate this partition, you must decrease the maximum memory setting in the profile, or you must free sufficient system memory.

HSCLA45E HSCLA45E

Explanation: There is an insufficient amount of memory available in the shared memory pool to add the required amount of I/O entitled memory to the partition.

Problem determination: Additional memory is needed. If you want to add the required amount of I/O entitled memory to this partition, perform one or more of the following actions first. 1. Increase the size of the shared memory pool. 2. Remove I/O entitled memory from any running shared memory partition.

HSCLA45F HSCLA45F

Explanation: Partition cannot be activated because it requires additional I/O entitled memory.

Problem determination: The amount exceeds the amount of desired logical memory for the partition. Increase the desired logical memory setting in the profile you are trying to activate, and try again.

HSCLA460 HSCLA460

Explanation: A Virtual I/O Server (VIOS) partition cannot be added to the pool because there are already two VIOS partitions assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA461 HSCLA461

Explanation: The Virtual I/O Server partition is already assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA462 HSCLA462

Explanation: The Virtual I/O Server (VIOS) partition cannot be removed from the pool because it is the only VIOS partition assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA463 HSCLA463

Explanation: Partition cannot be removed from the pool because it is not currently assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA464 HSCLA464

Explanation: The partition specified to be replaced in the pool is not currently assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA465 HSCLA465

Explanation: The paging Virtual I/O Server (VIOS) partition cannot be removed from the shared memory pool because the following running shared memory partitions are configured to use this paging VIOS partition.

Problem determination: If you want to remove this paging VIOS partition from the shared memory pool, you must shut down all of these running shared memory partitions first.

HSCLA466 HSCLA466

Explanation: The managed system allows only one Virtual I/O Server partition to be assigned to the shared memory pool to provide paging services.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA467 HSCLA467

Explanation: A device name must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA468 HSCLA468

Explanation: The Virtual I/O Server partition which has the specified device must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA469 HSCLA469

Explanation: The specified partition is not a Virtual I/O Server partition that is assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA46A HSCLA46A

Explanation: The device is not available on Virtual I/O Server partition to be added to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA46B HSCLA46B

Explanation: The device on Virtual I/O Server partition is not in the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA46C HSCLA46C

Explanation: Two Virtual I/O Server partitions must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA46D HSCLA46D

Explanation: The specified Virtual I/O Server partitions are already assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA46E HSCLA46E

Explanation: The paging space device on Virtual I/O Server partition is already in the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA471 HSCLA471

Explanation: The Partition is not a Virtual I/O Server partition which is assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA472 HSCLA472

Explanation: No system memory is available and no memory can be removed from any shutdown or suspended dedicated memory partition.

Problem determination: If you want to activate this partition, remove memory from a running dedicated memory partition, and try again.

HSCLA473 HSCLA473

Explanation: A primary paging Virtual I/O Server partition must be specified.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA475 HSCLA475

Explanation: The secondary paging Virtual I/O Server (VIOS) partition cannot be the same as the primary paging VIOS partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA476 HSCLA476

Explanation: A secondary paging Virtual I/O Server (VIOS) partition cannot be specified for this partition because only one VIOS partition is currently assigned to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA477 HSCLA477

Explanation: There is an error in the management console's internal database.

Problem determination: Run the rebuild managed system operation, and try again.

HSCLA47A HSCLA47A

Explanation: There is no RMC connection between the management console and the Virtual I/O Server (VIOS) partition which is assigned to the pool.

Problem determination: This could be because the

VIOS partition is not in the Running state. Check the VIOS partition state, and also check the network setup.

HSCLA47B HSCLA47B

Explanation: There is no RMC connection between the management console and any of the Virtual I/O Server (VIOS) partition(s) that are assigned to the pool.

Problem determination: This could be because the VIOS partition(s) are not in the Running state. Check the VIOS partition state(s), and also check the network setup.

HSCLA47C HSCLA47C

Explanation: The Partition cannot be activated with the paging Virtual I/O Server (VIOS) partition configuration specified in the profile because one of the paging VIOS partitions is not available, or a paging space device that can be used with that paging VIOS configuration is not available.

Problem determination: However, this partition can be activated with a different paging VIOS partition configuration now. If this partition is configured to use redundant paging VIOS partitions, then this partition can be activated to use a non-redundant paging VIOS partition. If this partition is configured to use non-redundant paging VIOS partitions, then this partition can be activated to use a different paging VIOS partition than the one specified in the profile. If you want to activate this partition with the paging VIOS configuration that is available now, then run the chsysstate command with the --force option to activate this partition.

HSCLA47D HSCLA47D

Explanation: The partition cannot be activated because it is configured to use redundant paging Virtual I/O Server (VIOS) partitions, but the managed system does not support the assignment of two paging VIOS partitions to the shared memory pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA47E HSCLA47E

Explanation: The Partition is not configured to use redundant paging Virtual I/O Server partitions.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA480 HSCLA480

Explanation: A Virtual I/O Server (VIOS) partition cannot be added to the pool at this time because there is no RMC connection between the management console and the VIOS partition that is currently assigned to the pool.

Problem determination: Verify that partition is in the Running state, and check the network setup. When an RMC connection between the management console and partition has been established, then you can add another VIOS partition to the pool.

HSCLA481 HSCLA481

Explanation: The specified Virtual I/O Server (VIOS) partition cannot be removed from the pool at this time because there is no RMC connection between the management console and the other VIOS partition that is assigned to the pool.

Problem determination: Verify that partition is in the Running state, and check the network setup. When an RMC connection between the management console and partition has been established, then you can remove the specified VIOS partition from the pool.

HSCLA483 HSCLA483

Explanation: The operation to query devices failed on Virtual I/O Server partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA484 HSCLA484

Explanation: The operation to add paging space device failed on Virtual I/O Server partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA485 HSCLA485

Explanation: The operation to remove device failed on Virtual I/O Server partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA486 HSCLA486

Explanation: The operation to update device from redundant to non-redundant failed on Virtual I/O Server partition.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA487 HSCLA487

Explanation: The specified Virtual I/O Server (VIOS) partition cannot be changed in the pool at this time because there is no RMC connection between the management console and the other VIOS partition that is currently assigned to the pool.

Problem determination: Verify that partition is in the Running state, and check the network setup. When an RMC connection between the management console and partition has been established, then you can change the specified VIOS partition in the pool.

HSCLA488 HSCLA488

Explanation: The pool was created successfully. However, not all of the requested devices were successfully added to the pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA489 HSCLA489

Explanation: One or more of the add device operations failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA48A HSCLA48A

Explanation: The add device operation failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA48B HSCLA48B

Explanation: One or more of the remove device operations failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA48C HSCLA48C

Explanation: The remove paging operation failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA48D HSCLA48D

Explanation: The Virtual I/O Server partition assigned to the pool was modified successfully. However, at least one of the resulting device operations failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA48E HSCLA48E

Explanation: The Virtual I/O Server partition was successfully added to the pool. However, at least one of the resulting device operations failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA48F HSCLA48F

Explanation: The Virtual I/O Server partition was successfully removed from the pool. However, at least one of the resulting device operations failed.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA490 HSCLA490

Explanation: The Partition specified was not found.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA491 HSCLA491

Explanation: The partition could not be switched over to its redundant paging Virtual I/O Server (VIOS) partition because the paging VIOS partition that is currently providing the paging services for the partition could not be determined.

Problem determination: Run the rebuild managed system operation, and try again.

HSCLA492 HSCLA492

Explanation: The partition could not be switched over to its redundant paging Virtual I/O Server (VIOS) partition because the paging space device being used by the partition could not be found on the redundant paging VIOS partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA493 HSCLA493

Explanation: You cannot request more than one add, remove, or change operation on the Virtual I/O Server partitions assigned to the shared memory pool at the same time.

Problem determination: These operations must be performed one at a time.

HSCLA494 HSCLA494

Explanation: There are non-redundant paging space devices in the shared memory pool that can now be accessed by both paging Virtual I/O Server (VIOS) partitions.

Problem determination: These devices could not be updated to redundant paging space devices because the paging VIOS partition does not support this operation. Please upgrade the paging VIOS partition. To update the non-redundant paging space devices in the shared memory pool, remove the paging space devices from the shared memory pool, then add them again.

HSCLA495 HSCLA495

Explanation: The partition could not be activated with the full system profile because a shared memory pool or a reserved storage device pool exists on the managed system.

Problem determination: To activate a partition with a full system profile, you must delete the shared memory pool and the reserved storage device pool first.

HSCLA496 HSCLA496

Explanation: The Partition cannot be activated because the configuration of the paging Virtual I/O Server (VIOS) partition is incomplete.

Problem determination: Please shut down the paging VIOS partition, then reactivate it to restore its configuration. Then try to activate partition again.

HSCLA497 HSCLA497

Explanation: The Virtual I/O Server (VIOS) partition was successfully removed from the pool. However, the devices remaining in the pool could not be updated because there is no RMC connection between the management console and the other VIOS partition that is assigned to the pool.

Problem determination: When an RMC connection is established to the VIOS partition, you will need to update any redundant devices in the pool, since those devices are no longer redundant. To update the devices, remove them from the pool then add them again.

HSCLA498 HSCLA498

Explanation: The operation to add device failed on Virtual I/O Server (VIOS) partition.

Problem determination: Please make sure the reserve policy of storage device on VIOS partition and storage device on VIOS partition is "no_reserve", then try the operation again.

HSCLA499 HSCLA499

Explanation: The device selection type is not supported on the Virtual I/O Server partition.

Problem determination: Please upgrade the Virtual I/O Server partition to a level that supports device selection type and try the operation again.

HSCLA49A HSCLA49A

Explanation: The device is being used by the partition and cannot be removed.

HSCLA49B HSCLA49B

Explanation: The Virtual I/O Server (VIOS) partition cannot be removed from the pool because the partitions are configured to use this Virtual I/O Server partition.

Problem determination: If you want to remove from the pool, you will need to do the following to the desired partitions. 1. Shut down the shared memory partitions. 2. Resume the suspended partitions.

HSCLA49C HSCLA49C

Explanation: The Virtual I/O Server (VIOS) partition returned error.

Problem determination: One possible cause is that there is not enough free space in the / file system on the VIOS partition. Check the free space in the / file system. If necessary, free up space in that file system, then try the operation again.

HSCLA49D HSCLA49D

Explanation: The operation to create a reserved storage device pool is not supported on this managed system.

HSCLA49E HSCLA49E

Explanation: The operation to create a non-redundant paging device failed because there is already a paging device with the same backing device created on the Virtual I/O Server.

HSCLA49F HSCLA49F

Explanation: The partition is not a Virtual I/O Server partition that supports manual selection of reserved storage devices.

HSCLA4A0 HSCLA4A0

Explanation: The operation failed because the managed system does not support Active Memory Sharing or partition suspend and resume operations.

HSCLA4A1 HSCLA4A1

Explanation: The Virtual I/O Server (VIOS) partitions support different capabilities, which may be caused by different OS levels. This may cause future shared memory, partition suspend, or partition resume operations to fail.

Problem determination: Please ensure that the OS levels on both VIOS partitions are the same.

HSCLA4A2 HSCLA4A2

Explanation: The size of the shared memory pool cannot be less than the amount of memory that system firmware is using.

HSCLA4A3 HSCLA4A3

Explanation: The operation failed to get the device details from Virtual I/O Server (VIOS). This could be because no reserved storage device is attached partition or the attached reserved storage device type is not supported for this operation.

Problem determination: Please correct the configuration and try the operation.

HSCLA4B0 HSCLA4B0

Explanation: Partition cannot be activated because the managed system does not support Active Memory Expansion.

Problem determination: Turn off Active Memory Expansion in the partition profile, and try again.

HSCLA4B1 HSCLA4B1

Explanation: The managed system does not support Active Memory Expansion.

HSCLA4B2 HSCLA4B2

Explanation: This operation can only be performed when the partition is currently configured to use Active Memory Expansion.

HSCLA4B3 HSCLA4B3

Explanation: The Active Memory Expansion factor specified is not valid.

HSCLA4B4 HSCLA4B4

Explanation: Active Memory Expansion can only be used with POWER7 processor compatibility modes.

HSCLA4B5 HSCLA4B5

Explanation: The Active Memory Expansion value specified is not valid.

Problem determination: The value must be 0, or it must be between values.

HSCLA4B6 HSCLA4B6

Explanation: The partition cannot be migrated because it is configured to use Active Memory Expansion, and the destination managed system does not support Active Memory Expansion.

HSCLA4C0 HSCLA4C0

Explanation: The managed system does not support virtual fibre channel.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4C1 HSCLA4C1

Explanation: AIX, Linux, and IBM i partitions cannot have virtual fibre channel server adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4C2 HSCLA4C2

Explanation: Virtual I/O Server partitions cannot have virtual fibre channel client adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4C3 HSCLA4C3

Explanation: The remote virtual fibre channel adapter is being used by another virtual fibre channel adapter.

Problem determination: Choose a different remote virtual fibre channel adapter, and try again.

HSCLA4C4 HSCLA4C4

Explanation: The WWPN pair assigned to the virtual fibre channel adapter is already in use.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4C5 HSCLA4C5

Explanation: There are no WWPNs remaining for this managed system that can be assigned to a virtual fibre channel adapter.

Problem determination: To obtain additional WWPNs for this managed system, request a WWPN renewal code from the Capacity on Demand website. Then enter this code on the management console.

HSCLA4C6 HSCLA4C6

Explanation: The WWPN prefix has not been configured for this managed system.

Problem determination: The WWPN prefix is required to generate WWPNs for virtual fibre channel adapters. To configure the WWPN prefix for this managed system, request a WWPN renewal code from the Capacity on Demand website. Then enter this code on the management console.

HSCLA4C7 HSCLA4C7

Explanation: The Virtual I/O Server (VIOS) slot number specified for virtual fibre channel adapter on VIOS partition for the destination managed system is not valid.

Problem determination: Please issue the command to list the available slots on the destination VIOS partitions that can host this client adapter, and try the operation again using a slot number from the available slot number list. Alternatively, allow the management console to make the selection by not specifying a slot number.

HSCLA4C8 HSCLA4C8

Explanation: The Virtual I/O Server VIOS slot number specified for virtual SCSI adapter on VIOS partition for the destination managed system is not valid.

Problem determination: Please issue the command to list the available slots on the destination VIOS partitions that can host this client adapter, and try the operation again using a slot number from the available slot number list. Alternatively, allow the management console to make the selection by not specifying a slot number.

HSCLA4C9 HSCLA4C9

Explanation: The destination management console does not support maintaining the slot numbers of the source Virtual I/O Server VIOS partitions.

Problem determination: Slot numbers may not have been maintained in the destination VIOS partitions.

HSCLA4CA HSCLA4CA

Explanation: The source management console does not support maintaining the slot numbers of the source Virtual I/O Server (VIOS) partitions.

Problem determination: Slot numbers may not have been maintained in the destination VIOS partitions.

HSCLA4CB HSCLA4CB

Explanation: The destination management console does not support slot number selections for the destination Virtual I/O Server (VIOS) partitions.

Problem determination: Therefore, the destination VIOS slot number selections made by the destination management console may not be the same as those that you specified or those that are currently in use on the source VIOS partitions.

HSCLA4CC HSCLA4CC

Explanation: The management console cannot maintain the source Virtual I/O Server (VIOS) slot number for virtual SCSI adapter on the destination VIOS partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4CD HSCLA4CD

Explanation: The management console cannot maintain the source Virtual I/O Server (VIOS) slot number for virtual fibre channel adapter on the destination VIOS partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4CE HSCLA4CE

Explanation: The specified source Mover Service Partition (MSP) IP address is not valid.

Problem determination: Run the command to list valid MSP IP addresses to find a valid IP address.

HSCLA4CF HSCLA4CF

Explanation: The specified destination Mover Service Partition (MSP) IP address is not valid.

Problem determination: Run the command to list valid MSP IP addresses to find a valid IP address.

HSCLA4D0 HSCLA4D0

Explanation: The desired processor setting exceeds the limit of processors for a partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4D1 HSCLA4D1

Explanation: The desired virtual processor setting exceeds the limit of virtual processors for a partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4D2 HSCLA4D2

Explanation: The partition cannot be activated because the minimum processor setting in the profile exceeds the limit of processors for a partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4D3 HSCLA4D3

Explanation: The partition cannot be activated because the minimum virtual processor setting in the profile exceeds the limit of virtual processors for a partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4D4 HSCLA4D4

Explanation: The new total number of processors for this partition exceeds the limit of processors for a partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4D5 HSCLA4D5

Explanation: The new total number of virtual processors for this partition exceeds the limit of virtual processors for a partition.

Problem determination: If the problem persists,

contact your next level of support or your service provider.

HSCLA4D6 HSCLA4D6

Explanation: The number of current processors exceeds the processor limit for a partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4D7 HSCLA4D7

Explanation: The number of current virtual processors exceeds the virtual processor limit for a partition.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4D8 HSCLA4D8

Explanation: The source Virtual I/O Server does not support virtual fibre channel adapters.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4E0 HSCLA4E0

Explanation: The managed system does not support resource dumps.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4E1 HSCLA4E1

Explanation: The resource selector entered is not valid.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4E2 HSCLA4E2

Explanation: The managed system cannot start the specified resource dump at this time.

Problem determination: Wait for previous resource dumps to complete and rerun the operation.

HSCLA4E3 HSCLA4E3

Explanation: You are not authorized to use the specified resource selector from a management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4F0 HSCLA4F0

Explanation: The managed system does not support Active Memory Deduplication.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4F1 HSCLA4F1

Explanation: Active Memory Deduplication is already enabled for the shared memory pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4F2 HSCLA4F2

Explanation: Active Memory Deduplication is already disabled for the shared memory pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA4F3 HSCLA4F3

Explanation: The deduplication table ratio cannot be specified when Active Memory Deduplication is disabled for the shared memory pool.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA500 HSCLA500

Explanation: An internal error occurred.

Problem determination: Try the operation again. If the operation continues to fail, contact your service representative.

HSCLA501 HSCLA501

Explanation: An error occurred while trying to unmount the media.

Problem determination: Ensure the media is not being shared and try the operation again.

HSCLA502 HSCLA502

Explanation: The removable media is write protected.

Problem determination: Remove the write protection and try the operation again.

HSCLA503 HSCLA503

Explanation: An error occurred while trying to mount the media.

Problem determination: Ensure the media is inserted properly and try the operation again.

HSCLA504 HSCLA504

Explanation: An error occurred while trying to write data to the file.

Problem determination: Ensure that space is available on the media and try the operation again.

HSCLA505 HSCLA505

Explanation: An error occurred while trying to mount the remote NFS file system.

Problem determination: Verify the host name or IP address, mount resource location, and mount options are correct and try the operation again.

HSCLA506 HSCLA506

Explanation: An error occurred while trying to write a file to the mounted NFS file system.

Problem determination: Check permissions and storage space on the target file system.

HSCLA507 HSCLA507

Explanation: An error occurred while trying to change directories on the mounted NFS file system.

Problem determination: Ensure the directory entered is valid and try the operation again.

HSCLA508 HSCLA508

Explanation: Unable to log in to the FTP server.

Problem determination: Verify the user ID and password are correct and try the operation again.

HSCLA509 HSCLA509

Explanation: Unable to connect to the FTP server.

Problem determination: Check if the FTP server is available and try the operation again.

HSCLA50A HSCLA50A

Explanation: Unable to find the FTP server.

Problem determination: Check the FTP server host name or IP address and try the operation again.

HSCLA50B HSCLA50B

Explanation: An FTP error occurred while trying to transfer a file.

Problem determination: Check permissions of the target location and try the operation again.

HSCLA50C HSCLA50C

Explanation: An unknown FTP error occurred.

Problem determination: Verify the FTP options are correct and try the operation again.

HSCLA50D HSCLA50D

Explanation: An error occurred while trying to change directories on the FTP server.

Problem determination: Ensure the directory entered is valid and try the operation again.

HSCLA50E HSCLA50E

Explanation: An FTP error occurred because there is insufficient space on the target FTP server.

Problem determination: Free up space on the target FTP server and try the operation again.

HSCLA50F HSCLA50F

Explanation: A backup task is already in progress.

Problem determination: Please wait and try again later.

HSCLA510 HSCLA510

Explanation: An error occurred while trying to remove an expired backup task lock.

Problem determination: Run `bkconsdata -r none` to remove the backup task lock and then try the operation again. If the operation continues to fail, contact your service representative.

HSCLA511 HSCLA511

Explanation: Unable to find the specified media device.

Problem determination: Verify the device exists. If the device does not exist, try the operation with a different media device.

HSCLA512 HSCLA512

Explanation: An FTP error occurred while trying to transfer a file. A firewall may be blocking communication between the management console and the remote FTP server.

HSCLA601 HSCLA601

Explanation: The managed system cannot start a system dump at this time because a concurrent maintenance operation is in progress.

Problem determination: Wait for the concurrent maintenance operation to complete, then initiate the system dump again.

HSCLA604 HSCLA604

Explanation: No dumps of the specified type were found on the specified managed system or frame.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA801 HSCLA801

Explanation: The managed system does not support IBM i network installs.

HSCLA802 HSCLA802

Explanation: Network install parameters can only be specified for IBM i partitions.

HSCLA803 HSCLA803

Explanation: Network install parameters can only be specified when the IPL source is set to D.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCLA900 HSCLA900

Explanation: A reserved storage device pool is not configured.

Problem determination: Configure the reserved storage device pool, then try the operation again.

HSCLA901 HSCLA901

Explanation: The selected partition cannot be suspended. Only AIX or Linux partitions can be suspended.

HSCLA902 HSCLA902

Explanation: The partition cannot be suspended because it is designated as the service partition for the managed system.

HSCLA903 HSCLA903

Explanation: The partition cannot be suspended because it is enabled as a redundant error path reporting partition.

HSCLA904 HSCLA904

Explanation: The selected partition cannot be suspended. Only AIX, Linux or IBM i partitions can be suspended.

HSCLA905 HSCLA905

Explanation: The partition is not configured to be suspend capable.

HSCLA906 HSCLA906

Explanation: The partition cannot be suspended because it is using Barrier Synchronization Register (BSR) arrays.

HSCLA907 HSCLA907

Explanation: The partition cannot be suspended because it is using huge page memory.

HSCLA908 HSCLA908

Explanation: The partition cannot be suspended because it belongs to a workload group.

HSCLA909 HSCLA909

Explanation: The partition cannot be suspended because it is using physical I/O.

HSCLA90A HSCLA90A

Explanation: The partition cannot be suspended because it is using a Host Ethernet Adapter.

HSCLA90B HSCLA90B

Explanation: The partition cannot be suspended because it is using an HCA adapter.

HSCLA90C HSCLA90C

Explanation: The partition cannot be suspended because it is using an SNI adapter.

HSCLA90E HSCLA90E

Explanation: The managed system does not support suspended or resume operations for IBM i partitions.

HSCLA90F HSCLA90F

Explanation: The partition could not be found.

Problem determination: Run the rebuild managed system operation, and try again.

HSCLA910 HSCLA910

Explanation: The managed system does not support partition suspend or resume operations.

HSCLA911 HSCLA911

Explanation: The partition cannot be suspended because a reserved storage device pool is not configured.

HSCLA912 HSCLA912

Explanation: The primary Virtual I/O Server partition must be specified.

HSCLA913 HSCLA913

Explanation: The partition cannot be activated with profile.

HSCLA914 HSCLA914

Explanation: The profile contains Host Ethernet adapter resources, which are not supported by a suspend capable partition.

HSCLA915 HSCLA915

Explanation: The profile contains a Host Channel Adapter resources, which are not supported by a suspend capable partition.

HSCLA916 HSCLA916

Explanation: The profile contains an SNI adapter, which is not supported by a suspend capable partition.

HSCLA917 HSCLA917

Explanation: The has redundant error path reporting enabled, which is not supported by a suspend capable partition.

HSCLA918 HSCLA918

Explanation: The profile contains an SMCA adapter, which is not supported by a suspend capable partition.

HSCLA919 HSCLA919

Explanation: The profile has a workload group setting, which is not supported by a suspend capable partition.

HSCLA91A HSCLA91A

Explanation: The profile contains Barrier Synchronization Register (BSR) arrays, which are not supported by a suspend capable partition.

HSCLA91B HSCLA91B

Explanation: The profile contains huge page memory, which is not supported by a suspend capable partition.

HSCLA91C HSCLA91C

Explanation: The profile contains physical I/O adapters, which are not supported by a suspend capable partition.

HSCLA91D HSCLA91D

Explanation: The partition profile for the partitions belongs to a system profile. After the partition is suspended, its profile will be deleted from the system profile.

HSCLA91E HSCLA91E

Explanation: The partition cannot be suspended because it is using an OptiConnect adapter.

HSCLA91F HSCLA91F

Explanation: The partition cannot be suspended because it is using a virtual OptiConnect adapter.

HSCLA920 HSCLA920

Explanation: The partition cannot be suspended because it is using an SMCA adapter.

HSCLA921 HSCLA921

Explanation: The partition cannot be suspended because it belongs to an I/O pool.

HSCLA922 HSCLA922

Explanation: The partition cannot be suspended because it belongs to an IOP group.

HSCLA923 HSCLA923

Explanation: The partition cannot be suspended because it is using a non-default virtual serial adapter.

HSCLA924 HSCLA924

Explanation: The partition may have an open virtual terminal session. The management console will force termination of the partition's open virtual terminal session when the suspend operation has completed.

HSCLA925 HSCLA925

Explanation: The partition has one or more power controlling partitions.

HSCLA926 HSCLA926

Explanation: The suspended capable partition cannot be activated with a profile that contains virtual SCSI server adapters.

HSCLA927 HSCLA927

Explanation: The suspended capable partition cannot be activated with a profile that contains virtual SCSI server adapters that are hosted by IBM i partitions.

HSCLA928 HSCLA928

Explanation: The Virtual I/O Server (VIOS) partition is not in the Running state. This operation is only allowed when the VIOS partition is running.

HSCLA929 HSCLA929

Explanation: There is no non-redundant device available in the reserved storage device pool that can be used by this partition. This partition requires a device with a larger size.

Problem determination: Add a device of at least that size to the reserved storage device pool, then try the operation again.

HSCLA92A HSCLA92A

Explanation: The suspended capable partition cannot be activated with a full system profile.

HSCLA92B HSCLA92B

Explanation: The partition cannot be suspended because the partition hosting one of its virtual SCSI adapters is not a Virtual I/O Server partition.

HSCLA92C HSCLA92C

Explanation: The partition cannot be suspended because it has a virtual SCSI server adapter that is hosting virtual SCSI client adapters.

HSCLA930 HSCLA930

Explanation: There is no redundant device available in the reserved storage device pool that can be used by this partition. This partition requires a device with a larger size.

Problem determination: Add a device of at least that size to the reserved storage device pool, then try the operation again.

HSCLA931 HSCLA931

Explanation: There is no RMC connection between the management console and the partition.

HSCLA933 HSCLA933

Explanation: The partition cannot be suspended at this time because the managed system has already reached its maximum number of concurrent active partition migration, suspend, and resume operations.

Problem determination: Try the operation again later.

HSCLA934 HSCLA934

Explanation: A command failed on the managed system.

Problem determination: Contact your service representative.

HSCLA935 HSCLA935

Explanation: A command failed on the managed system.

Problem determination: Contact your service representative.

HSCLA936 HSCLA936

Explanation: An unknown error occurred during the partition suspend operation.

Problem determination: Try the operation again. If the failure persists, contact your hardware service representative.

HSCLA938 HSCLA938

Explanation: The OS level of the Virtual I/O Server partition does not support partition suspend or resume operations.

HSCLA939 HSCLA939

Explanation: This operation cannot be performed while the partition is suspending, resuming, or shutting down.

HSCLA940 HSCLA940

Explanation: An error occurred while writing management console data to the reserved storage device for the partition.

Problem determination: Try the operation again later. If this error persists, contact your service representative.

HSCLA941 HSCLA941

Explanation: The operation to check the partition for suspend readiness has failed.

HSCLA942 HSCLA942

Explanation: The operation to prepare the partition to be suspended has failed.

HSCLA943 HSCLA943

Explanation: The request to prepare the partition for suspend has failed.

Problem determination: Try the operation again later.

HSCLA945 HSCLA945

Explanation: An error occurred while reading the management console data on the partition's reserved storage device.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA946 HSCLA946

Explanation: This operation is not allowed while the partition is being suspended.

HSCLA947 HSCLA947

Explanation: This operation is not allowed while the partition is being migrated.

HSCLA948 HSCLA948

Explanation: The request to stop the partition suspend operation has failed because a suspend operation is not in progress, or you have attempted to stop the suspend operation from an management console that does not control the suspend operation.

Problem determination: If a suspend operation is in progress, try to stop the suspend operation again from

the management console which was used to start the suspend operation.

HSCLA949 HSCLA949

Explanation: The request to stop the partition resume operation cannot be accepted, because a resume operation is not in progress, or you have attempted to stop the resume operation from an management console that does not control the resume operation.

Problem determination: If a resume operation is in progress, try to stop the resume operation again on the management console which was used to start the resume operation.

HSCLA950 HSCLA950

Explanation: The request to stop the partition suspend operation cannot be accepted, possibly because the suspend operation has either progressed beyond the point where it can safely be stopped, or the suspend operation has not reached a point where it can initiate the stop operation.

HSCLA951 HSCLA951

Explanation: The request to stop the partition resume operation cannot be accepted, possibly because the resume operation has either progressed beyond the point where it can safely be stopped, or the resume operation has not reached a point where it can initiate the stop operation.

HSCLA952 HSCLA952

Explanation: The request to stop the operation cannot be accepted.

HSCLA953 HSCLA953

Explanation: This operation is only allowed when the partition is in the suspended state.

HSCLA954 HSCLA954

Explanation: There is not a device available in the reserved storage device pool that can be used by this partition. This partition requires a device with a larger size.

Problem determination: Add a device larger to the reserved storage device pool, and try the operation again.

HSCLA955 HSCLA955

Explanation: The recovery operation has failed.

Problem determination: If possible, perform the recovery operation from the management console that was used to perform the suspend operation. Otherwise,

perform the recovery operation again from this management console using the force option.

HSCLA956 HSCLA956

Explanation: Only the hypervisor state for the partition can be cleaned up with the recovery operation, because the HMC is not able to determine the unique identifier for the suspend operation to be recovered.

HSCLA957 HSCLA957

Explanation: The management console is unable to locate or recreate the partition's transaction recovery file. Without the transaction recovery file, the management console may be limited in its ability to perform a complete recovery of the suspend operation.

Problem determination: If possible, issue the recovery operation from the management console that was used to perform the suspend operation, which the saved transaction recovery file. Otherwise, use the force option to force the recovery to proceed without it on this management console

HSCLA958 HSCLA958

Explanation: The current suspend state of this partition does not support a recovery operation because it is not a lost-connection suspend state.

Problem determination: Use the force option to recover a partition that is not in a lost-connection suspend state.

HSCLA959 HSCLA959

Explanation: An unknown error occurred during the recovery operation.

Problem determination: Try the operation again. If the failure persists, contact your hardware service representative.

HSCLA960 HSCLA960

Explanation: The recover request cannot be accepted because a partition migration is currently being performed for the partition.

HSCLA961 HSCLA961

Explanation: A recovery operation cannot be performed at this time.

Problem determination: Try again later.

HSCLA962 HSCLA962

Explanation: A partition suspend operation was started but did not complete successfully. Recovery procedures were started but did not complete successfully.

HSCLA963 HSCLA963

Explanation: The recovery operation has failed because the partition suspend operation is still in progress.

HSCLA964 HSCLA964

Explanation: The partition suspend operation has finished, and the management console is performing cleanup for the partition on the managed system.

HSCLA965 HSCLA965

Explanation: The recovery operation has failed because the managed system has been restarted.

Problem determination: Issue the recovery operation again with the force option on this management console

HSCLA966 HSCLA966

Explanation: The partition cannot be resumed because the reserved storage device containing the data needed to resume the partition is not valid.

Problem determination: Please contact your service representative.

HSCLA970 HSCLA970

Explanation: This mirrored memory defragmentation operation cannot be started because there is another mirrored memory defragmentation operation currently in progress on the managed system.

Problem determination: Try the operation again later.

HSCLA971 HSCLA971

Explanation: The request to start this mirrored memory defragmentation operation failed on the managed system.

Problem determination: Try the operation again later. If this error persists, contact your service representative.

HSCLA972 HSCLA972

Explanation: The amount of mirrored memory specified must be a multiple of the memory region size for the managed system.

HSCLA973 HSCLA973

Explanation: This mirrored memory defragmentation operation has already ended on the managed system.

HSCLA974 HSCLA974

Explanation: No mirrored memory defragmentation operation is currently in progress on the managed system.

HSCLA975 HSCLA975

Explanation: The request to stop the mirrored memory defragmentation operation on the managed system failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLA976 HSCLA976

Explanation: There is an insufficient amount of mirrored memory available on the managed system to activate this partition. Additional mirrored memory is needed.

Problem determination: If you want to activate this partition, you must free mirrored memory by shutting down one or more running partitions, or you must reduce the amount of mirrored memory needed for this partition. To reduce the amount of mirrored memory needed for this partition, you must reduce the maximum memory setting or the number of virtual adapters in the profile you are trying to activate.

HSCLA977 HSCLA977

Explanation: There is an insufficient amount of mirrored memory available on the managed system to perform this operation. Additional mirrored memory is needed.

Problem determination: If you want to perform this operation, you must free mirrored memory by performing a mirrored memory defragmentation operation or by shutting down one or more running partitions.

HSCLA978 HSCLA978

Explanation: No memory can be defragmented at this time.

Problem determination: If you want to make more mirrored memory available, you must free an amount of system memory that is approximately equal to twice the amount of mirrored memory that you want to make available, then run the memory defragmentation operation again.

HSCLA979 HSCLA979

Explanation: No additional mirrored memory can be made available because all of the mirrored memory that is not currently in use by system firmware is already available.

HSCLA97A HSCLA97A

Explanation: The operation failed.

Problem determination: Please ensure that the managed system is configured with memory that can be mirrored.

HSCLA97B HSCLA97B

Explanation: The operation to take the ownership of the reserved storage paging device has failed.

Problem determination: Check the device and ensure that it is not in use.

HSCLA980 HSCLA980

Explanation: This operation is only allowed when system firmware memory is fully mirrored.

HSCLA981 HSCLA981

Explanation: The suspend capable partition cannot be activated because optiConnect is enabled..

HSCLA984 HSCLA984

Explanation: The recovery operation has failed.

Problem determination: If possible, perform the recovery operation from the management console that was used to perform the resume operation. Otherwise, perform the recovery operation again from this management console using the force option.

HSCLA985 HSCLA985

Explanation: Only the hypervisor state from the partition can be cleaned up with the recovery operation, because the HMC is not able to determine the unique identifier for the resume operation to be recovered.

HSCLA986 HSCLA986

Explanation: The management console is unable to locate or recreate the partition's transaction recovery file. Without the transaction recovery file, the management console may be limited in its ability to perform a complete recovery of the resume operation..

Problem determination: If possible, issue the recovery operation from the management console that was used to perform the resume operation, which should have

the saved trasaction recovery file. Otherwise, use the force option to force the recovery to proceed without it on this management console

HSCLA987 HSCLA987

Explanation: The current resume state of this partition does not support a recovery operation because it is not a lost- connection resume state.

Problem determination: Use the force option to recover a partition that is not in a lost-connection resume state.

HSCLA988 HSCLA988

Explanation: A partition resume operation was started but did not complete successfully. Recovery procedures were started but did not complete successfully.

HSCLA989 HSCLA989

Explanation: The recovery operation has failed because the partition resume operation is still in progress.

HSCLA990 HSCLA990

Explanation: The partition resume operation has finished, and the management console is performing cleanup for the partition on the managed system.

HSCLA991 HSCLA991

Explanation: The specified device name is not valid.

HSCLA992 HSCLA992

Explanation: The primary VIOS is not valid.

HSCLA993 HSCLA993

Explanation: The secondary VIOS is not valid.

HSCLA994 HSCLA994

Explanation: The device you specified is to small.

HSCLA995 HSCLA995

Explanation: The device you specified is already in use by another partition.

HSCLA996 HSCLA996

Explanation: The remote restart capable partition cannot be a full system partition.

HSCLA999 HSCLA999

Explanation: The remote restart capable partition cannot have any Host Channel Adapter resource assigned to it.

HSCLA99A HSCLA99A

Explanation: The remote restart capable partition cannot have huge page memory.

HSCLA99B HSCLA99B

Explanation: The remote restart capable partition cannot have Barrier Synchronization Register arrays.

HSCLA99C HSCLA99C

Explanation: Device on Virtual I/O Server partition is not a manual selection type device in the reserved storage device pool.

HSCLA99D HSCLA99D

Explanation: Device on Virtual I/O Server partition is not a manual selection type redundant device in the reserved storage device pool.

HSCLA99E HSCLA99E

Explanation: The partition cannot be configured to be suspend capable at this time because its current configuration has resources or settings that are not allowed for suspend capable partitions.

HSCLA99F HSCLA99F

Explanation: The partition cannot be suspended because the reserved storage device assigned to the partition cannot be used.

Problem determination: Ensure that the device is not in use, and try the operation again.

HSCLA9A0 HSCLA9A0

Explanation: The remote restart operation cannot be performed because a reserved storage device pool does not exist.

HSCLA9A1 HSCLA9A1

Explanation: The remote restart operation cannot be performed because no Virtual I/O Server (VIOS) partitions are available.

Problem determination: Ensure that your VIOS partitions are running, have a network connection to the management console, and support partition remote restart.

HSCLA9A2 HSCLA9A2

Explanation: The remote restart operation cannot be performed because Virtual I/O Server (VIOS) partitions is not available.

Problem determination: Ensure that your VIOS partitions are running, have a network connection to the management console, and supports partition remote restart.

HSCLA9A3 HSCLA9A3

Explanation: The remote restart cannot be performed because Virtual I/O Server partitions is able to access the reserved storage device assigned to the partition. not available.

Problem determination: Check the device description entry, then try the operation again. If this error persists, contact your service representative.

HSCLA9A4 HSCLA9A4

Explanation: Details of the device containing the partition data is not valid in the management console save area. not available. Either the system or partition is not remote restart capable or there may not be a device associated with the remote restart capable partition.

Problem determination: Check the configuration and try the operation again. If the error persists, contact your service representative.

HSCLA9A5 HSCLA9A5

Explanation: The managed system object manager could not be found.

Problem determination: Run the rebuild managed system operation, and try again.

HSCLA9A6 HSCLA9A6

Explanation: The current suspend state of the partition does not support the suspend or resume operation requested. A suspend or resume operation can be started only on a partition that is not suspended or resuming, and it can be stopped only if it is not too late in the suspend or resume process to safely stop.

Problem determination: Please try a recover operation if a previous suspend or resume operation has failed, then try the suspend or resume operation again.

HSCLA9A7 HSCLA9A7

Explanation: The managed system does not support partition remote restart operations.

HSCLA9A8 HSCLA9A8

Explanation: The remote restart operation cannot be performed because the reserved storage device assigned to the partition is not in the reserved storage device pool.

Problem determination: Add the device to the reserved storage device pool and try the operation again. The reserved storage device can be accessed from the following VIOS partitions.

HSCLA9A9 HSCLA9A9

Explanation: A partition with name already exists on the managed system.

Problem determination: Provide another name for this partition.

HSCLA9AA HSCLA9AA

Explanation: The remote restart operation cannot be performed because the reserved storage device containing the partition data does not have a selection type of manual.

Problem determination: Remove the device from the reserved storage device pool and add it back to the pool with a selection type of manual, then try the operation again.

HSCLA9AB HSCLA9AB

Explanation: The remote restart operation cannot be performed because the reserved storage device containing the partition data has been assigned to another partition with ID. The data might be corrupted.

Problem determination: Remove the device from the partition with ID, then try the operation again. If the failure persists, contact your hardware service representative.

HSCLA9AC HSCLA9AC

Explanation: The partition was not found.

HSCLA9AD HSCLA9AD

Explanation: Retrieval of the partition data from the management console save area has failed.

Problem determination: Try the operation again. If the failure persists, contact your hardware service representative.

HSCLA9AE HSCLA9AE

Explanation: An error occurred while writing the partition data to the management console save area.

Problem determination: Try the operation again. If the

failure persists, contact your hardware service representative.

HSCLA9AF HSCLA9AF

Explanation: A reserved storage device can be assigned to the partition only when the partition is in the Not Activated state.

HSCLA9B0 HSCLA9B0

Explanation: The partition is not in a valid remote restart state to perform the cleanup operation. A cleanup operation can be performed for a remote restarted partition only.

HSCLA9B1 HSCLA9B1

Explanation: The operation to lock the source adapter on Virtual I/O Server partition has failed.

HSCLA9B2 HSCLA9B2

Explanation: The operation to unlock the Virtual adapters on Virtual I/O Server partition has failed.

HSCLA9B3 HSCLA9B3

Explanation: The operation to finish the remote operations on Virtual I/O Server partition has failed.

HSCLA9B4 HSCLA9B4

Explanation: The operation to lock the source adapter has failed.

HSCLA9B5 HSCLA9B5

Explanation: The operation to unlock the virtual adapters has failed.

HSCLA9B6 HSCLA9B6

Explanation: The operation to finish the remote restart operation has failed.

HSCLA9B7 HSCLA9B7

Explanation: The operation is only allowed when the partition is in the Not Activated state.

HSCLA9B8 HSCLA9B8

Explanation: The specified partition name does not match the partition name in the management console data on the reserved storage device.

Problem determination: Please enter as the partition name and try the command again.

HSCLA9B9 HSCLA9B9

Explanation: Partition is not remote restart capable.

HSCLA9BA HSCLA9BA

Explanation: A suspend capable partition cannot be set as the service partition for the managed system.

HSCLA9BB HSCLA9BB

Explanation: A suspend capable partition cannot have any physical I/O adapters.

HSCLA9BC HSCLA9BC

Explanation: A suspend capable partition cannot use Host Ethernet Adapters.

HSCLA9BD HSCLA9BD

Explanation: A suspend capable partition cannot belong to a workload group.

HSCLA9BE HSCLA9BE

Explanation: A reserved storage device pool cannot be deleted because a shared memory pool is configured.

Problem determination: If you want to delete the reserved storage device pool, you must delete the shared memory pool first.

HSCLA9BF HSCLA9BF

Explanation: The reserved storage device pool cannot be deleted because there are partitions using the reserved storage devices in this pool.

Problem determination: If you want to delete reserved storage device pool, you must resume all of the suspended partitions first.

HSCLA9C0 HSCLA9C0

Explanation: The remote restart of partition is already in progress.

HSCLA9C1 HSCLA9C1

Explanation: The partition suspend or resume operation has stopped unexpectedly.

Problem determination: If necessary, perform a suspend or resume recovery operation for this partition.

HSCLA9C2 HSCLA9C2

Explanation: The partition suspend or resume operation has been stopped because orchestrator detected an error.

HSCLA9C3 HSCLA9C3

Explanation: The partition suspend or resume operation has been stopped because partition firmware detected an error.

HSCLA9C4 HSCLA9C4

Explanation: The partition suspend or resume operation has been stopped because platform firmware detected an error.

HSCLA9C5 HSCLA9C5

Explanation: The partition suspend or resume operation has been stopped because the partition detected an error.

HSCLA9C6 HSCLA9C6

Explanation: The partition suspend or resume operation has been stopped by the user.

HSCLA9C7 HSCLA9C7

Explanation: The remote restart state of the partition is not valid for the recovery operation. The recovery operation can be performed for remote restarting partitions only.

HSCLA9C8 HSCLA9C8

Explanation: The remote restart of the partition was started but did not complete successfully. Recovery procedures were started but did not complete successfully.

HSCLA9C9 HSCLA9C9

Explanation: The recovery operation has failed.

Problem determination: If possible, perform the recovery operation from the management console that was used to perform the remote restart operation. Otherwise, perform the recovery operation again from this management console using the force option.

HSCLA9CA HSCLA9CA

Explanation: The remote restart capable partition cannot be set as the service partition for the managed system.

HSCLA9CB HSCLA9CB

Explanation: The remote restart capable partition cannot have physical I/O adapters.

HSCLA9CC HSCLA9CC

Explanation: The remote restart capable partition cannot use Host Ethernet Adapters.

HSCLA9CD HSCLA9CD

Explanation: A remote restart can be performed for the partition only if its state is remote restartable.

HSCLA9CE HSCLA9CE

Explanation: The managed system is not in a valid state to support partition remote restart operations.

HSCLA9CF HSCLA9CF

Explanation: Remote restart of partition is not in progress.

HSCLA9D0 HSCLA9D0

Explanation: The remote restart of partition cannot be stopped at this point.

HSCLA9D1 HSCLA9D1

Explanation: An error occurred while removing device from the reserved storage device pool. This device was assigned to partition, for which a remote restart and source side cleanup have been performed.

Problem determination: Please try to manually remove the device from the reserved storage device pool.

HSCLA9D2 HSCLA9D2

Explanation: A request to stop the remote restart of partition is already in progress.

HSCLA9D3 HSCLA9D3

Explanation: The remote restart of partition did not complete. A user may have stopped the operation from another interface.

HSCLA9D4 HSCLA9D4

Explanation: A remote restart capable partition cannot be enabled for redundant error path reporting.

HSCLA9D5 HSCLA9D5

Explanation: A remote restart capable partition cannot belong to a workload group.

HSCLA9D6 HSCLA9D6

Explanation: The configuraiton change was successful, however the configuraiton data on the reserved storage device, which is used during remote restart of the partition, could not be updated.

Problem determination: Please run the refdev command to update the reserved storage device for the partition after you correct the errors.

HSCLA9D7 HSCLA9D7

Explanation: The data on the reserved storage device, which is used during remote restart of the partition, could not be updated.

Problem determination: Please run the refdev command to update the reserved storage device for the partition after you correct the errors.

HSCLA9D8 HSCLA9D8

Explanation: The operation to take ownership of the reserved storage device assigned to the partition has failed.

Problem determination: Check the device and ensure that it is not in use, then try the operation again.

HSCLA9D9 HSCLA9D9

Explanation: There is no reserved storage device information in the management console save area for ths partition.

Problem determination: Ensure that a reserved storage device is assigned to the partition.

HSCLA9DA HSCLA9DA

Explanation: The recovery operation has failed.

Problem determination: If possible, perform the recovery operation from the management console that was used to perform the remote restart operation. Otherwise, perform the recovery operation again from this management console using the force option.

HSCLA9DB HSCLA9DB

Explanation: The manual resync operation failed, because the partition is not in a valid remote restart state.

HSCLA9DC HSCLA9DC

Explanation: The manual resync operation failed because the partition is missing its active profile. Either the active profile has been removed or the partition has never been activated.

Problem determination: Activate the partition to establish an active profile.

HSCLA9E0 HSCLA9E0

Explanation: The partition cannot be migrated at this time because the partition is not the remote restart state.

HSCLA9E1 HSCLA9E1

Explanation: The operation to update the partition data on the reserved storage device assigned to the partition has failed. The migrated partition may not be able to be remote restarted.

HSCLA9E2 HSCLA9E2

Explanation: The remote restart capable partition cannot use shared memory.

HSCLA9E3 HSCLA9E3

Explanation: The partition cannot be migrated because it is a remote restart capable partition that is using shared memory.

HSCLA9E4 HSCLA9E4

Explanation: The recovery operation has failed.

HSCLA9E5 HSCLA9E5

Explanation: Perform the operation again using the force option.

HSCLA9E6 HSCLA9E6

Explanation: The destination managed system does not support virtual Trusted Platform Modules.

HSCLA9E7 HSCLA9E7

Explanation: The partition cannot be migrated because all of the virtual Trusted Platform Modules on the destination managed system are already in use.

HSCLA9E8 HSCLA9E8

Explanation: The partition cannot be set to be suspend capable because it has physical I/O Currently assigned to it.

HSCLA9E9 HSCLA9E9

Explanation: The operation on the remote restart capable partition failed.

Problem determination: Assign a reserved storage device to the partition, then try the operation again.

HSCLA9EA HSCLA9EA

Explanation: The destination managed system does not support partition placement configuration. The partition placement setting of partition will be lost after migration.

HSCLA9EB HSCLA9EB

Explanation: The virtual SCSI client adapter in slot on partition is not valid since its server adapter is not on a Virtual I/O Server (VIOS) partition. A virtual SCSI client adapter on a suspend capable partition must use a server adapter on a VIOS partition.

HSCLA9EC HSCLA9EC

Explanation: Virtual I/O Server partition has reached its maximum concurrent partition migrations limit.

HSCLA9ED HSCLA9ED

Explanation: The remote restart state of the partition can be set to Remote Restarted only when its current remote restart state is Source Remote Restarting or Forced Source Side Restart.

HSCLA9F0 HSCLA9F0

Explanation: The partition cannot be resumed because the processing resources it requires exceed the available processing resources in the managed system's shared processor pool.

Problem determination: If possible, free processing resources from that shared processor pool, and try the operation again.

HSCLA9F1 HSCLA9F1

Explanation: The recover request cannot be accepted because the last operation does not match the specified type of state change operation.

HSCLA9F2 HSCLA9F2

Explanation: The cleanup operation has failed.

Problem determination: Perform the operation again using the force option.

HSCLA9F3 HSCLA9F3

Explanation: Cleanup of the remote restarted partition cannot be performed on the source managed system since the reserved storage device assigned to the partition is still owned by the source managed system.

HSCLAA00 HSCLAA00

Explanation: The dump file cannot be removed.

HSCLAA01 HSCLAA01

Explanation: The dump file was not found.

HSCLAA05 HSCLAA05

Explanation: The partition cannot be migrated because a partition hosting one of its virtual SCSI adapters is not a Virtual I/O Server partition.

HSCLAA06 HSCLAA06

Explanation: The partition cannot be migrated because it has a virtual SCSI server adapter that is hosting virtual SCSI client adapters.

Problem determination: Check the device and ensure that it is not in use, then try the operation again.

HSCLAA07 HSCLAA07

Explanation: The partition cannot be migrated because the destination managed system does not support IBM i partition mobility.

HSCLAA08 HSCLAA08

Explanation: IBM i partition has returned error code to the management console's request to perform a check for migration readiness. The partition is not ready to be migrated at this time.

Problem determination: Try the operation again later.

HSCLAA09 HSCLAA09

Explanation: The operation is not allowed because the managed system does not support IBM i partition mobility.

HSCLAA10 HSCLAA10

Explanation: The managed system does not support virtual Trusted Platform Modules.

HSCLAA11 HSCLAA11

Explanation: The attributes can only be specified for an AIX, Linux, or Virtual I/O Server partition.

HSCLAA12 HSCLAA12

Explanation: All virtual Trusted Platform Modules are in use by other partitions.

HSCLAA13 HSCLAA13

Explanation: The trusted system key length is wrong or the key is badly formatted.

HSCLAA14 HSCLAA14

Explanation: The trusted system key is wrong.

HSCLAA16 HSCLAA16

Explanation: An internal error occurred.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLAA17 HSCLAA17

Explanation: A partition must be in the Not Activated state to perform the restore trusted system key operation.

HSCLAA18 HSCLAA18

Explanation: The virtual Trusted Platform Module adapter for the partition is in virtual slot.

Problem determination: Check the device and ensure that it is not in use, then try the operation again.

HSCLAA19 HSCLAA19

Explanation: There is no virtual slot available for the virtual Trusted Platform Module adapter.

HSCLAA1A HSCLAA1A

Explanation: The trusted system key cannot be changed at this time because the last key change has not completed.

HSCLAA1B HSCLAA1B

Explanation: Virtual Trusted Platform Module can be used with POWER7, or later, processor compatibility modes only.

HSCLAA1C HSCLAA1C

Explanation: An internal error occurred.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLAA20 HSCLAA20

Explanation: The OS level of the partition does not support partition mobility.

(HSCLBxxx) Reference codes

HSCLB000 HSCLB000

Explanation: Please specify the SRIOV Ethernet virtual adapter slot ID that you want to remove.

HSCLB001 HSCLB001

Explanation: The operation to remove SRIOV Ethernet virtual adapter(s) on partition failed or partially failed.

HSCLB003 HSCLB003

Explanation: The SRIOV Ethernet virtual adapter(s) to be removed on virtual slot of partition are not assigned to the partition.

HSCLB004 HSCLB004

Explanation: The operation to add SRIOV Ethernet virtual adapter on slot failed because the management console cannot retrieve the SRIOV Ethernet virtual adapter information after assigning a SRIOV Ethernet logical port to the partition.

HSCLB010 HSCLB010

Explanation: This operation is only allowed when the service processor is in the Standby, EOCT, or Running state.

HSCLB011 HSCLB011

Explanation: The boot string can be specified for P71H systems only.

HSCLB012 HSCLB012

Explanation: This operation is not supported for the managed system.

HSCLB013 HSCLB013

Explanation: The specified octant configuration is not valid.

HSCLB020 HSCLB020

Explanation: The RMC connection between the management console and partition has been interrupted. This could be because the partition is no longer in the Running state, or the partition is hung.

Problem determination: Check the state of the partition.

HSCLB021 HSCLB021

Explanation: The request issued to partition has failed.

Problem determination: Try the operation again. If this error persists, contact your service representative.

HSCLB022 HSCLB022

Explanation: The mapping of virtual fibre channel client adapter to virtual fibre channel server adapter on Virtual I/O Server partition is not valid.

Problem determination: Map the client and server adapters, then try the operation again.

HSCLB023 HSCLB023

Explanation: Virtual fibre channel server adapter for the virtual fibre channel client adapter was not found on Virtual I/O Server partition.

Problem determination: Create and map the server adapter, then try the operation again.

HSCLB024 HSCLB024

Explanation: This operation is not supported Virtual I/O Server partition.

HSCLB025 HSCLB025

Explanation: The specified partition or partition profile does not have any virtual fibre channel client adapters.

HSCLB026 HSCLB026

Explanation: This operation is not supported on Virtual I/O Server partitions.

HSCLB060 HSCLB060

Explanation: The operation is not allowed at this time because there are one of more management consoles connected to the managed system that do not support the function you are trying to use.

Problem determination: Disconnect management consoles and try the operation again.

HSCLB061 HSCLB061

Explanation: Performing the operation will cause the managed system to become incompatible with management consoles that do not support this operation.

HSCLB062 HSCLB062

Explanation: The incompatibility warning value is not valid for the function.

HSCLB063 HSCLB063

Explanation: The function name is not valid.

HSCLB070 HSCLB070

Explanation: The reserved storage device assigned to a remote restart capable partition must be a physical volume.

HSCLB071 HSCLB071

Explanation: The destination managed system does not support Virtual Ethernet Port Aggregator (VEPA) configuration.

HSCLB072 HSCLB072

Explanation: The switch mode for virtual switch cannot be maintained on the destination managed system.

HSCLB073 HSCLB073

Explanation: The destination managed system does not support Virtual Station Interface (VSI) configuration.

HSCLB074 HSCLB074

Explanation: The maximum number of allowed Virtual Station Interface (VSI) profiles is already reached on the destination managed system.

HSCLB075 HSCLB075

Explanation: The partition cannot be suspended because it is using Virtual Ethernet Port Aggregator (VEPA) or Virtual Station Interface (VSI) profiles configuration.

HSCLB076 HSCLB076

Explanation: The partition cannot be remote restarted because it is using Virtual Ethernet Port Aggregator (VEPA) or Virtual Station Interface (VSI) profiles configuration.

HSCLB080 HSCLB080

Explanation: An error occurred while collecting partition configuration data.

HSCLB090 HSCLB090

Explanation: The managed system does not have the capability to get the processor VPD information.

HSCLB100 HSCLB100

Explanation: There is an insufficient amount of mirrored memory available on the managed system to perform this operation. An additional MB of mirrored memory is needed.

Problem determination: If you want to perform this operation, you must free mirrored memory by performing a mirrored memory defragmentation operation or by removing memory from partitions.

HSCLB101 HSCLB101

Explanation: There is an insufficient amount of memory available on the managed system to perform this operation. An additional MB of memory is needed.

Problem determination: If you want to perform this operation, you must free memory by removing memory from partitions.

(HSCP) Reference codes

HSCP0001 HSCP0001

Explanation: The Backup Critical Data request completed successfully.

HSCP0002 HSCP0002

Explanation: Ensure the media is inserted correctly into the drive and try the operation again.

Problem determination: Verify that the media is inserted correctly in the drive and try the operation again.

HSCP0003 HSCP0003

Explanation: The Backup Critical Data request failed.

Problem determination: An internal management console error occurred. Contact your next level of support or your service provider.

HSCP0004 HSCP0004

Explanation: The media is write protected. Remove write protection and try the operation again.

Problem determination: Remove write protection and try the operation again.

HSCP0005 HSCP0005

Explanation: The Backup Critical Data request is in progress. Please wait.

HSCP0010 HSCP0010

Explanation: The Format Removable Media request completed successfully.

HSCP0011 HSCP0011

Explanation: Ensure the media is inserted correctly into the drive and try the operation again.

HSCP0012 HSCP0012

Explanation: The media is write protected. Remove the write protection and try the operation again.

HSCP0013 HSCP0013

Explanation: An unknown error occurred. Replace the media and try the operation again.

HSCP0014 HSCP0014

Explanation: The Format Removable Media request failed.

HSCP0015 HSCP0015

Explanation: Please wait while the media is being formatted.

HSCP0020 HSCP0020

Explanation: The Save Upgrade Data request completed successfully.

HSCP0021 HSCP0021

Explanation: The Save Upgrade Data request failed.

HSCP0022 HSCP0022

Explanation: The Save Upgrade Data request failed. Ensure the removable media is inserted correctly into the drive.

HSCP0023 HSCP0023

Explanation: The media is write protected. Remove the write protection and try the operation again.

HSCP0024 HSCP0024

Explanation: An error occurred while copying the upgrade data. Ensure the removable media is inserted correctly into the drive and retry the operation.

HSCP0025 HSCP0025

Explanation: An error occurred while saving the upgrade data. Try the operation again. If the problem continues, contact your service representative.

HSCP0026 HSCP0026

Explanation: An error occurred while trying to mount the media. Ensure the removable media is inserted correctly and try the operation again.

HSCP0027 HSCP0027

Explanation: An error occurred while trying to unmount the media. Ensure the media is not being shared.

HSCP0028 HSCP0028

Explanation: An non-recoverable error occurred. Refer

HSCP0029 • HSCP0046

to the management console console log for detailed information.

Problem determination: Refer to the management console console log for more information. If the problem persists, contact your next level of support or your service provider.

HSCP0029 HSCP0029

Explanation: An error occurred while instantiating the save upgrade data target class.

HSCP0030 HSCP0030

Explanation: An error occurred creating the file that processes the save upgrade data on the next reboot. Try the operation again.

Problem determination: Rebuild the managed system. If the problem persists, contact your next level of support or your service provider.

HSCP0031 HSCP0031

Explanation: Generating archives of subsystem files. Please wait.

HSCP0036 HSCP0036

Explanation: Authentication of the corrective service package failed. Try the operation again.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCP0037 HSCP0037

Explanation: The corrective service file was successfully applied. Select the checkbox below to install the next corrective service package.

HSCP0038 HSCP0038

Explanation: The corrective service file was NOT successfully applied due to missing pre-requisites.

HSCP0039 HSCP0039

Explanation: The corrective service file was successfully applied. The changes will take effect when another console session is started, by logout and login again, or after rebooting the management console.

HSCP0040 HSCP0040

Explanation: The corrective service file was successfully downloaded to this system console. Press OK to continue and install this update.

HSCP0041 HSCP0041

Explanation: The corrective service file was successfully applied. Wait until all tasks complete and reboot the management console for the changes to take place.

HSCP0042 HSCP0042

Explanation: An unrecoverable error occurred during the corrective service file download. Try the operation again. If the problem continues, contact your service representative.

Problem determination: Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCP0043 HSCP0043

Explanation: An unrecoverable error occurred during the corrective service installation. Try the operation again. If the problem continues, contact your service representative.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCP0044 HSCP0044

Explanation: The removable media cannot be mounted. Ensure the media is inserted correctly into the drive and try the operation again.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. If the error persists, contact your next level of support or your service provider.

HSCP0045 HSCP0045

Explanation: The corrective service data is corrupt. Ensure the media is inserted correctly into the drive and try the operation again.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. If the error persists, contact your next level of support or your service provider.

HSCP0046 HSCP0046

Explanation: An error occurred while attempting to remotely connect to the server. Try the operation again. If the problem continues, contact your service representative.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCP0047 HSCP0047

Explanation: An unspecified error occurred while downloading the corrective service file. Try the operation again. If the problem continues, contact your service representative.

Problem determination: Try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCP0048 HSCP0048

Explanation: An unknown error occurred. Try the operation again. If the problem continues, contact your service representative.

Problem determination: Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCP0049 HSCP0049

Explanation: The Install Corrective Service request is in progress. Please wait.

HSCP0050 HSCP0050

Explanation: The download file is corrupt. Try the operation again.

HSCP0051 HSCP0051

Explanation: The corrective service file download was unsuccessful.

Problem determination: Refer to the text on the error message window.

HSCP0052 HSCP0052

Explanation: Successfully downloaded file. Installing, please wait.

HSCP0053 HSCP0053

Explanation: Corrective service installation was successful.

HSCP0054 HSCP0054

Explanation: Corrective service installation has failed.

Problem determination: Refer to the text on the error message window.

HSCP0055 HSCP0055

Explanation: View the console log for details.

HSCP0056 HSCP0056

Explanation: Halting service installation.

HSCP0057 HSCP0057

Explanation: Corrective service file download in progress...

HSCP0058 HSCP0058

Explanation: The corrective service file downloaded successfully, continuing...

HSCP0059 HSCP0059

Explanation: The filesystem is full.

Problem determination: Cleanup filesystem to free up some space. Try the task again. If the problem persists, contact your next level of support or your service provider.

HSCP0060 HSCP0060

Explanation: The Customize Date/Time request completed successfully. Please reboot the management console.

Problem determination: Shut down and restart the management console.

HSCP0061 HSCP0061

Explanation: The Customize Date/Time request failed.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. If the problem persists, contact your next level of support or your service provider.

HSCP0070 HSCP0070

Explanation: Enter an integer value between 1 and 99.

HSCP0071 HSCP0071

Explanation: You cannot schedule an event in the past. Set the date and time to schedule the event in the future.

Problem determination: Select a date and time that is after the present time.

HSCP0080 HSCP0080

Explanation: There are no system events.

HSCP0081 HSCP0081

Explanation: Unable to display the log data.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. If the problem persists, contact your next level of support or your service provider.

HSCP0082 HSCP0082

Explanation: Unable to retrieve log data.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. If the problem persists, contact your next level of support or your service provider.

HSCP0083 HSCP0083

Explanation: An error occurred while processing the exit request.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. If the problem persists, contact your next level of support or your service provider.

HSCP0090 HSCP0090

Explanation: Cannot check both the 'Export default gateway' and 'Silent' options for 'routed'.

Problem determination: Select either Export default gateway or Silent for the Routed option.

HSCP0091 HSCP0091

Explanation: Your updates have been saved to the system configuration files. You may need to reboot for all Network Settings changes to take affect.

Problem determination: Restart the management console.

HSCP0092 HSCP0092

Explanation: Unable to save your Network Settings updates to the system configuration files.

Problem determination: Try the operation again. Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0093 HSCP0093

Explanation: Ethernet driver cannot be set.

Problem determination: Select a valid speed for the adapter. Select Auto-negotiate speed. Shut down and restart the management console.

HSCP0100 HSCP0100

Explanation: No managed systems were detected that are attached to this system console.

Problem determination: If you have a managed system attached, shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCP0101 HSCP0101

Explanation: No logical partitions have been defined for this managed system.

Problem determination: Check to ensure that Service Focal Point is communicating correctly with the managed system. Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0102 HSCP0102

Explanation: A blank or incorrect entry was entered in the partition password field.

Problem determination: Re-enter a valid password in the entry field and try the operation again.

HSCP0103 HSCP0103

Explanation: A blank or incorrect entry was entered in the listening port field.

Problem determination: Re-enter a valid listening port and try the operation again.

HSCP0104 HSCP0104

Explanation: A blank or incorrect entry was entered in the IP address field.

Problem determination: Re-enter the IP address and try the operation again.

HSCP0110 HSCP0110

Explanation: The Inventory Scout Services command completed successfully.

HSCP0111 HSCP0111

Explanation: The Inventory Scout Services command request failed.

Problem determination: Try the operation again. Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0112 HSCP0112

Explanation: The removable media cannot be mounted. Ensure the media is inserted correctly into the drive and try the operation again.

Problem determination: Insert a correctly formatted diskette into the drive. Try using an alternate diskette. If the error persists, contact your next level of support or your service provider.

HSCP0113 HSCP0113

Explanation: The media is write protected. Remove the write protection and try the operation again.

Problem determination: Remove write protection on the media and retry the operation.

HSCP0114 HSCP0114

Explanation: The Inventory Scout request failed. Ensure the removable media is inserted correctly into the drive.

Problem determination: Insert the correctly formatted diskette into the drive. Try using an alternate diskette. If the error persists, contact your next level of support or your service provider.

HSCP0115 HSCP0115

Explanation: An error occurred while copying the Inventory Scout data. Verify that a blank formatted diskette is inserted correctly in the drive and retry the operation.

Problem determination: Ensure that there is enough space on the media. Try using an alternate diskette and retry the operation. If the error persists, contact your next level of support or your service provider.

HSCP0116 HSCP0116

Explanation: An error occurred while compressing the Inventory Scout data. Try the operation again.

HSCP0117 HSCP0117

Explanation: An error occurred while trying to unmount the media.

HSCP0118 HSCP0118

Explanation: The Inventory Scout daemon was restarted successfully.

HSCP0119 HSCP0119

Explanation: The Inventory Scout daemon cannot be restarted. Reboot the management console and try the operation again.

Problem determination: Try the operation again. Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0120 HSCP0120

Explanation: The managed system name is malformed.

Problem determination: Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0121 HSCP0121

Explanation: The Inventory Scout request failed. An error occurred while copying data to removable media.

Problem determination: Retry the operation. Restart the invscout daemon. If the error persists, contact your next level of support or your service provider.

HSCP0122 HSCP0122

Explanation: The system partition(s) did not respond to query attempts.

Problem determination: Check to ensure that Service Focal Point is communicating correctly with the managed system. Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0123 HSCP0123

Explanation: Unable to start the terminal session using available error data. Return to Service Management interface and attempt to start the TTY session from there.

Problem determination: Return to the Service Management interface and attempt to start the virtual terminal session. If the problem persists, contact your next level of support or your service provider.

HSCP0124 HSCP0124

Explanation: Unrecoverable error attempting to start a TTY session. Return to Service Management interface and attempt to start the TTY session from there.

HSCP0125 • HSCP0138

Problem determination: Return to the Service Management interface and attempt to start the virtual terminal session. If the problem persists, contact your next level of support or your service provider.

HSCP0125 HSCP0125

Explanation: An incorrect user ID and password combination was entered. Specify a valid user ID and password and try the operation again.

Problem determination: Specify a valid user ID and password and retry the operation. Ensure that the remote service (FTP) site is operational. If the problem persists, contact your next level of support or your service provider.

HSCP0126 HSCP0126

Explanation: The corrective service file was not found on the server. Ensure the correct fully qualified path and filename has been specified for the 'Patch file' field and retry the operation.

Problem determination: Specify a valid user ID and password and retry the operation. Ensure that the remote service (FTP) site is operational. If the problem persists, contact your next level of support or your service provider.

HSCP0127 HSCP0127

Explanation: An error occurred while unpacking the corrective service file. The file may be corrupt, or the management console may have run out of disk space. Try the operation again. If the problem continues, contact your service representative.

Problem determination: Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0128 HSCP0128

Explanation: A required file is missing from the service package. Contact your service representative.

Problem determination: Contact your next level of support or your service provider.

HSCP0129 HSCP0129

Explanation: An attempt was made to apply incorrect service to this version of management console software. Ensure the correct service filename has been specified and retry the operation.

Problem determination: Ensure that the correct service file name has been entered and try the operation again. If the problem persists, contact your next level of support or your service provider.

HSCP0130 HSCP0130

Explanation: The target directory for service file extraction does not exist. Contact your service representative.

Problem determination: Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0131 HSCP0131

Explanation: A fatal error occurred during service file installation. The system may be unstable. Contact your service representative.

Problem determination: Shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCP0135 HSCP0135

Explanation: Error processing data on removable media.

Problem determination: Attempt to download and apply the service file again. Save management console upgrade data to preserve configuration data. Reinstall the management console from the recovery CD as if doing an upgrade. If the problem persists, contact your next level of support or your service provider.

HSCP0136 HSCP0136

Explanation: The corrective service file was successfully copied to the management console. Select the Frame 'Install Corrective Service' task to apply this update.

Problem determination: Select the frame Install Corrective Service task to apply this update.

HSCP0137 HSCP0137

Explanation: The corrective service file was successfully downloaded to the management console. Select the Frame 'Install Corrective Service' task to apply this update.

Problem determination: Select the frame Install Corrective Service task to apply this update.

HSCP0138 HSCP0138

Explanation: An internal error occurred during Save Upgrade Data processing. Refer to the management console console log for detailed information and recovery actions.

Problem determination: Refer to the management console console log for detailed information and recovery actions.

HSCP0139 HSCP0139

Explanation: The DVD device is currently in use. Wait until all current DVD operations have been completed and try the operation again.

HSCP0140 HSCP0140

Explanation: The DVD media is write protected. Remove the write protection and try the operation again.

HSCP0141 HSCP0141

Explanation: Ensure the DVD media is inserted correctly into the drive and try the operation again.

HSCP0142 HSCP0142

Explanation: An invalid or missing file system exists on the DVD media. Reformat the DVD and try the operation again.

HSCP0143 HSCP0143

Explanation: The DVD device is not functioning correctly. Contact your service representative.

HSCP0144 HSCP0144

Explanation: An error was detected while mounting the remote server. Verify that the parameters have been entered correctly and try the operation again.

HSCP0145 HSCP0145

Explanation: The userId and password combination to log in to the remote server is incorrect. Ensure the combination is valid and try the operation again.

HSCP0146 HSCP0146

Explanation: The temporary space used to create the backup archive has been exhausted. You can attempt to free disk space by deleting any pending dump files, or contact your service representative.

HSCP0147 HSCP0147

Explanation: An error occurred while writing the informative description for this dump file. The backup task will now continue without this information.

HSCP0148 HSCP0148

Explanation: No dump files exist on the remote server.

HSCP0149 HSCP0149

Explanation: No detailed dump information exists for this archive.

HSCP0150 HSCP0150

Explanation: An error occurred while reading the backup archive detailed information. The remote server may be busy. Try the operation again.

HSCP0151 HSCP0151

Explanation: An error occurred while downloading the archive to this management console. View the console log to see the detailed error information. Try the operation again.

HSCP0152 HSCP0152

Explanation: An error occurred while copying the archive to this management console. View the console log to see the detailed error information. Try the operation again.

HSCP0153 HSCP0153

Explanation: The Backup Critical Console Data task was completed successfully.

HSCP0154 HSCP0154

Explanation: The critical console data archive file was successfully offloaded to this management console. Reboot the management console and this data will be restored.

HSCP0155 HSCP0155

Explanation: The task is unavailable. Please try again later.

HSCP0156 HSCP0156

Explanation: An error occurred attempting to contact the remote system. Ensure a valid hostname or IP address has been entered and try the operation again.

HSCP0157 HSCP0157

Explanation: An unrecoverable error occurred while transferring the file to the remote server. Verify that the target environment on the remote server can accommodate the request and try the operation again. If the failure persists, initiate the 'View Problem Logs' task from the Service Utilities menu for detailed error information. This will require 'hscp' authority.

HSCP0158 HSCP0158

Explanation: VPD collection was not successful. Verify all partition profiles associated with the managed system are active and accessible. Error details:

HSCP0159 HSCP0159

Explanation: VPD collection from the managed system was successful.

HSCP0160 HSCP0160

Explanation: VPD collection has failed. Verify all partition profiles associated with the managed system are active and accessible. Try the operation again. Error details:

HSCP0161 HSCP0161

Explanation: A Back up Critical Console Data task is currently in progress. When this task completes, try the operation again.

HSCP0162 HSCP0162

Explanation: An error occurred trying to obtain a lock for this task. Try the operation again.

Problem determination: If the failure persists, initiate the View management console Logs task for detailed error information. hmcpe authority will be required.

HSCP0163 HSCP0163

Explanation: An error occurred trying to free a prior lock set for this task. Try the operation again.

Problem determination: If the failure persists, initiate the View management console Logs task for detailed error information. hmcpe authority will be required.

HSCP0164 HSCP0164

Explanation: An unrecoverable error occurred trying to communicate with the remote server. Try the operation again.

Problem determination: If the failure persists, initiate the View management console Logs task for detailed error information. hmcpe authority will be required.

HSCP0165 HSCP0165

Explanation: An error occurred while transferring data from the remote server. Verify the target environment on the remote server can accommodate the request and try the operation again.

Problem determination: If the failure persists, initiate the View management console Logs task for detailed error information. hmcpe authority will be required.

HSCP0166 HSCP0166

Explanation: The directory on the remote server could not be accessed. Verify the location has been entered correctly and try the operation again.

Problem determination: If the failure persists, initiate the View management console Logs task for detailed error information. hmcpe authority will be required.

HSCP0167 HSCP0167

Explanation: The checksum value of the offloaded backup archive file does not match the calculated value. As a result of this, the file integrity is in question. Try the operation again with different media.

Problem determination: If the failure persists, initiate the View management console Logs task for detailed error information. hmcpe authority will be required.

HSCP0168 HSCP0168

Explanation: The VPD collection task completed successfully and the resulting output was successfully copied to the selected media.

HSCP0169 HSCP0169

Explanation: The VPD collection task failed and no data has been copied to the selected media. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0170 HSCP0170

Explanation: The VPD collection task failed due to an internal error. No data has been copied to the selected media. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0171 HSCP0171

Explanation: The VPD collection task failed due to an internal I/O error. No data has been copied to the selected media. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0172 HSCP0172

Explanation: The command to collect VPD information timed out prior to completion. No data has been copied to the selected media. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0173 HSCP0173

Explanation: The command to collect VPD information was only partially successful. Some system partitions may not have responded. All returned output data was successfully offloaded to the selected media.

Problem determination: If the failure persists, contact your next level of support.

HSCP0174 HSCP0174

Explanation: The selected media is unavailable. Replace or re-insert the media and try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0175 HSCP0175

Explanation: The VPD collection command completed successfully, but an unrecoverable error prevented the returned data from being copied to the selected media. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0176 HSCP0176

Explanation: The command to collect VPD information did not fully complete and an unrecoverable error prevented the returned data from being copied to the selected media. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0177 HSCP0177

Explanation: The VPD collection task completed successfully and the resulting output was copied to the selected media. The output was not copied to this user's home directory.

HSCP0178 HSCP0178

Explanation: The command to collect VPD information was only partially successful. Some system partitions may not have responded. All returned output data was successfully offloaded to the selected media. The output was not copied to this user's home directory.

HSCP0179 HSCP0179

Explanation: The VPD collection command succeeded, but there is not enough free space on the selected output media to copy the resulting output. Replace or

free additional space on the media and try the operation again.

HSCP0180 HSCP0180

Explanation: The command to collect VPD information did not fully complete. There is not enough free space on the selected output media to copy the resulting output. Replace or free additional space on the media and try the operation again.

HSCP0181 HSCP0181

Explanation: The VPD collection command succeeded, but the resulting output could not be packaged for copying. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0182 HSCP0182

Explanation: The command to collect VPD information did not fully complete. The resulting output could not be packaged for copying. Try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0183 HSCP0183

Explanation: The VPD data file copied to the selected media does not match the file on the management console. Insert different media and try the operation again.

HSCP0184 HSCP0184

Explanation: An unexpected error occurred attempting to launch the subsequent graphic panel. Exit the current task and try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0185 HSCP0185

Explanation: The signature of the corrective service file did not match the expected value. A file contained within the service bundle may be corrupt. Obtain a new copy of the corrective service package and try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0186 HSCP0186

Explanation: The corrective service package did not properly authenticate. The package may be invalid. Obtain a new copy of the corrective service package and try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0187 HSCP0187

Explanation: An internal problem was encountered while installing the management console corrective service package. View the management console log file to determine the cause and try the operation again.

Problem determination: If the failure persists, contact your next level of support.

HSCP0188 HSCP0188

Explanation: The checksum value of the offloaded upgrade archive file does not match the calculated value. As a result of this, the file integrity is in question. Try the operation again with different media.

Problem determination: If the failure persists, contact your next level of support.

HSCP0189 HSCP0189

Explanation: The new server was successfully added to the NTP configuration file. The NTP service has been restarted if it was previously running.

HSCP0190 HSCP0190

Explanation: The specified server could not be added to the NTP configuration file. The details of this failure have been logged.

Problem determination: Contact your next level of support.

HSCP0191 HSCP0191

Explanation: The selected server was successfully removed from the NTP configuration file. The NTP service has been restarted if it was previously running.

HSCP0192 HSCP0192

Explanation: The specified server could not be removed from the NTP configuration file. The details of this failure have been logged.

Problem determination: Contact your next level of support.

HSCP0193 HSCP0193

Explanation: The NTP service has been successfully enabled and started on this management console.

HSCP0194 HSCP0194

Explanation: The NTP service could not be started on this management console. The details of this failure have been logged.

Problem determination: Contact your next level of support.

HSCP0195 HSCP0195

Explanation: The NTP client service was successfully stopped and disabled on this management console.

HSCP0196 HSCP0196

Explanation: The NTP service could not be stopped on this management console. The details of this failure have been logged.

Problem determination: Contact your next level of support.

HSCP0197 HSCP0197

Explanation: The server value entered is already configured for the NTP service. Please specify a different server name or IP address and try the operation again.

HSCP0198 HSCP0198

Explanation: There is not enough free space to copy the backup archive to the destination media. Reformatting the media may correct this condition.

Problem determination: If this condition persists after formatting, consider offloading the archive to a remote server or contact your service provider.

HSCP0199 HSCP0199

Explanation: A required file is missing from the service package.

Problem determination: Retry the operation and if the problem persists, contact your next level of support.

HSCP0200 HSCP0200

Explanation: The requested file action could not be taken possibly due to remote access control restrictions. The target directory either doesn't exist or the file access permissions do not allow the specified action.

Problem determination: Verify the server can accommodate the request with the specified userid and try the operation again.

HSCP0201 HSCP0201

Explanation: No management console corrective service files could be located on the target repository. Select a different location where service files can be located.

Problem determination: Retry the operation and if the problem persists, contact your next level of support.

HSCP0202 HSCP0202

Explanation: No management console corrective service package file was selected. Choose a package file from the table and try the operation again.

HSCP0203 HSCP0203

Explanation: Unable to obtain an I/O lock for the DVD-RAM device. Verify no other task is accessing the drive and try the operation again.

HSCP0204 HSCP0204

Explanation: The corrective service for the management console was successfully applied. Wait until all tasks complete and manually reboot the management console for the changes to take effect.

HSCP0205 HSCP0205

Explanation: The corrective service for the management console was successfully applied. The software installed was one component of a multi-part package. Clicking the 'OK' button will return to the installation task where the next service package can be selected.

HSCP0206 HSCP0206

Explanation: The portmapping service could not be started. This process is required to access the remote server.

Problem determination: Retry the operation and if the problem persists, contact your next level of support.

HSCP0207 HSCP0207

Explanation: An unspecified error occurred while retrieving the corrective service file information from the remote server.

Problem determination: Retry the operation and if the problem persists, contact your next level of support.

HSCP0208 HSCP0208

Explanation: Corrective service file offload from remote server is in progress.

HSCP0209 HSCP0209

Explanation: The corrective service file offload was successful. Continuing with management console service installation.

HSCP0210 HSCP0210

Explanation: The corrective service file offload was unsuccessful.

Problem determination: Retry the operation and if the problem persists, contact your next level of support.

HSCP0211 HSCP0211

Explanation: The server value entered is invalid. Please specify a different server name or IP address and try the operation again.

HSCP0212 HSCP0212

Explanation: The remote filesystem is full.

Problem determination: Free up space on the remote filesystem and try the command again. If the problem persists, contact your next level of support or your service provider.

HSCP0213 HSCP0213

Explanation: Downloading the corrective service files from the server took longer than expected, and the operation has been canceled.

Problem determination: Either try the operation again, or download the corrective service file via another method.

(HSCS) Reference codes

HSCS0001 HSCS0001

Explanation: Unable to obtain Serviceable Events from the Problem Manager.

Problem determination: The management console could not retrieve the Serviceable Events. Wait and try the previous function again. If the error continues, shut down and restart the management console. If error persists, contact your next level of support or your service provider.

HSCS0002 HSCS0002

Explanation: Unable to process request.

Problem determination: The management console could not process your request to make changes to the Serviceable Event. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0003 HSCS0003

Explanation: Unable to update the attribute on the Serviceable Event.

Problem determination: The management console could not process your request to make changes to the Serviceable Event. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0004 HSCS0004

Explanation: At least one Serviceable Event you attempted to act on could not be located. It may have expired from the Problem Manager. Please do a new query to refresh the list of Serviceable Events and try your action again.

Problem determination: The management console could not locate the Serviceable Event you are trying to view or update. It might have expired or otherwise been closed. Exit the Select Serviceable Event dialog and retry.

HSCS0005 HSCS0005

Explanation: Function Failed: Error occurred attempting to display a Serviceable Event panel.

Problem determination: The management console was unable to locate or launch a panel you have requested. This is an internal management console error. Back up critical management console data. If the problem

persists, contact your next level of support or your service provider.

HSCS0006 HSCS0006

Explanation: This Serviceable Event might contain more information than this version of the management console can display. You might want to upgrade your management console to the latest version.

Problem determination: In order to see Serviceable Event data made available in more recent management console versions, upgrade this management console to the most recent version or switch to an management console that has already been upgraded.

HSCS0007 HSCS0007

Explanation: The system you have chosen is not identified as the reporting system in any available serviceable events.

Problem determination: The default selection panel will be displayed so that you may search for other events.

HSCS0008 HSCS0008

Explanation: Function Failed: An error occurred when retrieving machine names.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0020 HSCS0020

Explanation: Function Failed: An error occurred when launching the Service Focal Point Settings panel.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0021 HSCS0021

Explanation: Function Failed: Error occurred getting information to display the Service Focal Point settings.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0022 HSCS0022

Explanation: Function Failed: An error occurred when updating Service Focal Point settings.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0023 HSCS0023

Explanation: Function Failed: Error occurred processing button for the Service Focal Point Settings panel.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0025 HSCS0025

Explanation: Function Failed: Error occurred while processing Double Click for the Service Focal Point Settings panel.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0026 HSCS0026

Explanation: Service Focal Point settings have been saved successfully.

HSCS0047 HSCS0047

Explanation: Function Failed: An error occurred when attempting to Close the Serviceable Event.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0060 HSCS0060

Explanation: Cannot change state from Unknown for machine

Problem determination: The requested machine state is not allowed at this time. Close and then restart the enable and disable menu s for updated machine information.

HSCS0061 HSCS0061

Explanation: Insert scratch diskette.

Problem determination: Insert a scratch diskette and select the appropriate button.

HSCS0062 HSCS0062

Explanation: Insert DVD cartridge and press the appropriate button.

Problem determination: Insert a formatted DVD cartridge and push the appropriate button.

HSCS0064 HSCS0064

Explanation: No extended error data available.

Problem determination: Select a serviceable event that has extended error data associated with it.

HSCS0065 HSCS0065

Explanation: Error writing to floppy diskette.

Problem determination: Ensure there is a diskette in the diskette drive. Try the operation again.

HSCS0066 HSCS0066

Explanation: Error writing to DVD cartridge.

Problem determination: Ensure there is a formatted DVD cartridge in the DVD drive. Try the operation again.

HSCS0067 HSCS0067

Explanation: Error reading extended error data.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0068 HSCS0068

Explanation: Error creating temporary file.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. If the problem persists, contact your next level of support or your service provider.

HSCS0069 HSCS0069

Explanation: Error writing to temporary file.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the

operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. If the problem persists, contact your next level of support or your service provider.

HSCS0070 HSCS0070

Explanation: Error formatting floppy diskette.

Problem determination: Ensure there is a diskette in the diskette drive. Try the operation again.

HSCS0071 HSCS0071

Explanation: Extended error data has been saved successfully.

HSCS0072 HSCS0072

Explanation: The saving of extended error data has been cancelled.

Problem determination: No action is needed. The operation was cancelled as a result of your request.

HSCS0080 HSCS0080

Explanation: Error encountered while getting the partition information.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0081 HSCS0081

Explanation: Error encountered while reading the partition information.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0082 HSCS0082

Explanation: Error encountered while getting the extended error data.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0083 HSCS0083

Explanation: Unexpected error encountered while saving the extended error data.

Problem determination: Verify that the removable media is correctly inserted in the drive and try the operation again. Try the operation with different media. Run PC Doctor to determine if there is a problem with the hardware. If the problem persists, contact your next level of support or your service provider.

HSCS0084 HSCS0084

Explanation: Error encountered while attempting to call home with the extended error information.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0085 HSCS0085

Explanation: Error encountered while attempting to call home with the extended error information.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0086 HSCS0086

Explanation: Request to call home the extended error information has been successfully submitted.

Problem determination: The operation was successful.

HSCS0087 HSCS0087

Explanation: Error encountered while attempting to call home the Serviceable Event.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0088 HSCS0088

Explanation: Error encountered while attempting to call home the Serviceable Event.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0089 HSCS0089

Explanation: Request to call home the Serviceable Event has been successfully submitted.

Problem determination: The operation was successful.

HSCS0090 HSCS0090

Explanation: Unexpected return code encountered while creating a temporary packaging file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0096 HSCS0096

Explanation: No items selected when button was pressed.

Problem determination: Not all functions might be operating. Wait and try the previous function again. If the error continues, shut down and restart the management console. If the error persists, contact your next level of support or your service provider.

HSCS0099 HSCS0099

Explanation: Both connections to the management console must be established for this task to operate properly.

Problem determination: Ensure the connection state of the secondary Service Processor indicates that a valid connection is established.

HSCS0100 HSCS0100

Explanation: Please wait while the extended error data is being saved.

Problem determination: The extended error data is being saved to the appropriate removable media.

HSCS0101 HSCS0101

Explanation: Error writing to DVD cartridge.

Problem determination: Ensure there is a formatted DVD cartridge in the DVD drive. Try the operation again.

HSCS0102 HSCS0102

Explanation: Error unmounting DVD cartridge after writing data successfully.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0103 HSCS0103

Explanation: DVD drive is already mounted.

HSCS0104 HSCS0104

Explanation: The LED request did not complete successfully. Initiate the 'View Problems Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

Problem determination: If you do not have 'hscpe' authority, you will not see the View Problem Logs selection in the Service Utilities menu. Retry the task. Log out and then back in to the management console interface. Shut down and restart the management console. If the problem persists, contact your next level of support or your service provider.

HSCS0105 HSCS0105

Explanation: The LED request completed successfully.

HSCS0107 HSCS0107

Explanation: Error establishing RMC session.

HSCS0108 HSCS0108

Explanation: I/O error while creating a connection monitoring type serviceable event.

HSCS0109 HSCS0109

Explanation: Communications to the SFP component are unavailable.

HSCS0110 HSCS0110

Explanation: Error adding managed object to connection monitoring type serviceable event.

HSCS0111 HSCS0111

Explanation: Error getting managed objects in connection monitoring type serviceable event.

HSCS0112 HSCS0112

Explanation: Error incrementing duplicate count in connection monitoring type serviceable event.

HSCS0113 HSCS0113

Explanation: Error getting connection monitoring type serviceable events.

HSCS0114 HSCS0114

Explanation: Communications to the SFP component are unavailable. This is probably due to authentication problems.

HSCS0115 HSCS0115

Explanation: Communications to the SFP component are unavailable. This is probably due to the RMC daemon on the management console being down.

HSCS0116 HSCS0116

Explanation: Communications to the SFP component are unavailable. However a network path to the partition is available.

HSCS0117 HSCS0117

Explanation: Communications to the SFP component are unavailable. This is probably due to the partition being down.

HSCS0118 HSCS0118

Explanation: Communications to the SFP component are unavailable. This is probably due to no network path being available.

HSCS0119 HSCS0119

Explanation: Communications to the SFP component are unavailable. Check logs for the return code on the call to start an RMC session.

HSCS0120 HSCS0120

Explanation: Communications to the SFP component are unavailable. Check logs for the return code for the session interruption.

HSCS0121 HSCS0121

Explanation: Communications to the SFP component are unavailable due to no network path being available.

HSCS0122 HSCS0122

Explanation: Communication lost with the ctrmc RMC subsystem on the management console.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0125 HSCS0125

Explanation: I/O error while creating a customer upgrade on demand type serviceable event.

HSCS0126 HSCS0126

Explanation: An error occurred while attempting to connect to the management console information manager. The LED command has failed. Initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0127 HSCS0127

Explanation: An unexpected internal error has occurred. The LED command has failed. Initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0128 HSCS0128

Explanation: An error occurred when attempting to query the HMC's hostname. The LED processing cannot continue.

HSCS0129 HSCS0129

Explanation: An internal LED command processing error has occurred. The LED command has failed. Initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0130 HSCS0130

Explanation: The dump requested was successfully initiated. The resulting dump will automatically be offloaded to the management console. The amount of time required for the offload will vary based on the system configuration. To view this dump, refresh the main screen accordingly.

HSCS0131 HSCS0131

Explanation: An error occurred while attempting to connect to the management console information manager. The dump command has failed. Initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0132 HSCS0132

Explanation: An unexpected internal error has occurred. The dump command has failed. Initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. Contact your service representative.

HSCS0133 • HSCS0180

HSCS0133 HSCS0133

Explanation: An error occurred when attempting to query the HMC's hostname. The specified dump task cannot continue.

HSCS0134 HSCS0134

Explanation: An internal dump command processing error has occurred. The dump command has failed. Initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0135 HSCS0135

Explanation: The dump offload request was successful.

HSCS0136 HSCS0136

Explanation: The DVD device could not be locked for writing. Try the operation again.

HSCS0137 HSCS0137

Explanation: The DVD device is write protected. Remove the write protection and try the operation again.

HSCS0138 HSCS0138

Explanation: No DVD media was found. Insert a properly formatted DVD and try the operation again.

HSCS0139 HSCS0139

Explanation: The DVD device returned an error. Try the operation again.

HSCS0140 HSCS0140

Explanation: An unknown error occurred while accessing the DVD device. Try the operation again.

HSCS0141 HSCS0141

Explanation: An error occurred while copying the selected file to the DVD media. Ensure there is available space on the media and try the operation again.

HSCS0142 HSCS0142

Explanation: A file system error has occurred on the DVD media. Try the operation again with a properly formatted DVD.

HSCS0143 HSCS0143

Explanation: The selected file was successfully copied to the DVD media.

HSCS0144 HSCS0144

Explanation: The selected dump file was successfully deleted from the management console.

HSCS0145 HSCS0145

Explanation: An error occurred while removing the dump file from the management console. Refresh the Manage Dumps interface table to ensure the dump file still exists on the management console and try the operation again.

HSCS0146 HSCS0146

Explanation: An unexpected error occurred while removing the dump file from the management console. Initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0149 HSCS0149

Explanation: Error retrieving connection monitoring settings.

HSCS0150 HSCS0150

Explanation: Error applying connection monitoring settings.

HSCS0151 HSCS0151

Explanation: Connection monitoring settings were saved.

HSCS0164 HSCS0164

Explanation: Your request was processed successfully.

HSCS0170 HSCS0170

Explanation: Request to call home has been successfully submitted.

HSCS0171 HSCS0171

Explanation: Error encountered while attempting to call home.

HSCS0180 HSCS0180

Explanation: The ASM menu was launched successfully.

HSCS0181 HSCS0181

Explanation: An error occurred while attempting to launch the ASM menu. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required. Contact your service representative.

HSCS0182 HSCS0182

Explanation: The Lamp Test command was successfully initiated.

HSCS0183 HSCS0183

Explanation: An error occurred while attempting to initiate the LED Lamp Test. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required. Contact your service representative.

HSCS0184 HSCS0184

Explanation: The I/O unit ownership was successfully removed.

HSCS0185 HSCS0185

Explanation: An error occurred while removing the I/O unit ownership. Try the operation again. If the failure persists, initiate the 'View Event Logs ' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0186 HSCS0186

Explanation: An error occurred when attempting to invoke the Repair/Verify subsystem. Contact your service representative.

HSCS0187 HSCS0187

Explanation: An error occurred while retrieving the current list of problems for this system. Try the operation again.

HSCS0200 HSCS0200

Explanation: The MTMS update was successful.

HSCS0201 HSCS0201

Explanation: The following error occurred while editing the MTMS:

HSCS0202 HSCS0202

Explanation: The format of the MTMS is not correct.

HSCS0203 HSCS0203

Explanation: The format of the Config ID is not correct.

HSCS0204 HSCS0204

Explanation: The format of the Config ID is not correct.

HSCS0205 HSCS0205

Explanation: An error occurred while editing the Config ID.

HSCS0206 HSCS0206

Explanation: View the system event log file for detailed error information.

HSCS0207 HSCS0207

Explanation: No changes to the MTMS or the Config ID were made.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0210 HSCS0210

Explanation: The FRU was successfully replaced.

HSCS0211 HSCS0211

Explanation: An error occurred while replacing the FRU. Try the operation again. If the failure persists, initiate the 'View Event Logs ' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0220 HSCS0220

Explanation: The enclosure was successfully replaced.

HSCS0221 HSCS0221

Explanation: An error occurred while replacing the enclosure. Try the operation again. If the failure persists, initiate the 'View Event Logs ' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0222 HSCS0222

Explanation: The LED deactivation command completed successfully.

Problem determination: There still may be open problems within the system and the System Attention LED cannot be manually activated.

HSCS0223 HSCS0223

Explanation: The LED deactivation command completed successfully.

Problem determination: There still may be open problems within the logical partition and the System Attention LED cannot be manually activated.

HSCS0224 HSCS0224

Explanation: An error encountered while attempting to call home the selected dump. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0225 HSCS0225

Explanation: The request to call home the selected dump has been successfully submitted.

HSCS0226 HSCS0226

Explanation: The selected dump file size is too large to be called home. Offload the dump to DVD media and contact your service representative.

HSCS0227 HSCS0227

Explanation: The FRU was successfully removed.

HSCS0228 HSCS0228

Explanation: An error occurred while removing the FRU. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0229 HSCS0229

Explanation: The enclosure was successfully removed.

HSCS0230 HSCS0230

Explanation: An error occurred while removing the enclosure. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0231 HSCS0231

Explanation: An error occurred while attempting to launch the selected task. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. 'hscpe' authority will be required.

HSCS0232 HSCS0232

Explanation: The FRU was successfully added.

HSCS0233 HSCS0233

Explanation: An error occurred while adding the FRU. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0234 HSCS0234

Explanation: The enclosure was successfully added.

HSCS0235 HSCS0235

Explanation: An error occurred while adding the enclosure. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0236 HSCS0236

Explanation: An error occurred while determining the list of enclosures associated with the system. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0237 HSCS0237

Explanation: An error occurred while determining the list of FRUs contained within the selected enclosure. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0238 HSCS0238

Explanation: An error occurred while determining the list of installed components within the system. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0239 HSCS0239

Explanation: An unexpected error was return from the Repair/Verify subsystem. Contact your service representative.

HSCS0240 HSCS0240

Explanation: An error occurred while attempting to launch the eServer Information Center task. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0241 HSCS0241

Explanation: An invalid hostname was detected on the management console. Verify the HMC's network settings and try the operation again.

HSCS0242 HSCS0242

Explanation: An unrecoverable error has occurred. Could not obtain a CIM client instance. Try the operation again. If the failure persists, initiate the 'View Problem Logs' task from the Service Utilities menu for detailed error information.

HSCS0243 HSCS0243

Explanation: An unrecoverable error has occurred. No CIM client instance was returned. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information.

HSCS0244 HSCS0244

Explanation: An unrecoverable error has occurred. The Repair/Verify subsystem could not be invoked.

HSCS0245 HSCS0245

Explanation: An unrecoverable management console internal error has occurred. Try the operation again. If the failure persists, initiate the 'View Event Logs' task from the Service Utilities menu for detailed error information. Contact your service representative.

HSCS0246 HSCS0246

Explanation: A required parameter is missing to access the remote server. Ensure all required fields are filled in and try the operation again.

HSCS0247 HSCS0247

Explanation: The specified dump no longer resides on this management console.

HSCS0248 HSCS0248

Explanation: The user ID and password combination to log in to the remote server is incorrect. Ensure the combination is valid and try the operation again.

HSCS0249 HSCS0249

Explanation: An error occurred attempting to change directories on the remote server. Ensure the directory entry is valid and try the operation again.

HSCS0250 HSCS0250

Explanation: An unrecoverable error occurred while transferring the file to the remote server. Verify the target environment on the remote server can accommodate the request and try the operation again.

HSCS0251 HSCS0251

Explanation: An error occurred attempting to contact the remote system. Ensure a valid hostname or IP address has been entered and try the operation again.

HSCS0252 HSCS0252

Explanation: The selected file was successfully copied to the remote server.

HSCS0253 HSCS0253

Explanation: The managed system is not in the Operating state. Place the system in the correct state and try the operation again.

HSCS0254 HSCS0254

Explanation: This operation is not allowed when the managed system is in the {0} state. After you have established a connection from the management console to the managed system and have entered a valid management console access password, try the operation again.

HSCS0255 HSCS0255

Explanation: This operation is not allowed when a FRU LED within the selected enclosure is active.

HSCS0256 HSCS0256

Explanation: Service Processor failover command executed successfully

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0257 HSCS0257

Explanation: Service Processor failover command failed.

Problem determination: Try the operation again at a later time. If the failure persists, view the management console events log file for detailed error information.

HSCS0258 HSCS0258

Explanation: Unexpected exception occurred while initiating the Service Processor failover.

Problem determination: View the management console events log file for details.

HSCS0259 HSCS0259

Explanation: Service Processor failover was enabled successfully

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0260 HSCS0260

Explanation: Service Processor failover could not be enabled.

Problem determination: Try the operation again at a later time. If the failure persists, view the management console events log file for detailed error information.

HSCS0261 HSCS0261

Explanation: Unexpected exception occurred while enabling or disabling the Service Processor failover.

Problem determination: View the management console events log file for details.

HSCS0262 HSCS0262

Explanation: An error occurred while querying the redundant Service Processor information.

Problem determination: Try the operation again. If the failure persists, initiate the 'View event Logs' task for detailed error information.

HSCS0263 HSCS0263

Explanation: Service Processor failover was disabled successfully

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0264 HSCS0264

Explanation: Service Processor failover could not be disabled.

Problem determination: Try the operation again at a later time. If the failure persists, view the management console events log file for detailed error information.

HSCS0265 HSCS0265

Explanation: The managed system is not in a valid state to perform the operation.

Problem determination: Check the state of the managed system and retry the operation.

HSCS0266 HSCS0266

Explanation: A Serviceable Event has been opened.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0267 HSCS0267

Explanation: The System Processor did not reply to subsequent failover query commands within the allotted time-out.

Problem determination: Check the state of the managed system and retry the operation.

HSCS0268 HSCS0268

Explanation: Administrative Service Processor failover enablement is prohibited while the system is in the process of initiating a dump.

Problem determination: Re-launch this task when the dump has completed if this capability is required.

HSCS0269 HSCS0269

Explanation: No service processors are currently connected.

Problem determination: Verify the state of the managed system and try the operation again.

HSCS0270 HSCS0270

Explanation: No connection between the primary service processor and the management console can be established.

Problem determination: Verify the state of the managed system and the physical network connections. Try the operation again.

HSCS0271 HSCS0271

Explanation: No connection between the secondary service processor and the management console can be established.

Problem determination: Verify the state of the managed system and the physical network connections. Try the operation again.

HSCS0272 HSCS0272

Explanation: The service processors' connection information has not changed after the failover completed.

Problem determination: Contact your next level of support.

HSCS0273 HSCS0273

Explanation: The USB flash memory device could not be locked for writing.

Problem determination: Try the operation again.

HSCS0274 HSCS0274

Explanation: The USB flash memory device is write protected.

Problem determination: Remove the write protection and try the operation again.

HSCS0275 HSCS0275

Explanation: No USB flash memory device was found.

Problem determination: Insert a properly formatted USB flash memory device and try the operation again.

HSCS0276 HSCS0276

Explanation: The USB flash memory device returned an unspecified error.

Problem determination: Re-insert the device and try the operation again.

HSCS0277 HSCS0277

Explanation: An unknown error occurred while accessing the USB flash memory device.

Problem determination: Re-insert the device and try the operation again.

HSCS0278 HSCS0278

Explanation: An error occurred while copying the selected file to the USB flash memory device.

Problem determination: Ensure there is available space on the device and try the operation again.

HSCS0279 HSCS0279

Explanation: A file system error has occurred on the USB flash memory device.

Problem determination: Try the operation again with a different USB flash memory device.

HSCS0280 HSCS0280

Explanation: The file was successfully copied to the USB flash memory device.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0281 HSCS0281

Explanation: The current dump policies cannot be read from the targetted system.

Problem determination: Try the operation again.

HSCS0282 HSCS0282

Explanation: The targetted system's dump policies have successfully been updated.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0283 HSCS0283

Explanation: The dump policies cannot be saved to the targetted system.

Problem determination: Try the operation again.

HSCS0284 HSCS0284

Explanation: The command to query the dump offload progress was successful.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0286 HSCS0286

Explanation: The command to query the dump offload progress failed.

Problem determination: Try the operation again.

HSCS0287 HSCS0287

Explanation: This HMC's IP address could not be determined.

Problem determination: Ensure the system's Network settings have been configured properly and try the operation again.

HSCS0288 HSCS0288

Explanation: There are no primary Service Processor connections detected.

Problem determination: The ASM interface can not be launched from this management console.

HSCS0289 HSCS0289

Explanation: The targetted system's machine type, model, and serial number is invalid.

Problem determination: Correct this VPD information and try the operation again.

HSCS0290 HSCS0290

Explanation: An internal error has occurred determining the associated data from the targetted managed system.

Problem determination: Contact your next level of support.

HSCS0291 HSCS0291

Explanation: No dumps available on this HMC

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0292 HSCS0292

Explanation: A dump is already in progress on the selected service processor.

Problem determination: Wait until the current dump completes before attempting to initiate a new dump.

HSCS0293 HSCS0293

Explanation: The managed system does not support this operation.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0294 HSCS0294

Explanation: The internal information used to submit the selected dump for call home submission is not valid.

Problem determination: This dump file may be corrupt and cannot be automatically called home. Offload the file to media or to a remote server then manually submit the data.

HSCS0295 HSCS0295

Explanation: Service processor failover cannot be performed because the managed system is either restarting or powering off.

Problem determination: Wait until this state completes and try the operation again.

HSCS0296 HSCS0296

Explanation: Service processor failover cannot be performed because the secondary service processor is in a state which does not support failover.

Problem determination: If this condition persists for longer than one hour, contact your hardware service representative.

HSCS0297 HSCS0297

Explanation: Enablement or disablement of FSP failover capability is not allowed when the service processor located in position B has the primary role.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0298 HSCS0298

Explanation: Service processor failover cannot be performed because Licensed Internal Code update is in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0299 HSCS0299

Explanation: Service processor failover cannot be performed because a system dump is in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0300 HSCS0300

Explanation: Service processor failover cannot be performed because service processor failover is already in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0301 HSCS0301

Explanation: Enabling or disabling service processor redundancy is not permitted when the managed system is powered on.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0302 HSCS0302

Explanation: Service processor failover cannot be performed because a concurrent maintenance operation is in progress.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0303 HSCS0303

Explanation: The requested operation cannot be performed because another management or service task is already running.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0304 HSCS0304

Explanation: Service processor failover has been temporarily disabled by the service processor.

Problem determination: The service processor will automatically enable failover again when it is ready.

HSCS0305 HSCS0305

Explanation: The internal communication path between the secondary service processor and the POWER hypervisor cannot be established.

Problem determination: Contact your hardware service representative.

HSCS0306 HSCS0306

Explanation: The dump initiation is disabled due to a policy setting.

Problem determination: Adjust the platform system dump parameters to enable this value.

HSCS0307 HSCS0307

Explanation: The service processor dump initiation is disabled due to a policy setting.

Problem determination: Enable the service processor dump policy setting through the ASM interface.

HSCS0308 HSCS0308

Explanation: A Platform System dump already exists.

Problem determination: You may not initiate another Platform System dump without first extracting and invalidating the existing one. Wait for the existing Platform System dump to automatically extract, then try the operation again.

HSCS0309 HSCS0309

Explanation: An FSP (or Power) dump already exists.

Problem determination: You may not initiate another FSP (or Power) dump without first extracting and invalidating the existing one. Wait for the extract the existing FSP (or Power) dump, then try the operation again.

HSCS0310 HSCS0310

Explanation: Cannot initiate a Platform System dump because the FSP is already collecting a Platform System dump.

Problem determination: Wait until the Platform System dump has been collected, extracted, and invalidated, then try the operation again.

HSCS0320 HSCS0320

Explanation: The command issued to collect the network data did not complete in the expected amount of time.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0321 HSCS0321

Explanation: The task has been launched against a frame which does not support the command to collect the network data.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0322 HSCS0322

Explanation: A communication error has occurred while attempting to collect the network data.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0323 HSCS0323

Explanation: An unexpected return code was returned by the command which collects the network data.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0324 HSCS0324

Explanation: An unexpected error has occurred while trying to connect to the frame.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0325 HSCS0325

Explanation: An exception has occurred while trying to issue the command which collects network data.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0326 HSCS0326

Explanation: An unexpected exception has occurred while trying to issue the command which collects network data.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0327 HSCS0327

Explanation: No service processor node controllers are in the 'Operational' state.

Problem determination: If the problem persists, contact your next level of support or your service provider.

HSCS0328 HSCS0328

Explanation: Primary and secondary service processors are at different code levels.

Problem determination: If this condition persists after performing a code update, contact your hardware service representative.

HSCS0329 HSCS0329

Explanation: The media could not be locked for writing.

Problem determination: Ensure no other task are accessing the device and try the operation again.

HSCS0330 HSCS0330

Explanation: The removable media is write protected.

Problem determination: Remove the write protection and try the operation again.

HSCS0331 HSCS0331

Explanation: No removable media was found.

Problem determination: Insert properly formatted media and try the operation again.

HSCS0332 HSCS0332

Explanation: The removable media device returned an error.

Problem determination: Detailed error information has been logged. Try the operation again.

HSCS0333 HSCS0333

Explanation: A non-recoverable error occurred while accessing the removable media.

Problem determination: Detailed error information has been logged. Re-insert the removable media and try the operation again.

HSCS0334 HSCS0334

Explanation: A non-recoverable internal error occurred while copying the selected file to the removable media.

Problem determination: Re-insert the removable media and try the operation again.

HSCS0335 HSCS0335

Explanation: A file system error has occurred on the removable media.

Problem determination: Try the operation again with properly formatted media.

HSCS0336 HSCS0336

Explanation: No resource selector was specified.

Problem determination: Not specifying a resource selector will produce a large dump that will temporarily block other dumps from being offloaded. Press 'Yes' to return to specify a resource selector given by your service provider. Press 'No' to continue without specifying a resource selector.

HSCS0337 HSCS0337

Explanation: Remove 12X I/O Enclosure guided procedure is supported only for the 9119 machine type.

Problem determination: The instructions for removing enclosures on other managed system types are available from the IBM Hardware Information Center website.

HSCS0338 HSCS0338

Explanation: No Frame Cage slots are available to add an I/O Enclosure, or the maximum number of I/O Enclosures per Frame would be exceeded.

HSCS0340 HSCS0340

Explanation: This operation is not supported by the currently installed firmware level. Please upgrade the firmware.

HSCS0341 HSCS0341

Explanation: This operation will reduce the threshold for fabric errors. This should only be performed by qualified personnel. Are you sure you want to continue?

HSCS0342 HSCS0342

Explanation: Fabric Threshold Mode enabled successfully.

HSCS0343 HSCS0343

Explanation: This level of the management console does not support Power On/Off for the Managed System.

HSCS0344 HSCS0344

Explanation: The dump file name was not given.

HSCS0345 HSCS0345

Explanation: This tasklet must be launched from the Server rather than the Frame for this system type.

HSCS0346 HSCS0346

Explanation: Multiple nodes can not be selected.

HSCS2069 HSCS2069

Explanation: Error writing to temporary file.

Problem determination: If the problem persists, contact your next level of support or your service provider.

Notices

This information was developed for products and services offered in the U.S.A.

The manufacturer may not offer the products, services, or features discussed in this document in other countries. Consult the manufacturer's representative for information on the products and services currently available in your area. Any reference to the manufacturer's product, program, or service is not intended to state or imply that only that product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any intellectual property right of the manufacturer may be used instead. However, it is the user's responsibility to evaluate and verify the operation of any product, program, or service.

The manufacturer may have patents or pending patent applications covering subject matter described in this document. The furnishing of this document does not grant you any license to these patents. You can send license inquiries, in writing, to the manufacturer.

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law: THIS INFORMATION IS PROVIDED "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. The manufacturer may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.

Any references in this information to websites not owned by the manufacturer are provided for convenience only and do not in any manner serve as an endorsement of those websites. The materials at those websites are not part of the materials for this product and use of those websites is at your own risk.

The manufacturer may use or distribute any of the information you supply in any way it believes appropriate without incurring any obligation to you.

Any performance data contained herein was determined in a controlled environment. Therefore, the results obtained in other operating environments may vary significantly. Some measurements may have been made on development-level systems and there is no guarantee that these measurements will be the same on generally available systems. Furthermore, some measurements may have been estimated through extrapolation. Actual results may vary. Users of this document should verify the applicable data for their specific environment.

Information concerning products not produced by this manufacturer was obtained from the suppliers of those products, their published announcements or other publicly available sources. This manufacturer has not tested those products and cannot confirm the accuracy of performance, compatibility or any other claims related to products not produced by this manufacturer. Questions on the capabilities of products not produced by this manufacturer should be addressed to the suppliers of those products.

All statements regarding the manufacturer's future direction or intent are subject to change or withdrawal without notice, and represent goals and objectives only.

The manufacturer's prices shown are the manufacturer's suggested retail prices, are current and are subject to change without notice. Dealer prices may vary.

This information is for planning purposes only. The information herein is subject to change before the products described become available.

This information contains examples of data and reports used in daily business operations. To illustrate them as completely as possible, the examples include the names of individuals, companies, brands, and products. All of these names are fictitious and any similarity to the names and addresses used by an actual business enterprise is entirely coincidental.

If you are viewing this information in softcopy, the photographs and color illustrations may not appear.

The drawings and specifications contained herein shall not be reproduced in whole or in part without the written permission of the manufacturer.

The manufacturer has prepared this information for use with the specific machines indicated. The manufacturer makes no representations that it is suitable for any other purpose.

The manufacturer's computer systems contain mechanisms designed to reduce the possibility of undetected data corruption or loss. This risk, however, cannot be eliminated. Users who experience unplanned outages, system failures, power fluctuations or outages, or component failures must verify the accuracy of operations performed and data saved or transmitted by the system at or near the time of the outage or failure. In addition, users must establish procedures to ensure that there is independent data verification before relying on such data in sensitive or critical operations. Users should periodically check the manufacturer's support websites for updated information and fixes applicable to the system and related software.

Ethernet connection usage restriction

This product is not intended to be connected directly or indirectly by any means whatsoever to interfaces of public telecommunications networks.

Trademarks

IBM, the IBM logo, and ibm.com are trademarks or registered trademarks of International Business Machines Corp., registered in many jurisdictions worldwide. Other product and service names might be trademarks of IBM or other companies. A current list of IBM trademarks is available on the Web at Copyright and trademark information at www.ibm.com/legal/copytrade.shtml.

INFINIBAND, InfiniBand Trade Association, and the INFINIBAND design marks are trademarks and/or service marks of the INFINIBAND Trade Association.

Linux is a registered trademark of Linus Torvalds in the United States, other countries, or both.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Oracle and/or its affiliates.

UNIX is a registered trademark of The Open Group in the United States and other countries.

Other product and service names might be trademarks of IBM or other companies.

Electronic emission notices

When attaching a monitor to the equipment, you must use the designated monitor cable and any interference suppression devices supplied with the monitor.

Class A Notices

The following Class A statements apply to the IBM servers that contain the POWER7[®] processor and its features unless designated as electromagnetic compatibility (EMC) Class B in the feature information.

Federal Communications Commission (FCC) statement

Note: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case the user will be required to correct the interference at his own expense.

Properly shielded and grounded cables and connectors must be used in order to meet FCC emission limits. IBM is not responsible for any radio or television interference caused by using other than recommended cables and connectors or by unauthorized changes or modifications to this equipment. Unauthorized changes or modifications could void the user's authority to operate the equipment.

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Industry Canada Compliance Statement

This Class A digital apparatus complies with Canadian ICES-003.

Avis de conformité à la réglementation d'Industrie Canada

Cet appareil numérique de la classe A est conforme à la norme NMB-003 du Canada.

European Community Compliance Statement

This product is in conformity with the protection requirements of EU Council Directive 2004/108/EC on the approximation of the laws of the Member States relating to electromagnetic compatibility. IBM cannot accept responsibility for any failure to satisfy the protection requirements resulting from a non-recommended modification of the product, including the fitting of non-IBM option cards.

This product has been tested and found to comply with the limits for Class A Information Technology Equipment according to European Standard EN 55022. The limits for Class A equipment were derived for commercial and industrial environments to provide reasonable protection against interference with licensed communication equipment.

European Community contact:
IBM Deutschland GmbH
Technical Regulations, Department M456
IBM-Allee 1, 71139 Ehningen, Germany
Tele: +49 7032 15-2937
email: tjahn@de.ibm.com

Warning: This is a Class A product. In a domestic environment, this product may cause radio interference, in which case the user may be required to take adequate measures.

VCCI Statement - Japan

この装置は、クラスA 情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。

VCCI-A

The following is a summary of the VCCI Japanese statement in the box above:

This is a Class A product based on the standard of the VCCI Council. If this equipment is used in a domestic environment, radio interference may occur, in which case, the user may be required to take corrective actions.

Japanese Electronics and Information Technology Industries Association (JEITA) Confirmed Harmonics Guideline (products less than or equal to 20 A per phase)

高調波ガイドライン適合品

Japanese Electronics and Information Technology Industries Association (JEITA) Confirmed Harmonics Guideline with Modifications (products greater than 20 A per phase)

高調波ガイドライン準用品

Electromagnetic Interference (EMI) Statement - People's Republic of China

声 明

此为 A 级产品, 在生活环境中, 该产品可能会造成无线电干扰。在这种情况下, 可能需要用户对其干扰采取切实可行的措施。

Declaration: This is a Class A product. In a domestic environment this product may cause radio interference in which case the user may need to perform practical action.

Electromagnetic Interference (EMI) Statement - Taiwan

警告使用者：
這是甲類的資訊產品，在居住的環境中使用時，可能會造成射頻干擾，在這種情況下，使用者會被要求採取某些適當的對策。

The following is a summary of the EMI Taiwan statement above.

Warning: This is a Class A product. In a domestic environment this product may cause radio interference in which case the user will be required to take adequate measures.

IBM Taiwan Contact Information:

台灣IBM 產品服務聯絡方式：
台灣國際商業機器股份有限公司
台北市松仁路7號3樓
電話：0800-016-888

Electromagnetic Interference (EMI) Statement - Korea

이 기기는 업무용(A급)으로 전자파적합기기로서 판매자 또는 사용자는 이 점을 주의하시기 바라며, 가정외의 지역에서 사용하는 것을 목적으로 합니다.

Germany Compliance Statement

Deutschsprachiger EU Hinweis: Hinweis für Geräte der Klasse A EU-Richtlinie zur Elektromagnetischen Verträglichkeit

Dieses Produkt entspricht den Schutzanforderungen der EU-Richtlinie 2004/108/EG zur Angleichung der Rechtsvorschriften über die elektromagnetische Verträglichkeit in den EU-Mitgliedsstaaten und hält die Grenzwerte der EN 55022 Klasse A ein.

Um dieses sicherzustellen, sind die Geräte wie in den Handbüchern beschrieben zu installieren und zu betreiben. Des Weiteren dürfen auch nur von der IBM empfohlene Kabel angeschlossen werden. IBM übernimmt keine Verantwortung für die Einhaltung der Schutzanforderungen, wenn das Produkt ohne Zustimmung von IBM verändert bzw. wenn Erweiterungskomponenten von Fremdherstellern ohne Empfehlung von IBM gesteckt/eingebaut werden.

EN 55022 Klasse A Geräte müssen mit folgendem Warnhinweis versehen werden:
"Warnung: Dieses ist eine Einrichtung der Klasse A. Diese Einrichtung kann im Wohnbereich Funk-Störungen verursachen; in diesem Fall kann vom Betreiber verlangt werden, angemessene Maßnahmen zu ergreifen und dafür aufzukommen."

Deutschland: Einhaltung des Gesetzes über die elektromagnetische Verträglichkeit von Geräten

Dieses Produkt entspricht dem "Gesetz über die elektromagnetische Verträglichkeit von Geräten (EMVG)". Dies ist die Umsetzung der EU-Richtlinie 2004/108/EG in der Bundesrepublik Deutschland.

Zulassungsbescheinigung laut dem Deutschen Gesetz über die elektromagnetische Verträglichkeit von Geräten (EMVG) (bzw. der EMC EG Richtlinie 2004/108/EG) für Geräte der Klasse A

Dieses Gerät ist berechtigt, in Übereinstimmung mit dem Deutschen EMVG das EG-Konformitätszeichen - CE - zu führen.

Verantwortlich für die Einhaltung der EMV Vorschriften ist der Hersteller:
International Business Machines Corp.
New Orchard Road
Armonk, New York 10504
Tel: 914-499-1900

Der verantwortliche Ansprechpartner des Herstellers in der EU ist:
IBM Deutschland GmbH
Technical Regulations, Abteilung M456
IBM-Allee 1, 71139 Ehningen, Germany
Tel: +49 7032 15-2937
email: tjahn@de.ibm.com

Generelle Informationen:

Das Gerät erfüllt die Schutzanforderungen nach EN 55024 und EN 55022 Klasse A.

Electromagnetic Interference (EMI) Statement - Russia

**ВНИМАНИЕ! Настоящее изделие относится к классу А.
В жилых помещениях оно может создавать
радиопомехи, для снижения которых необходимы
дополнительные меры**

Class B Notices

The following Class B statements apply to features designated as electromagnetic compatibility (EMC) Class B in the feature installation information.

Federal Communications Commission (FCC) statement

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult an IBM-authorized dealer or service representative for help.

Properly shielded and grounded cables and connectors must be used in order to meet FCC emission limits. Proper cables and connectors are available from IBM-authorized dealers. IBM is not responsible for any radio or television interference caused by unauthorized changes or modifications to this equipment. Unauthorized changes or modifications could void the user's authority to operate this equipment.

This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Industry Canada Compliance Statement

This Class B digital apparatus complies with Canadian ICES-003.

Avis de conformité à la réglementation d'Industrie Canada

Cet appareil numérique de la classe B est conforme à la norme NMB-003 du Canada.

European Community Compliance Statement

This product is in conformity with the protection requirements of EU Council Directive 2004/108/EC on the approximation of the laws of the Member States relating to electromagnetic compatibility. IBM cannot accept responsibility for any failure to satisfy the protection requirements resulting from a non-recommended modification of the product, including the fitting of non-IBM option cards.

This product has been tested and found to comply with the limits for Class B Information Technology Equipment according to European Standard EN 55022. The limits for Class B equipment were derived for typical residential environments to provide reasonable protection against interference with licensed communication equipment.

European Community contact:
IBM Deutschland GmbH
Technical Regulations, Department M456
IBM-Allee 1, 71139 Ehningen, Germany
Tele: +49 7032 15-2937
email: tjahn@de.ibm.com

VCCI Statement - Japan

この装置は、クラスB情報技術装置です。この装置は、家庭環境で使用することを目的としていますが、この装置がラジオやテレビジョン受信機に近接して使用されると、受信障害を引き起こすことがあります。

取扱説明書に従って正しい取り扱いをして下さい。 VCCI-B

Japanese Electronics and Information Technology Industries Association (JEITA) Confirmed Harmonics Guideline (products less than or equal to 20 A per phase)

高調波ガイドライン適合品

Japanese Electronics and Information Technology Industries Association (JEITA) Confirmed Harmonics Guideline with Modifications (products greater than 20 A per phase)

高調波ガイドライン準用品

IBM Taiwan Contact Information

台灣IBM 產品服務聯絡方式：
台灣國際商業機器股份有限公司
台北市松仁路7號3樓
電話：0800-016-888

Electromagnetic Interference (EMI) Statement - Korea

이 기기는 가정용(B급)으로 전자파적합기기로서 주로 가정에서 사용하는 것을 목적으로 하며, 모든 지역에서 사용할 수 있습니다.

Germany Compliance Statement

Deutschsprachiger EU Hinweis: Hinweis für Geräte der Klasse B EU-Richtlinie zur Elektromagnetischen Verträglichkeit

Dieses Produkt entspricht den Schutzanforderungen der EU-Richtlinie 2004/108/EG zur Angleichung der Rechtsvorschriften über die elektromagnetische Verträglichkeit in den EU-Mitgliedsstaaten und hält die Grenzwerte der EN 55022 Klasse B ein.

Um dieses sicherzustellen, sind die Geräte wie in den Handbüchern beschrieben zu installieren und zu betreiben. Des Weiteren dürfen auch nur von der IBM empfohlene Kabel angeschlossen werden. IBM übernimmt keine Verantwortung für die Einhaltung der Schutzanforderungen, wenn das Produkt ohne Zustimmung von IBM verändert bzw. wenn Erweiterungskomponenten von Fremdherstellern ohne Empfehlung von IBM gesteckt/eingebaut werden.

Deutschland: Einhaltung des Gesetzes über die elektromagnetische Verträglichkeit von Geräten

Dieses Produkt entspricht dem "Gesetz über die elektromagnetische Verträglichkeit von Geräten (EMVG)". Dies ist die Umsetzung der EU-Richtlinie 2004/108/EG in der Bundesrepublik Deutschland.

Zulassungsbescheinigung laut dem Deutschen Gesetz über die elektromagnetische Verträglichkeit von Geräten (EMVG) (bzw. der EMC EG Richtlinie 2004/108/EG) für Geräte der Klasse B

Dieses Gerät ist berechtigt, in Übereinstimmung mit dem Deutschen EMVG das EG-Konformitätszeichen - CE - zu führen.

Verantwortlich für die Einhaltung der EMV Vorschriften ist der Hersteller:
International Business Machines Corp.
New Orchard Road
Armonk, New York 10504
Tel: 914-499-1900

Der verantwortliche Ansprechpartner des Herstellers in der EU ist:
IBM Deutschland GmbH
Technical Regulations, Abteilung M456
IBM-Allee 1, 71139 Ehningen, Germany
Tel: +49 7032 15-2937
email: tjahn@de.ibm.com

Generelle Informationen:

Das Gerät erfüllt die Schutzanforderungen nach EN 55024 und EN 55022 Klasse B.

Terms and conditions

Permissions for the use of these publications is granted subject to the following terms and conditions.

Personal Use: You may reproduce these publications for your personal, noncommercial use provided that all proprietary notices are preserved. You may not distribute, display or make derivative works of these publications, or any portion thereof, without the express consent of the manufacturer.

Commercial Use: You may reproduce, distribute and display these publications solely within your enterprise provided that all proprietary notices are preserved. You may not make derivative works of these publications, or reproduce, distribute or display these publications or any portion thereof outside your enterprise, without the express consent of the manufacturer.

Except as expressly granted in this permission, no other permissions, licenses or rights are granted, either express or implied, to the publications or any information, data, software or other intellectual property contained therein.

System Reference Codes (1xxx-Axxx)

ESCALA Power7



REFERENCE
86 A1 49FF 02

ESCALA Power7

System Reference Codes (1xxx-Axxx)

The ESCALA Power7 publications concern the following models:

- Bull Escala E5-700 (Power 750 / 8233-E8B)
- Bull Escala M6-700 (Power 770 / 9117-MMB)
- Bull Escala M6-705 (Power 770 / 9117-MMC)
- Bull Escala M7-700 (Power 780 / 9179-MHB)
- Bull Escala M7-705 (Power 780 / 9179-MHC)
- Bull Escala E1-700 (Power 710 / 8231-E2B)
- Bull Escala E1-705 (Power 710 / 8231-E1C)
- Bull Escala E2-700 / E2-700T (Power 720 / 8202-E4B)
- Bull Escala E2-705 / E2-705T (Power 720 / 8202-E4C)
- Bull Escala E3-700 (Power 730 / 8231-E2B)
- Bull Escala E3-705 (Power 730 / 8231-E2C)
- Bull Escala E4-700 / E4-700T (Power 740 / 8205-E6B)
- Bull Escala E4-705 (Power 740 / 8205-E6C)

References to Power 755 / 8236-E8C models are irrelevant.

Hardware

October 2011

BULL CEDOC
357 AVENUE PATTON
B.P.20845
49008 ANGERS CEDEX 01
FRANCE

REFERENCE
86 A1 49FF 02

The following copyright notice protects this book under Copyright laws which prohibit such actions as, but not limited to, copying, distributing, modifying, and making derivative works.

Copyright © Bull SAS 2011

Printed in France

Suggestions and criticisms concerning the form, content, and presentation of this book are invited. A form is provided at the end of this book for this purpose.

To order additional copies of this book or other Bull Technical Publications, you are invited to use the Ordering Form also provided at the end of this book.

Trademarks and Acknowledgements

We acknowledge the right of proprietors of trademarks mentioned in this book.

The information in this document is subject to change without notice. Bull will not be liable for errors contained herein, or for incidental or consequential damages in connection with the use of this material.

The manufacturer reserves the right to withdraw the permissions granted herein whenever, in its discretion, the use of the publications is detrimental to its interest or, as determined by the manufacturer, the above instructions are not being properly followed.

You may not download, export or re-export this information except in full compliance with all applicable laws and regulations, including all United States export laws and regulations.

THE MANUFACTURER MAKES NO GUARANTEE ABOUT THE CONTENT OF THESE PUBLICATIONS. THESE PUBLICATIONS ARE PROVIDED "AS-IS" AND WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO IMPLIED WARRANTIES OF MERCHANTABILITY, NON-INFRINGEMENT, AND FITNESS FOR A PARTICULAR PURPOSE.