

Doc. reference : DT-ENG-045-EN	FAQ	
Product : novascale Blade BL265, BL265+	Issued : March 26th, 2012	
Object : HBAs and other PCI devices may stop responding in VMware ESX/ESXi 4.1 and ESX5.0		
Abstract : This note explains how to solve this problem.		

Problem:

Symptoms on VMware ESX/ESXi 4.1 and ESX5.0:

The Host Bus Adapters (HBAs) stop responding, other PCIs devices may also stop responding.

Illegal vector shortly before the Host Bus Adapter (HBA) stops responding to the driver

For example:

```
# vmkernel: 6:01:34:46.970 cpu0:4120)ALERT: APIC: 1823: APICID  
0x00000000 - ESR = 0x40
```

The HBA stops responding to commands.

For example:

```
vmkernel: 6:01:42:36.189 cpu15:4274)<6>qla2xxx 0000:1a:00.0:  
qla2x00_abort_isp: **** FAILED ****
```

```
vmkernel: 6:01:47:36.383 cpu14:4274)<4>qla2xxx 0000:1a:00.0: Failed  
mailbox send register test
```

The HBA card gets marked offline.

For example:

```
vmkernel: 6:01:47:36.383 cpu14:4274)<4>qla2xxx 0000:1a:00.0: ISP error  
recovery failed - board disabled
```

Affected configurations:

The system may be any of the following blade servers:

novascale BL265

novascale BL265+

The system is configured with at least one of the following:

- * VMware ESX Server 4.1, any Update
- * VMware ESXi 4.1 Embedded, any Update
- * VMware ESXi 4.1 Installable, any Update

The system is configured with one or more of the following Options:

Emulex 8 Gigabit Fibre Channel Expansion Card (CIOv) MI= CFSN204-8000

USB Memory Key for VMware ESXi 4.1, MI= USBNESXi-4100

QLogic 4 Gigabit Fibre Channel Expansion Card (CIOv) MI= CFSN203-4000

QLogic 8 Gigabit Fibre Channel Expansion Card (CIOv) MI= CFSN203-8000

QLogic Ethernet and 4 Gigabit Fibre Channel Expansion Card (CFFh) MI= CFEBUB0-0000

QLogic Ethernet and 8 Gigabit Fibre Channel Expansion Card (CFFh) MI= CFEBUB1-0000

Note: This does not imply that the network operating system will work under all combinations of

hardware and software.

Solution:

Update Unified Extensible Firmware Interface (UEFI) to the level specified below:
novascale BL265 and BL265+, update UEFI to version 1.14 (BuildID P9EG53B) or higher.

The file is available from the Bull Support on Line web site at the following URL:
<http://support.bull.com>

Workaround:

Follow these instructions and then read VMware Knowledge Base article 1030265, available at the following URL:

[http://kb.vmware.com/selfservice/microsites/search.do?
language=en_US&cmd=displayKC&externalId=1030265](http://kb.vmware.com/selfservice/microsites/search.do?language=en_US&cmd=displayKC&externalId=1030265)

Also, manually disable interrupt remapping on these two (2) novascale Blades:

- BL265
- BL265+

To disable interrupt remapping, perform one of these options:

For ESX/ESXi 4.1

Run these commands from a console or SSH session:

```
# esxcfg-advcfg -k TRUE iovDisableIR  
# reboot
```

To check if interrupt mapping is set after the reboot, enter the following command:

```
# esxcfg-info -c  
iovDisableIR=TRUE
```

For the vSphere Client:

- a. Select **Configuration**, then (Software) Click **Advanced Settings**, and Click **VMkernel**.
- b. Select **VMkernel.Boot.iovDisableIR** and Click **OK**.
- c. Reboot the **ESX host**.

For ESXi 5.0

ESXi 5.0 does not provide this parameter as a GUI client configurable option. It can only be changed via esxcli or PowerCLI.

To set the interrupt mapping via **esxcli**:

List the present setting:

```
# esxcli system settings kernel list -o iovDisableIR
```

The output is similar to:

Name	Type	Description	Configured	Runtime	Default
------	------	-------------	------------	---------	---------

iovDisableIR Bool Disable Interrrupt Routing in the IOMMU FALSE FALSE FALSE

Disable interrupt mapping on the host with this command:

```
# esxcli system settings kernel set --setting=iovDisableIR -v TRUE
```

Reboot the host after running the command.

To set the interrupt mapping through **PowerCLI**:

```
PowerCLI> Connect-VIServer -Server 10.21.69.233 -User Administrator  
-Password passwd  
PowerCLI> $myesxcli = Get-EsxCli -VMHost 10.21.69.111  
PowerCLI> $myesxcli.system.settings.kernel.list("iovDisableIR")  
  
Configured : FALSE  
Default : FALSE  
Description : Disable Interrrupt Routing in the IOMMU  
Name : iovDisableIR  
Runtime : FALSE  
Type : Bool  
  
PowerCLI> $myesxcli.system.settings.kernel.set("iovDisableIR", "TRUE")  
true  
  
PowerCLI> $myesxcli.system.settings.kernel.list("iovDisableIR")  
  
Configured : TRUE  
Default : FALSE  
Description : Disable Interrrupt Routing in the IOMMU  
Name : iovDisableIR  
Runtime : FALSE  
Type : Bool
```

After the host has finished booting you see this entry in the log file /var/log/boot.gz confirming that interrupt mapping has been disabled:

```
TSC: 543432 cpu0:0)BootConfig: 419: iovDisableIR = TRUE
```