

**Document Title:** How to update RAID BIOS of ROMB (Embedded SAS RAID) ?

**Document ID:** TID0701261424

**Creation Date:** 26 Jan. 2007

**Modified Date:**


**Document Revision:** 0  
1 move BBU troubleshooting to TID0612071320

**Product Class:** Servers

**Product and Version:** T880 / R480

## Symptoms / Facts

ROMB RAID controller is not properly identified on POST "???" see below:



Note: in this screen shot, there is also an error about BBU. See TID0612071320 for this problem

## Cause

BIOS coming by default with motherboard is not up to date.

## Solutions / Fixes

---

Update Flash ROMB firmware using BOOT\_CD 1.0.7 or higher

To confirm flash is ok, “???” should be replaced by “ROMB” on .

## See also (if applicable)

---

This update will be included in automatic mode in version 1.0.7 of BOOT\_CD.

**Document owner:** COE Servers

**Applies to:** T880 / R480