

Emulex LPe12000 Family Firmware Release Notes

Versions: 2.01a11

Date: March 2013

Purpose and Contact Information

These release notes describe the resolved known issues and current known issues associated with this firmware release.

For the latest product documentation, go to www.Emulex.com. If you have questions or require additional information, contact an authorized Emulex® technical support representative at tech.support@emulex.com, 800-854-7112 (US/Canada toll free), +1 714-885-3402 (US/International), or +44 1189-772929 (Europe, Middle East, and Africa).

Resolved Issues from Firmware Version 2.01a10

1. **Added support for disabling out-of-order frame handling.**
2. **Added support for 4G loopback tests.**
3. **Added support to disable the laser during a firmware core dump.**
4. **Corrected an issue that occurred when injecting Ref Tag errors that caused an invalid PCIE address.**
5. **Sequence Responder bit is no longer incorrectly set after the first XFR-RDY.**
6. **Corrected an issue with ABTS retries and BA_ACC checking not being performed (ABTS retry in Target mode).**
7. **Corrected an issue with the adapter hanging during link bounce due to the incorrect release of SPECIAL_TX_BUFFER.**

Known Issues

There are no known issues for this release.

Copyright © 2013 Emulex. All rights reserved worldwide. This document refers to various companies and products by their trade names. In most, if not all cases, their respective companies claim these designations as trademarks or registered trademarks. This information is provided for reference only. Although this information is believed to be accurate and reliable at the time of publication, Emulex assumes no responsibility for errors or omissions. Emulex reserves the right to make changes or corrections without notice. This report is the property of Emulex and may not be duplicated without permission from the Company.