



esxi6.5.0.update02-8294253-Bullion-S-1.0

Release notes *(June 2018)*

This document describes the content of esxi6.5.0.update02-8294253-Bullion-S-1.0 custom image.

- ISO Image: **esxi6.5.0.update02-8294253-Bullion-S-1.0.iso**
- MD5SUM: 0F1D1CDD6ABDFD3C5DFB3E6E8F9023E6

Description of components

Additional and updated components:

| Name | Version | Vendor | Acceptance Level |
|----------------------------|-----------------------------------|--------|------------------|
| elxnet | 11.4.1255.0-1OEM.650.0.0.4598673 | EMU | VMwareCertified |
| brcmfcoe | 11.4.1216.0-1OEM.650.0.0.4598673 | EMU | PartnerSupported |
| emulex-cim-provider | 11.2.156.19-01OEM.650.0.0.4240417 | EMU | VMwareAccepted |
| lpfc | 11.2.266.0-1OEM.650.0.0.4598673 | EMU | VMwareCertified |
| brcm-cim-provider | 11.4.1160.0-01OEM.650.0.0.4598673 | EMU | VMwareAccepted |
| lsiprovider | 500.04.V0.70-0004 | LSI | VMwareAccepted |
| vmware-esx-storcli-1.23.02 | 1.23.02-01 | LSI | PartnerSupported |