



# ESXi 5.5 Custom Image 3.1 for bullion

## Release Notes (2013-11-07)

This **Release Notes** describes the content of ESXi 5.5 Custom Image 3.1 for bullion machines

### 1 **Description of components**

- 1 Base Image Profile from *VMware*

#### **ESXi-5.5.0-1331820-standard**

Standard ESXi 5.5 hypervisor

- 2 Additional and updated components from *Emulex*

- 2.1 CIM Provider

#### **emulex-cim-provider 3.8.19.1**

The *Emulex CIM Provider* is required by the *Emulex One Command Manager* vCenter plugin, which allows to update most *Emulex* firmwares on the fly

- 2.2 UCNA and HBA FC/FCoE lpfc driver

#### **lpfc 10.0.575.8**

- 2.3 UCNA Ethernet elxnet driver

#### **elxnet 10.0.575.7**

- 2.4 UCNA iSCSI driver

#### **scsi-be2iscsi/ima-be2iscsi 4.6.261.0**

- 3 Updated components from *Intel*

- 3.1 ixgbe driver (for Intel X520 10Gb/s Ethernet PCIe adapters)

#### **net-ixgbe 3.18.7**

- 3.2 igb driver (for Intel 1Gb/s Ethernet PCIe adapters)

#### **net-igb 5.0.5.1**

- 4 Additional and updated components from *LSI*

- 4.1 CIM Provider

#### **lsiprovider 00.39.V0.02**

The *LSI CIM Provider* allows to manage RAID array via *LSI MegaRAID Storage Manager* software

- 4.2 Updated mpt2sas driver

#### **mpt2sas 17.00.01.00**