



ESXi 6.5 Patch 02 build 7388607 custom image for BullSequana S

Release notes (February 2018)

This document describes the content of ESXi 6.5 Patch 02 build 7388607 custom image for BullSequana S.

- ISO Image: **esxi6.5-7388607-SequanaS-1.1.iso**
- MD5 HASH : C120101F9ABB374F7B00D6DEADA6F2A5

Description of components

Additional and updated components:

Name	Version	Vendor	Acceptance Level
lsi-mr3	7.702.14.00-1OEM.650.0.0.4598673	Avago	VMwareCertified
lsi-msgpt3	15.00.02.00-1OEM.650.0.0.4598673	Avago	VMwareCertified
emulex-cim-provider	11.4.142.17-01OEM.650.0.0.4598673	EMU	VMwareAccepted
lpfc	11.4.199.0-1OEM.650.0.0.4598673	EMU	VMwareCertified
net-i40e	2.0.7-1OEM.600.0.0.2494585	INT	VMwareCertified
net-igb	5.3.3-1OEM.600.0.0.2494585	INT	VMwareCertified
net-ixgbe	4.5.3-1OEM.600.0.0.2494585	INT	VMwareCertified
lsiprovider	500.04.V0.66-0002	LSI	VMwareAccepted
vmware-esx-storcli-1.23.02	1.23.02-01	LSI	PartnerSupported
nmlx5-core	4.16.10.3-1OEM.650.0.0.4598673	MEL	VMwareCertified
nmlx5-rdma	4.16.10.3-1OEM.650.0.0.4598673	MEL	VMwareCertified
nmst	4.8.0.26-1OEM.650.0.0.4598673	MEL	PartnerSupported
mft	4.8.0.26-0	Mellanox	PartnerSupported
bnxtnet	20.8.10.0-1OEM.650.0.0.4598673	BCM	VMwareCertified