

Hardware Management Console Readme

For use with Version 9 Release 1 Maintenance 910 (V9 R1 M910)

Updated: 14 May 2018

(C) Copyright International Business Machines Corp., 2018 All rights reserved.

Contents

The information in this Readme contains the fix list and other package information about the Hardware Management Console.

- [PTF MH01734](#)
- [PTF MH01736](#)
- [List of fixes](#)
- [Installation](#)

PTF MH01734

This package includes fixes for HMC V9 R1 M910. You can reference this package by APAR MB04120 and PTF MH01734. This image must be installed on top of Recovery image HMC V9 R1 M910 (PTF MH01733).

<i>Package information</i>				
Package name	Size	Checksum (sha1sum)	APAR#	PTF#
MH01734_x86.is	300059238	c9ba041cd774290400337b1d18deaeffc64235	MB0412	MH0173
o	4	78	0	4
Splash Panel information (or lshmc -V output)				
"version= Version: 9 Release: 1 Service Pack: 910 HMC Build level 1803291143 MH01734 - Required fix for HMC V9R1 M910 (Base) [x86_64] ", "base_version=V9R1 "				

PTF MH01736

This package includes fixes for HMC V9 R1 M910. You can reference this package by APAR MB04122 and PTF MH01736. This image must be installed on top of Recovery image HMC V9 R1 M910 (PTF MH01735).

<i>Package information</i>				
Package name	Size	Checksum (sha1sum)	APAR#	PTF#
MH01736_ppc.iso	2957154304	cd2c254205c8c49a349bc34714252240c9efb874	MB04122	MH01736
Splash Panel information (or lshmc -V output)				
<pre>"version= Version: 9 Release: 1 Service Pack: 910 HMC Build level 1803291143 MH01736 - Required fix for HMC V9R1 M910 (Base) [ppc64le] ";"base_version=V9R1 "</pre>				

List of fixes

General fixes

- Fixed an issue where after a power off of the managed system system logical partitions and vios servers are not visible in the enhanced UI. Refreshing the view with F5 makes them visible again.
- Fixed an issue where server properties that are modified while the server is powered off appear to be saved without any error however the new setting is discarded.
- Fixed an issue with the Net Promoter Score prompt where the HMC appliance MTMS was not listed and selecting some servers resulted in the error "*could not parse parameter: offeringID*".
- Corrected the list of feature codes displayed for the following physical I/O adapters: CCIN 5729, 577D, 577F, 578D, 578E, 578F.
- Fixed **lshwres** command to list vNICs to provide and store the value for parameter 'os_device_name' for the first instance of execution unless user invokes explicitly with **-Fos_device_name** to query.

Installation

Installation instructions for HMC Version 9 upgrades and corrective service can be found at these locations:

[Upgrading or restoring HMC Version 9](#)

[Updating, upgrading, and migrating your HMC machine code](#)

Instructions and images for upgrading via a remote network install can be found here:

[HMC V9 network installation images and installation instructions](#)